10/09/2008 14:58:23

Page 1 of 3

Document Types: IR, LER From 01/01/2007 to 12/31/2007

U.S. Nuclear Regulatory Commission Human Factors Information System (HFIS) IR/LER Category Analysis by Docket Report

Total Number of Hits: 54
National Average: 41
2x National Average: 82
National Median: 24

Average for Selected Dockets: 54

	Facility Name: Browns Ferry 2 Docket (050- 00260)			
Details	Department	Work Type	Docket/Report	
Communication / IR				
161 - Communication LTA	O - Operations	O - Control Room Ops	050-00260/2007-002	
Number of Items for this Docket: 1				
Percent of Total for this Docket: 2				
Fitness for Duty / IR				
125 - Work hour control	I - Instrumentation & Control	M - Maintenance / Repair	050-00260/2007-002	
Number of Items for this Docket: 1 Percent of Total for this Docket: 2				
Human-System Interface & Environmnt / IR				
170 - HSI or information availability / quality LTA	O - Operations	B - Bal of Plant Ops	050-00260/2007-008	
Number of Items for this Docket: 1 Percent of Total for this Docket: 2				
Oversight / IR				
130 - Inadequate suprevision / command and control	M - Mechanical	M - Maintenance / Repair	050-00260/2007-003	
130 - Inadequate suprevision / command and control	O - Operations	O - Control Room Ops	050-00260/2007-002	
131 - Management expectations or directions LTA	I - Instrumentation & Control	M - Maintenance / Repair	050-00260/2007-002	
131 - Management expectations or directions LTA	O - Operations	O - Control Room Ops	050-00260/2007-002	
Number of Items for this Docket: 4 Percent of Total for this Docket: 7				
Procedures & Reference Document / IR				
110 - No procedure / reference documents	O - Operations	O - Control Room Ops	050-00260/2007-004	
111 - Procedure / reference document technical content	I - Instrumentation & Control	S - Surveillance	050-00260/2007-008	
111 - Procedure / reference document technical content	M - Mechanical	M - Maintenance / Repair	050-00260/2007-003	
111 - Procedure / reference document technical content	M - Mechanical	R - Refueling	050-00260/2007-002	
111 - Procedure / reference document technical content	O - Operations	O - Control Room Ops	050-00260/2007-008	
111 - Procedure / reference document technical content	O - Operations	S - Surveillance	050-00260/2007-008	
111 - Procedure / reference document technical content	O - Operations	S - Surveillance	050-00260/2007-008	
111 - Procedure / reference document technical content	O - Operations	S - Surveillance	050-00260/2007-008	
113 - Procedure / reference document development and maintenance L'	I - Instrumentation & Control	S - Surveillance	050-00260/2007-003	
Number of Items for this Docket: 9 Percent of Total for this Docket: 17				
Problem Identification & Resolution / IR				
140 - Problem not completely or accurately identified	M - Mechanical	M - Maintenance / Repair	050-00260/2007-008	

10/09/2008 14:58:23

Page 2 of 3

Document Types: IR, LER From 01/01/2007 to 12/31/2007

U.S. Nuclear Regulatory Commission Human Factors Information System (HFIS) IR/LER Category Analysis by Docket Report

Total Number of Hits: 54
National Average: 41
2x National Average: 82

National Median: 24
Average for Selected Dockets: 54

	Facility Name: Browns Ferry 2 Do	Facility Name: Browns Ferry 2 Docket (050- 00260)		
Details	Department	Work Type	Docket/Report	
Problem Identification & Resolution / IR				
140 - Problem not completely or accurately identified	M - Mechanical	M - Maintenance / Repair	050-00260/2007-008	
142 - Operating experience (OE) review LTA	C - Chemistry	S - Surveillance	050-00260/2007-008	
143 - Tracking / trending LTA	X - Site-wide	X - Site-wide	050-00260/2007-003	
143 - Tracking / trending LTA	X - Site-wide	X - Site-wide	050-00260/2007-008	
145 - Causal development LTA	M - Mechanical	F - Modification	050-00260/2007-008	
145 - Causal development LTA	M - Mechanical	M - Maintenance / Repair	050-00260/2007-008	
146 - Evaluation LTA	S - Specialized task force	W - Assessment	050-00260/2007-003	
147 - Individual corrective action LTA	O - Operations	O - Control Room Ops	050-00260/2007-002	
147 - Individual corrective action LTA	O - Operations	O - Control Room Ops	050-00260/2007-002	
148 - Action not yet started or untimely	M - Mechanical	M - Maintenance / Repair	050-00260/2007-008	
148 - Action not yet started or untimely	M - Mechanical	M - Maintenance / Repair	050-00260/2007-008	
150 - Programmatic deficiency	E - Electrical	M - Maintenance / Repair	050-00260/2007-008	
150 - Programmatic deficiency	X - Site-wide	X - Site-wide	050-00260/2007-008	
Number of Items for this Docket: 14 Percent of Total for this Docket: 26				
Training / IR				
100 - Training LTA	T - Training	T - Testing	050-00260/2007-002	
100 - Training LTA	T - Training	T - Testing	050-00260/2007-002	
101 - Training process problem	T - Training	T - Testing	050-00260/2007-002	
101 - Training process problem	T - Training	T - Testing	050-00260/2007-002	
103 - Simulator training LTA	O - Operations	O - Control Room Ops	050-00260/2007-002	
103 - Simulator training LTA	O - Operations	O - Control Room Ops	050-00260/2007-002	
Number of Items for this Docket: 6 Percent of Total for this Docket: 11				
Work Planning & Practices / IR				
180 - Scheduling and planning LTA	A - Administrative Support	A - Administrative	050-00260/2007-003	
181 - Inadequate staffing / task allocation	O - Operations	O - Control Room Ops	050-00260/2007-004	
182 - Work package quality LTA	M - Mechanical	F - Modification	050-00260/2007-004	
182 - Work package quality LTA	M - Mechanical	M - Maintenance / Repair	050-00260/2007-003	
183 - Pre-job activities LTA	O - Operations	O - Control Room Ops	050-00260/2007-003	
185 - Procedural adherence LTA	H - Health Physics	H - Health Physics	050-00260/2007-002	

10/09/2008 14:58:23

Page 3 of 3

Document Types: IR, LER From 01/01/2007 to 12/31/2007

Total Items for this Docket: 54

U.S. Nuclear Regulatory Commission Human Factors Information System (HFIS) IR/LER Category Analysis by Docket Report

Total Number of Hits: 54
National Average: 41

2x National Average: 82

National Median: 24

Average for Selected Dockets: 54

Facility Name: Browns Ferry 2 Docket (050- 00260)					
Details	Department	Work Type	Docket/Report		
Work Planning & Practices / IR					
185 - Procedural adherence LTA	H - Health Physics	Y - Shipping / transportatic	050-00260/2007-002		
185 - Procedural adherence LTA	M - Mechanical	M - Maintenance / Repair	050-00260/2007-003		
185 - Procedural adherence LTA	M - Mechanical	M - Maintenance / Repair	050-00260/2007-003		
185 - Procedural adherence LTA	O - Operations	O - Control Room Ops	050-00260/2007-002		
185 - Procedural adherence LTA	O - Operations	O - Control Room Ops	050-00260/2007-003		
186 - Failure to take action / meet requirements	M - Mechanical	M - Maintenance / Repair	050-00260/2007-008		
188 - Work practice or craft skill LTA	I - Instrumentation & Control	S - Surveillance	050-00260/2007-003		
189 - Recognition of adverse condition / questioning attitude LTA	M - Mechanical	M - Maintenance / Repair	050-00260/2007-008		
189 - Recognition of adverse condition / questioning attitude LTA	O - Operations	O - Control Room Ops	050-00260/2007-002		
190 - Failure to stop work / non-conservative decision making	M - Mechanical	M - Maintenance / Repair	050-00260/2007-008		
196 - Independent verification / plant tours LTA	M - Mechanical	M - Maintenance / Repair	050-00260/2007-003		
Number of Items for this Docket: 18					
Percent of Total for this Docket: 33					