

**U.S. Nuclear Regulatory Commission  
 Human Factors Information System (HFIS)  
 IR/LER Category Analysis by Docket Report**

Total Number of Hits: 3662  
 National Average: 35  
 2x National Average: 70  
 National Median: 21  
 Average for Selected Dockets: 35

**Facility Name: Oconee 1 Docket (050- 00269)**

Details	Department	Work Type	Docket/Report
<b>Human-System Interface &amp; Environmnt / IR</b>			
170 - HSI or information availability / quality LTA	I - Instrumentation & Control	T - Testing	050-00269/2008-003
170 - HSI or information availability / quality LTA	M - Mechanical	M - Maintenance / Repair	050-00269/2008-006
173 - Physical conditions LTA	M - Mechanical	M - Maintenance / Repair	050-00269/2008-006
<b>Number of Items for this Docket: 3</b>			
<b>Percent of Total for this Docket: 9</b>			
<b>Oversight / IR</b>			
130 - Inadequate supervision / command and control	O - Operations	O - Control Room Ops	050-00269/2008-008
131 - Management expectations or directions LTA	O - Operations	O - Control Room Ops	050-00269/2008-008
<b>Number of Items for this Docket: 2</b>			
<b>Percent of Total for this Docket: 6</b>			
<b>Procedures &amp; Reference Document / IR</b>			
111 - Procedure / reference document technical content	G - Engineering	G - Design	050-00269/2008-006
111 - Procedure / reference document technical content	M - Mechanical	M - Maintenance / Repair	050-00269/2008-003
111 - Procedure / reference document technical content	M - Mechanical	M - Maintenance / Repair	050-00269/2008-004
111 - Procedure / reference document technical content	O - Operations	O - Control Room Ops	050-00269/2008-008
<b>Number of Items for this Docket: 4</b>			
<b>Percent of Total for this Docket: 13</b>			
<b>Problem Identification &amp; Resolution / IR</b>			
140 - Problem not completely or accurately identified	O - Operations	O - Control Room Ops	050-00269/2008-008
142 - Operating experience (OE) review LTA	G - Engineering	G - Design	050-00269/2008-006
146 - Evaluation LTA	O - Operations	O - Control Room Ops	050-00269/2008-008
148 - Action not yet started or untimely	O - Operations	O - Control Room Ops	050-00269/2008-008
148 - Action not yet started or untimely	O - Operations	O - Control Room Ops	050-00269/2008-008
<b>Number of Items for this Docket: 5</b>			
<b>Percent of Total for this Docket: 16</b>			
<b>Work Planning &amp; Practices / IR</b>			
185 - Procedural adherence LTA	G - Engineering	G - Design	050-00269/2007-005
185 - Procedural adherence LTA	M - Mechanical	M - Maintenance / Repair	050-00269/2008-002
185 - Procedural adherence LTA	O - Operations	O - Control Room Ops	050-00269/2008-008
185 - Procedural adherence LTA	O - Operations	O - Control Room Ops	050-00269/2008-008
185 - Procedural adherence LTA	O - Operations	O - Control Room Ops	050-00269/2008-008
185 - Procedural adherence LTA	O - Operations	O - Control Room Ops	050-00269/2008-008

**U.S. Nuclear Regulatory Commission  
Human Factors Information System (HFIS)  
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 3662

National Average: 35

2x National Average: 70

National Median: 21

Average for Selected Dockets: 35

---

**Facility Name: Oconee 1 Docket (050- 00269)**

**Details****Work Planning & Practices / IR**

	<b>Department</b>	<b>Work Type</b>	<b>Docket/Report</b>
185 - Procedural adherence LTA	O - Operations	O - Control Room Ops	050-00269/2008-008
186 - Failure to take action / meet requirements	I - Instrumentation & Control	T - Testing	050-00269/2008-003
186 - Failure to take action / meet requirements	O - Operations	O - Control Room Ops	050-00269/2008-008
187 - Action implementation LTA	G - Engineering	G - Design	050-00269/2008-006
187 - Action implementation LTA	G - Engineering	G - Design	050-00269/2008-006
188 - Work practice or craft skill LTA	M - Mechanical	M - Maintenance / Repair	050-00269/2008-002
189 - Recognition of adverse condition / questioning attitude LTA	O - Operations	O - Control Room Ops	050-00269/2008-008
189 - Recognition of adverse condition / questioning attitude LTA	O - Operations	O - Control Room Ops	050-00269/2008-008
190 - Failure to stop work / non-conservative decision making	G - Engineering	G - Design	050-00269/2008-006
190 - Failure to stop work / non-conservative decision making	O - Operations	O - Control Room Ops	050-00269/2008-008
190 - Failure to stop work / non-conservative decision making	O - Operations	O - Control Room Ops	050-00269/2008-008
197 - Self-check LTA	M - Mechanical	T - Testing	050-00269/2008-002
<b>Number of Items for this Docket:</b> 18			
<b>Percent of Total for this Docket:</b> 56			

---

**Total Items for this Docket:** 32

---