

U.S. Nuclear Regulatory Commission  
Human Factors Information System (HFIS)  
IR/LER Category Analysis by Docket Report

Total Number of Hits: 3662  
National Average: 35  
2x National Average: 70  
National Median: 21  
Average for Selected Dockets: 35

---

Facility Name: Peach Bottom 2 Docket (050- 00277)

Details	Department	Work Type	Docket/Report
<b>Procedures &amp; Reference Document / IR</b>			
111 - Procedure / reference document technical content	D - Emergency Planning	Q - Fire Protection	050-00277/2008-002
111 - Procedure / reference document technical content	H - Health Physics	H - Health Physics	050-00277/2008-502
111 - Procedure / reference document technical content	M - Mechanical	M - Maintenance / Repair	050-00277/2007-005
113 - Procedure / reference document development and maintenance L	D - Emergency Planning	Q - Fire Protection	050-00277/2008-002
<b>Number of Items for this Docket: 4</b>			
<b>Percent of Total for this Docket: 17</b>			
<hr/>			
<b>Problem Identification &amp; Resolution / IR</b>			
140 - Problem not completely or accurately identified	G - Engineering	G - Design	050-00277/2007-005
142 - Operating experience (OE) review LTA	M - Mechanical	M - Maintenance / Repair	050-00277/2007-005
146 - Evaluation LTA	G - Engineering	G - Design	050-00277/2007-005
147 - Individual corrective action LTA	E - Electrical	S - Surveillance	050-00277/2008-007
147 - Individual corrective action LTA	G - Engineering	G - Design	050-00277/2007-005
148 - Action not yet started or untimely	E - Electrical	S - Surveillance	050-00277/2008-007
<b>Number of Items for this Docket: 6</b>			
<b>Percent of Total for this Docket: 26</b>			
<hr/>			
<b>Work Planning &amp; Practices / IR</b>			
185 - Procedural adherence LTA	D - Emergency Planning	Q - Fire Protection	050-00277/2008-002
185 - Procedural adherence LTA	M - Mechanical	M - Maintenance / Repair	050-00277/2007-005
186 - Failure to take action / meet requirements	E - Electrical	S - Surveillance	050-00277/2008-007
186 - Failure to take action / meet requirements	H - Health Physics	H - Health Physics	050-00277/2008-502
186 - Failure to take action / meet requirements	M - Mechanical	M - Maintenance / Repair	050-00277/2007-005
186 - Failure to take action / meet requirements	M - Mechanical	Q - Fire Protection	050-00277/2008-003
187 - Action implementation LTA	E - Electrical	G - Design	050-00277/2008-007
187 - Action implementation LTA	G - Engineering	G - Design	050-00277/2008-007
187 - Action implementation LTA	H - Health Physics	H - Health Physics	050-00277/2008-502
189 - Recognition of adverse condition / questioning attitude LTA	D - Emergency Planning	Q - Fire Protection	050-00277/2008-002
189 - Recognition of adverse condition / questioning attitude LTA	M - Mechanical	M - Maintenance / Repair	050-00277/2007-005
190 - Failure to stop work / non-conservative decision making	D - Emergency Planning	Q - Fire Protection	050-00277/2008-002

U.S. Nuclear Regulatory Commission  
Human Factors Information System (HFIS)  
IR/LER Category Analysis by Docket Report

Total Number of Hits: 3662  
National Average: 35  
2x National Average: 70  
National Median: 21  
Average for Selected Dockets: 35

---

**Facility Name: Peach Bottom 2 Docket (050- 00277)**

Details	Department	Work Type	Docket/Report
<b>Work Planning &amp; Practices / IR</b>			
194 - Housekeeping LTA	M - Mechanical	Q - Fire Protection	050-00277/2008-003
<b>Number of Items for this Docket:</b> 13			
<b>Percent of Total for this Docket:</b> 57			

---

**Total Items for this Docket:** 23

---