

**U.S. Nuclear Regulatory Commission
Human Factors Information System (HFIS)
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 3662

National Average: 35

2x National Average: 70

National Median: 21

Average for Selected Dockets: 35

Facility Name: Sequoyah 2 Docket (050- 00328)

Details	Department	Work Type	Docket/Report
Communication / IR			
160 - No communication / information not communicated	A - Administrative Support	A - Administrative	050-00328/2007-005
Number of Items for this Docket: 1			
Percent of Total for this Docket: 4			
<hr/>			
Human-System Interface & Environmnt / IR			
170 - HSI or information availability / quality LTA	M - Mechanical	Q - Fire Protection	050-00328/2008-006
Number of Items for this Docket: 1			
Percent of Total for this Docket: 4			
<hr/>			
Procedures & Reference Document / IR			
111 - Procedure / reference document technical content	M - Mechanical	M - Maintenance / Repair	050-00328/2008-002
113 - Procedure / reference document development and maintenance L	E - Electrical	M - Maintenance / Repair	050-00328/2007-005
Number of Items for this Docket: 2			
Percent of Total for this Docket: 8			
<hr/>			
Problem Identification & Resolution / IR			
147 - Individual corrective action LTA	G - Engineering	Q - Fire Protection	050-00328/2008-006
Number of Items for this Docket: 1			
Percent of Total for this Docket: 4			
<hr/>			
Training / IR			
101 - Training process problem	T - Training	N - Training	050-00328/2007-005
Number of Items for this Docket: 1			
Percent of Total for this Docket: 4			
<hr/>			
Work Planning & Practices / IR			
182 - Work package quality LTA	M - Mechanical	M - Maintenance / Repair	050-00328/2008-002
184 - Tag outs LTA	D - Emergency Planning	Q - Fire Protection	050-00328/2008-002
184 - Tag outs LTA	M - Mechanical	M - Maintenance / Repair	050-00328/2008-002
185 - Procedural adherence LTA	D - Emergency Planning	Q - Fire Protection	050-00328/2008-002
185 - Procedural adherence LTA	M - Mechanical	M - Maintenance / Repair	050-00328/2007-005
185 - Procedural adherence LTA	M - Mechanical	M - Maintenance / Repair	050-00328/2008-002
185 - Procedural adherence LTA	M - Mechanical	Q - Fire Protection	050-00328/2008-006
185 - Procedural adherence LTA	M - Mechanical	T - Testing	050-00328/2008-002
185 - Procedural adherence LTA	O - Operations	O - Control Room Ops	050-00328/2008-004
186 - Failure to take action / meet requirements	D - Emergency Planning	Q - Fire Protection	050-00328/2008-002
186 - Failure to take action / meet requirements	M - Mechanical	M - Maintenance / Repair	050-00328/2008-002

**U.S. Nuclear Regulatory Commission
Human Factors Information System (HFIS)
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 3662

National Average: 35

2x National Average: 70

National Median: 21

Average for Selected Dockets: 35

Facility Name: Sequoyah 2 Docket (050- 00328)

Details	Department	Work Type	Docket/Report
Work Planning & Practices / IR			
186 - Failure to take action / meet requirements	M - Mechanical	M - Maintenance / Repair	050-00328/2008-004
186 - Failure to take action / meet requirements	M - Mechanical	Q - Fire Protection	050-00328/2008-006
186 - Failure to take action / meet requirements	M - Mechanical	Q - Fire Protection	050-00328/2008-006
186 - Failure to take action / meet requirements	M - Mechanical	Q - Fire Protection	050-00328/2008-006
186 - Failure to take action / meet requirements	O - Operations	O - Control Room Ops	050-00328/2008-004
187 - Action implementation LTA	G - Engineering	G - Design	050-00328/2007-005
188 - Work practice or craft skill LTA	M - Mechanical	M - Maintenance / Repair	050-00328/2007-005
189 - Recognition of adverse condition / questioning attitude LTA	M - Mechanical	Q - Fire Protection	050-00328/2008-006
194 - Housekeeping LTA	M - Mechanical	M - Maintenance / Repair	050-00328/2007-005

Number of Items for this Docket: 20**Percent of Total for this Docket:** 77

Total Items for this Docket: 26
