

8.4 REGULATORY INSPECTION SUMMARY

Date: 12-06-06
To: (Plant Mgr.) Mike Beckham
From: Linda Campbell

Regulatory Inspection Summary

- 1. Facility Inspected Kingston Fossil Plant
2. Date of Inspection & duration 12-06-06 1 hour
3. Purpose of Inspection (routine compliance, NOV follow-up, permit renewal) Routine Compliance plus inspection of new seep on stacking cells.
4. Media covered during inspection Solid Waste
5. Name of Inspector & Agency Rick Brown, TDEC
6. Facility personnel participating or contacted during inspection Linda Campbell, Jim Settles, & Matt Phillips

7. Observations or problem identified by inspector - Observations: "A small seep (actually several) has occurred on the back side along the public road near where it happened before. They have stopped sluicing ash into upper (original) cells & have let them dry out. The surface is solid & dry right now. They are sluicing into the interim cell now. They have placed piezometers along seep area and are studying it; also pumping water out from a well. Soon they will dig into it as part of the study. They placed rock along the seeps to keep ash from coming out. Observe the site, it is in satisfactory condition." NOTE: The above information was taken from Mr. Brown's evaluation form.

8. Samples collected No

9. Records Reviewed No

10. Deficiencies No

Submitted by: Linda Campbell

cc: Mgr., ENV. AFF. (Betty Dyer)

NOTE: This summary is to be provided to the facility manager and faxed or e-mailed to ENV AFF (751-7011) by the close of business on the day following the inspection. (See Section 6.2.6)