

Event Page

On way in mine I opened dust in the air when we got to 5 Ellis tail. Once we rounded the S curve I started seeing metal on the track we calmed to over cast and several blades were blown out and laying on track. We stopped and moved them. Then started on I noticed apr 3 stopping at different locations on left side of track going in that was blown out when we got to apr 50 BK dust was getting heavier when we got to apr 55 BK we saw a light coming down the track We stopped and it was Tim Blake He said they hold for blades to stop the Man trip and he couldn't get it stopped quick he said that the men were up the track 20 BKs so we left man trip set got the SCSRS off trip and took them back to where the Man trip was setting on the track got the Men out and tried to revive them but couldn't we loaded them back up and brought them out I gave CPR & Mouth to Mouth to one of the men but didn't help We measured 0% CH4 and .20 CO at the scene

Tim also stated that we tried to put the man SCSRS on them he stated he tried for apr 35 man or man He said he couldn't hear one of the men's SCSR