

DEPARTMENT OF THE ARMY
Wilmington District, Corps of Engineers
69 Darlington Avenue
Wilmington, North Carolina 28403

CESAW-OP-N

September 30, 2013

NAVIGATION NOTICE NO. 2013-NH-016

HATTERAS CHANNELS,
ROLLINSON CHANNEL

A hazard to navigation exists in the Hatteras Channels at Rollinson Channel (authorized depth -12 ft.) near Hatteras, NC. Severe shoaling restricts the entire width of the Federal Navigation Channel between US Coast Guard buoys 33 & 35. Conditions in this channel are shallower than -6 ft at Mean Low Water.

Mariners are urged to transit at their slowest safe speed and proceed with extreme caution. The latest hydrographic survey information can be viewed and downloaded from the Wilmington District website: <http://www.saw.usace.army.mil/Missions/Navigation/HydrographicSurveys/SideChannelsSmallHarbors.aspx>

The point of contact with the Wilmington District is Mr. Todd Horton, Chief of Waterways Management, at (910) 251-4067.



ROGER BULLOCK
Deputy, Operations Division
Chief, Navigation Branch