

Logistics Service Bulletin

THE BILLBOARD

ISSUE 16-16 The Billboard is Published by
Primus Solutions, Inc., Fort Sill Project
12 September 2016 Expires 12 September 2017

Safety Issue – Motor Vehicle Chock Blocks and Drip Pans

- 1. All Tactical vehicles require chock blocks and drip pans be present when turning equipment in for repair at the LRC Maintenance facility.**
- 2. No tactical vehicles will be accepted and no work orders opened without required chock blocks and drip pans.**
- 3. Any questions can be directed to the Maintenance Division Chief at 442-3708.**

/signed/

Director of Logistics Readiness Center

Note: Current fiscal copies of The Billboard can be viewed on the Logistics Readiness Center's Website, Billboard Tab, at <http://sill-www.army.mil/USAG/DOL/index.html>.
Billboards consisting of sensitive information will not be posted to the website.
If you wish to be placed on the distribution list to automatically receive The Billboard each time it is published, please call 442-3856.