




US Army Corps of Engineers
St. Louis District

Navigation Channel Condition Status Report - 17 March 2016



Dredge Status:
Dredge Potter: Docksider until further notice.

Channel Marker Status:
Be aware that there may be other buoys off station/missing than the ones mentioned in this report. Mariners should use caution.
For ATON or Buoy issues please contact SUMRWaterways@uscg.mil or 319-520-8556.
The Pathfinder docksider next week.

Additional Risks / Concerns

Navigation Notices

Local Notice to Mariners

Weather
Highs in the lower 60's; Lows in the lower 30's, rain Saturday.

Hannibal, MO

St. Louis, MO

Cape Girardeau, MO

Cairo, IL

Web Information

For additional River Training Structure information, see the link below:
<http://www.mvs.usace.army.mil/Mission/Navigation/Construction/Current.aspx>

For the most recent channel patrol and pre-dredge surveys, see the link below:
<http://www.mvs.usace.army.mil/Mission/Navigation/Surveys/ChannelPatrol.aspx>

The new electronic Navigation charts for the Upper Mississippi River are now available online for download or to order at the below link:
<http://www2.mvr.usace.army.mil/NIC2/>

More Status Reports

Click for older status reports

Key:

- ◆ Anticipated Dredging Locations
- ☆ Groundings
- △ Dredge Potter
- ▽ Dredge Goetz

Very Likely to be Problematic at Low Water

Could be Problematic at Low Water

Problem Resolved

Probable "Hot" Spots

River Mile	Min Depth at Low Water	Problematic On:	Dredge ETA	Dredge Complete	Dredge

Please email comments or suggestions to mvsnavstatus@usace.army.mil