

UNITED STATES DEPARTMENT OF THE INTERIOR
MINERALS MANAGEMENT SERVICE
GULF OF MEXICO REGION
ACCIDENT INVESTIGATION REPORT

1. OCCURRED

DATE: **11-JAN-2008** TIME: **1921** HOURS

2. OPERATOR: **BP Exploration & Production Inc.**

REPRESENTATIVE: **Wiltz, Gregory**

TELEPHONE: **(281) 366-5647**

CONTRACTOR:

REPRESENTATIVE:

TELEPHONE:

3. OPERATOR/CONTRACTOR REPRESENTATIVE/SUPERVISOR ON SITE AT TIME OF INCIDENT:

4. LEASE: **G08823**

AREA: **MC** LATITUDE:

BLOCK: **522** LONGITUDE:

5. PLATFORM:

RIG NAME: **T.O. MARIANAS**

6. ACTIVITY:

EXPLORATION(POE)
 DEVELOPMENT/PRODUCTION (DOC/POD)

7. TYPE:

HISTORIC INJURY
 REQUIRED EVACUATION 1
 LTA (1-3 days)
 LTA (>3 days) 1
 RW/JT (1-3 days)
 RW/JT (>3 days)
 Other Injury

FATALITY
 POLLUTION
 FIRE
 EXPLOSION

LWC HISTORIC BLOWOUT
 UNDERGROUND
 SURFACE
 DEVERTER
 SURFACE EQUIPMENT FAILURE OR PROCEDURES

COLLISION HISTORIC >\$25K <=\$25K

STRUCTURAL DAMAGE
 CRANE
 OTHER LIFTING DEVICE
 DAMAGED/DISABLED SAFETY SYS.
 INCIDENT >\$25K
 H2S/15MIN./20PPM
 REQUIRED MUSTER
 SHUTDOWN FROM GAS RELEASE
 OTHER

6. OPERATION:

PRODUCTION
 DRILLING
 WORKOVER
 COMPLETION
 HELICOPTER
 MOTOR VESSEL
 PIPELINE SEGMENT NO.
 OTHER

8. CAUSE:

EQUIPMENT FAILURE
 HUMAN ERROR
 EXTERNAL DAMAGE
 SLIP/TRIP/FALL
 WEATHER RELATED
 LEAK
 UPSET H2O TREATING
 OVERBOARD DRILLING FLUID
 OTHER

9. WATER DEPTH: **6934** FT.

10. DISTANCE FROM SHORE: **61** MI.

11. WIND DIRECTION:
SPEED: M.P.H.

12. CURRENT DIRECTION:
SPEED: M.P.H.

13. SEA STATE: FT.

17. DESCRIBE IN SEQUENCE HOW ACCIDENT HAPPENED:

On January 11, 2008, on the Transocean Marianas, located at BP E&P Inc.'s Lease OCS-G 8823, Mississippi Canyon (MC) Block 522, a Roustabout suffered a back sprain while moving heavy equipment. The Injured Person (IP) was moving heavy equipment into an enclosed container for shipment when a pry bar slipped and the IP sustained the weight on a 2x6x4 piece of wood he was placing underneath the equipment. IP was evacuated on a scheduled flight to Houma. Loss time accident >3 days.

18. LIST THE PROBABLE CAUSE(S) OF ACCIDENT:

Human Error:
Inattention to job being performed.

19. LIST THE CONTRIBUTING CAUSE(S) OF ACCIDENT:

20. LIST THE ADDITIONAL INFORMATION:

21. PROPERTY DAMAGED:

None

NATURE OF DAMAGE:

None

ESTIMATED AMOUNT (TOTAL):

\$

22. RECOMMENDATIONS TO PREVENT RECURRENCE NARRATIVE:

The New Orleans District makes no recommendations to MMS.

23. POSSIBLE OCS VIOLATIONS RELATED TO ACCIDENT: **NO**

24. SPECIFY VIOLATIONS DIRECTLY OR INDIRECTLY CONTRIBUTING. NARRATIVE:

25. DATE OF ONSITE INVESTIGATION:

26. ONSITE TEAM MEMBERS:

No onsite investigation /

29. ACCIDENT INVESTIGATION

PANEL FORMED: **NO**

OCS REPORT:

30. DISTRICT SUPERVISOR:

Troy Trosclair

APPROVED

DATE: **04-JUN-2008**