UNITED STATES DEPARTMENT OF THE INTERIOR MINERALS MANAGEMENT SERVICE GULF OF MEXICO REGION

ACCIDENT INVESTIGATION REPORT

	OCCURRED DATE: 30-JAN-2007 TIME: 0920 HOURS OPERATOR: W & T Offshore, L.L.C. REPRESENTATIVE: Bea Stong TELEPHONE: (713) 626-8525 CONTRACTOR: Diamond Offshore Drilling, Inc REPRESENTATIVE: Joseph Brewer TELEPHONE: (713) 378-2871	STRUCTURAL DAMAGE CRANE OTHER LIFTING DEVICE DAMAGED/DISABLED SAFETY SYS. INCIDENT >\$25K H2S/15MIN./20PPM REQUIRED MUSTER SHUTDOWN FROM GAS RELEASE OTHER
3.	OPERATOR/CONTRACTOR REPRESENTATIVE/SUPERVISOR ON SITE AT TIME OF INCIDENT:	6. OPERATION:
	LEASE: G26229 AREA: EW LATITUDE: BLOCK: 989 LONGITUDE: PLATFORM: RIG NAME: DIAMOND OCEAN NEW ERA	PRODUCTION X DRILLING WORKOVER COMPLETION HELICOPTER MOTOR VESSEL PIPELINE SEGMENT NO. OTHER
6.	ACTIVITY: EXPLORATION (POE)	8. CAUSE:
7.	DEVELOPMENT/PRODUCTION (DOCD/POD) TYPE: HISTORIC INJURY X REQUIRED EVACUATION 1 LTA (1-3 days) X LTA (>3 days 1 RW/JT (1-3 days) RW/JT (>3 days)	EQUIPMENT FAILURE HUMAN ERROR EXTERNAL DAMAGE SLIP/TRIP/FALL WEATHER RELATED LEAK UPSET H20 TREATING OVERBOARD DRILLING FLUID OTHER
	Other Injury	9. WATER DEPTH: 523 FT.
	FATALITY POLLUTION FIRE EXPLOSION	10. DISTANCE FROM SHORE: 75 MI.
	LWC HISTORIC BLOWOUT UNDERGROUND SURFACE DEVERTER	11. WIND DIRECTION: SSE SPEED: 10 M.P.H. 12. CURRENT DIRECTION: N SPEED: 1 M.P.H.
	SURFACE EQUIPMENT FAILURE OR PROCEDURES	
	COLLISION HISTORIC >\$25K <=\$25K	13. SEA STATE: 4 FT.

MMS - FORM 2010 PAGE: 1 OF 4

17. DESCRIBE IN SEQUENCE HOW ACCIDENT HAPPENED:

Two roustabouts were working on the pipe rack, laying down the work string. The crane crew was using a water hose to wash away any residual material from the work string as it was laid down. The water contained Zinc Bromide (ZnBr) from the work string. Both injured parties had on slicker suits, but the suits were not secured with enough duct tape and allowed the water to make contact with their pants. chemical burns resulted to the lower legs of both individuals. Both employees noticed irritation around the top edge of their boots but thought it was just from their boots rubbing their legs. They were seen limping by the company man and were told to go see the safety representative to be checked out. One of the injured workers had dark red areas with small ulcers on both legs. The ulcers appeared to be healing. The other injured worker had two ulcer type wounds and red areas on both legs. Both injured parties were flown in to see a doctor. One of the injured parties was released back to full work duty that day. The other injured party was away from work for seven days. Both employees have since returned and are currently back at work. If the injured parties would have reported their injuries as soon as the pain was noticed, the burns would not have been as severe and they probably would not have missed any work.

18. LIST THE PROBABLE CAUSE(S) OF ACCIDENT:

The cause of the incident is the prolonged contact the individuals had with the Zinc Bromide. At first, the injured parties were unaware that they had even come in contact with the ZnBr.

19. LIST THE CONTRIBUTING CAUSE(S) OF ACCIDENT:

The prolonged contact with the Zinc Bromide contributed to the severity of the burns that the injured parties received.

MMS - FORM 2010 PAGE: 2 OF 4

21. PROPERTY DAMAGED:

NATURE OF DAMAGE:

None

n/a

ESTIMATED AMOUNT (TOTAL):

\$

22. RECOMMENDATIONS TO PREVENT RECURRANCE NARRATIVE:

Due to the specific nature of this incident, the Houma District has no recommendations to report to the Regional Office.

- 23. POSSIBLE OCS VIOLATIONS RELATED TO ACCIDENT: NO
- 24. SPECIFY VIOLATIONS DIRECTLY OR INDIRECTLY CONTRIBUTING. NARRATIVE:

None

- 25. DATE OF ONSITE INVESTIGATION:
- 26. ONSITE TEAM MEMBERS:

Amy Wilson /

29. ACCIDENT INVESTIGATION PANEL FORMED: NO

OCS REPORT:

30. DISTRICT SUPERVISOR:

Michael J. Saucier

APPROVED

DATE: **27-MAR-2007**

MMS - FORM 2010 PAGE: 3 OF 4

EV2010R

INJURY/FATALITY/WITNESS ATTACHMENT

OPERATOR REPI		X INJURY	
	EPRESENTATIVE	☐ FATALITY	
OTHER		WITNESS	
NAME:			
HOME ADDRESS:			
CITY:		STATE:	
WORK PHONE:	TOTA	L OFFSHORE EXPERIENCE:	
EMPLOYED BY:	Diamond Offshore Dri	ling, Inc. / 20293	
BUSINESS ADDRESS	S: 111 Veterans Mem	orial Blvd.	
CITY:	Metairie	STATE: LA	
ZIP CODE:	70005 RESENTATIVE	X INJURY	
X CONTRACTOR RE	RESENTATIVE EPRESENTATIVE	FATALITY	
OPERATOR REPI	RESENTATIVE		
OPERATOR REPI	RESENTATIVE EPRESENTATIVE	FATALITY	
OPERATOR REPI CONTRACTOR RI OTHER NAME:	RESENTATIVE EPRESENTATIVE	FATALITY	
OPERATOR REPI CONTRACTOR RI OTHER	RESENTATIVE EPRESENTATIVE	FATALITY	
OPERATOR REPI CONTRACTOR RI OTHER NAME: HOME ADDRESS:	RESENTATIVE EPRESENTATIVE	FATALITY WITNESS	
OPERATOR REPI CONTRACTOR RI OTHER NAME: HOME ADDRESS: CITY: WORK PHONE:	RESENTATIVE EPRESENTATIVE	FATALITY WITNESS STATE: L OFFSHORE EXPERIENCE:	
OPERATOR REPRESENTANT OF THE CONTRACTOR REPRESENTANT OF THE CO	RESENTATIVE EPRESENTATIVE TOTA	FATALITY WITNESS STATE: L OFFSHORE EXPERIENCE: Lling, Inc. / 20293	
OPERATOR REPI CONTRACTOR RI OTHER NAME: HOME ADDRESS: CITY: WORK PHONE: EMPLOYED BY:	RESENTATIVE EPRESENTATIVE TOTA Diamond Offshore Drii	FATALITY WITNESS STATE: L OFFSHORE EXPERIENCE: Lling, Inc. / 20293	

MMS - FORM 2010 PAGE: 4 OF 4