UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF SAFETY AND ENVIRONMENTAL ENFORCEMENT PACIFIC OCS REGION

ACCIDENT INVESTIGATION REPORT

For Public Release

	× *	
1.	OCCURRED DATE: 07-OCT-2012 TIME: 0745 HOURS	STRUCTURAL DAMAGE CRANE OTHER LIFTING DEVICE
2.	OPERATOR: DCOR, L.L.C. REPRESENTATIVE: TELEPHONE: CONTRACTOR: REPRESENTATIVE: TELEPHONE:	DAMAGED/DISABLED SAFETY SYS. INCIDENT >\$25K H2S/15MIN./20PPM REQUIRED MUSTER SHUTDOWN FROM GAS RELEASE X OTHER BOAT COLLISION
3.	OPERATOR/CONTRACTOR REPRESENTATIVE/SUPERVISOR ON SITE AT TIME OF INCIDENT:	6. OPERATION:
	LEASE: P00241 AREA: LA LATITUDE: BLOCK: 6658 LONGITUDE: PLATFORM: B RIG NAME:	PRODUCTION DRILLING WORKOVER COMPLETION HELICOPTER MOTOR VESSEL PIPELINE SEGMENT NO. OTHER
6.	ACTIVITY: EXPLORATION (POE) DEVELOPMENT/PRODUCTION	8. CAUSE: EQUIPMENT FAILURE
7.	TYPE: HISTORIC INJURY REQUIRED EVACUATION LTA (1-3 days) LTA (>3 days RW/JT (1-3 days) RW/JT (>3 days) RW/JT (~3 days) RW	X HUMAN ERROR EXTERNAL DAMAGE SLIP/TRIP/FALL WEATHER RELATED LEAK UPSET H2O TREATING OVERBOARD DRILLING FLUID OTHER
	Other Injury FATALITY POLLUTION FIRE EXPLOSION	9. WATER DEPTH: 200 FT. 10. DISTANCE FROM SHORE: 6 MI. 11. WIND DIRECTION: NE
	LWC HISTORIC BLOWOUT UNDERGROUND SURFACE DEVERTER SURFACE EQUIPMENT FAILURE OR PROCEDURES	SPEED: 3 M.P.H. 12. CURRENT DIRECTION: SPEED: M.P.H.
	COLLISION HISTORIC >\$25K <=\$25K	23. 52. 52.
		14. PICTURES TAKEN: YES 15. STATEMENT TAKEN: YES

MMS - FORM 2010

EV2010R

PAGE: 1 OF 4

18-MAR-2013

17. INVESTIGATION FINDINGS:

The M.V. Donna Gail collided with platform B on the north east corner.

- 18. LIST THE PROBABLE CAUSE(S) OF ACCIDENT:
- 19. LIST THE CONTRIBUTING CAUSE(S) OF ACCIDENT:
- 20. LIST THE ADDITIONAL INFORMATION:

21. PROPERTY DAMAGED:

NATURE OF DAMAGE:

Damage to sacffolding, grating & parted fire water pump #2 slip line.

There is evidence of the vessel scraping the supports on the main leg.

ESTIMATED AMOUNT (TOTAL):

- 22. RECOMMENDATIONS TO PREVENT RECURRANCE NARRATIVE:
- 23. POSSIBLE OCS VIOLATIONS RELATED TO ACCIDENT: NO
- 24. SPECIFY VIOLATIONS DIRECTLY OR INDIRECTLY CONTRIBUTING. NARRATIVE:
- 25. DATE OF ONSITE INVESTIGATION:

28. ACCIDENT CLASSIFICATION:

09-OCT-2012

MINOR

26. ONSITE TEAM MEMBERS:

Louis Fernandez /

29. ACCIDENT INVESTIGATION PANEL FORMED: NO

OCS REPORT:

30. DISTRICT SUPERVISOR:

Mike Mitchell (Acting)

27. OPERATOR REPORT ON FILE: YES

MMS - FORM 2010 PAGE: 2 OF 4

EV2010R 18-MAR-2013

APPROVED 22-NOV-2012

MMS - FORM 2010

EV2010R

PAGE: 3 OF 4

18-MAR-2013

MMS - FORM 2010

PAGE: 4 OF 4 EV2010R 18-MAR-2013