UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF SAFETY AND ENVIRONMENTAL ENFORCEMENT GULF OF MEXICO REGION

ACCIDENT INVESTIGATION REPORT

1	OCCURRED	For Public Release
	DATE: 12-JUL-2012 TIME: 0130 HOURS	STRUCTURAL DAMAGE CRANE OTHER LIFTING DEVICE
2.	OPERATOR: Chevron U.S.A. Inc. REPRESENTATIVE: TELEPHONE: CONTRACTOR: REPRESENTATIVE: TELEPHONE:	DAMAGED/DISABLED SAFETY SYS. INCIDENT >\$25K H2S/15MIN./20PPM REQUIRED MUSTER SHUTDOWN FROM GAS RELEASE X OTHER leg fracture
3.	OPERATOR/CONTRACTOR REPRESENTATIVE/SUPERVISOR ON SITE AT TIME OF INCIDENT:	6. OPERATION:
4.	LEASE: G01260 AREA: ST LATITUDE: BLOCK: 177 LONGITUDE:	PRODUCTION DRILLING WORKOVER COMPLETION HELICOPTER MOTOR VESSEL
5.	PLATFORM: E RIG NAME:	PIPELINE SEGMENT NO. OTHER
6.	ACTIVITY: EXPLORATION (POE) X DEVELOPMENT/PRODUCTION (DOCD/POD)	8. CAUSE: EQUIPMENT FAILURE
7.	TYPE: HISTORIC INJURY REQUIRED EVACUATION 1 LTA (1-3 days) LTA (>3 days X RW/JT (1-3 days) 1	HUMAN ERROR EXTERNAL DAMAGE X SLIP/TRIP/FALL WEATHER RELATED LEAK UPSET H20 TREATING OVERBOARD DRILLING FLUID OTHER
	RW/JT (>3 days) Other Injury FATALITY POLLUTION	9. WATER DEPTH: 141 FT. 10. DISTANCE FROM SHORE: 37 MI.
	FIRE EXPLOSION LWC HISTORIC BLOWOUT UNDERGROUND	11. WIND DIRECTION: N SPEED: 1 M.P.H.
	SURFACE DEVERTER SURFACE EQUIPMENT FAILURE OR PROCEDURES	12. CURRENT DIRECTION: N SPEED: 1 M.P.H.
	COLLISION THISTORIC T>\$25K T <=\$25K	12 CEA CEACE. 1 EE

MMS - FORM 2010 PAGE: 1 OF 5

17. INVESTIGATION FINDINGS:

On July 12, 2012, the Injured Person (IP) was carrying a fire extinguisher down a flight of stairs. The IP was using the three point method when walking down the stairs. This means that the IP had one hand on the hand rail while the other hand was carrying the fire extinguisher. When reaching the bottom of the stairs, the IP took a step thinking that the he had one more stair to clear. This resulted in the IP severely twisting his ankle at the bottom of the stairs. IP reported to the medic and was flown into a medical facility onshore, he had x-rays taken and the physician determined the fibula in the left leg was broken. The IP underwent surgery to repair the broken bone and will be on restricted duty for four weeks. A pre-job safety meeting occurred prior to the work being performed. All the hazards were addressed in the JSA. The injured person had used all safety precautions including using the three point method when walking down the stairs.

18. LIST THE PROBABLE CAUSE(S) OF ACCIDENT:

The probable cause of the accident was determined to be an accidental slip/trip. A pre-job safety meeting occurred prior to the work being performed. All the hazards were addressed in the JSA. The injured person had used all safety precautions including using the three point method when walking down the stairs.

19. LIST THE CONTRIBUTING CAUSE(S) OF ACCIDENT:

None

20. LIST THE ADDITIONAL INFORMATION:

None

21. PROPERTY DAMAGED:

NATURE OF DAMAGE:

None None

ESTIMATED AMOUNT (TOTAL):

Ş

22. RECOMMENDATIONS TO PREVENT RECURRANCE NARRATIVE:

The Houma District has no recommendations at this time.

- 23. POSSIBLE OCS VIOLATIONS RELATED TO ACCIDENT: NO
- 24. SPECIFY VIOLATIONS DIRECTLY OR INDIRECTLY CONTRIBUTING. NARRATIVE:

None

25. DATE OF ONSITE INVESTIGATION:

MMS - FORM 2010 PAGE: 2 OF 5

EV2010R 12-OCT-2012

26. ONSITE TEAM MEMBERS: Paul Nelson /

29. ACCIDENT INVESTIGATION PANEL FORMED:

OCS REPORT:

30. DISTRICT SUPERVISOR:

Bryan A. Domangue

APPROVED DATE: 04-OCT-2012

MMS - FORM 2010 PAGE: 3 OF 5

EV2010R 12-OCT-2012

INJURY/FATALITY/WITNESS ATTACHMENT

OPERATOR REPRESENTATIVE X CONTRACTOR REPRESENTATIVE		
OTHER NAME:	WITNESS	
HOME ADDRESS:	ama ma	
CITY:	STATE:	
WORK PHONE:	TOTAL OFFSHORE EXPERIENCE:	YEARS
EMPLOYED BY:		
BUSINESS ADDRESS:		
CITY:	STATE:	
ZIP CODE:		

MMS - FORM 2010 PAGE: 4 OF 5

MMS - FORM 2010 PAGE: 5 OF 5
EV2010R 12-OCT-2012