

Fig.13f: PGA hazard curves for southwest Puerto Rico (18.0,-67.0).