

Agreed Order Signed August 6, 2013

National Onshore
Docket No. GUD 09864

Company ID 6888, Dickenson, Galveston County, Texas
System ID 91817

Rule(s) violated:

The operator did not designate to the Commission's Pipeline Safety Section on a system-by-system or segment within each system basis, by February 1, 2002, whether the operator has chosen to use a risk-based analysis or a prescriptive plan in accordance with 16 TAC 8.101.	Requirement: Title 16, 8.101(b)
---	---------------------------------

Date violations began: 5/16/2006

Penalty paid: \$2,500