



AirData

MOL.20070724.0337

You are here: [EPA Home](#) | [Air & Radiation](#) | [AirData](#) | [Reports and Maps](#) | [Select Geography](#) | [Select Report/Map](#) | [Facility SIC Report](#)
[Criteria](#) | [Facility SIC Report](#)

Facility SIC Report - Criteria Air Pollutants

Geographic Area: Worcester Co, MA

Pollutant: Nitrogen Oxides, Particulate (size < 2.5 micrometers), Volatile Organic Compounds

Year: 1999

Emissions In Tons Per Year

139 Rows

[See Disclaimer](#)

Row #	Industry Type (SIC)	Number of Facilities	Percent of Total Facilities	Pollutant Emissions			Percent of Total Emissions		
				NOx	PM2.5	VOC	NOx	PM2.5	VOC
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
1	1422 - Crushed And Broken Limestone	1	0.31		2.87			0.76	
2	1429 - Crushed And Broken Stone Nec	2	0.62	9.00	1.55	1.00	0.24	0.41	0.06
3	1442 - Construction Sand And Gravel	1	0.31		0.33			0.09	
4	2033 - Canned Fruits And Vegetables	1	0.31	1.00	7.23	2.00	0.03	1.92	0.12
5	2043 - Cereal Breakfast Foods	1	0.31	12.7	4.47	0.69	0.34	1.19	0.04
6	2051 - Bread Cake And Related Product	1	0.31	3.31	0.03	10.4	0.09	0.01	0.60
7	2099 - Food Preparations Nec	1	0.31	0.002	1.69	11.0	< 0.01	0.45	0.64
8	2221 - Weaving Mills, Synthetics	1	0.31	0.21	0.01		0.01	< 0.01	
9	2231 - Weaving & Finishing Mills Wool	1	0.31	5.00			0.13		
10	2259 - Knitting Mills, Nec	1	0.31	14.1	4.12	4.00	0.37	1.09	0.23
11	2261 - Finishing Plants, Cotton	1	0.31	54.1	8.04	91.7	1.44	2.14	5.33

12	2284 - Thread Mills	1	0.31	0.04		25.0	< 0.01		1.45
13	2295 - Coated Fabrics, Not Rubberized	4	1.23	3.23	1.08	46.3	0.09	0.29	2.69
14	2298 - Cordage And Twine	1	0.31	6.51	1.22	0.11	0.17	0.32	0.01
15	2299 - Textile Goods, Nec	2	0.62	8.38	1.55	7.45	0.22	0.41	0.43
16	2421 - Sawmills & Planing Mills General	1	0.31	2.00		2.00	0.05		0.12
17	2499 - Wood Products, Nec	1	0.31			6.82			0.40
18	2511 - Wood Household Furniture	15	4.63	8.20	19.4	224	0.22	5.15	13.04
19	2512 - Upholstered Household Furniture	1	0.31			2.00			0.12
20	2521 - Wood Office Furniture	1	0.31			15.0			0.87
21	2522 - Metal Office Furniture	1	0.31	18.7	0.08		0.50	0.02	
22	2611 - Pulp Mills	1	0.31	1.00			0.03		
23	2621 - Paper Mills Exc Building Paper	4	1.23	141	14.8	50.2	3.75	3.93	2.92
24	2631 - Paperboard Mills	1	0.31	16.0	8.00	17.0	0.43	2.12	0.99
25	2651 - Folding Paperboard Boxes (1977)	1	0.31	0.96	1.13	7.24	0.03	0.30	0.42
Grand Total		324		3,760	377	1,720			

< Page 1 of 6 >

Select page: Go

[All Pages](#)

[About pages](#)

Export this report to a text file

Create comma-delimited or tab-delimited values, compatible with PC spreadsheets and databases.

[Comma](#)

[Tab](#)

[About exporting](#)

Disclaimer: Information for this report comes from an extract of EPA's National Emission Inventory (NEI) database. Data were extracted in August 2005 from the Final 1999 NEI Version 3. NEI is an emissions database developed by EPA. It is based partially on emission data obtained from State and local agencies, but it is not a database of official State emissions data. Please contact the appropriate State agency to obtain information on a State's official emission inventory. Please [contact EPA](#) to report errors.

Readers are cautioned not to infer a qualitative ranking order of geographic areas based on AirData reports. Air pollution levels measured in the vicinity of a particular monitoring site may not be representative of the prevailing air quality of a county or urban area. Pollutants emitted from a particular source may have little impact on the immediate geographic area, and the

amount of pollutants emitted does not indicate whether the source is complying with applicable regulations.