



AirData

MOL.20070724.0338

You are here: [EPA Home](#) | [Air & Radiation](#) | [AirData](#) | [Reports and Maps](#) | [Select Geography](#) | [Select Report/Map](#) | [Facility SIC Report](#)
[Criteria](#) | [Facility SIC Report](#)

Facility SIC Report - Criteria Air Pollutants

Geographic Area: Guilford Co, NC

Pollutant: Nitrogen Oxides, Particulate (size < 2.5 micrometers), Volatile Organic Compounds

Year: 1999

Emissions In Tons Per Year

99 Rows

See [Disclaimer](#)

Row #	Industry Type (SIC)	Number of Facilities	Percent of Total Facilities	Pollutant Emissions			Percent of Total Emissions		
				NOx	PM2.5	VOC	NOx	PM2.5	VOC
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
1	1423 - Crushed And Broken Granite	5	2.22		28.3			8.62	
2	1499 - Nonmetallic Minerals, Nec	2	0.89	13.2	3.30	1.07	2.13	1.00	0.02
3	2041 - Flour & Other Grain Mill Prod	1	0.44		0.31			0.10	
4	2051 - Bread Cake And Related Product	1	0.44	2.71	0.42	53.0	0.44	0.13	0.99
5	2077 - Animal And Marine Fats And Oil	1	0.44	12.7	1.99	0.31	2.04	0.60	0.01
6	2087 - Flavoring Extracts And Syrups,Nec	1	0.44	0.10	0.01	0.01	0.02	< 0.01	< 0.01
7	2111 - Cigarettes	1	0.44	16.6	9.75	396	2.67	2.97	7.39
8	2211 - Weaving Mills, Cotton	1	0.44	189	7.47	83.4	30.49	2.28	1.56
9	2252 - Hosiery, Nec	2	0.89	10.1	3.18	1.89	1.63	0.97	0.04
10	2258 - Warp Knit Fabric Mills	2	0.89	14.1	13.5	16.4	2.26	4.11	0.31
11	2262 - Finishing Plants, Synthetics	2	0.89	28.6	1.84	18.8	4.61	0.56	0.35

12	2269 - Finishing Plants, Nec	3	1.33	29.2	9.64	34.6	4.71	2.94	0.65
13	2282 - Throwing And Winding Mills	1	0.44	0.88	0.20	0.02	0.14	0.06	< 0.01
14	2297 - Nonwoven Fabrics	3	1.33	2.30	1.13	2.06	0.37	0.34	0.04
15	2299 - Textile Goods, Nec	2	0.89	2.27	0.76	4.31	0.37	0.23	0.08
16	2426 - Hardwood Dimension & Flooring	2	0.89	1.37	2.96	12.3	0.22	0.90	0.23
17	2431 - Millwork	2	0.89		11.3	35.0		3.44	0.65
18	2434 - Wood Kitchen Cabinets	1	0.44	14.0	18.4	485	2.25	5.62	9.07
19	2435 - Hardwood Veneer And Plywood	2	0.89	1.40	2.26	24.3	0.23	0.69	0.45
20	2448 - Wood Pallets And Skids	1	0.44		0.64			0.20	
21	2499 - Wood Products, Nec	5	2.22	15.7	6.43	50.3	2.53	1.96	0.94
22	2511 - Wood Household Furniture	19	8.44	39.4	26.6	381	6.35	8.12	7.12
23	2512 - Upholstered Household Furniture	6	2.67	10.1	3.41	103	1.63	1.04	1.93
24	2514 - Metal Household Furniture	2	0.89	1.00	1.01	35.0	0.16	0.31	0.65
25	2519 - Household Furniture, Nec	1	0.44	0.05	2.01	9.00	0.01	0.61	0.17
Grand Total		225		621	328	5,352			

< Page 1 of 4 >

Select page: Go

[All Pages](#)

[About pages](#)

Export this report to a text file

Create comma-delimited or tab-delimited values, compatible with PC spreadsheets and databases.

[Comma](#)

[Tab](#)

[About exporting](#)

Disclaimer: Information for this report comes from an extract of EPA's National Emission Inventory (NEI) database. Data were extracted in August 2005 from the Final 1999 NEI Version 3. NEI is an emissions database developed by EPA. It is based partially on emission data obtained from State and local agencies, but it is not a database of official State emissions data. Please contact the appropriate State agency to obtain information on a State's official emission inventory. Please [contact EPA](#) to report errors.

Readers are cautioned not to infer a qualitative ranking order of geographic areas based on AirData reports. Air pollution levels measured in the vicinity of a particular monitoring site may not be representative of the prevailing air quality of a county or urban area. Pollutants emitted from a particular source may have little impact on the immediate geographic area, and the amount of pollutants emitted does not indicate whether the source is complying with applicable regulations.