## 2001 Human Factors Information System Report for Plant Docket 400

Combined IR/ER/LER Report Docket: 50-400 HARRIS 1 Total Number of Hits in Date Range: 19 From 01/01/2001 to 01/01/2002 2x National Average: 76 Details Department Work Type Docket/Report Communications IR Number of items: 0 Percent of total: 0 Communications ER Number of items: 0 Percent of total: 0 Communications LER Number of items: 0 Percent of total: 0 Human-System Interface and Environm IR Number of items: 0 Percent of total: 0 Human-System Interface and Environm ER Number of items: 0 Percent of total: 0 Human-System Interface and Environm LER Number of items: 0 Percent of total: 0 Management and Supervision IR Number of items: 4 Percent of total: 21.05 47-Root Cause LTA O-Operations Z-Other 50-400/2001004 47-Root Cause LTA G-Engineering Z-Other 50-400/2001007 Management and Supervision ER Number of items: 0 Percent of total: 0 Management and Supervision LER Number of items: 0 Percent of total: 0 Organizational Issues IR Number of items: 0 Percent of total: 0 Organizational Issues ER Number of items: 0 Percent of total: 0 Organizational Issues LER Number of items: 0 Percent of total: 0 Procedures and Reference Document IR Number of items: 1 Percent of total: 5.26 12-Procedure techni P-Procedure Writers P-Procedure Dev 50-400/2001004 Procedures and Reference Document ER Number of items: 0

## Human Factors Information System Report

```
Percent of total: 0
Procedures and Reference Document LER
 Number of items: 0
Percent of total: 0
Training IR
 Number of items: 0
Percent of total: 0
Training ER
 Number of items: 0
Percent of total: 0
Training LER
 Number of items: 0
Percent of total: 0
Work Factors IR
 Number of items: 13
Percent of total: 68.42
            Page: 1
                              Date:08/15/2002
            Combined IR/ER/LER Report
            Docket: 50-400 HARRIS 1
      Total Number of Hits in Date Range: 19
      From 01/01/2001 to 01/01/2002
      2x National Average: 76
Details
                         Department
                                                 Work Type
                                                                        Docket/Report
Work Factors IR
 Number of items: 13
Percent of Total: 68.42
83-Work practice or G-Engineering
84-Non-conserv. dec G-Engineering
84-Non-conserv. dec G-Engineering
                                                                          50-400/2001003
                                                 Z-Other

        Z-Other
        S0 100/2001007

        V-Troubleshooting
        50-400/2001007

        V-Troubleshooting
        50-400/2001007

        Z-Other
        50-400/2001007

                                                Z-Other50-400/2001008Z-Other50-400/2001008Z-Other50-400/2001008Z-Other50-400/2001008Z-Other50-400/2001008
93-Awareness or att G-Engineering
                                               Z-Other
93-Awareness or att G-Engineering
93-Awareness or att G-Engineering
                                               Z-Other
93-Awareness or att G-Engineering
                                               Z-Other
                                                                        50-400/2001008
86-Work untimely G-Engineering
                                                                        50-400/2001008
                                               Z-Other
93-Awareness or att G-Engineering
93-Awareness or att G-Engineering
                                               Z-Other
                                                                        50-400/2001008
                                                Z-Other
                                                                        50-400/2001008
Work Factors ER
 Number of items: 0
Percent of total: 0
Work Factors LER
 Number of items: 1
Percent of total: 5.26
89-Housekeeping LTA M-Mechanical
                                           M-Maint / Repair 50-400/200100300
            Page: 2
                        Date:08/15/2002
```

## [End of File for Plant Docket 400 (2001)]