Combined IR/ER/LER Report
Docket: 50-275 DIABLO CANYON 1

Total Number of Hits in Date Range: 65

From 01/01/2003 to 01/01/2004

2x National Average: 85

| Details | Department | Work Type | Docket/Report | |
|--|---|--|---------------|--|
| Communications IR Number of items: 2 Percent of total: 3.08 53-Communication LT O-Operations | M-Maint / Repair | 50-275/2003005 | ; | |
| O-Operations 54-No communication O-Operations O-Operations | M-Maint / Repair | 50-275/2003010 | | |
| Communications ER Number of items: 0 Percent of total: 0 | | | | |
| Communications LER Number of items: 2 Percent of total: 3.08 53-Communication LT W-Work Control / S | c S-Surveillance S-Surveillance | 50-275/2003001 50-275/2003001 | | |
| Human-System Interface and Environm IR Number of items: 0 Percent of total: 0 | | | | |
| Human-System Interface and Environm ER Number of items: 0 Percent of total: 0 | | | | |
| Human-System Interface and Environm LE. Number of items: 0 Percent of total: 0 | R | | | |
| Management and Supervision IR Number of items: 19 Percent of total: 29.23 41-Action not begun G-Engineering 47-Root Cause LTA G-Engineering 41-Action not begun G-Engineering 47-Root Cause LTA G-Engineering 47-Root Cause LTA G-Engineering 40-Individual Corre G-Engineering 41-Action not begun G-Engineering 41-Action not begun G-Engineering 44-Corrective Actio G-Engineering 47-Root Cause LTA G-Engineering 47-Root Cause LTA G-Engineering 41-Action not begun G-Engineering Page: 1 Dat | M-Maint / Repair V-Troubleshooting M-Maint / Repair M-Maint / Repair V-Troubleshooting M-Maint / Repair W-Troubleshooting V-Troubleshooting W-Troubleshooting M-Maint / Repair M-Maint / Repair M-Maint / Repair W-Troubleshooting V-Troubleshooting V-Troubleshooting V-Troubleshooting V-Troubleshooting V-Troubleshooting V-Troubleshooting V-Troubleshooting V-Troubleshooting V-Troubleshooting E:05/24/2004 | 50-275/2003006 50-275/2003006 50-275/2003007 50-275/2003010 50-275/2003010 50-275/2003010 50-275/2003010 50-275/2003010 50-275/2003010 50-275/2003010 50-275/2003010 50-275/2003010 50-275/2003010 50-275/2003010 50-275/2003010 50-275/2003010 | | |
| Combined IR/ER/LER Report Docket: 50-275 DIABLO CANYON 1 | | | | |
| Total Number of Hits in Date Range: 65 From 01/01/2003 to 01/01/2004 | | | | |

Work Type

Docket/Report

Management and Supervision IR

2x National Average: 85

Department

Details

```
Number of items: 19
Percent of Total: 29.23
4/-Root Cause LTA G-Engineering M-Maint / Repair 50-275/2003010
40-Individual Corre G-Engineering M-Maint / Repair 50-275/2003010
47-Root Cause LTA G-Engineering M-Maint / Repair 50-275/2003010
Management and Supervision ER
 Number of items: 0
Percent of total: 0
Management and Supervision LER
 Number of items: 3
Percent of total: 4.62
48-Audits or proble E-Electrical
                                                 M-Maint / Repair 50-323/200300700
                                                 M-Maint / Repair 50-323/200300700
43-Operating Experi E-Electrical
48-Audits or proble E-Electrical
                                                 M-Maint / Repair 50-323/200300701
Organizational Issues IR
 Number of items: 0
Percent of total: 0
Organizational Issues ER
 Number of items: 0
Percent of total: 0
Organizational Issues LER
 Number of items: 2
Percent of total: 3.08
22-Poor Task Alloca W-Work Control / Sc S-Surveillance 50-275/200300100 22-Poor Task Alloca O-Operations S-Surveillance 50-275/200300100
Procedures and Reference Document IR
 Number of items: 7
Percent of total: 10.77
12-Procedure techni O-Operations Q-Fire Protection 50-275/2003002
                                                                            50-275/2003006
13-Procedure has hu P-Procedure Writers P-Procedure Dev
12-Procedure techni O-Operations Q-Fire Protection 50-275/2003007
12-Procedure techni O-Operations Q-Fire Protection 50-275/2003007
13-Procedure has hu G-Engineering V-Troubleshooting 50-275/2003010
13-Procedure has hu G-Engineering V-Troubleshooting 50-275/2003010
13-Procedure has hu G-Engineering V-Troubleshooting 50-275/2003010
Procedures and Reference Document ER
 Number of items: 0
Percent of total: 0
Procedures and Reference Document LER
 Number of items: 2
Percent of total: 3.08
12-Procedure techni E-Electrical M-Maint / Repair 12-Procedure techni E-Electrical M-Maint / Repair
                                                                             50-323/200300700
                                                                             50-323/200300701
Training IR
 Number of items: 0
Percent of total: 0
Training ER
 Number of items: 0
Percent of total: 0
Training LER
 Number of items: 0
Percent of total: 0
Work Factors IR
 Number of items: 26
Percent of total: 40.
                                                 V-Troubleshooting 50-275/2002005
86-Work untimely
                       G-Engineering
                       Page: 2
                                             Date:05/24/2004
```

Combined IR/ER/LER Report
Docket: 50-275 DIABLO CANYON 1

Total Number of Hits in Date Range: 65 From 01/01/2003 to 01/01/2004 2x National Average: 85

| Details | Department | Work Type | Docket/Report |
|--|--|---|--|
| Work Factors IR Number of items: 20 Percent of Total: 40 89-Housekeeping LTA 89-Housekeeping LTA 91-Verification / p 83-Work practice or | U-Unknown U-Unknown U-Unknown O-Operations O-Operations | M-Maint / Repair M-Maint / Repair B-Bal of Plant Ops B-Bal of Plant Ops | 50-275/2002005 50-275/2002005 50-275/2002005 50-275/2002005 |
| 84-Non-conserv. dec 83-Work practice or 83-Work practice or 91-Verification / p 91-Verification / p 84-Non-conserv. dec | O-Operations O-Operations M-Mechanical G-Engineering | M-Maint / Repair M-Maint / Repair O-Control Room Ops M-Maint / Repair M-Maint / Repair V-Troubleshooting | 50-275/2003005 50-275/2003005 50-275/2003005 50-275/2003006 50-275/2003006 50-275/2003006 |
| 94-Log-keeping or r 84-Non-conserv. dec 84-Non-conserv. dec 84-Non-conserv. dec 84-Non-conserv. dec 84-Non-conserv. dec 84-Non-conserv. dec 84-Non-conserv. dec 84-Non-conserv. dec 83-Work practice or | G-Engineering G-Engineering E-Electrical G-Engineering E-Electrical O-Operations O-Operations O-Operations | V-Troubleshooting V-Troubleshooting V-Troubleshooting V-Troubleshooting M-Maint / Repair M-Maint / Repair M-Maint / Repair O-Control Room Ops O-Control Room Ops O-Control Room Ops | 50-275/2003006 50-275/2003010 50-275/2003010 50-275/2003010 50-275/2003010 50-275/2003010 50-275/2003010 50-275/2003010 50-275/2003010 50-275/2003010 50-275/2003010 |
| 84-Non-conserv. dec 84-Non-conserv. dec 84-Non-conserv. dec 84-Non-conserv. dec 84-Non-conserv. dec | E-Electrical G-Engineering G-Engineering | M-Maint / Repair M-Maint / Repair M-Maint / Repair M-Maint / Repair G-Design | 50-275/2003010 50-275/2003010 50-275/2003010 50-275/2003010 50-275/2003010 |
| Work Factors ER Number of items: 0 Percent of total: 0 | | | |
| Work Factors LER Number of items: 2 Percent of total: 3 84-Non-conserv. dec 92-Self check LTA Pa | O-Operations E-Electrical | S-Surveillance M-Maint / Repair e:05/24/2004 | 50-275/200300100 50-323/200300701 |