Combined IR/ER/LER Report
Docket: 50-278 PEACH BOTTOM 3

Total Number of Hits in Date Range: 58 From 01/01/2003 to 01/01/2004

2x National Average: 85

Details

```
Communications IR
Number of items: 0
Percent of total: 0
Communications ER
Number of items: 0
Percent of total: 0
Communications LER
Number of items: 0
Percent of total: 0
Human-System Interface and Environm IR
Number of items: 3
Percent of total: 5.17
                                          B-Bal of Plant Ops 50-278/2003002
B-Bal of Plant Ops 50-278/2003002
72-Lighting LTA
                    O-Operations
72-Lighting LTA 0-Operations
72-Lighting LTA 0-Operations
                                          O-Control Room Ops 50-278/2003013
65-Information Cont O-Operations
Human-System Interface and Environm ER
Number of items: 0
Percent of total: 0
Human-System Interface and Environm LER
Number of items: 1
Percent of total: 1.72
75-Work area LTA I-Instrumentation & M-Maint / Repair 50-278/200300100
Management and Supervision IR
Number of items: 15
Percent of total: 25.86
40-Individual Corre G-Engineering
                                                                50-278/2002006
                                         M-Maint / Repair
40-Individual Corre E-Electrical
                                         M-Maint / Repair
                                                                50-278/2003002
                                         M-Maint / Repair
40-Individual Corre O-Operations
                                                               50-278/2003002
40-Individual Corre G-Engineering
                                        M-Maint / Repair 50-278/2003004
                                       M-Maint / Repair
47-Root Cause LTA G-Engineering
                                                               50-278/2003012
47-Root Cause LTA G-Engineering
                                        M-Maint / Repair 50-278/2003012
47-Root Cause LTA G-Engineering M-Maint / Repair 50-278/2003012
47-Root Cause LTA G-Engineering M-Maint / Repair 50-278/2003012
47-Root Cause LTA I-Instrumentation & M-Maint / Repair 50-278/2003012
40-Individual Corre G-Engineering M-Maint / Repair
                                                               50-278/2003013
40-Individual Corre G-Engineering
43-Operating Experi G-Engineering
47-Root Cause LTA G-Engineering
M-Maint / Repair
M Maint / Repair
40-Individual Corre G-Engineering
                                         M-Maint / Repair
                                                                50-278/2003013
                                                                50-278/2003013
                                                                50-278/2003013
                                         M-Maint / Repair
40-Individual Corre G-Engineering
                                                               50-278/2003013
                                         M-Maint / Repair
40-Individual Corre G-Engineering
                                                                50-278/2003013
Management and Supervision ER
Number of items: 0
Percent of total: 0
Management and Supervision LER
Number of items: 0
Percent of total: 0
Organizational Issues IR
 Number of items: 0
Percent of total: 0
Organizational Issues ER
Number of items: 0
Percent of total: 0
Organizational Issues LER
```

Department

Work Type

Docket/Report

file://c:\hfis\2782003.txt

```
Number of items: 0
Percent of total: 0
Procedures and Reference Document IR
Number of items: 13
Percent of total: 22.41
12-Procedure techni P-Procedure Writers P-Procedure Dev
                                                                50-278/2003003
                              Date:05/24/2004
                   Page: 1
                   Combined IR/ER/LER Report
                   Docket: 50-278 PEACH BOTTOM 3
         Total Number of Hits in Date Range: 58
         From 01/01/2003 to 01/01/2004
         2x National Average: 85
Details
                     Department
                                           Work Type
                                                                Docket/Report
Procedures and Reference Document IR
Number of items: 13
Percent of Total: 22.41
11-No procedure / r P-Procedure Writers P-Procedure Dev
                                                                50-278/2003003
13-Procedure has hu P-Procedure Writers P-Procedure Dev
                                                                50-278/2003003
12-Procedure techni T-Training
                                          R-Refueling
                                                                50-278/2003004
13-Procedure has hu T-Training
                                          R-Refueling
                                                                50-278/2003004
13-Procedure has hu T-Training
                                          R-Refueling
                                                               50-278/2003004
13-Procedure has hu G-Engineering
                                         G-Design
                                                               50-278/2003004
12-Procedure techni G-Engineering
                                        Q-Fire Protection 50-278/2003009
13-Procedure has hu P-Procedure Writers P-Procedure Dev 50-278/2003013 12-Procedure techni P-Procedure Writers P-Procedure Dev 50-278/2003013 12-Procedure techni P-Procedure Writers P-Procedure Dev 50-278/2003013 12-Procedure techni P-Procedure Writers P-Procedure Dev 50-278/2003013
13-Procedure has hu P-Procedure Writers P-Procedure Dev 50-278/2003013
Procedures and Reference Document ER
Number of items: 0
Percent of total: 0
Procedures and Reference Document LER
Number of items: 0
Percent of total: 0
Training IR
Number of items: 0
Percent of total: 0
Training ER
Number of items: 0
Percent of total: 0
Training LER
Number of items: 0
Percent of total: 0
Work Factors IR
Number of items: 24
Percent of total: 41.38
84-Non-conserv. dec G-Engineering
                                                                50-278/2002006
                                         M-Maint / Repair
83-Work practice or U-Unknown
                                          H-Health Physics
                                                                50-278/2002006
84-Non-conserv. dec G-Engineering
                                        G-Design
                                                                50-278/2002012
89-Housekeeping LTA I-Instrumentation & M-Maint / Repair 50-278/2003002
83-Work practice or O-Operations S-Surveillance
                                                               50-278/2003003
83-Work practice or I-Instrumentation & M-Maint / Repair 50-278/2003003
83-Work practice or D-Emergency Plannin A-Administrative
                                                                50-278/2003004
94-Log-keeping or r D-Emergency Plannin A-Administrative
                                                                50-278/2003004
84-Non-conserv. dec I-Instrumentation & C-Calibration
                                                                50-278/2003004
83-Work practice or I-Instrumentation & M-Maint / Repair
                                                                50-278/2003004
```

83-Work practice or D-Emergency Plannin D-Emergency Drill

83-Work practice or D-Emergency Plannin D-Emergency Drill

84-Non-conserv. dec D-Emergency Plannin F-Modification

50-278/2003004

50-278/2003004

50-278/2003008

B-Bal of Plant Ops 50-278/2003012

Date: 05/24/2004

91-Verification / p O-Operations

Page: 2

Combined IR/ER/LER Report
Docket: 50-278 PEACH BOTTOM 3

Total Number of Hits in Date Range: 58 From 01/01/2003 to 01/01/2004

2x National Average: 85

Details

Work Factors IR		
Number of items: 24		
Percent of Total: 41.38		
91-Verification / p O-Operations	B-Bal of Plant Ops	50-278/2003012
91-Verification / p O-Operations	B-Bal of Plant Ops	50-278/2003012
84-Non-conserv. dec E-Electrical	V-Troubleshooting	50-278/2003012
84-Non-conserv. dec E-Electrical	V-Troubleshooting	50-278/2003012
83-Work practice or G-Engineering	V-Troubleshooting	50-278/2003013
84-Non-conserv. dec G-Engineering	V-Troubleshooting	50-278/2003013
84-Non-conserv. dec G-Engineering	V-Troubleshooting	50-278/2003013
84-Non-conserv. dec G-Engineering	V-Troubleshooting	50-278/2003013
84-Non-conserv. dec B-Plant Management	V-Troubleshooting	50-278/2003013
83-Work practice or O-Operations	O-Control Room Ops	50-278/2003013
Work Factors ER		
Number of items: 0		
Percent of total: 0		
refeelit of total.		
Work Factors LER Number of items: 2		
Percent of total: 3.45		
92-Self check LTA I-Instrumentation &	M-Maint / Repair	50-278/200300100
		•
Page: 3 Date: 05/24/2004		
83-Work practice or I-Instrumentation &	M-Maint / Repair	50-278/200300100

Department Work Type Docket/Report