08/10/2005 12:58:23 Page 1 of 2 Document Types: IR, LER From 01/01/2004 to 12/31/2004

## U.S. Nuclear Regulatory Commission Human Factors Information System (HFIS) IR/LER Category Analysis by Docket Report

Total Number of Hits: 22 National Average: 43

2x National Average: 86

National Median: 21

Average for Selected Dockets: 22

	Facility Name: Hatch 1 Docket (050- 00321)		
Details	Department	Work Type	Docket/Report
Management and Supervision / IR			
40 - Individual Corrective Action LTA	M - Mechanical	M - Maint / Repair	050-00321/2004-002
41 - Action not begun or untimely	M - Mechanical	M - Maint / Repair	050-00321/2004-002
43 - Operating Experience Review LTA	G - Engineering	V - Troubleshooting	050-00321/2003-008
44 - Corrective Action program LTA	G - Engineering	A - Administrative	050-00321/2004-002
Number of Items for this Docket: 4 Percent of Total for this Docket: 18			
Work Factors / IR			
83 - Work practice or craft skill LTA	G - Engineering	G - Design	050-00321/2004-003
83 - Work practice or craft skill LTA	G - Engineering	G - Design	050-00321/2004-003
84 - Non-conserv. decision / Questioning LTA	G - Engineering	F - Modification	050-00321/2004-004
84 - Non-conserv. decision / Questioning LTA	O - Operations	F - Modification	050-00321/2004-004
93 - Awareness or attention LTA	G - Engineering	A - Administrative	050-00321/2004-003
93 - Awareness or attention LTA	G - Engineering	A - Administrative	050-00321/2004-003
93 - Awareness or attention LTA	G - Engineering	A - Administrative	050-00321/2004-003
93 - Awareness or attention LTA	G - Engineering	A - Administrative	050-00321/2004-003
93 - Awareness or attention LTA	G - Engineering	A - Administrative	050-00321/2004-003
93 - Awareness or attention LTA	G - Engineering	A - Administrative	050-00321/2004-003
Number of Items for this Docket: 10 Percent of Total for this Docket: 45			
Procedures and Reference Document / LER			
12 - Procedure technical content LTA	E - Electrical	M - Maint / Repair	050-00321/2004-003-00
12 - Procedure technical content LTA	G - Engineering	F - Modification	050-00321/2004-002-00
12 - Procedure technical content LTA	M - Mechanical	M - Maint / Repair	050-00321/2004-004-00
12 - Procedure technical content LTA	O - Operations	T - Testing	050-00321/2004-004-00
12 - Procedure technical content LTA	Z - Other	F - Modification	050-00321/2004-002-00
Number of Items for this Docket:5Percent of Total for this Docket:23			
Work Factors / LER			
83 - Work practice or craft skill LTA	M - Mechanical	M - Maint / Repair	050-00321/2004-004-00
83 - Work practice or craft skill LTA	Z - Other	F - Modification	050-00321/2004-001-00

8/10/2005 12:58:23 age 2 of 2 ocument Types: IR, LER rom 01/01/2004 to 12/31/2004	Human Factors Information System (HFIS) Des: IR, LER IR/LER Category Analysis by Docket Report		Total Number of Hits:22National Average:432x National Average:86National Median:21Average for Selected Dockets:22	
	Facility Name: Hatch 1 D	ocket (050- 00321)		
Details	Department	Work Type	Docket/Report	
Work Factors / LER				
84 - Non-conserv. decision / Questioning LTA	Z - Other	F - Modification	050-00321/2004-001-00	
Number of Items for this Docket: 3				
Percent of Total for this Docket: 14				