

**U.S. Nuclear Regulatory Commission
Human Factors Information System (HFIS)
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 35

National Average: 43

2x National Average: 86

National Median: 21

Average for Selected Dockets: 35

Facility Name: Farley 2 Docket (050- 00364)

Details	Department	Work Type	Docket/Report
Management and Supervision / IR			
40 - Individual Corrective Action LTA	G - Engineering	M - Maint / Repair	050-00364/2004-003
40 - Individual Corrective Action LTA	G - Engineering	M - Maint / Repair	050-00364/2004-003
41 - Action not begun or untimely	G - Engineering	M - Maint / Repair	050-00364/2004-009
44 - Corrective Action program LTA	G - Engineering	M - Maint / Repair	050-00364/2004-003
47 - Root Cause LTA	G - Engineering	M - Maint / Repair	050-00364/2004-002
47 - Root Cause LTA	G - Engineering	M - Maint / Repair	050-00364/2004-003
47 - Root Cause LTA	G - Engineering	M - Maint / Repair	050-00364/2004-003
Number of Items for this Docket: 7			
Percent of Total for this Docket: 20			

Procedures and Reference Document / IR

11 - No procedure / reference documents	H - Health Physics	H - Health Physics	050-00364/2003-005
12 - Procedure technical content LTA	G - Engineering	G - Design	050-00364/2004-004
12 - Procedure technical content LTA	G - Engineering	G - Design	050-00364/2004-004
12 - Procedure technical content LTA	G - Engineering	G - Design	050-00364/2004-007
12 - Procedure technical content LTA	H - Health Physics	H - Health Physics	050-00364/2003-005
12 - Procedure technical content LTA	P - Procedure Writers	P - Procedure Dev	050-00364/2004-004
12 - Procedure technical content LTA	P - Procedure Writers	P - Procedure Dev	050-00364/2004-009
13 - Procedure has human factors deficiencies	G - Engineering	G - Design	050-00364/2004-004
13 - Procedure has human factors deficiencies	P - Procedure Writers	P - Procedure Dev	050-00364/2004-009
Number of Items for this Docket: 9			
Percent of Total for this Docket: 26			

Training / IR

02 - Training LTA	O - Operations	O - Control Room Ops	050-00364/2004-004
02 - Training LTA	O - Operations	O - Control Room Ops	050-00364/2004-004
Number of Items for this Docket: 2			
Percent of Total for this Docket: 6			

Work Factors / IR

83 - Work practice or craft skill LTA	O - Operations	O - Control Room Ops	050-00364/2004-004
83 - Work practice or craft skill LTA	O - Operations	O - Control Room Ops	050-00364/2004-004
83 - Work practice or craft skill LTA	O - Operations	Q - Fire Protection	050-00364/2004-004
83 - Work practice or craft skill LTA	Z - Other	M - Maint / Repair	050-00364/2004-004
84 - Non-conserv. decision / Questioning LTA	O - Operations	O - Control Room Ops	050-00364/2004-003

**U.S. Nuclear Regulatory Commission
Human Factors Information System (HFIS)
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 35

National Average: 43

2x National Average: 86

National Median: 21

Average for Selected Dockets: 35

Facility Name: Farley 2 Docket (050- 00364)

Details	Department	Work Type	Docket/Report
Work Factors / IR			
84 - Non-conserv. decision / Questioning LTA	O - Operations	O - Control Room Ops	050-00364/2004-003
93 - Awareness or attention LTA	G - Engineering	F - Modification	050-00364/2004-004
93 - Awareness or attention LTA	G - Engineering	F - Modification	050-00364/2004-004
93 - Awareness or attention LTA	G - Engineering	G - Design	050-00364/2004-007
93 - Awareness or attention LTA	G - Engineering	M - Maint / Repair	050-00364/2004-002
94 - Log-keeping or review LTA	O - Operations	A - Administrative	050-00364/2004-004
94 - Log-keeping or review LTA	O - Operations	A - Administrative	050-00364/2004-004
Number of Items for this Docket: 12			
Percent of Total for this Docket: 34			
Procedures and Reference Document / LER			
12 - Procedure technical content LTA	I - Instrumentation & Control	M - Maint / Repair	050-00364/2004-003-00
12 - Procedure technical content LTA	O - Operations	A - Administrative	050-00364/2004-002-00
Number of Items for this Docket: 2			
Percent of Total for this Docket: 6			
Work Factors / LER			
83 - Work practice or craft skill LTA	I - Instrumentation & Control	M - Maint / Repair	050-00364/2004-003-00
84 - Non-conserv. decision / Questioning LTA	O - Operations	A - Administrative	050-00364/2004-002-00
84 - Non-conserv. decision / Questioning LTA	O - Operations	A - Administrative	050-00364/2004-002-00
Number of Items for this Docket: 3			
Percent of Total for this Docket: 9			
Total Items for this Docket: 35			
