

**U.S. Nuclear Regulatory Commission
Human Factors Information System (HFIS)
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 18

National Average: 43

2x National Average: 86

National Median: 24

Average for Selected Dockets: 18

Facility Name: Beaver Valley 2 Docket (050- 00412)

Details	Department	Work Type	Docket/Report
Procedures & Reference Document / IR			
111 - Procedure / reference document technical content	D - Emergency Planning	Q - Fire Protection	050-00412/2006-008
Number of Items for this Docket: 1			
Percent of Total for this Docket: 6			
Problem Identification & Resolution / IR			
146 - Evaluation LTA	G - Engineering	G - Design	050-00412/2006-004
146 - Evaluation LTA	G - Engineering	G - Design	050-00412/2006-004
150 - Programmatic deficiency	D - Emergency Planning	D - Emergency Drill	050-00412/2006-009
150 - Programmatic deficiency	H - Health Physics	H - Health Physics	050-00412/2006-009
Number of Items for this Docket: 4			
Percent of Total for this Docket: 22			
Work Planning & Practices / IR			
185 - Procedural adherence LTA	D - Emergency Planning	Q - Fire Protection	050-00412/2006-002
187 - Action implementation LTA	G - Engineering	F - Modification	050-00412/2006-004
187 - Action implementation LTA	G - Engineering	G - Design	050-00412/2006-003
187 - Action implementation LTA	H - Health Physics	H - Health Physics	050-00412/2006-003
188 - Work practice or craft skill LTA	E - Electrical	M - Maintenance / Repair	050-00412/2005-008
197 - Self-check LTA	O - Operations	B - Bal of Plant Ops	050-00412/2005-008
Number of Items for this Docket: 6			
Percent of Total for this Docket: 33			
Oversight / LER			
130 - Inadequate supervision / command and control	M - Mechanical	M - Maintenance / Repair	050-00412/2006-003-01
130 - Inadequate supervision / command and control	M - Mechanical	M - Maintenance / Repair	050-00412/2006-003-01
131 - Management expectations or directions LTA	M - Mechanical	M - Maintenance / Repair	050-00412/2006-003-01
Number of Items for this Docket: 3			
Percent of Total for this Docket: 17			
Problem Identification & Resolution / LER			
147 - Individual corrective action LTA	M - Mechanical	M - Maintenance / Repair	050-00412/2006-003-01
147 - Individual corrective action LTA	M - Mechanical	M - Maintenance / Repair	050-00412/2006-003-01
Number of Items for this Docket: 2			
Percent of Total for this Docket: 11			

**U.S. Nuclear Regulatory Commission
Human Factors Information System (HFIS)
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 18
National Average: 43
2x National Average: 86
National Median: 24
Average for Selected Dockets: 18

Facility Name: Beaver Valley 2 Docket (050- 00412)

Details	Department	Work Type	Docket/Report
Training / LER			
100 - Training LTA	M - Mechanical	M - Maintenance / Repair	050-00412/2006-003-01
Number of Items for this Docket: 1			
Percent of Total for this Docket: 6			
Work Planning & Practices / LER			
185 - Procedural adherence LTA	M - Mechanical	M - Maintenance / Repair	050-00412/2006-003-01
Number of Items for this Docket: 1			
Percent of Total for this Docket: 6			
Total Items for this Docket: 18			
