

**U.S. Nuclear Regulatory Commission
Human Factors Information System (HFIS)
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 38

National Average: 43

2x National Average: 86

National Median: 24

Average for Selected Dockets: 38

Facility Name: Grand Gulf 1 Docket (050- 00416)

Details	Department	Work Type	Docket/Report
Communication / IR			
162 - Communication Equipment LTA	M - Mechanical	M - Maintenance / Repair	050-00416/2006-002
162 - Communication Equipment LTA	O - Operations	O - Control Room Ops	050-00416/2006-002
Number of Items for this Docket: 2			
Percent of Total for this Docket: 5			
<hr/>			
Human-System Interface & Environmnt / IR			
170 - HSI or information availability / quality LTA	M - Mechanical	M - Maintenance / Repair	050-00416/2005-005
170 - HSI or information availability / quality LTA	M - Mechanical	M - Maintenance / Repair	050-00416/2005-005
Number of Items for this Docket: 2			
Percent of Total for this Docket: 5			
<hr/>			
Oversight / IR			
130 - Inadequate suprevison / command and control	M - Mechanical	M - Maintenance / Repair	050-00416/2005-005
Number of Items for this Docket: 1			
Percent of Total for this Docket: 3			
<hr/>			
Procedures & Reference Document / IR			
111 - Procedure / reference document technical content	G - Engineering	G - Design	050-00416/2006-008
Number of Items for this Docket: 1			
Percent of Total for this Docket: 3			
<hr/>			
Problem Identification & Resolution / IR			
140 - Problem not completely or accurately identified	O - Operations	O - Control Room Ops	050-00416/2006-003
140 - Problem not completely or accurately identified	S - Specialized task force	W - Assessment	050-00416/2006-010
141 - Problem not properly classified or prioritized	M - Mechanical	M - Maintenance / Repair	050-00416/2006-002
141 - Problem not properly classified or prioritized	M - Mechanical	M - Maintenance / Repair	050-00416/2006-002
142 - Operating experience (OE) review LTA	F - Fuel Handling	R - Refueling	050-00416/2005-005
142 - Operating experience (OE) review LTA	M - Mechanical	M - Maintenance / Repair	050-00416/2005-005
142 - Operating experience (OE) review LTA	M - Mechanical	M - Maintenance / Repair	050-00416/2006-010
146 - Evaluation LTA	O - Operations	O - Control Room Ops	050-00416/2006-002
146 - Evaluation LTA	O - Operations	O - Control Room Ops	050-00416/2006-002
148 - Action not yet started or untimely	G - Engineering	G - Design	050-00416/2006-002
148 - Action not yet started or untimely	M - Mechanical	M - Maintenance / Repair	050-00416/2006-010
150 - Programmatic deficiency	M - Mechanical	M - Maintenance / Repair	050-00416/2006-010
Number of Items for this Docket: 12			
Percent of Total for this Docket: 32			

**U.S. Nuclear Regulatory Commission
Human Factors Information System (HFIS)
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 38

National Average: 43

2x National Average: 86

National Median: 24

Average for Selected Dockets: 38

Facility Name: Grand Gulf 1 Docket (050- 00416)

Details	Department	Work Type	Docket/Report
Work Planning & Practices / IR			
182 - Work package quality LTA	G - Engineering	G - Design	050-00416/2006-002
183 - Pre-job activities LTA	G - Engineering	G - Design	050-00416/2006-002
185 - Procedural adherence LTA	M - Mechanical	M - Maintenance / Repair	050-00416/2006-002
185 - Procedural adherence LTA	M - Mechanical	M - Maintenance / Repair	050-00416/2006-004
185 - Procedural adherence LTA	O - Operations	O - Control Room Ops	050-00416/2006-003
185 - Procedural adherence LTA	O - Operations	O - Control Room Ops	050-00416/2006-003
185 - Procedural adherence LTA	O - Operations	O - Control Room Ops	050-00416/2006-004
186 - Failure to take action / meet requirements	I - Instrumentation & Control	S - Surveillance	050-00416/2006-008
186 - Failure to take action / meet requirements	I - Instrumentation & Control	T - Testing	050-00416/2006-008
187 - Action implementation LTA	G - Engineering	G - Design	050-00416/2006-002
187 - Action implementation LTA	G - Engineering	G - Design	050-00416/2006-002
187 - Action implementation LTA	G - Engineering	G - Design	050-00416/2006-004
187 - Action implementation LTA	G - Engineering	G - Design	050-00416/2006-008
187 - Action implementation LTA	G - Engineering	G - Design	050-00416/2006-008
187 - Action implementation LTA	G - Engineering	G - Design	050-00416/2006-008
187 - Action implementation LTA	G - Engineering	G - Design	050-00416/2006-010
188 - Work practice or craft skill LTA	F - Fuel Handling	R - Refueling	050-00416/2005-005
188 - Work practice or craft skill LTA	M - Mechanical	M - Maintenance / Repair	050-00416/2005-005
194 - Housekeeping LTA	M - Mechanical	M - Maintenance / Repair	050-00416/2005-005
194 - Housekeeping LTA	X - Site-wide	X - Site-wide	050-00416/2006-004
196 - Independent verification / plant tours LTA	G - Engineering	G - Design	050-00416/2006-002

Number of Items for this Docket: 20

Percent of Total for this Docket: 53

Total Items for this Docket: 38
