



U.S. Department  
of Transportation

**Pipeline and  
Hazardous Materials Safety  
Administration**

400 Seventh Street, S.W.  
Washington, D.C. 20590

APR 25 2005

Ms. Gretchen Watkins  
Vice President  
Dome Pipeline Corporation  
240 4th Avenue, SW  
Calgary, Alberta, Canada  
T2P 4H4

RE: CPF No. 3-2001-5008H

Dear Ms. Watkins:

A Corrective Action Order was issued on May 8, 2001 by the Associate Administrator for Pipeline Safety in the above-referenced case. The Order required Dome Pipeline Corporation to take the necessary corrective action to protect the public and the environment from potential hazards associated with its 12 3/4-inch diameter Cochin Line between the North Dakota-Canada border and the Orrin Pump Station. The Director, Central Region, OPS has determined that all actions required by the Order have been completed. This case is now closed. Thank you for your cooperation in our joint effort to ensure pipeline safety.

Sincerely,

James Reynolds  
Pipeline Compliance Registry  
Office of Pipeline Safety

cc: Mr. David Millage  
Manager, NGL Operations  
Dome Pipeline Corporation  
2959 Sierra Court, SW  
Iowa City, IA 52240

**CERTIFIED MAIL - RETURN RECEIPT REQUESTED**