

UNITED STATES NUCLEAR REGULATORY COMMISSION

REGION II

SAM NUNN ATLANTA FEDERAL CENTER 61 FORSYTH STREET SW SUITE 23T85 ATLANTA, GEORGIA 30303-8931

June 26, 2003

SAFEGUARDS INFORMATION

Carolina Power & Light Company
ATTN: Mr. J. W. Moyer
Vice President
H. B. Robinson Steam Electric Plant Unit 2
3581 West Entrance Road
Hartsville, SC 29550

SUBJECT: ROBINSON NUCLEAR PLANT - NRC SAFEGUARDS INSPECTION

REPORT 50-261/03-07

Dear Mr. Moyer:

On May 23, 2003, the U.S. Nuclear Regulatory Commission (NRC) completed an inspection at your Robinson Nuclear Plant. The enclosed inspection report documents the inspection findings, which were discussed on May 23, 2003, with Mr. T. Cleary and other members of your staff.

The inspection examined activities conducted under your license as they relate to safety and compliance with an Order issued on February 25, 2002, which required your site to implement specific measures related to security of your facility. The inspection used Temporary Instruction 2515/148, "Inspection of Nuclear Reactor Safeguards Interim Compensatory Measures," to verify implementation of the Order as clarified in your responses dated March 15 and August 30, 2002. The inspection also included evaluations of other selected areas of the security program including performance indicators, access control, intrusion detection and assessment system testing, and aspects of contingency response. Within these areas, the inspection consisted of selected examination of procedures and records, observation of activities, and interviews with personnel.

In accordance with 10 CFR 2.790 of the NRC's "Rules of Practice," a copy of this letter, without the enclosed Safeguards Information, will be available electronically for public inspection in the NRC Public Document Room or from the Publicly Available Records (PARS) component of NRC's document system (ADAMS). ADAMS is accessible from the NRC Web site at http://www.nrc.gov/reading-rm/adams.html (the Public Electronic Reading Room).

DOCUMENT CONTAINS
SAFEGUARDS INFORMATION

ENCLOSURE CONTAINS
SAFEGUARDS INFORMATION
UPON SEPARATION THIS
PAGE IS DECONTROLLED

SAFEGUARDS INFORMATION REMOVED

CP&L

2

Should you have any questions concerning this letter, please contact us.

Sincerely,

/RA/

Anne T. Boland, Chief Plant Support Branch Division of Reactor Safety

Docket No. 50-261 License No. DPR-23

Enclosure: NRC Inspection Report

50-261/03-07 w/Supplemental Information (Contains Safeguards Information)

cc w/encl: See Page 3

DOCUMENT CONTAINS
SAFEGUARDS INFORMATION

cc w/Safeguards Information:

Chris L. Burton
Director, Site Operations
Carolina Power & Light Company
H. B. Robinson Steam Electric Plant
3581 West Entrance Road
Hartsville, SC 29550

T. P. Cleary
Plant General Manager
Carolina Power & Light Company
H. B. Robinson Steam Electric Plant
3581 West Entrance Road
Hartsville, SC 29550

C. T. Baucom, Supervisor Licensing/Regulatory Programs H. B. Robinson Steam Electric Plant 3581 West Entrance Road Hartsville, SC 29550

cc w/o Safeguards Information:

J. W. Holt, Manager Performance Evaluation and Regulatory Affairs CPB 9 Carolina Power & Light Company P. O. Box 1551 Raleigh, NC 27602-1551

B. L. Fletcher III, Manager Support Services - Nuclear Carolina Power & Light Company H. B. Robinson Steam Electric Plant 3581 West Entrance Road Hartsville, SC 29550

Henry J. Porter, Director
Div. of Radioactive Waste Mgmt.
Dept. of Health and Environmental
Control
2600 Bull Street
Columbia, SC 29201

(continued on Page 4)

DOCUMENT CONTAINS
SAFEGUARDS INFORMATION

(cc w/o Safeguards Information - continued)

Beverly Hall, Acting Director Division of Radiation Protection N. C. Department of Environment, Health and Natural Resources 3825 Barrett Drive Raleigh, NC 27609-7721

Steven R. Carr Associate General Counsel - Legal Dept. Progress Energy Service Company, LLC P. O. Box 1551 Raleigh, NC 27602-1551

John H. O'Neill, Jr. Shaw, Pittman, Potts & Trowbridge 2300 N. Street, NW Washington, DC 20037-1128

Peggy Force Assistant Attorney General State of North Carolina P. O. Box 629 Raleigh, NC 27602

Chairman of the North Carolina Utilities Commission P. O. Box 29510 Raleigh, NC 27626-0510

Robert P. Gruber Executive Director Public Staff - NCUC 4326 Mail Service Center Raleigh, NC 27699-4326

Public Service Commission State of South Carolina P. O. Box 11649 Columbia, SC 29211

DOCUMENT CONTAINS
SAFEGUARDS INFORMATION

Distribution w/o Safeguards Information:

- J. Peralta (encrypted copy)
- L. Olshan, NRR
- C. Evans (Part 72 Only)
- L. Slack, RII EICS

RIDSRIDSNRRDIPMLIPB

PUBLIC

OFFICE	RII:DRS		RII:DRS		RII:DRS		RII:DRS		NSIR		RII:DRP		RII:DRS	
SIGNATURE	DBF		JDE		JAC		WS via phone		B Hughes for		S Cahill for		ATB	
NAME	FORBES		ENNIS		CANADY		SARTOR		WESTREICH		FREDRICKSON		BOLAND	
DATE	6/12/03		6/13/03		6/24/03		6/25/03		6/24/03		6/24/03		6/2603	
E-MAIL COPY?	YES	NO	YES	NO	YES	NO	YES	NO	YES	NO	YES	NO	YES	NO
PUBLIC DOCUMENT	YES w/o encl													

OFFICIAL RECORD COPY DOCUMENT NAME: C:\ORPCheckout\FileNET\ML031780160.wpd

DOCUMENT CONTAINS SAFEGUARDS INFORMATION

SAFEGUARDS INFORMATION

ENCLOSURE

U.S. NUCLEAR REGULATORY COMMISSION

REGION II

Docket No.: 50-261

License No.: DPR-23

Report No.: 50-261/03-07

Licensee: Carolina Power and Light Company

Facility: Robinson Nuclear Plant

Location: 3581 West Entrance Road

Hartsville, SC 29550

Date: May 19-23, 2003

Inspectors: Donald B. Forbes, Senior Physical Security Inspector

Jerry D. Ennis, Physical Security Inspector

William M. Sartor, Senior Emergency Preparedness Inspector

James A. Canady, Resident Inspector, North Anna

Approved by: Anne T. Boland, Chief

Plant Support Branch Division of Reactor Safety

DOCUMENT CONTAINS
SAFEGUARDS INFORMATION

SAFEGUARDS INFORMATION

SUMMARY OF FINDINGS

IR 05000261/2003-007: Carolina Power and Light Company; 05/19-23/03; Robinson Nuclear Plant, Unit 1; Temporary Instruction (TI) 2515/148, Verification of Compliance with Interim Compensatory Measures Order.

The report covered an announced inspection by two regional physical security inspectors, an emergency preparedness inspector, and a resident inspector. One issue, the significance of which is to be determined, was identified. Pending further review, this issue is characterized as an unresolved item. The NRC's program for overseeing the safe operation of commercial nuclear power reactors is described in NUREG-1649, "Reactor Oversight Process," Revision 3, dated July 2000.

A. <u>Inspector-Identified and Self-Revealing Findings</u>

Cornerstone: Physical Security

- The inspectors identified an unresolved item concerning the licensee's implementation of Interim Compensatory Measure B.2.c of the February 25, 2002 Order. (Section III.D)
- B. <u>Licensee-Identified Violations</u>

None

DOCUMENT CONTAINS
SAFEGUARDS INFORMATION