

UNITED STATES NUCLEAR REGULATORY COMMISSION

REGION II

SAM NUNN ATLANTA FEDERAL CENTER 61 FORSYTH STREET, SW, SUITE 23T85 ATLANTA, GEORGIA 30303-8931

March 3, 2008

Mr. David A. Christian Senior Vice President and Chief Nuclear Officer Virginia Electric and Power Company Innsbrook Technical Center 5000 Dominion Boulevard Glen Allen, VA 23060

SUBJECT: ANNUAL ASSESSMENT LETTER - SURRY POWER STATION

(NRC INSPECTION REPORT 05000280/2008001 AND 05000281/2008001)

Dear Mr. Christian:

On February 6, 2008, the NRC staff completed its performance review of the Surry Power Station. Our technical staff reviewed performance indicators (PIs) for the most recent guarter and inspection results for the period from January 1 through December 31, 2007. The purpose of this letter is to inform you of our assessment of your safety performance during this period and our plans for future inspections at your facility.

This performance review and enclosed inspection plan do not include security information. A separate letter designated and marked as "Official Use Only--Security Related Information" will include the security cornerstone review and resultant inspection plan.

Overall, Surry Power Station Units 1 and 2 operated in a manner that preserved public health and safety and fully met all cornerstone objectives. Plant performance for the most recent quarter, as well as for the first three quarters of the assessment cycle, was within the Licensee Response column of the NRC's Action Matrix, based on all inspection findings being classified as having very low safety significance (Green) and all PIs indicating performance at a level requiring no additional NRC oversight (Green). Therefore, we plan to conduct reactor oversight process (ROP) baseline inspections at your facility. We also plan on conducting several non-ROP inspections which include: TI 2515/166, "Pressurized Water Reactor Containment Sump Blockage;" TI 2515/171, "Verification of Site Specific Implementation of B.5.b Phase 2 & 3 Mitigating Strategies;" and TI 2515/172, "Reactor Coolant System Dissimilar Metal Butt Welds."

The enclosed inspection plan details the inspections, less those related to physical protection scheduled through June 30, 2009. The inspection plan is provided to allow for the resolution of any scheduling conflicts and personnel availability issues well in advance of inspector arrival onsite. Routine resident inspections are not listed due to their ongoing and continuous nature. The inspections in the last nine months of the inspection plan are tentative and may be revised at the mid-cycle review.

VEPCO 2

In accordance with 10 CFR 2.390 of the NRC's "Rules of Practice," a copy of this letter and its enclosure will be made available electronically for public inspection in the NRC Public Document Room or from the Publicly Available Records (PARS) component of NRC's document system (ADAMS). ADAMS is accessible from the NRC Web site at http://www.nrc.gov/reading-rm/adams.html (the Public Electronic Reading Room).

If circumstances arise which cause us to change this inspection plan, we will contact you to discuss the change as soon as possible. Please contact me at (404) 562-4662 with any questions you may have regarding this letter or the inspection plan.

Sincerely,

/RA/

Eugene Guthrie, Chief Reactor Projects Branch 5 Division of Reactor Projects

Docket Nos.: 50-280, 50-281 License Nos.: DPR-32, DPR-37

Enclosure: Surry Inspection/Activity Plan (03/01/08 - 06/30/09)

cc w/encl.: (See page 3)

VEPCO 3

cc w/encl.:

Chris L. Funderburk
Director
Nuclear Licensing and Operations Support
Virginia Electric and Power Company
Electronic Mail Distribution

Donald E. Jernigan Site Vice President Surry Power Station Virginia Electric & Power Company Electronic Mail Distribution

Virginia State Corporation Commission Division of Energy Regulation P.O. Box 1197 Richmond, VA 23209

Lillian M. Cuoco, Esq.
Senior Counsel
Dominion Resources Services, Inc.
Millstone Power Station
Electronic Mail Distribution

Page 1 of 2

03/03/2008 08:13:27

Report 22

Surry Inspection / Activity Plan 03/01/2008 - 06/30/2009

Unit No. of Staff **Planned Dates** Inspection Number Inspection Activity Title on Site Start **End** Type OL EXAM - INITIAL EXAM 4 V23279 SURRY/MARCH 2008 EXAM AT POWER FACILITIES 1 03/17/2008 03/28/2008 Not Applicable EB1-SUMP - TI 2515/166 CONTAINMENT SUMP INSPECTION 1 IP 2515/166 Pressurized Water Reactor Containment Sump Blockage [NRC GENERIC LETTER 2004-02] 2 05/05/2008 05/09/2008 Safety Issues - UNIT 2 - ISI EB3-ISI 2 2 IP 7111108P Inservice Inspection Activities - PWR 05/05/2008 05/09/2008 Baseline Inspections EB3TI172 - TI-172 2 Reactor Coolant System Dissimiliar Metal Butt Welds 1, 2 IP 2515/172 05/05/2008 05/09/2008 Generic Safety Inspectio EB3SGISI - U2 SG ISI 1 2 IP 7111108P Inservice Inspection Activities - PWR 05/12/2008 05/16/2008 **Baseline Inspections** PSB1-RP - RADIATION PROTECTION PREINSPECTION VISIT 1 1.2 IP 7112101 06/25/2008 06/23/2008 Access Control to Radiologically Significant Areas Baseline Inspections EB3-HS - HEAT SINK 1 1.2 IP 7111107B Heat Sink Performance 06/23/2008 06/27/2008 **Baseline Inspections** PSB1-EP - EP INSP 1 Alert and Notification System Testing 1.2 IP 7111402 07/14/2008 07/18/2008 **EP Baseline Inspection Emergency Response Organization Augmentation Testing** 1. 2 IP 7111403 07/14/2008 07/18/2008 **EP Baseline Inspection** 1, 2 Emergency Action Level and Emergency Plan Changes 07/14/2008 IP 7111404 07/18/2008 **EP Baseline Inspection** 1, 2 IP 7111405 Correction of Emergency Preparedness Weaknesses and Deficiencies 07/14/2008 07/18/2008 **EP Baseline Inspection** 1, 2 IP 71151-EP01 Drill/Exercise Performance 07/14/2008 07/18/2008 **Baseline Inspections** 1, 2 IP 71151-EP02 **ERO Drill Participation** 07/14/2008 07/18/2008 **Baseline Inspections** 1. 2 IP 71151-EP03 Alert & Notification System 07/14/2008 07/18/2008 **Baseline Inspections** PSB1-RP - RADIATION PROTECTION PUBLIC BASELINE 4 1.2 IP 7112101 Access Control to Radiologically Significant Areas 07/28/2008 08/01/2008 Baseline Inspections 1.2 IP 7112103 Radiation Monitoring Instrumentation and Protective Equipment 07/28/2008 08/01/2008 **Baseline Inspections** 1.2 IP 7112201 Radioactive Gaseous and Liquid Effluent Treatment and Monitoring Systems 07/28/2008 08/01/2008 Baseline Inspections 1.2 IP 7112203 Radiological Environmental Monitoring Program (REMP) And Radioactive Material Control Program 07/28/2008 08/01/2008 **Baseline Inspections** 1.2 IP 71151-OR01 Occupational Exposure Control Effectiveness 07/28/2008 08/01/2008 **Baseline Inspections** 1.2 **RETS/ODCM Radiological Effluent** IP 71151-PR01 07/28/2008 08/01/2008 Baseline Inspections TI-171 B.5.B PHASE 2&3 3 IP 2515/171 Verification of Site Specific Implementation Of B.5.b Phase 2 & 3 Mitigating Strategies 1, 2 08/04/2008 08/08/2008 Generic Safety Inspectio OL RQ - REQUAL INSPECTION 2 IP 7111111B Licensed Operator Requalification Program 1, 2 04/06/2009 04/10/2009 **Baseline Inspections** EB3ISI - UNIT 1 ISI 1 1 IP 7111108P Inservice Inspection Activities - PWR 04/27/2009 05/01/2009 **Baseline Inspections**

This report does not include INPO and OUTAGE activities.

This report shows only on-site and announced inspection procedures.

Page 2 of 2

Surry Inspection / Activity Plan

03/03/2008 08:13:27 Report 22 03/01/2008 - 06/30/2009

Unit Number	Inspection Activity)[Title	No. of on S		Planned Start	d Dates End	Inspection Type
	TFPI - TFPI				6			
1, 2	IP 7111105T	Fire Protection [Triennial]				06/08/2009	06/12/2009	Baseline Inspections
1, 2	IP 7111105T	Fire Protection [Triennial]				06/22/2009	06/26/2009	Baseline Inspections