

JOB CHANGE ORDER FORM

Originator Name Route To — Matt Kern	Planner Nar Route To — Mark Johns	Route To		Asset Supt. Ray Hawkins					
UNIT: Isom									
Initiated 03/07/2005 Date:					DATE JCO Completed:				
JCO LEVEL — Indicate by checking below. ACQUIRING JOB APPROVALS IS THE RESPONSIBILITY OF THE REQUESTER. Unit System Equipment Name Job Note Number Charge Number (W.O. #)									
Raffinate		5 miscellaneous valves		(05-009R Rev. 1		30030594040		
JCO Category − (Check One) ⊠ NEW WORK ☐ SCOPE REVISION ☐ OTHER ☐ DELETION									
Job Justification – Provide necessary information for adding to Work Scope:									
One valve and most of the bolting on the natural gas feed line to the B-1101 have experienced severe cooling water overspray									
corrosion and must be replaced, two bleed valves at pressure controller PV-5012 have broken handwheels and do not operate,									
and the two block valves which isolate a troublesome 5100 level transmitter leak by. Replace five small valves and corroded bolting.									
Job Description – Provide all details as necessary to describe job requirements and attach job note if necessary:									
Natural gas valves and LT-5100 valves are flanged and only required removal and installation of new. PV-5012 valves are welded									
but the spool pieces can be easily removed for replacing these valves. All of these valve replacements will be included in a revision to									
job note 05-009R rev. 1.									
Preliminary Cost Estimate: \$2400									
***********Following is completed by Asset Team************************************									
Job Change Order Approval					Schedule Impact ⊠ NO □ Yes □ MOC REQ'D				
Signature Da			Date		Comments:				
Originator:					⊠ Expense □ Capital				
Planner:				[Cost Estimate Summary				
Supervisor:			_ _	[Man-hours 25		Labor\$ \$1500	Material/Service \$ \$900	
Asset Supt.:					Estimated Total Cost \$: \$2400				