


# North Fork Mill Creek Restoration Project



Treatment	Acres
Aspen/Cottonwood Enhancement	48
Sapling thinning	26
Thinning	2125
Underburn	671
<b>Total</b>	<b>2870</b>

## Legend

- Proposed Trails**
  - Horse, Hike
  - Horse, Hike, Bike
- Proposed Road Management**
  - Road Decommision
  - Seasonal Closures
  - Road Closures
- Restoration Treatment**
  - Aspen/Cottonwood Enhancement
  - Sapling thinning
  - Thinning
  - Underburn
- Proposed Culvert Removal
- Streams
- Other Ownership
- National Forest Boundary

This product is reproduced from information prepared by the USDA, Forest Service or from other suppliers. The Forest Service cannot assure the reliability or suitability of this information for a particular purpose. The data and product accuracy may vary due to compilation from various sources, including modeling and interpretation, and may not meet National Map Accuracy Standards. This information may be updated, corrected or otherwise modified without notification. For more information contact: Mt. Hood National Forest Supervisors Office at 503-668-1700. The USDA is an equal opportunity provider and employer.



Produced by J. Vandenbrook, GIS Specialist, Mt. Hood National Forest  
February 25, 2008

E

1:36,000