
### **Hope Creek 1**

#### 1Q/2000 Performance Indicators

Licensee's General Comments: none

### Unplanned Scrams per 7000 Critical Hrs




Thresholds: White > 3.0 Yellow > 6.0 Red > 25.0

#### Notes

Unplanned Scrams per 7000 Critical Hrs	1Q/99	2Q/99	3Q/99	4Q/99	1Q/00
Unplanned scrams	0	0	0	0	0
Critical hours	1078.0	2183.0	2128.0	2209.0	2184.0
Indicator value	0.9	0.9	0.9	0	0

### Scrams with Loss of Normal Heat Removal




Thresholds: White > 2.0 Yellow > 10.0 Red > 20.0

#### Notes

Scrams with Loss of Normal Heat Removal	1Q/99	2Q/99	3Q/99	4Q/99	1Q/00
Scrams	0	0	0	0	0
Indicator value	0	0	0	0	0

# Unplanned Power Changes per 7000 Critical Hrs




Thresholds: White > 6.0

### Notes

Unplanned Power Changes per 7000 Critical Hrs	1Q/99	2Q/99	3Q/99	4Q/99	1Q/00
Unplanned power changes	0	1.0	2.0	1.0	0
Critical hours	1078.0	2183.0	2128.0	2209.0	2184.0
Indicator value	1.9	2.8	3.8	3.7	3.2

## Safety System Unavailability, Emergency AC Power, >2EDG



Thresholds: White > 2.5% Yellow > 10.0% Red > 20.0%

### Notes

Safety System Unavailability, Emergency AC Power, >2EDG	1Q/99	2Q/99	3Q/99	4Q/99	1Q/00
Train 1					
Planned unavailable hours	0	46.80	0.50	0.40	19.50
Unplanned unavailable hours	0	0	0	0	0
Fault exposure hours	0	0	0	0	0
Effective Reset hours	0	0	0	0	0
Required hours	2160.00	2183.00	2208.00	2209.00	2184.00
Train 2					
Planned unavailable hours	0	35.18	0.70	52.60	9.10
Unplanned unavailable hours	0	0	0	20.17	0
Fault exposure hours	0	0	0	0	0
Effective Reset hours	0	0	0	0	0
Required hours	2160.00	2183.00	2208.00	2209.00	2184.00
Train 3					
Planned unavailable hours	0	0.60	1.10	100.20	1.20
Unplanned unavailable hours	0	0	0	0	0
Fault exposure hours	0	0	0	0	0
Effective Reset hours	0	0	0	0	0
Required hours	2160.00	2183.00	2208.00	2209.00	2184.00
Train 4					
Planned unavailable hours	0	0.40	1.30	0.10	134.50
Unplanned unavailable hours	0	0	0	0	0
Fault exposure hours	0	0	0	0	0
Effective Reset hours	0	0	0	0	0
Required hours	2160.00	2183.00	2208.00	2209.00	2184.00
Indicator value	1.6%	1.6%	1.5%	1.5%	1.2%


Licensee Comments:

4Q/99: The Planned Unavailable hours for the 2nd, 3rd & 4th quarters of 1999 were revised to include the time for EDG Barring and Lube.

3Q/99: The Planned Unavailable hours for the 2nd, 3rd & 4th quarters of 1999 were revised to include the time for EDG Barring and Lube.

2Q/99: The Planned Unavailable hours for the 2nd, 3rd & 4th quarters of 1999 were revised to include the time for EDG Barring and Lube.

### Safety System Unavailability, High Pressure Injection System (HPCI)




Thresholds: White > 4.0% Yellow > 12.0% Red > 50.0%

#### Notes

Safety System Unavailability, High Pressure Injection System (HPCI)	1Q/99	2Q/99	3Q/99	4Q/99	1Q/00
Train 1					
Planned unavailable hours	4.80	0	0	120.90	0.40
Unplanned unavailable hours	0	0	9.02	0	0
Fault exposure hours	0	0	0	0	0
Effective Reset hours	0	0	0	0	0
Required hours	1078.60	2183.00	2156.50	2209.00	2184.00
Indicator value	2.5%	2.4%	1.7%	2.0%	1.5%

## Safety System Unavailability, Heat Removal System (RCIC)




Thresholds: White > 4.0% Yellow > 12.0% Red > 50.0%

### Notes

Safety System Unavailability, Heat Removal System (RCIC)	1Q/99	2Q/99	3Q/99	4Q/99	1Q/00
Train 1					
Planned unavailable hours	9.62	0	0	126.60	0
Unplanned unavailable hours	0	0	0	0	0
Fault exposure hours	0	0	0	0	0
Effective Reset hours	0	0	0	0	0
Required hours	1078.60	2183.00	2156.50	2209.00	2184.00
Indicator value	6.3%	5.8%	5.6%	1.8%	1.4%

### Safety System Unavailability, Residual Heat Removal System



Thresholds: White > 1.5% Yellow > 5.0% Red > 10.0%


#### Notes

Safety System Unavailability, Residual Heat Removal System	1Q/99	2Q/99	3Q/99	4Q/99	1Q/00
Train 1					
Planned unavailable hours	25.65	40.70	1.84	16.82	83.80
Unplanned unavailable hours	0	0	8.20	2.68	14.20
Fault exposure hours	0	0	0	0	0
Effective Reset hours	0	0	0	0	0
Required hours	2160.00	2183.00	2208.00	2209.00	2184.00
Train 2					
Planned unavailable hours	5.73	40.38	27.53	32.80	9.80
Unplanned unavailable hours	0	0	0	0.55	0
Fault exposure hours	0	0	0	0	0
Effective Reset hours	0	0	0	0	0
Required hours	2160.00	2183.00	2208.00	2209.00	2184.00
Indicator value	0.9%	1.0%	1.0%	1.1%	1.1%

#### Licensee Comments:

1Q/98: Unplanned Unavailable hours for train 2 was revised from 32.60 to 58.07 hours. This was found as a result of a recent self-assessment. This does not result in a change to the PI value.

# Safety System Functional Failures (BWR)




Thresholds: White > 6.0

#### Notes

Safety System Functional Failures (BWR)	1Q/99	2Q/99	3Q/99	4Q/99	1Q/00
Safety System Functional Failures	1	0	0	1	0
Indicator value	2	1	1	2	1

## **Reactor Coolant System Activity**




Thresholds: White > 50.0 Yellow > 100.0

### Notes

Reactor Coolant System Activity	4/99	5/99	6/99	7/99	8/99	9/99	10/99	11/99	12/99	1/00	2/00	3/00
Maximum activity	0.000031	0.000072	0.000032	0.000051	0.000035	0.000042	0	0	0	0	0.000065	0.000058
Technical specification limit	0.2	0.2	0.2	0.2	0.2	0.2	0.2	0.2	0.2	0.2	0.2	0.2
Indicator value	0	0	0	0	0	0	0	0	0	0	0	0

## Reactor Coolant System Leakage




Thresholds: White > 50.0 Yellow > 100.0

### Notes

Reactor Coolant System Leakage	4/99	5/99	6/99	7/99	8/99	9/99	10/99	11/99	12/99	1/00	2/00	3/00
Maximum leakage	3.000	2.330	2.030	2.180	2.260	2.160	2.120	2.560	2.910	2.310	2.450	2.110
Technical specification limit	25.0	25.0	25.0	25.0	25.0	25.0	25.0	25.0	25.0	25.0	25.0	25.0
Indicator value	12.0	9.3	8.1	8.7	9.0	8.6	8.5	10.2	11.6	9.2	9.8	8.4

### **Drill/Exercise Performance**




Thresholds: White < 90.0% Yellow < 70.0%

### Notes

Drill/Exercise Performance	1Q/99	2Q/99	3Q/99	4Q/99	1Q/00
Successful opportunities	12.0	9.0	2.0	94.0	37.0
Total opportunities	12.0	10.0	3.0	97.0	39.0
Indicator value	99.0%	97.9%	96.7%	96.6%	95.7%

## **ERO Drill Participation**




Thresholds: White < 80.0% Yellow < 60.0%

#### Notes

ERO Drill Participation	1Q/99	2Q/99	3Q/99	4Q/99	1Q/00
Participating Key personnel	53.0	66.0	72.0	70.0	72.0
Total Key personnel	65.0	77.0	76.0	75.0	77.0
Indicator value	81.5%	85.7%	94.7%	93.3%	93.5%

## **Alert & Notification System**




Thresholds: White < 94.0% Yellow < 90.0%

### Notes

Alert & Notification System	1Q/99	2Q/99	3Q/99	4Q/99	1Q/00
Successful siren-tests	495	485	496	496	497
Total sirens-tests	497	497	497	497	497
Indicator value	99.1%	98.7%	99.0%	99.2%	99.3%

# Occupational Exposure Control Effectiveness



Thresholds: White > 2.0 Yellow > 5.0


### Notes

Occupational Exposure Control Effectiveness	1Q/99	2Q/99	3Q/99	4Q/99	1Q/00
High radiation area occurrences	0	0	0	0	0
Very high radiation area occurrences	0	0	0	0	0
Unintended exposure occurrences	0	0	0	0	0
Indicator value	0	0	0	0	0

Licensee Comments:

1Q/00:

# **RETS/ODCM Radiological Effluent**




Thresholds: White > 1.0 Yellow > 3.0

#### Notes

RETS/ODCM Radiological Effluent	1Q/99	2Q/99	3Q/99	4Q/99	1Q/00
RETS/ODCM occurrences	0	0	0	0	0
Indicator value	0	0	0	0	0

## **Protected Area Security Performance Index**




Thresholds: White > 0.080

### Notes

Protected Area Security Performance Index	1Q/99	2Q/99	3Q/99	4Q/99	1Q/00
IDS compensatory hours	728.60	1084.50	693.20	686.40	439.80
CCTV compensatory hours	26.9	0	0	0	0
IDS normalization factor	3.80	3.80	3.80	3.80	3.80
CCTV normalization factor	2.8	2.8	2.8	2.8	2.8
Index Value	0.060	0.064	0.054	0.049	0.044

# **Personnel Screening Program**




Thresholds: White > 2.0 Yellow > 5.0

### Notes

Personnel Screening Program	1Q/99	2Q/99	3Q/99	4Q/99	1Q/00
Program failures	0	0	0	0	0
Indicator value	0	0	0	0	0

### FFD/Personnel Reliability



Thresholds: White > 2.0 Yellow > 5.0

#### Notes

FFD/Personnel Reliability	1Q/99	2Q/99	3Q/99	4Q/99	1Q/00
Program Failures	0	0	0	0	0
Indicator value	0	0	0	0	0

Licensee Comments: none

A PI Summary | Inspection Findings Summary | Reactor Oversight Process

Last Modified: April 1, 2002