Peter E. Katz Vice President Calvert Cliffs Nuclear Power Plant Constellation Generation Group, LLC 1650 Calvert Cliffs Parkway Lusby, Maryland 20657 410 495-4455 410 495-3500 Fax



April 17, 2003

U. S. Nuclear Regulatory Commission Washington, DC 20555

ATTENTION:

Document Control Desk

SUBJECT:

Calvert Cliffs Nuclear Power Plant

Unit Nos. 1 & 2; Docket Nos. 50-317 & 50-318

Information Regarding Interim Inspection Requirements for Reactor Pressure

Vessel Head (TAC Nos. MB7752 and MB7753)

In References (a), (b), and (c) Calvert Cliffs Nuclear Power Plant, Inc. requested relaxation from aspects of the Nuclear Regulatory Commission Order on reactor vessel head inspections (Reference d). We understand that you desire to place the following condition in our Renewed Operating License Nos. DPR-53 and DPR-69 for Unit Nos. 1 and 2, respectively, as part of granting the requested relaxation:

If the NRC staff finds that the crack growth formula in industry report MRP-55 is unacceptable, the licensee shall revise its analysis that justifies relaxation of the Order within 30 days after the NRC informs the licensee of an NRC-approved crack growth formula. If the licensee's revised analysis shows that the crack growth acceptance criteria are exceeded prior to the end of the current operating cycle, this relaxation is rescinded and the licensee shall, within 72 hours, submit to the NRC written justification for continued operation. If the revised analysis shows that the crack growth acceptance criteria are exceeded during the subsequent operating cycle, the licensee shall, within 30 days, submit the revised analysis for NRC review. If the revised analysis shows that the crack growth acceptance criteria are not exceeded during either the current operating cycle or the subsequent operating cycle, the licensee shall, within 30 days, submit a letter to the NRC confirming that its analysis has been revised.

We agree to the condition, as worded above, that you wish to place in our license.

Should you have questions regarding this matter, we will be pleased to discuss them with you.

Very truly yours,

Refer E Kar

PEK/PSF/bjd

AIDI

Document Control Desk April 17, 2003 Page 2

REFERENCES:

- (a) Letter from Mr. P. E. Katz (CCNPP) to Document Control Desk (NRC), dated February 18, 2003, Response to Issuance of Order Establishing Interim Inspection Requirements for Reactor Pressure Vessel Heads at Pressurized Water Reactors
- (b) Letter from Mr. P. E. Katz (CCNPP) to Document Control Desk (NRC), dated March 13, 2003, Response to Request for Additional Information Regarding Interim Inspection Requirements for Reactor Pressure Vessel Head (TAC Nos. MB7752 and MB7753)
- (c) Letter from Mr. P. E. Katz (CCNPP) to Document Control Desk (NRC), dated April 4, 2003, Response to Request for Additional Information Regarding Interim Inspection Requirements for Reactor Pressure Vessel Head (TAC Nos. MB7752 and MB7753)
- (d) Letter from Mr. S. J. Collins (NRC) to Holders of Licenses for Operating Pressurized Water Reactors, dated February 11, 2003, Issuance of Order Establishing Interim Inspection Requirements for Reactor Pressure Vessel Heads at Pressurized Water Reactors (EA-03-009)

cc: J. Petro, Esquire
J. E. Silberg, Esquire
Director, Project Directorate I-1, NRC
G. S. Vissing, NRC

H. J. Miller, NRC Resident Inspector, NRC R. I. McLean, DNR