

Amusement Ride-Related Injuries and Deaths in the United States: 1987-1999

July 2000

C. Craig Morris, Ph.D.
U.S. Consumer Product Safety Commission
Directorate for Epidemiology
Division of Hazard Analysis
4330 East West Highway
Bethesda, MD 20814

No Mirs PrviLbles of D
Products identified
Excepted by
Firms Notified,
Comments Processed

### **Executive Summary**

This report describes U.S. Consumer Product Safety Commission (CPSC) data on amusement ride-related fatalities and hospital emergency room-treated injuries. Fatality data are presented for calendar years 1987 through 1999. Injury data are presented for calendar years 1993 through 1999. Hazard scenario data derived from in-depth investigations and incident reports are presented for the period from 1 Jan 1990 through 30 April 2000.

- An estimated 10,400 hospital emergency room-treated *injuries* occurred in 1999, with about 7,000 involving fixed rides and 3,000 involving mobile rides. An estimated 23.5 injuries per million attendance occurred at fixed-site parks in 1999. Attendance data are not currently available for mobile rides.
- There was a marginally significant upward trend in fixed-site and total amusement riderelated *injuries* from 1993 through 1999 due to a sharp increase in fixed-site injuries beginning in 1997.
- The estimated annual average number of non-occupational amusement ride-related fatalities from 1987 through 1998 was 4.3 fatalities each year, and there was a marginally significant upward trend in fatalities from 1993 through 1999.
- A hazard sketch summarizing CPSC investigations of amusement ride incidents revealed

   hazard patterns associated with mechanical failure, operator behavior, consumer
   behavior, other factors, and combinations of these factors.

# **Table of Contents**

Executive Summary	Page 2
Introduction and Definition of Amusement Rides	4
Amusement Ride-Related Injuries	4
Amusement Ride-Related Fatalities	9
Hazard Patterns Associated with Amusement Ride-Related Incidents	12
References	13
Appendix A - Technical Note	14
Appendix B - Reported Fatalities	15
Appendix C – Investigated Cases	26

### Amusement Ride-Related Injuries and Deaths in the United States: 1987-1999

This report describes U.S. Consumer Product Safety Commission (CPSC) data on amusement ride-related fatalities and hospital emergency room-treated injuries. Fatality data are presented for calendar years 1987 through 1999. Injury data are presented for calendar years 1993 through 1999. A hazard sketch is presented to summarize in-depth investigations and incident reports of amusement ride incidents from 1 Jan 1990 through 30 April 2000. This report replaces previous CPSC reports summarizing amusement ride incidents [1,2,3,4].

### **Definition** of Amusement Rides

Section 3(a)(1) of the Consumer Product Safety Act describes an amusement ride as:

...any mechanical device which carries or conveys passengers along, around, or over a fixed or restricted route within a defined area for the purpose of giving its passengers amusement, which is customarily controlled or directed by an individual who is employed for that purpose and who is not a consumer with respect to that device, and which is not permanently fixed to a site.

Although fixed-site amusement rides are excluded from CPSC jurisdiction by Section 3 (a) (1), CPSC data collection systems receive data on amusement rides that do not, at the outset, distinguish between fixed-site and mobile rides. Additional analysis must be undertaken in order to determine which incidents involve mobile rides and whether a fixed-site ride that was the subject of an incident is also a mobile ride. Data regarding fixed-site ride incidents are included in this report, along with data on mobile ride incidents, since those data are immediately available to CPSC through the process described above and are useful for comparison purposes. Only non-occupational incidents, which involve non-employee victims injured while on, in, or around an amusement ride, are included in this report.

## Amusement Ride-Related Injuries

#### Method

Data on non-occupational amusement ride-related injuries were obtained from CPSC's National Electronic Injury Surveillance System (NEISS). The NEISS is a stratified probability sample of hospitals with emergency rooms and 6 or more beds in the United States. There are currently 100 participating hospitals in the NEISS. NEISS hospital coders identify injury incidents associated with amusement rides by using the NEISS product code for amusement rides (1293). In this analysis, all NEISS records for calendar years 1993 through 1999 containing product code 1293 were reviewed. Based on information in narrative comments in the records, a single experienced coder (the author) classified each case into 1 of 5 mutually exclusive and exhaustive categories: not a ride (out of scope), fixed-site ride, mobile-site ride, unknown-site ride, or unknown if ride. Cases involving coin-operated rides or free-play attractions often found at restaurants or shopping centers, alpine and water slide amusements, wave machines, "moon walks," inflatable slides, mechanical bulls, playground equipment, etc., are examples of cases coded not a ride. Cases involving roller coasters or "whirling" rides are examples of cases coded fixed-site, mobile-site, or unknown-site ride: if the comment stated the name of an amusement park or that the incident occurred at a park or involved an amusement park ride, then the case was coded fixed-site; if the comment stated that the incident occurred at a carnival, fair,

or festival, then the case was coded *mobile-site*; if the comment gave no site information, then the case was coded *unknown-site*. Cases involving a "merry go round," with no indication of whether it was playground equipment or an amusement ride as defined by the Consumer Product Safety Act, are examples of cases coded *unknown if ride*.

### Estimate Adjustments

Adjustments of amusement ride-related injury estimates for prior years appear in this report. First, all NEISS cases from 1993 to 1999 were reviewed by an experienced coder to verify consistency in the coding of cases. A few codings were adjusted to improve consistency. Second, the NEISS sample of hospitals was updated in 1997 to reflect changes in the distribution and size of emergency room hospitals in the U.S. since the previous sample update in 1990. Periodic updates are required for the sample of NEISS hospitals to accurately represent the universe of hospitals with emergency rooms in the U.S. Data were collected concurrently from both the old and updated NEISS samples for 9 months in 1997 to provide a statistical basis for adjustments of prior estimates. Third, unknown-site estimates were allocated to fixed-site and mobile-site estimates in the proportions observed in known-site estimates each year. The adjusted estimates in this report differ from estimates given in previous CPSC publications.

#### Results

Figure 1 gives NEISS estimates with unknown-site estimates allocated to the fixed-site and mobile-site estimates in the proportions observed in known-site estimates each year. For example, the fixed-site estimate for 1999 is .699 of the sum of the fixed-site and mobile-site estimates, so .699 of the unknown-site estimate for 1999 is added to the fixed-site estimate, and .301 of the unknown-site estimate for 1999 is added to the mobile-site estimate. The proportions of unknown-site estimates allocated to fixed-site versus mobile-site estimates each year depend only on estimates for each year as in the above example for 1999. An estimated total of 10,400  $\pm$  5,600 hospital emergency room-treated injuries occurred in 1999. (The margin of error is 5,600 for a 95% confidence level). The increasing trends in fixed-site and total injuries from 1993 through 1999 were marginally significant, both p = .07, 1-tail exact Kendall Tau tests.




Figure 1. Estimated amusement ride-related injuries treated at US hospital emergency rooms from 1993 through 1999. Source: U.S. Consumer Product Safety Commission.

Table 1 gives the unallocated NEISS estimates for calendar years 1993 through 1999. Note that the *fixed-site* and *mobile-site* injury estimates in Table 1 underestimate actual totals due to the exclusion of *unknown-site* cases, all of which involve *fixed-site* or *mobile* amusement rides. The adjusted estimates in Figure 1 correct for the underestimation of *fixed-site* and *mobile* injuries in Table 1 by allocating the *unknown-site* estimates to the known *fixed-site* and *mobile* estimates in the same proportions observed in the known-site estimates (see Table 2).

Table 1
Unallocated Estimated Non-Occupational Amusement Ride Injuries by Year and Site of Ride

Year	Fixed	Mobile	Unknown-Site	Total	ME (Total)
1999	5,980	2,580	1,820	10,380	5,560
1998	4,760	2,110	2,500	9,370	3,950
1997	4,590	2,170	1,280	8,050	4,600
1996	3,220	2,530	900	6,650	4,010
1995	3,530	2,680	1,330	7,540	4,340
1994	3,080	2,420	1,260	6,760	3,930
1993	3,750	2,240	1,710	7,700	3,980

Note: Details may not sum to totals due to rounding. Margin of error (ME) for 95% confidence level. Source: U.S. Consumer Product Safety Commission.

Table 2 gives the allocated NEISS estimates for calendar years 1993 through 1999 presented graphically in Figure 1. As explained above, the adjusted estimates in Table 2 correct for the underestimation of fixed-site and mobile injuries in Table 1 by allocating the unknown-site estimates to the known fixed-site and mobile estimates in the same proportions observed in the known-site estimates.

Table 2
Allocated Estimated Non-Occupational Amusement Ride Injuries by Year and Site of Ride

Year	Fixed	Mobile	Total	ME (Total)
1999	7,260	3,120	10,380	5,560
1998	6,500	2,870	9,370	3,950
1997	5,460	2,580	8,050	4,600
1996	3,720	2,930	6,650	4,010
1995	4,290	3,260	7,540	4,340
1994	3,790	2,970	6,760	3,930
1993	4,830	2,880	7,700	3,980

Note: Details may not sum to totals due to rounding. Margin of error (ME) for 95% confidence level. Source: U.S. Consumer Product Safety Commission.

Table 3 gives estimated fixed-site injuries divided by estimated attendance at amusement parks [7] each year. The upward trend in risk is marginally significant, p < .07, 1-tail exact Kendall Tau test. Unknown-site estimates were allocated to fixed-site and mobile estimates as described above. Attendance data for mobile rides are not available.

Table 3
Risk of Non-Occupational Fixed-Site Amusement Ride Injury by Year

Year	Attendance (millions)	Risk
1999	309	23.5
1998	300	21.6
1997	300	18.2
1996	290	12.8
1995	280	15.3
1994	267	14.2
1993	275	17.5

Note: Risk is number of injuries per million attendance. Source: U.S. Consumer Product Safety Commission and International Association of Amusement Parks and Attractions.

Because an increasing trend in amusement ride-related injuries began in 1997, the same year the NEISS sample of hospitals was updated, it is important to determine whether the increase might be attributable to revision of the NEISS sample, i.e., replacement of about 30 hospitals in the sample of about 100 hospitals. Hospitals continuously present in NEISS from 1995 through 1999 were identified to determine the trend in amusement ride-related injuries at those hospitals. Table 4 gives sample counts, not estimates, from these hospitals. Although the total count dropped from 121 in 1995 to 95 in 1996, it steadily increased to 117 in 1997, 124 in 1998, and 167 in 1999. The increasing trend from 1996 to 1999 was statistically significant by an exact Kendall Tau 1-tailed test, p = .04. Thus, the trend in fixed-site and total amusement ride-related injuries does not appear to be an artifact of the updated NEISS sample in 1997.

Table 4
Non-Occupational Amusement Ride-Related Injury Counts for
Hospitals in NEISS from 1995 through 1999 by Year and Site of Ride

Year	Fixed	Mobile	Unknown	Total
1999	87	44	36	167
1998	62	29	33	124
1997	63	29	25	117
1996	49	33	13	95
1995	60	43	18	121
			_ <del>-</del>	

Source: U.S. Consumer Product Safety Commission.

Analysis of individual NEISS hospital data for calendar years 1995 through 1999 revealed one hospital (#58) that both records more amusement ride-related cases each year and exhibits a larger increasing trend over the period than all other NEISS hospitals. However, as discussed in Appendix A, reporting amusement ride-related injury estimates with hospital 58 excluded is inappropriate because the NEISS sample with hospital 58 removed is not statistically representative of all emergency room hospitals in the U.S.

In conclusion, current NEISS data indicate a total in 1999 of about  $10,400 \pm 5,600$  emergency room-treated, amusement ride-related injuries, with about 7,000 involving fixed-site rides and about 3,000 involving mobile rides (Figure 1). From 1993 through 1999, there was a marginally significant upward trend in fixed-site and total amusement ride-related injuries and in the risk of fixed-site injury defined as the estimated number of injuries per million attendance at amusement parks. It should be noted that, although there are fewer mobile as compared to fixed-site ride injuries, the amount of exposure is probably different for mobile versus fixed-site rides, so the relative risk of injury attributable to one versus the other cannot be determined without comparable exposure information for both types of rides.

### **Amusement Ride-Related Fatalities**

CPSC's files were searched for records of fatalities involving amusement rides during calendar years 1987 through 1999. These files were the death certificate file (DTHS), the injury or potential injury incident file (IPII), and the National Electronic Injury Surveillance System file (NEISS). Information in the narrative field of the records was used to classify cases using the criteria defined above in the *Method* section for the NEISS injury analyses.

DTHS and IPII files recorded 49 non-occupational fatalities from 1987 through 1999; NEISS files recorded no amusement ride-related fatalities during this period. Appendix B lists the 49 documented non-occupational fatality cases. Due to the logistical difficulty of capturing all fatalities related to any product or event, these counts do not account for all amusement ride-related fatalities. Methods for estimating true totals given 2 or more independent data sources are known as "capture-recapture" or "multiple record systems" methods [8,9]. Capture-recapture analyses were conducted on 43 documented cases during 1987 through 1998 to estimate the total and annual average number of non-occupational amusement ride-related fatalities during that period. Lags in fatality reporting preclude estimation of fatalities for the last full calendar year. The capture-recapture analyses treated the DTHS and IPII files as independent samples of all non-occupational amusement ride-related deaths during the study period. The estimated number of non-occupational amusement ride-related fatalities from 1987 through 1998 was 52 (95% confidence interval = 43 to 62), for an estimated annual average of 4.3 fatalities each year during that period.

Documented non-occupational fatalities from 1987 through 1999 were classified by ride type, location (state), and ride site. Site refers to fixed-site rides as in amusement parks, mobile rides as in carnivals or fairs, or rides of unknown site. From 1987 through 1999, there were 49 documented fatalities, including 30 fixed ride-related fatalities, 8 mobile ride-related fatalities, and 11 fatalities involving unknown ride mobility status. The following tables give documented fatalities by year and ride mobility (Table 4), ride type and mobility (Table 5), and state and ride mobility (Table 6).

ζ

Table 4 gives fatalities by year and site. The fatalities observed in 1998 (7) and 1999 (6) were the most since 1988. From 1993 through 1999, there was a marginally significant upward trend in both fixed-site and total fatalities, both p = .08, exact Kendall Tau 1-tailed tests.

Table 4
Non-Occupational Amusement Ride-Related Fatalities by Year and Ride Site

Year	Fixed	Mobile	Unknown	Total
1999	6	0	0	6*
1998	3	2	2	7*
1997	1	0	3	4
1996	2	1	0	3
1995	3	1	0	4
1994	2	0	0	2
1993	1	1	2	4
1992	0	2	0	2
1991	3	0	0	3
1990	0	0	0	0
1989	3	0	0	3
1988.	2	1	4	7
1987	4	0	0	4
Total	30	8	11	49

<sup>\*</sup> Data for 1998-1999 are incomplete; counts will increase if additional reports are received. Source: U.S. Consumer Product Safety Commission.

Table 5 gives documented non-occupational amusement ride fatalities by type and mobility. The majority of deaths were associated with roller coasters and "whirling" rides.

Table 5
Non-Occupational Amusement Ride-Related Fatalities from 1987
through 1999 by Ride Type and Mobility

Type of Ride	Fixed	Mobile	Unknown	Total
Roller Coaster	12	0	3	15
Whirling	2	4	4	10
Water	5	0	0	5
Train	2	1	0	3
Ferris Wheel	2	0	0	2
Sleigh	1	0	0	1
Unknown	6	3	4	13
Total	31	7	11	49

Note: Data for 1998-1999 are incomplete; counts will increase if additional reports are received. Source: U.S. Consumer Product Safety Commission.

Table 6 gives the number of documented non-occupational amusement ride fatalities by state and mobility. States with the largest number of documented fatalities included California (6), New Jersey (6), and New York (5).

Table 6
Non-Occupational Amusement Ride-Related Fatalities from 1987 through 1999 by
State and Ride Mobility

State	Fixed	Mobile	Unknown	Total
CA	3	1	2	6
CT	1	0	0	1
FL	1	1	2	4
GA	0	0	1	1
ഥ	1	2	0	3
IN	1	0	0	1
MA	1	0	0	1
MD	0	0	1	1
MN	2	0	0	2
NE	1	0	0	1
NJ.	5	0	1	6
NM	0	1	0	1
NV	0	0	1	1
NY	4	1	0	5
OH	2	0	1	3
OK	0	0	1	1
PA	1	0	0	1
SC	2	0	0	2
TN	0	0	1	1
TX	2	2	0	4
UT	2	0	0	2
VA	1	0	0	1
Total	30	8	11	49

Note: Data for 1998-1999 are incomplete; counts will increase if additional reports are received. Source: U.S. Consumer Product Safety Commission.

#### Hazard Patterns Associated with Amusement Ride-Related Incidents

A review of in-depth investigation (INDP) reports by CPSC staff from 1 Jan 1990 through 30 April 2000 revealed several hazard patterns associated with amusement ride-related incidents. The investigated cases were neither a probability sample nor complete account of all such incidents, so estimates of the proportions or numbers of incidents involving the scenarios observed in these investigations are not provided. Appendix C lists selected information in CPSC files about each of 85 in-scope investigated incidents. Review of the 85 cases revealed hazard patterns involving mechanical failure, operator behavior, consumer behavior, other factors, and combinations of these factors.

Mechanical failures associated with amusement ride-related incidents included missing safety pins, broken welds or structural components, exposed electrical wires, broken drive chains, malfunctioning lap bars or other safety restraints, failure to shutoff, improper detachment of cars, and improper detachment of structural components.

Operator behaviors associated with amusement ride-related incidents included abruptly stopping the ride (e.g., following an apparent mechanical failure), improperly assembling or maintaining the ride, and defeating safety equipment such as brakes and automatic overheat cutoff switches.

Consumer behaviors associated with amusement ride-related incidents included intentionally rocking cars, standing up, defeating safety restraints, sitting improperly (e.g., sideways or with feet above lap bar), holding a child above the safety restraint, and in one instance, a disembarking passenger intentionally restarting the ride by pressing the start button as other passengers were disembarking.

The other hazard pattern applies to rides that can injure people while apparently functioning normally, without any unusual or inappropriate behavior on the part of consumers or operators. An example is a hand-powered ride called the "Spaceball" in which the occupant is spun extremely rapidly Five reports of eye hemorrhage, and one report of retinal tear and possible cerebral edema, were associated with this ride. CPSC files document reported cases of amusement ride-related cerebral and retinal hemorrhage, subdural hematoma, loss of consciousness, headache, and dizziness. Fatalities with little or no overt trauma have occurred during or after rides which induce abrupt changes in speed and direction (e.g., cases 19, 27, 32, 36, 40, and 43 in Appendix B).

Several incidents involved combinations of the above hazard patterns. In one incident, for example, an operator abruptly stopped a ride upon hearing an unusual "thumping" sound due to a bent rail. In another case, the victim reported that the operator spun him longer and more vigorously than usual in a ride called the "Spaceball."

#### References

- 1. Cassidy S. Deaths and Injuries Associated with Amusement Rides, 21 May 1996, US Consumer Product Safety Commission, Washington, DC.
- 2. Morris CC. Amusement Ride-Related Injuries and Deaths, 10 Oct 1997, US Consumer Product Safety Commission, Washington, DC.
- 3. Morris CC. Amusement Ride-Related Injuries and Deaths, 16 June 1998, US Consumer Product Safety Commission, Washington, DC.
- 4. Morris CC. Amusement Ride-Related Injuries and Deaths in the United States, 15 July 1999, US Consumer Product Safety Commission, Washington, DC.
- 5. Kessler E, Schroeder T. National Electronic Injury Surveillance System (NEISS)

  Estimated Generalized Relative Sampling Errors, Sep 1998, US Consumer Product Safety
  Commission, Washington, DC.
- 6. Gibbons JD. Nonparametric Measures of Association, 1993, Sage Publications, Newbury Park, CA.
- 7. Personal communication from the International Association of Amusement Parks and Attractions, Alexandria, VA to James DeMarco, US Consumer Product Safety Commission, Washington DC.
- 8. Hook EB, Regal RR Capture-recapture methods in epidemiology: methods and limitations, 1995, *Epidemiologic Reviews*, 17(2);243-264.
- 9. Fienberg SE. The multiple recapture census for closed populations and incomplete 2K contingency tables, 1972, *Biometrika*, 59(3);591-603.

7.

٠.

### Appendix A

Inspection of individual NEISS hospital data for calendar years 1995 through 1999 revealed one hospital (#58) that both contributes many more amusement ride-related cases to the NEISS each year and exhibits a larger increasing trend over the period than all other NEISS hospitals. To assess the "leverage" exerted by this hospital on estimates in the complete NEISS sample, national estimates were recomputed with this hospital removed from the sample. The revised unknown-site estimates were allocated to the revised fixed-site and mobile estimates in the same proportions as in the revised known-site estimates. Results were as follows.

Exclusion of hospital 58 reduced fixed-site annual injury estimates from 10% to 44%, depending on the year, with larger reductions for more recent years. In contrast, exclusion of hospital 58 increased mobile annual estimates from 1% to 9%, depending on the year, with larger increases for more recent years. Exclusion of hospital 58 reduced total (fixed-site plus mobile) annual injury estimates from 5% to 27%, depending on the year, with larger reductions for more recent years. None of the revised estimates yielded significant annual trends from 1993 through 1999, 1-tail exact Kendall Tau tests.

However, reporting amusement ride-related injury estimates with hospital 58 excluded is inappropriate because the NEISS sample with hospital 58 removed is not a probability sample of all emergency room hospitals in the U.S. The NEISS is a stratified sample of 100 hospitals out of the universe of 5,388 U.S. hospitals with emergency departments and 6 or more beds. There are 5 strata in the NEISS, with 4 strata corresponding to sizes in terms of annual emergency room visits (small, medium, large, and very large) and a 5th stratum corresponding to children's hospitals. Hospital 58 is one of 9 randomly sampled hospitals representing 674 "large" hospitals in the U.S. Because the 9 hospitals were randomly sampled from the universe of 674 "large" hospitals, the 9 hospitals are by definition a probability sample of the 674 "large" hospitals. However, if one of the 9 hospitals is removed based on the number of amusement ride cases it reported, then the resulting sample of 8 hospitals does not meet the random selection criterion of a probability sample, an essential requirement for valid statistical estimation. In particular, if the hospital with the most amusement ride cases is removed from the NEISS sample, the resulting sample is likely to underestimate the true total of amusement ride cases because other "large" hospitals with similar numbers of amusement ride cases in the universe of 674 hospitals are no longer represented in the NEISS sample.

## Appendix B

Records of Reported Non-Occupational Amusement Ride Fatalities from 1987 through 1999 in CPSC Files

Appendix B lists records of amusement ride-related fatality cases in CPSC files. Many fatalities are documented in 2 or more records in CPSC files (and in Appendix B), with each record often providing additional information about the case. Fatality cases 48 and 49 occurred in the same incident and are documented in the same record in CPSC files (record number 112 in Appendix B). Ride sites F, M, and U, refer to fixed-, mobile, and unknown sites. Ride types RC and U refer to roller coasters and unknown types.

RECORD	CASE	FILE	DTACC	AGE	SEX	STATE	CITY	TKNO	DOCNO	MOBIL	TYPE
1	1	DTHS	04/19/87	15	М	TX	AMARILLO		8748035344	F	U
2	2	INDP	05/16/87	33	М	NJ	<del></del>	871013CCC0014	X87A5248A	F	RC
3	2	iPii	07/09/87	33	М	NJ	SEASIDE HEIGHTS	871013CCC0014	X87A5248A	F	RC
4	3	DTHS	06/16/87	19	F	NJ	FREEHOLO TWP	870618NYC5088	8734032977	F	RC
5	3	INDP	06/17/87	19	F	NJ		870618NYC5088	N8765088	F	RC
6	3	IPII	06/17/87	19	F	NJ	CHESTER	870618NYC5088	N8765088A	F	RC
7	3	IPII	06/17/87	19	F	NJ	JACKSON TWP	870618NYC5088	X8764119B	F	RC
8	3	IPII	06/17/87	19	F	NJ	TRENTON	870618NYC5088	X8774298A	F	RC
9 1	4	DTHS	07/18/87	18	M	MA	HOLYOKE	900309HCC1715	8725000595	F	TRAIN
10	4	INDP	07/18/87	18	M	MA	HOLYOKE	900309HCC1715	8725000595	F	TRAIN
11	4	IPII	07/17/87	18	M	MA	HOLYOKE	900309HCC1715	N8780115A	F	TRAIN
12	5	IPII	01/01/88	10	F	FL	BROWARD	50000011001110	N9440244C	<del>-</del>	U
13	5	IPII	01/01/88	<del>   </del>	Ü	FL	BROWARD COUNTY		X97C1427B	<del></del> -	Ü
14	6	DTHS	03/26/88	15	м	FL		880331CCC0266	8812026200	М —	U
15	6	INDP	03/26/88	15	M	FL	LAUDERDALE LAKE	880331CCC0266	X8836769A	M	U
16	-6	IPII	03/27/88	15	M	IL.	LAUDERDALE LAKE		<del></del>		
17	7	INDP	05/15/88	4	F	GA	ATLANTA	880331CCC0266 880517CEN1089	X8836769A	M U	U
18	7	IPI	05/15/88		F	GA GA	ATLANTA	880517CEN1089	G8850100A		
								OBUST/CENTU89	G8850100A	U_	U V
19	8	DTHS	05/15/88	5	F	TN	NASHVILLE		8947004026	U	WHIRLING
20	9	DTHS	08/10/88	30	M	NE	OMAHA	<u> </u>	8831009287	F	U
21	9	IPII	01/01/88	의	M	NE	OMAHA	<b></b>	C8895003A	F	U
22	9	IPII	08/11/88	31	M	NE	OMAHA		X8888671A	F	U
23	10	INDP	08/23/88	26	M	NY	BROOKLYN	900327HCC1741	8836313951	F	RC
24	10	IPII	08/23/88	26	M	NY	CONEY ISLAND	900327HCC1741	N8880195A	F	RC
25	11	DTHS	11/23/88	17	F	FL	MIAMI	881125NYC5011	8812112936	U	WHIRLING
26	11	INDP	11/23/88	17	F	FL	HALLANDALE	881125NYC5011	N88B0142	<u> </u>	WHIRLING
27	11	IPII I	11/01/88	17	F	FL	FORT LANDERDALE	881125NYC5011	F8960123A	U	WHIRLING
28	11	IPII	11/01/88	17	F	FL	MIDWAY	881125NYC5011	N8990190A	U	WHIRLING
29	11	IPIL	11/23/88	17	F	FL	HALLANDALE	881125NYC5011	N88B0142	U	WHIRLING
30	11	IPII	11/30/88	17	F	FL	COOPER CITY	881125NYC5011	N8990159B	U	WHIRLING
31	12	DTHS	04/30/89	- 6	M	UT	FARMINGTON	890522WES4002	8949003161	F	RC
32	12	INDP	04/30/89	6	M	UT	FARMINGTON	890522WES4002	F8954002	F	RC
33	12	(Pii	04/30/89	6	М	5	FARMINGTON	890522WES4002	X8952246A	F	RC
34	13	DTHS	06/09/89	13	F	Ú	FARMINGTON		8949004082	F	RC
35	14	DTHS	07/03/89	9	М	CA	SANTA CLARA	890714WES5008	8906100727	F	LOG RIDE
36	14	INDP	07/03/89	9	M	Š	SANTA CLARA	890714WES5008	F8975008	F	LOG RIDE
37	14	IPII	01/01/89	9	М	CA	SANTA CLARA	890714WES5008	F9890039B	F	LOG RIDE
38	14	IPIL	07/03/89	9	М	CA	SANTA CLARA	890714WES5008	F8975008A	F	LOG RIDE
39	15	IPII	06/09/91	0	F	ОН	CINCINNATI		G9160095A	F	CAPSULE
40	16	iPii	01/01/91	17	М	SC	MYRTLE BEACH		X9951690C	F	FERRIS WHEEL
41	16	IPII	07/20/91	17	М	SC	MYRTLE		N9190131A	F	FERRIS WHEEL
42	17	IPli	08/11/91	14	М	NY	GRAND ISLAND	1	X9186478A	F	FERRIS WHEEL
43	18	DTHS	07/25/92	35	F	NM	TAOS	920730CWE6001	9235006257	М	WHIRLING
44	18	INDP	07/25/92	22	F	NM	TAOS	920730CWE6001	F9276001A	M	WHIRLING
45	18	IPII	07/25/92	22	F	NM	TAOS	920730CWE6001	F9276001A	М	WHIRLING
46	18	(PI)	07/25/92	22	F	NM	TAOS	920730CWE6001	X92A0263A	М	WHIRLING
47	19	IPII	08/09/92	11	F	NY	EDAN		X9296202A	M	WHIRLING
48	19	IPII	08/09/92	11	F	NY	EDEN	<del></del>	N9290191A	М	WHIRLING
49	20	IPII	04/13/93	32	M	MD	HAGERSTOWN	930621CCC1417	N9350152A	<del>"</del>	WHIRLING
50	21	IPII	06/09/93	0	F	ОН	HILLSBORO		G9360231A	<del>- ŭ</del> -	U
51	22		06/10/93	67	F	IL.	ELGIN	<del> </del>	9317034940	F	SLEIGH
52	23	DTHS	09/11/93	50	M	TX	LACKLAND AFB	<del>                                     </del>	9348090527	M	U
53	24	DTHS	07/09/94	6	F	sc	SPARTANBURG	<del> </del>	9445017487	F	BUMPER BOAT
54	24	IPIL	01/01/94	6	F	SC	SPARTANBURG	<del></del> -	X9951690B	F	BUMPER BOAT
55	24	IPIL	07/09/94	6	F	sc	SPARTANBURG	<del> </del>	N9480105A	F	BUMPER BOAT
	44	II-II	01/03/34	<u>اگ</u>	Г ;	30	SPARIANDUKG	<u> </u>	MS460105A	<u> </u>	DUMPER BUAT

RECORD	CASE	NARRATIVE 1
1 1	1	FELL FROM AN AMUSEMENT PARK RIDE - BLUNT FORCE TRAUMA TO HEAD - AUTOPSY YES
2	2	A 33 YEAR OLD MALE SUSTAINED HEAD INJURIES WHEN HE APPARENTLY WAS LEANING OUT THE SIDE OF A CAR TO A FIXED SITE ROL
3	_	A 33-YEAR OLD MAN KILLED AFTER HE APPARENTLY UNFASTENED SEAT BELT ON AMUSEMENT RIDE AND FELL OUT
4	3	DECEDENT WAS THROWN FROM AMUSEMENT PARK RIDE LIGHTNING LOOPS - AVULSION OF THE BRAIN, MASSIVE SKULL FRACTURES -
5	_	A 19 YEAR OLD FEMALE FELL TO HER DEATH WHEN RIDING UPON A FIXED SITE ROLLER COASTER AT AN AMUSEMENT PARK. THE ROLL
6	3	A 19YOF DIED WHEN SHE FELL FROM AN ROLLER COASTER AT AN AMUSEMENT PARK.
7	3	19 YEAR OLD WOMAN FELL OUT OF A ROLLER COASTER AND DIED
8	3	A 19-YEAR OLD WOMAN DIED WHEN SHE FELL FROM AN AMUSEMENT RIDE APPAREN TLY CAUSED BY FAILURE TO HAVE SAFETY HARN.
9	4	RIDING ON SMALL TRAIN AT PARK WHICH DERAILED AND OVERTURNED - MULTIPLE INJURIES OF CHEST AND ABDOMEN, AMUSEMENT P
10	4	AN 18 YEAR OLD MALE RIDING A MINATURE TRAIN FIXED RIDE AT AN AMUSEMENT PARK WAS KILLED WHEN THE CAR IN WHICH HE WAS
11	4	18 YEAR OLD MAN DIED FROM INJURIES SUSTAINED WHILE RIDING AN AMUSEMENT RIDE.
12	5	A TEENAGE GIRL WAS KILLED WHEN AN AMUSEMENT RIDE MALFUNCTIONED
13	5	A TEENAGER KILLED IN AN AMUSEMENT RIDE. METAL FATIGUE WAS BLAMED
14	- 6	DECEASED FELL FROM CARNIVAL RIDE - EXSANGUINATION, INCISED WOUND OF ABDOMEN - AUTOPSY YES
15	6	AT ABOUT 9 15 PM ON 3/26/88 A 15 YEAR OLD MALE WAS EJECTED FROM A MOBILE AMUSEMENT RIDE. WHILE ATTEMPTING EITHER TO
16	6	A 15 YEAR OLD BOY DIED AFTER HE CLIMBED UP UNDER SAFETY BAR OF AMUSEM ENT RIDE AND FELL
17		A 4-YEAR-OLD FEMALE RECEIVED A FRACTURED SKULL AND A LACERATED FORE- HEAD AFTER SHE SLIPPED OFF AN AMUSEMENT RID
18	7	A 4 YEAR OLD GIRL HOSPITALIZED AFTER THROWN FROM AMUSEMENT RIDE.
19	8	WAS THROWN FROM CAR OF TILT WHEEL' RIDE - RESPIRATORY FAILURE, TRACHEAL STENOSIS, ACCIDENT - AUTOPSY NO
20	9	FELL FROM RIDE AT AMUSEMENT PARK - MULTIPLE HEAD & INTERNAL INJURIES - FALL - AUTOPSY YES
21	9	YOUNG MAN DIED WHEN HE FELL OFF AN AMUSEMENT PARK RIDE.
22	9	A 31-YEAR OLD MAN WAS KILLED WHEN HE FELL FROM AN AMUSEMENT PARK RIDE
23	10	A 26 YEAR OLD MALE DIED WHEN HE FELL FROM A MOMING CYCLONE ROLLER COASTER RIDE AND LANDED ON THE STRUCTURES TRA
24	10	A 26-YEAR OLD MAN DIED WHEN HE FELL FROM AN AMUSEMENT RIDE HE WAS APP ARENTLY STANDING UP IN
25	11	DECEASED, OCCUPANT OF AN AMUSEMENT RIDE THAT COLLAPSED STRUCK HER IN HEAD - BLUNT HEAD TRAUMA - AUTOPSY YES
26	11	A SEVENTEEN (17) YEAR OLD FEMALE WAS KILLED AND SIX OTHER INDIVIDUAL SUFFERED VARIOUS INJURIES WHEN THE SMEEP COM
27	11	17 YR OLD GIRL WAS KILLED AND 6 OTHER PEOPLE WERE INJURED WHEN THE FAULTY ARM OF AN AMUSEMENT RIDE BROKE.
28	11	17 YEAR OLD GIRL WAS KILLED WHEN THE ARM OF AN AMUSEMENT RIDE BROKE A ND FELL ON HER.
29	11	A 17-YEAR OLD FEMALE WAS KILLED, A 23-YEAR OLD MAN HOSPITALIZED AND FIVE OTHER PEOPLE SLIGHTLY INJURED WHEN AN ARM
30	11	A 17 YEAR OLD FEMALE WAS KILLED WHEN AN ARM BROKE OFF AN AMUSEMENT RIDE STRICKING HER ON ANOTHER RIDE BELOW
31	12	FELL AND STRUCK BY AMUSEMENT RIDE - BLUNT FORCE INJURIES TO HEAD AND TORSO - AUTOPSY NO
32	12	6 YEAR OLD MALE VICTIM DIED OF BLUNT INJURIES TO HEAD AND TORSO SUSTAINED WHEN HE WAS STURCK BY ROLLER COASTER RI
33	12	A 6-YEAR OLD BOY WAS KILLED WHEN HE WAS STRUCK BY AN AMUSEMENT RIDE THAT HE HAD FALLEN FROM
/34	13	FELL FROM ROLLERCOASTER RIDE (40 FEET HEIGHT) - MULTIPLE INJURIES, BLUNT FORCE TRAUMA - AUTOPSY UNK
35	14	PINNED BETWEEN LOG-BOAT AND FLUIVE - MECHANICAL ASPHYXIA, ACCIDENT - AUTOPSY YES
36	14	THE VICTIM, A 9-YEAR OLD BOY, DIED AS A RESULT OF INJURIES SUSTAINED IN THIS ACCIDENT, INVOLVING AN AMUSEMENT RIDE. THE
37	14	A 9 YEAR OLD BOY WAS KILLED WHEN HE FELL UNDER A FIBERGLASS LOG ON A WATER RIDE AT AN AMUSEMENT PARK
38	14	A 9-YEAR OLD BOY WAS CRUSHED TO DEATH WHEN HE JUMPED FROM A LOG FLUME RIDE AT AN AMUSEMENT PARK AND BECAME TR
39		A WOMAN WAS KILLED AT AN AMUSEMENT PARK AFTER SHE FELL OUT OF A RIDE.
40		A BOY, AGE 17, DIED IN A 40 FOOT FALL FROM A FERRIS WHEEL
41	16	A 17 YEAR OLD MALE WAS KILLED AND EIGHT OTHERS INJURED (12 YEAR OLD F EWALE, 15 YEAR OLD MALE INCLUDED) WHEN THE SAF
42		A 14 YEAR OLD MALE DIED AFTER FALLING 60 FEET WHEN THE SEAT OF A FERR IS WHEEL SUPPED OFF ITS AXLE
43	-	FELL FROM CARNIVAL RIDE - CRANICCEREBRAL INJURIES AUTOPSY YES - 920730CWE9001
44	-	A 22 YEAR OLD FEMALE AND TWO OTHER YOUNG FEMALES WERE INJURED ON A MOBILE AMUSEMENT RIDE, THE HIMALAYA, WHEN A S
45	<del></del>	A 22 YEAR OLD FEMALE WAS KILLED AND A 16 YEAR OLD FEMALE AND 20 YEAR OLD FEMALE INJURED WHEN THROWN FROM AN AMUS
46		A 22 YEAR OLD FEMALE DIED WHEN SHE AND TWO FRIENDS WERE THROWN FROM A CARNIVAL RIDE WHEN THE SAFETY BAR FAILED
47	+	A 11 YEAR OLD FEMALE WAS FOUND DEAD AFTER THE AMUSEMENT RIDE SHE WAS ON STOPPED.
48	<del></del>	AN 11 YEAR OLD FEMALE DIED AFTER COLLAPSING ON AN AMUSEMENT RIDE AT A CARMIVAL.
49		A 32 YEAR OLD MALE DIED AFTER BEING CRUSHED IN THE SPOKES OF AN AMUSE MENT RIDE, ANOTHER MALE DIED AND ANOTHER WA
50		A FEWALE DIED AND A MALE AND FEMALE WERE INJURED WHEN APPARENTLY AN A MUSEMENT RIDE WAS STOP ABRUPTLY
51	+	SLEIGHRIDE TIPPED OVER AT AMUSEMENT PARK - CARDIO RESPIRATORY ARREST, BASILAR SKULL FRACTURE, TRAUMA - AUTOPSY N
52	+	FELL OFF CARNIVAL RIDE STRUCK ON HEAD - CRANICCEREBRAL INJURIES - AUTOPSY YES
33		TRAPPED UNDER BUMPER BOAT - RESPIRATORY INSUFFICIENCY, DROWNING - AUTOPSY YES
54	<del></del>	A GIRL, AGE 6, DROWNED WHEN SHE FELL OUT OF A WATER BOAT AMUSEMENT RIDE.
55_	24	A 6 YEAR OLD FEMALE DROWNED WHEN SHE FELL FROM AN AMUSEMENT RIDE INTO WATER AND HER SHIRT GOT CAUGHT IN A PROP

1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	RECORD	CASE	NARRATIVE 2
3 2 4 3 3 5 3 1 COORDITING THE RUN AND THE CARS ARE EQUIPPED WITH SHOULDER THYE HARNESS RESTRAINTS REPORTEDLY, THE VICTIM WA 6 3 3 7 1 3 9 4 4 ACCIDENT - AUTOPSY YES 10 4 DEPARLED AND THYED ON HIM. HE WAS REPORTED TO BE ROCKING THE CAR MANERATELY PRIOR TO THE ACCIDENT. THE EQUIPME 11 4 1 12 5 13 5 5 14 6 6 15 6 CHARGE SERTS WITH HIS YOUNGER SISTER OR TO STAND UP. THE VICTIM, 5F TALL 8 125 POUNDS, WAS PHYSICALLY AND MENTALLY. 15 6 6 16 6 CHARGE SERTS WITH HIS YOUNGER SISTER OR TO STAND UP. THE VICTIM, 5F TALL 8 125 POUNDS, WAS PHYSICALLY AND MENTALLY. 16 7 PURSUCAREA. SHE WAS ADMITTED FOR HOSPITALIZATION AT A LOCAL HOSPITAL VICTIM DIED IN HOSPITAL ON JAN 12, 1999 FROM HE. 15 7 PURSUCAREA. SHE WAS ADMITTED FOR HOSPITALIZATION AT A LOCAL HOSPITAL VICTIM DIED IN HOSPITAL ON JAN 12, 1999 FROM HE. 15 9 8 20 9 9 21 10 COASTER RIDE WAS PERMANENTLY INSTALLED IN AN ANALSEMENT PARK. 21 10 COASTER RIDE WAS PERMANENTLY INSTALLED IN AN ANALSEMENT PARK. 22 11 RIDE THEY WERE ON, BROKE APART. THE SWEEP FRACTURE CAUSED THE ATTACHED FOUR COCUPIED BUCKETS TO FALL TO THE 23 11 CORE CAUSING THEM TO FALL. 23 11 CORE CAUSING THEM TO FALL. 24 11 CORE CAUSING THEM TO FALL. 25 11 ATTEMPTING TO GREE OUT OF COASTER CAR WHICH HAD STOPPED COASTER RE-STARTED AND VICTIM FELL OUT OF CAR ONTO TRA 25 14 ATTEMPTING TO JUMP OFF OF THE LOG TO ADJUCENT SHORE, APPARENTLY SUPPED AND FELL INTO THE WATER AND BECAME TRAP 25 14 ATTEMPTING TO JUMP OFF OF THE LOG TO ADJUCENT SHORE, APPARENTLY SUPPED AND FELL INTO THE WATER AND BECAME TRAP 26 10 MILE RIDE 27 11 FIRST THE RIDE WAS IN OPERATION AND THEY WERE ELECTED. THE RIDE ROTATED ABOUT A CENTRAL MOTOR CAPER A CHARCE OF THE RIDE ROTATED ABOUT A CENTRAL MOTOR CAPER A CHARCE OF THE RIDE ROTATED ABOUT A CENTRAL MOTOR CAPER A CHARCE OF THE RIDE ROTATED ABOUT A CENTRAL MOTOR CAPER A CHARCE OF THE RIDE ROTATED ABOUT A CENTRAL MOTOR CAPER A CHARCE OF THE RIDE ROTATED ABOUT A CENTRAL MOTOR CAPER A CHARCE OF THE RIDE ROTATED ABOUT A CENTRAL MOTOR CAPER A CHARCE OF THE RIDE ROTATED ABOUT A CENTRAL MOTOR CAPER A CHARCE	1		
4 3 COPS DURING THE RUNAND THE CARS ARE EQUIPPED WITH SHOULDER THRE HARRESS RESTRANTS REPORTEDLY, THE VICTIM WAS 6 3 3 3 4 ACCIDENT - AUTOPSY YES 9 4 DEPARLED AND TIPPED ON HIM. HE WAS REPORTED TO BE ROOMING THE CAR MANEDATELY PRIOR TO THE ACCIDENT THE ECUIPME 11 4 1 1 1 4 1 1 1 1 1 1 1 1 1 1 1 1 1	2	2	IN OPERATION AND HIS HEAD STRUCK AN OBJECT. IT APPEARS THE VICTIM INTENTIONALLY DISENGAGED HIS SEAT BELT CONTRARY
5 3 LODPS DURING THE RUN AND THE CARS ARE EQUIPPED WITH SHOULDER TYPE HARNESS RESTRAINTS REPORTEDLY, THE VICTIM WA 6 3 3 7 3 3 8 3 4 ACCIDENT - AUTOPSY YES 10 4 DEPARLED AND TIPPED ON HIM. HE WAS REPORTED TO BE ROOMING THE CAR IMMEDIATELY PRIOR TO THE ACCIDENT. THE EQUIPME 11 4 6 12 5 13 5 14 6 6 13 5 14 6 6 15 6 OHANGE SEATS WITH HIS YOUNGER SISTER OR TO STAND UP. THE WICTIM SET TALL & 128 POLINGS WAS PHYSICALLY AND MENTALLY 16 6 6 17 7 P. RELIC AREA. SHE WAS ADMITTED FOR HOSPITALIZATION AT A LOCAL HOSPITAL WICTIM DIED IN HOSPITAL ON JAN 12, 1988 FROM HE 19 7 P. RELIC AREA. SHE WAS ADMITTED FOR HOSPITALIZATION AT A LOCAL HOSPITAL WICTIM DIED IN HOSPITAL ON JAN 12, 1988 FROM HE 19 9 6 20 9 9 21 9 9 22 10 COASTER RIDE WAS PERMANENTLY INSTALLED IN AN ANALSSMENT PARK. 22 11 IN RICE THEY WERE ON BROKE APART. THE SMEEP FRACTURE CAUSED THE ATTACHED FOUR COCUPIED BLOCKTS TO FALL TO THE 23 11 IN RICE THEY WERE ON BROKE APART. THE SMEEP FRACTURE CAUSED THE ATTACHED FOUR COCUPIED BLOCKTS TO FALL TO THE 24 11 OKE CAUSING THEM TO FALL 33 11 I. 2 35 11 I. 3 36 12 I. 3 37 14 I. 3 38 12 I. 3 39 14 ATTEMPTING TO GET OUT OF COASTER CAR WHICH HAD STOPPED. COASTER RE-STARTED AND WICTIM FELL OUT OF CAR ONTO TRA 39 15 I. 3 30 11 I. 3 31 12 I. 3 31 14 WALL OF FILME RIDE. 31 16 IS WHEEL AND THEY FELL. 32 17 II AND SELECTED. THE RIDE WAS IN OPERATION AND THEY WERE ELECTED. THE RIDE ROTATED ABOUT A CENTRAL MOTTOR OVER A CI. 39 19 10 II OKE CAUSING THEM TO THEY PREID. 30 11 II OKE CAUSING THEM TO FER PROPERTION AND THEY WERE ELECTED. THE RIDE ROTATED ABOUT A CENTRAL MOTTOR OVER A CI. 39 11 II OKE CAUSED. THE RIDE. 30 11 II OKE CAUSED. THE RIDE. 31 12 II OKE CAUSED. THE RIDE. 32 12 II OKE CAUSED. THE RIDE. 33 14 WALL OF FILME RIDE. 34 14 WALL OF FILME RIDE. 35 14 WALL OF FILME RIDE. 36 15 II OKE CAUSED. THE RIDE WAS IN OPERATION AND THEY WERE ELECTED. THE RIDE ROTATED ABOUT A CENTRAL MOTTOR OVER A CI. 35 12 I. 35 II OKE CAUSED. THE RIDE WAS IN OP	3	2	
6 3 7 3 3 8 3 8 3 9 4 ACCIDENT - AUTORSY YES 10 4 DEPAILED AND TIPPED ON HIM. HE WAS REPORTED TO BE ROOGING THE CAR IMMEDIATELY PRIOR TO THE ACCIDENT. THE ECURINE 11 4 12 6 13 5 14 6 6 OWNAGE SEATS WITH HIS YOUNGER SISTER OR TO STAND UP. THE VICTIM SIG TALL & 128 POUNDS, WAS PHYSICALLY AND MENTALLY 15 6 OWNAGE SEATS WITH HIS YOUNGER SISTER OR TO STAND UP. THE VICTIM SIG TALL & 128 POUNDS, WAS PHYSICALLY AND MENTALLY 16 6 17 7 PUBLIC AREA. SHE WAS ADMITTED FOR HOSPITALIZATION AT A LOCAL HOSPITAL VICTIM DIED IN HOSPITAL ON JAN 12, 1989 FROM HE. 19 7 8 20 19 9 21 9 22 19 0 COASTER RIDE WAS PERMANENTLY INSTALLED IN AN AMASEMENT PARK. 22 10 COASTER RIDE WAS PERMANENTLY INSTALLED IN AN AMASEMENT PARK. 23 11 OKE THEY WERE ON, BROKE APART. THE SWEEP FRACTURE CAUSED THE ATTACHED FOUR COCCUPIED BLOKETS TO FALL TO THE. 25 11 OKE CAUSING THEM TO FALL. 26 11 OKE CAUSING THEM TO FALL. 27 11 OKE CAUSING THEM TO FALL. 28 11 OKE CAUSING THEM TO FALL. 29 11 OKE CAUSING THEM TO FALL. 30 11 OKE CAUSING THEM TO FALL. 31 12 OKE CAUSING THEM TO FALL. 31 12 OKE CAUSING THEM TO FALL. 32 11 OKE CAUSING THEM TO FALL. 33 12 OKE CAUSING THEM TO FALL. 34 11 OKE CAUSING THEM TO FALL. 35 14 OKE CAUSING THEM TO FALL. 36 14 OKE CAUSING THEM TO FALL. 37 14 OKE CAUSING THEM TO FALL. 38 12 OKE CAUSING THEM TO FALL. 39 11 OKE CAUSING THEM TO FALL. 30 11 OKE CAUSING THEM TO FALL. 31 12 OKE CAUSING THEM TO FALL. 31 12 OKE CAUSING THEM TO FALL. 31 14 OKE CAUSING THEM TO FALL. 32 17 OKE CAUSING THEM TO FALL. 33 14 OKE CAUSING THEM TO FALL. 34 16 OKE CAUSING THEM TO FALL. 35 14 OKE CAUSING THEM TO FALL. 36 16 OKE CAUSING THEM TO FALL. 37 14 OKE CAUSING THEM TO FALL. 38 17 19 OKE CAUSING THEM TO FALL. 39 11 OKE CAUSING THEM TO FALL. 31 16 OKE CAUSING THEM TO FALL. 32 17 19 OKE CAUSING THEM TO FALL. 33 17 10 OKE CAUSING THEM TO FALL. 39 11 OKE CAUSING THEM TO FALL. 31 16 OKE CAUSING THEM TO FALL. 31 17 OKE CAUSING THEM TO FALL. 31 17 OKE CAUSING THEM TO FALL. 3			
7 3 6 3 8 3 9 4 ACCIDENT - AUTOPSY YES 9 4 ACCIDENT - AUTOPSY YES 10 1 4 DEPARLED AND TIPPED CNHIM. HE WAS REPORTED TO BE ROOKING THE CAR IMMEDIATELY PRIOR TO THE ACCIDENT. THE EQUIPME 11 1 4 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			LOOPS DURING THE RUN AND THE CARS ARE EQUIPPED WITH SHOULDER TYPE HARNESS RESTRAINTS REPORTEDLY, THE VICTIM WA
9   4   ACCIDENT - AUTORSY YES			
4 ACCIDENT: AUTOPSY YES 10 4 DEPAILED AND TIPPED ON HIM. HE WAS REPORTED TO BE ROOGING THE CAR IMMEDIATELY PRIOR TO THE ACCIDENT. THE EQUIPME 11 4 5 13 5 14 6 16 6 17 7 P. RELIC AREA. SHE WAS ADMITTED FOR HOSPITALIZATION AT A LOCAL HOSPITAL 8 126 POLADOS, WAS PHYSICALLY AND MENTALLY 18 6 19 7 19 8 20 9 21 9 22 10 COASTER RICE WAS PERMANENTLY INSTALLED IN AN AMUSEMENT PARK. 21 9 22 9 9 23 10 COASTER RICE WAS PERMANENTLY INSTALLED IN AN AMUSEMENT PARK. 22 11 OCCE CAUSING THEM TO FALL 23 11 OCCE CAUSING THEM TO FALL 24 10 OCC CAUSING THEM TO FALL 25 11 OCCE CAUSING THEM TO FALL 26 11 OCCE CAUSING THEM TO FALL 27 11 OCCE CAUSING THEM TO FALL 28 11 OCCE CAUSING THEM TO FALL 30 11 OCCE CAUSING THEM TO FALL 31 12 OCCE CAUSING THEM TO FALL 31 11 OCCE CAUSING THEM TO FALL 31 12 OCCE CAUSING THEM TO FALL 31 12 OCCE CAUSING THEM TO FALL 31 11 OCCE CAUSING THEM TO FALL 31 12 OCCE CAUSING THEM TO FALL 32 12 ATTEMPTING TO GET OUT OF COASTER CAR WHICH HAD STOPPED COASTER RE- STARTED AND VICTIM FELL OUT OF CAR CINTO THA 31 12 OCCE CAUSING THEM TO FALL 32 11 OCCE CAUSING THEM TO FALL 33 12 OCCE CAUSING THEM TO FALL 34 13 OCCE CAUSING THEM TO FALL 35 14 OCCE CAUSING THEM TO FALL 36 14 OCCE CAUSING THEM TO FALL 37 19 OCCE CAUSING THEM TO FALL 38 11 OCCE CAUSING THEM TO FALL 39 11 OCCE CAUSING THEM TO FALL 30 11 OCCE CAUSING THEM TO FALL 30 11 OCCE CAUSING THEM TO FALL 31 12 OCCE CAUSING THEM TO FALL 31 11 OCCE CAUSING THEM TO FALL 31 12 OCCE CAUSING THEM TO FALL 31 11 OCCE CAUSING THEM TO FALL 31 12 OCCE CAUSING THEM TO FALL 31 11 OCCE CAUSING THEM TO FALL 31 12 OCCE CAUSING THEM TO FALL 31 11 OCCE CAUSING THEM TO FALL 32 11 OCCE CAUSING THEM TO FALL 33 12 OCCE CAUSING THEM TO FALL 34 15 OCCE CAUSING THEM TO FALL 35 16 OCCE CAUSING THEM TO FALL 36 17 OCCE CAUSING THEM TO FALL 37 19 OCCE CAUSING THEM TO FALL 38 11 OCCE CAUSING THEM TO FALL 39 11 OCCE CAUSING THEM TO FALL 30 11 OCCE CAUSING THEM TO FALL 30 11 OCCE CAUSING THEM TO FALL 31			
DEPAILED AND TIPPED ON HIM. HE WAS REPORTED TO BE ROOKING THE CAR IMMEDIATELY PRIOR TO THE ACCIDENT. THE EQUIPME  11 4 6 12 5 13 5 14 6 6 15 6 CHANGE SEATS WITH HIS YOUNGER SISTER OR TO STAND UP. THE VICTIM 55" TALL 8 125 POLADS, WAS PHYSICALLY AND MENTALLY 16 6 17 7 PLEUC AREA. SHE WAS ADMITTED FOR HOSPITALIZATION AT A LOCAL HOSPITAL VICTIM DIED IN HOSPITAL ON UN 12, 1988 FROM HE 18 7 19 8 20 9 21 9 22 9 22 9 23 10 COASTER RIDE WAS PERMANENTLY INSTALLED IN AN ANUSEMENT PARK.  24 10 25 11 RIDE THEY WERE ON BROKE APART. THE SWEEP FRACTURE CAUSED THE ATTACHED FOUR OCCUPIED BUCKETS TO FALL TO THE 27 11 29 11 OCE CAUSING THEM TO FALL.  30 11 31 12 31 12 31 12 31 12 31 12 31 12 31 13 31 12 32 12 ATTEMPTING TO GET OUT OF COASTER CAR WHICH HAD STOPPED. COASTER RE: STARTED AND VICTIM FELL OUT OF CAR ONTO TRA.  35 14 ATTEMPTING TO JUMP OFF OF THE LOCS TO ADJACENT SHORE, APPARENTLY SUPPED AND FELL INTO THE WATER AND BECAME TRAP.  36 14 ATTEMPTING TO JUMP OFF OF THE LOCS TO ADJACENT SHORE, APPARENTLY SUPPED AND FELL INTO THE WATER AND BECAME TRAP.  36 14 ATTEMPTING TO JUMP OFF OF THE LOCS TO ADJACENT SHORE, APPARENTLY SUPPED AND FELL INTO THE WATER AND BECAME TRAP.  37 14 38 14 WALL OF FILMER RIDE.  39 15 40 18 RELEASED WHILE THE RIDE WAS IN OPERATION AND THEY WERE EJECTED. THE RIDE ROTATED ABOUT A CENTRAL MOTOR OVER A C.  46 19 47 19 48 19 49 20 OM THE RIDE.			
111			
12   5   5   13   5   5   14   6   6   CHANGE SEATS WITH HIS YOUNGER SISTER OR TO STAND UP THE VICTIM 56 TALL & 126 POUNDS, WAS PHYSICALLY AND MENTALLY   16   6   6   6   6   6   6   6   6			DEPAILED AND TIPPED ON HIM. HE WAS REPORTED TO BE ROCKING THE CAR IMMEDIATELY PRIOR TO THE ACCIDENT. THE EQUIPME
13 5 6 14 6 6 15 6 CHANGE SEATS WITH HIS YOUNGER SISTER OR TO STAND UP THE VICTIM 56 TALL & 126 POUNDS, WAS PHYSICALLY AND MENTALLY 16 6 6 17 7 PUBLIC AREA. SHE WAS ADMITTED FOR HOSPITALIZATION AT A LOCAL HOSPITAL VICTIM DIED IN HOSPITAL ON JAN 12, 1998 PROMINE 19 7 19 8 7 19 8 7 20 9 9 1 21 9 9 1 22 19 9 1 23 10 COASTER RIDE WAS PERMANENTLY INSTALLED IN AN AMUSEMENT PARK.  25 11 RIDE THEY WERE ON, BROKE APART. THE SWEEP FRACTURE CAUSED THE ATTACHED FOUR COCCUPIED BUCKETS TO FALL TO THE 27 11 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			
14		_	
15 6 CHANGE SEATS WITH HIS YOUNGER SISTER OR TO STAND UP THE VICTIM SET TALL & 126 POUNDS, WAS PARSCALLY AND MENTALLY 16 6 7 7 PUBLIC AREA. SHE WAS ADMITTED FOR HOSPITALIZATION AT A LOCAL HOSPITAL VICTIM DIED IN HOSPITAL ON JAN 12, 1989 FROM HE 18 7 19 8 20 9 21 9 22 9 23 10 COASTER RIDE WAS PERMANENTLY INSTALLED IN AN AMASEMENT PARK. 24 10 25 11 26 11 RIDE THEY WERE ON, BROKE APART. THE SWEEP FRACTURE CAUSED THE ATTACHED FOUR OCCUPIED BUCKETS TO FALL TO THE 27 11 28 11 29 11 OKE CAUSING THEM TO FALL. 30 11 31 12 32 12 ATTEMPTING TO GET OUT OF COASTER CAR WHICH HAD STOPPED. COASTER RE-STARTED AND VICTIM FELL OUT OF CAR ONTO TRA 33 12 34 13 35 14 36 14 ATTEMPTING TO JUMP OFF OF THE LOG TO ADJACENT SHORE, APPARENTLY SUPPED AND FELL INTO THE WATER AND BECAME TRAP 37 14 38 14 VALL OF FILME RIDE. 39 15 40 16 41 16 IS WHEEL AND THEY FELL. 41 17 43 18 44 18 46 18 47 19 48 19 48 19 49 20 OM THE RIDE.			
16 6 6 17 7 PUBLIC AREA. SHEWAS ADMITTED FOR HOSPITALIZATION AT A LOCAL HOSPITAL VICTIMIDED IN HOSPITAL ON JAN 12, 1988 FROM HE 18 7 19 8 20 9 21 9 22 10 COASTER RIDE WAS PERMANENTLY INSTALLED IN AN AMUSEMENT PARK 24 10 25 11 RIDE THEY WERE ON, BROKE APART. THE SWEEP FRACTURE CAUSED THE ATTACHED FOUR COCUPIED BUCKETS TO FALL TO THE 27 11 28 11 29 11 OKE CAUSING THEM TO FALL 30 11 31 12 31 12 32 12 ATTEMPTING TO GET OUT OF COASTER CAR WHICH HAD STOPPED. COASTER RE-STARTED AND VICTIM FELL OUT OF CAR ONTO TRA 33 12 34 13 35 14 36 14 ATTEMPTING TO JUMP OFF OF THE LOG TO ADJACENT SHORE, APPARENTLY SUPPED AND FELL INTO THE WAITER AND BECAME TRAP 37 14 38 14 WALL OF FILME RIDE. 39 15 40 16 41 16 IS SWHEEL AND THEY FELL 42 17 43 18 44 18 RELEASED WHILE THE RIDE WAS IN OPERATION AND THEY WERE ELECTED. THE RIDE ROTATED ABOUT A CENTRAL MOTOR OVER A G1 45 18 47 19 49 20 OM THE RIDE. 50 21 51 12 52 22 53 24 54 24			CHANGE SEATS WITH HIS YOUNGER SISTER OR TO STAND UP. THE MICTIM 56" TALL & 126 POLINDS WAS DEVISION UP AND MENTALLY
18 7 7 8 8 8 9 9 9 9 9 9 9 9 9 9 9 9 9 9			TO THE STATE OF TH
18 7 7 8 8 8 9 9 9 9 9 9 9 9 9 9 9 9 9 9	17	7	PUBLIC AREA. SHE WAS ADMITTED FOR HOSPITALIZATION AT A LOCAL HOSPITAL VICTIM DIED IN HOSPITAL ON JAN 12, 1999 FROM HE
20 9 21 9 22 9 9 22 110 COASTER RIDE WAS PERMANENTLY INSTALLED IN AN AMUSEMENT PARK 24 10 12 25 11 1 RIDE THEY WERE ON, BROKE APART THE SWEEP FRACTURE CAUSED THE ATTACHED FOUR OCCUPIED BUCKETS TO FALL TO THE 27 11 1 COE CAUSING THEM TO FALL 30 11 1 12 31 11 2 31 11 11 11 11 11 11 11 11 11 11 11 11	18		The state of the s
27 9 28 10 COASTER RIDE WAS PERMANENTLY INSTALLED IN AN AMUSEMENT PARK 29 11 RIDE THEY WERE ON, BROKE APART THE SWEEP FRACTURE CAUSED THE ATTACHED FOUR OCCUPIED BUCKETS TO FALL TO THE 27 11 PROVE THEY WERE ON, BROKE APART THE SWEEP FRACTURE CAUSED THE ATTACHED FOUR OCCUPIED BUCKETS TO FALL TO THE 28 11 CARREST THEM TO FALL 30 11 STATEMPTING TO GET OUT OF COASTER CAR WHICH HAD STOPPED COASTER RE-STARTED AND VICTIM FELL OUT OF CAR ONTO TRA 31 12 STATEMPTING TO GET OUT OF COASTER CAR WHICH HAD STOPPED COASTER RE-STARTED AND VICTIM FELL OUT OF CAR ONTO TRA 31 13 STATEMPTING TO JUMP OFF OF THE LOG TO ADJACENT SHORE, APPARENTLY SUPPED AND FELL INTO THE WATER AND BECAME TRAP 37 14 STATEMPTING TO JUMP OFF OF THE LOG TO ADJACENT SHORE, APPARENTLY SUPPED AND FELL INTO THE WATER AND BECAME TRAP 38 14 WALL OF FILME RIDE 39 15 40 16 STATEMPTING TO JUMP OFF OF THE LOG TO ADJACENT SHORE, APPARENTLY SUPPED AND FELL INTO THE WATER AND BECAME TRAP 41 16 STATEMPTING TO JUMP OFF OF THE LOG TO ADJACENT SHORE, APPARENTLY SUPPED AND FELL INTO THE WATER AND BECAME TRAP 44 11 16 STATEMPTING TO JUMP OFF OF THE LOG TO ADJACENT SHORE, APPARENTLY SUPPED AND FELL INTO THE WATER AND BECAME TRAP 45 18 STATEMPTING TO JUMP OFF OF THE LOG TO ADJACENT SHORE, APPARENTLY SUPPED AND FELL INTO THE WATER AND BECAME TRAP 46 18 STATEMPTING TO JUMP OFF OF THE LOG TO ADJACENT SHORE, APPARENTLY SUPPED AND FELL INTO THE WATER AND BECAME TRAP 46 18 STATEMPTING TO JUMP OFF OF THE LOG TO ADJACENT SHORE APPARENTLY SUPPED AND FELL INTO THE WATER AND BECAME TRAP 47 19 STATEMPTING TO JUMP OFF OF THE LOG TO ADJACENT SHORE APPARENTLY SUPPED AND FELL INTO THE WATER AND BECAME TRAP 48 19 OWALL OF FILME RIDE 51 22 STATEMPTING TO STATEMPT ON THE PROPERTY OF THE PROPERTY O	19	В	
22 9 10 COASTER RIDE WAS PERMANENTLY INSTALLED IN AN AMUSEMENT PARK.  34 10 2 25 11 RDE THEY WERE ON BROKE APART THE SWEEP FRACTURE CAUSED THE ATTACHED FOUR OCCUPIED BLOKETS TO FALL TO THE 27 11 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	20	9	
23 10 COASTER RIDE WAS PERMANENTLY INSTALLED IN AN AMUSEMENT PARK 24 10 25 111 26 111 RIDE THEY WERE ON, BROKE APART. THE SWEEP FRACTURE CAUSED THE ATTACHED FOUR COCUPIED BUCKETS TO FALL TO THE 27 11 28 111 29 111 OKE CAUSING THEM TO FALL 30 111 31 12 32 12 ATTEMPTING TO GET OUT OF COASTER CAR WHICH HAD STOPPED. COASTER RE-STARTED AND VICTIM FELL OUT OF CAR ONTO TRA 33 12 34 13 35 14 36 14 ATTEMPTING TO JUMP OFF OF THE LOG TO ADJACENT SHORE, APPARENTLY SUPPED AND FELL INTO THE WATER AND BECAME TRAP 37 14 38 14 WALL OF FLUME RIDE. 39 15 40 16 41 16 ISSWHEEL AND THEY FELL. 42 17 43 18 44 18 RELEASED WHILE THE RIDE WAS IN OPERATION AND THEY WERE EJECTED. THE RIDE ROTATED ABOUT A CENTRAL MOTOR OVER A CI 45 19 46 19 47 19 48 20 OM THE RIDE. 51 22 52 23 53 24 54 24	21	9	
25 11 26 11 27 11 28 11 29 11 29 11 30 11 31 12 31 12 32 12 31 13 31 12 32 12 34 13 35 14 35 14 36 14 37 14 38 14 39 15 30 14 31 13 31 12 31 13 31 12 32 12 33 11 34 13 35 14 36 18 37 14 38 18 39 15 40 16 39 15 40 16 40 16 40 16 41 18 RELEASED WHILE THE RIDE WAS IN OPERATION AND THEY WERE EJECTED. THE RIDE ROTATED ABOUT A CENTRAL MOTOR OVER A CI 45 18 46 18 47 19 48 19 49 20 OM THE RIDE. 51 22 52 23 53 24 54 24		_	
25 11 RICE THEY WERE ON, BROKE APART THE SWEEP FRACTURE CAUSED THE ATTACHED FOUR OCCUPIED BUCKETS TO FALL TO THE 27 11 CRE CAUSING THEM TO FALL 28 111 OKE CAUSING THEM TO FALL 30 111 31 12 32 12 ATTEMPTING TO GET OUT OF COASTER CAR WHICH HAD STOPPED COASTER RE-STARTED AND VICTIM FELL OUT OF CAR ONTO TRA 33 12 34 13 35 14 ATTEMPTING TO JUMP OFF OF THE LOG TO ADJACENT SHORE, APPARENTLY SUPPED AND FELL INTO THE WATER AND BECAME TRAP 37 14 38 14 WALL OF FILME RIDE 40 16 41 16 ISWHEEL AND THEY FELL 42 17 43 18 RELEASED WHILE THE RIDE WAS IN OPERATION AND THEY WERE EJECTED THE RIDE ROTATED ABOUT A CENTRAL MOTOR OVERA OF 45 18 46 18 47 19 48 19 49 20 CM THE RIDE 50 21 51 22 52 23 53 24 54 24			COASTER RIDE WAS PERMANENTLY INSTALLED IN AN AMUSEMENT PARK.
26 11 RIDE THEY WERE ON, BROKE APART. THE SWEEP FRACTURE CAUSED THE ATTACHED FOUR COCUPIED BUCKETS TO FALL TO THE 27 11   28 11   29 11   OKE CAUSING THEM TO FALL   30 11   31 12   31 12   31 12   31 13   32 12   31   31 13   32 12   34   35 14   36   37   38   39   31   38   39   31   39   31   30   31   31   32   33   34   35   36   37   38   39   31   39   31   30   31   31   32   33   34   35   36   37   38   39   31   39   31   30   31   31   32   33   34   35   36   37   38   39   31   39   31   30   31   31   32   33   34   35   36   37   38   39   31   30   31   31   32   33   34   35   36   37   38   39   31   30   31   31   32   33   34   35   36   37   38   39   31   30   31   31   32   33   34   35   36   37   38   39   30   31   31   31   32   33   34   35   36   37   38   39   30   31   31   31   32   33   34   35   36   37   38   39   30   31   31   32   33   34   35   36   37   38   39   30   30   31   31   32   33   34   35   36   37   38   39   30   30   30   30   30   30   30   30			
27			
28 11 OKE CAUSING THEM TO FALL  29 11 OKE CAUSING THEM TO FALL  30 11			HILE THEY WERE UN, BROKE APART. THE SWEEP FRACTURE CAUSED THE ATTACHED FOUR OCCUPIED BUCKETS TO FALL TO THE
29 11 OXE CALISING THEM TO FALL. 30 111 31 12 32 12 ATTEMPTING TO GET OUT OF COASTER CAR WHICH HAD STOPPED COASTER RE-STARTED AND VICTIM FELL OUT OF CAR ONTO TRA 33 12 34 13 35 14 36 14 ATTEMPTING TO JUMP OFF OF THE LOG TO ADJACENT SHORE, APPARENTLY SUPPED AND FELL INTO THE WATER AND BECAME TRAP 37 14 38 14 WALL OF FILME RIDE. 39 15 40 16 ISWHEEL AND THEY FELL 42 17 43 18 RELEASED WHILE THE RIDE WAS IN OPERATION AND THEY WERE EJECTED THE RIDE ROTATED ABOUT A CENTRAL MOTOR OVER A CI 45 18 46 18 47 19 49 20 OM THE RIDE.			
30 11   31 12   ATTEMPTING TO GET OUT OF COASTER CAR WHICH HAD STOPPED COASTER RE- STARTED AND VICTIM FELL OUT OF CAR ONTO TRA 33 12   34 13   35 14   ATTEMPTING TO JUMP OFF OF THE LOG TO ADJACENT SHORE, APPARENTLY SUPPED AND FELL INTO THE WATER AND BECAME TRAP 37 14   38 14   WALL OF FILME RIDE.   39 15   40 16   41 16   IS WHEEL AND THEY FELL   42 17   43 18   RELEASED WHILE THE RIDE WAS IN OPERATION AND THEY WERE EJECTED. THE RIDE ROTATED ABOUT A CENTRAL MOTOR OVER A CH 45 18   47 19   48 19   49 20   CM THE RIDE.   51 22   52 2 3   53 24   54 24			OKE CAUSING THEM TO FALL
31 12 32 12 ATTEMPTING TO GET OUT OF COASTER CAR WHICH HAD STOPPED COASTER RE-STARTED AND VICTIM FELL OUT OF CAR ONTO TRA 33 12 35 14 36 14 ATTEMPTING TO JUMP OFF OF THE LOG TO ADJACENT SHORE, APPARENTLY SUPPED AND FELL INTO THE WATER AND BECAME TRAP 37 14 38 14 WALL OF FILME RIDE 39 15 40 16 41 16 ISWHEEL AND THEY FELL 42 17 43 18 RELEASED WHILE THE RIDE WAS IN OPERATION AND THEY WERE EJECTED THE RIDE ROTATED ABOUT A CENTRAL MOTOR OVER A CI 45 18 46 18 47 19 48 19 49 20 OM THE RIDE 50 21 51 22 52 23 53 24			4445661124101742
33 12   34 13   35 14   37 14   38 14   38 14   38 14   39 15   40 16   41 16   41 16   42 17   43 18   44 18   45 RELEASED WHILE THE RIDE WAS IN OPERATION AND THEY WERE EJECTED THE RIDE ROTATED ABOUT A CENTRAL MOTOR OVER A CI 45 18   46 18   47 19   48 19   49 20   40 OM THE RIDE   51 22   52 23   53 24   54 24	31	12	
33 12   34 13   35 14   37 14   38 14   38 14   38 14   39 15   40 16   41 16   41 16   42 17   43 18   44 18   45 RELEASED WHILE THE RIDE WAS IN OPERATION AND THEY WERE EJECTED THE RIDE ROTATED ABOUT A CENTRAL MOTOR OVER A CI 45 18   46 18   47 19   48 19   49 20   40 OM THE RIDE   51 22   52 23   53 24   54 24	32	12	ATTEMPTING TO GET OUT OF COASTER CAR WHICH HAD STOPPED COASTER RE-STARTED AND VICTIM FELL OUT OF CAR ONTO TRA
35 14 ATTEMPTING TO JUMP OFF OF THE LOG TO ADJACENT SHORE, APPARENTLY SUPPED AND FELL INTO THE WATER AND BECAME TRAP 37 14 WALL OF FILME RIDE. 39 15 40 16 SWHEEL AND THEY FELL 40 16 IS WHEEL AND THEY FELL 41 18 RELEASED WHILE THE RIDE WAS IN OPERATION AND THEY WERE EJECTED. THE RIDE ROTATED ABOUT A CENTRAL MOTOR OVER A CI 45 18 41 42 45 45 45 45 45 45 45 45 45 45 45 45 45	33		
35 14 ATTEMPTING TO JUMP OFF OF THE LOG TO ADJACENT SHORE, APPARENTLY SUPPED AND FELL INTO THE WATER AND BECAME TRAP 37 14 38 14 WALL OF FLUME RIDE. 39 15 40 16 41 16 ISWHEEL AND THEY FELL. 42 17 43 18 44 18 RELEASED WHILE THE RIDE WAS IN OPERATION AND THEY WERE EJECTED THE RIDE ROTATED ABOUT A CENTRAL MOTOR OVER A CI 45 18 47 19 48 19 49 20 OM THE RIDE 50 21 51 22 52 23 53 24 54 24	34	13	
37 14   38 14   WALL OF FLUME RIDE   39 15   40 16   ISWHEEL AND THEY FELL   41 16   ISWHEEL AND THEY FELL   42 17   43 18   44 18   RELEASED WHILE THE RIDE WAS IN OPERATION AND THEY WERE EJECTED THE RIDE ROTATED ABOUT A CENTRAL MOTOR OVER A CI 45 18   46 18   47 19   48 19   49 20   OM THE RIDE   50 21   51 22   52 23   53 24   54 24   54 24   54 24   55 24   55 24   55 3 24   55 4 24   55 4 24   55 4 24   55 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5	35		
38 14 WALL OF FLUME RIDE. 39 15 40 16 41 16 ISWHEEL AND THEY FELL. 42 17 43 18 44 18 RELEASED WHILE THE RIDE WAS IN OPERATION AND THEY WERE EJECTED THE RIDE ROTATED ABOUT A CENTRAL MOTOR OVER A CI 45 18 46 18 47 19 48 19 49 20 OM THE RIDE 50 21 51 22 52 23 53 24	36	14_	ATTEMPTING TO JUMP OFF OF THE LOG TO ADJACENT SHORE, APPARENTLY SUPPED AND FELL INTO THE WATER AND BECAME TRAP
39 15   40 16   41 16   41 16   42 17   43 18   44 18   RELEASED WHILE THE RIDE WAS IN OPERATION AND THEY WERE EJECTED THE RIDE ROTATED ABOUT A CENTRAL MOTOR OVER A CI 45 18   46 18   47 19   48 19   49 20   40 20   51 22   51 22   52 23   53 24			
40 16			WALL OF FLUME RIDE.
41 16 ISWHEELAND THEY FELL  42 17  43 18  44 18 RELEASED WHILE THE RIDE WAS IN OPERATION AND THEY WERE EJECTED THE RIDE ROTATED ABOUT A CENTRAL MOTOR OVER A CI  45 18  46 18  47 19  48 19  49 20 OM THE RIDE  51 22  52 23  53 24  54 24	<b>——</b>	_	
42 17 43 18 44 18 RELEASED WHILE THE RIDE WAS IN OPERATION AND THEY WERE EJECTED THE RIDE ROTATED ABOUT A CENTRAL MOTOR OVER A CI 45 18 46 18 47 19 48 19 49 20 OM THE RIDE 50 21 51 22 52 23 53 24 54 24			ICHARTEL AND THEVETTI
43		_	12 AMEET WAT ILET LETT
44		_	<del></del>
45 18 46 18 47 19 48 49 20 CM THE RIDE.  50 21 51 22 52 53 54 54 24			RELEASED WHILE THE RIDE WAS IN CORRATION AND THEY WERE E ISSUED. THE RIDE POTATED AROUT A COUNTY ASSUED.
46 18			THE RULE RULA BULL A CENTRAL MOTOR COMERA CO
47 19 48 19 49 49 20 CM THE RIDE. 50 21 51 22 52 23 53 24 54 54 24			
48 19 49 20 OMTHERIDE 50 21 51 22 52 53 53 24 54 54 24			
49 20 OM THE RIDE. 50 21 51 22 52 53 53 24 554 24 555 24 555 24 555 25 5			
50     21       51     22       52     23       53     24       54     24	49	20	OM THE RIDE.
52 23 53 54 54 54 54 54 55 54 24 55 55 55 55 55 55 55 55 55 55 55 55 55	50		
53 24 54 54 24 54 54 54 54 54 54 54 54 54 54 54 54 54	51	222	
54 24	52		
55   24			
	55	24	

RECORD	CASE	NATRATIVE 3
1_	1	
2	2	RILES, VICTIMWAS SEEN STANDING UP AND LEANING OUT OF THE CAR BY WITNESSES. VICTIM DIED 7 WEEKS LATER FROM COMPU
3	2	
4_	3	
5	3	SHOULDER TYPE HARNESS AND STATE INVESTIGATORS FALLT PARK EMPLOYEES FOR NOT HAND CHECKING THE HARNESS PRIOR TO
6	3	
7	3	
8	3	
10	4	INSPECTION
11	4	
12	5	<del></del>
13	5	
14	6	
15	6	APPARENTLY WAS COAXED TO RIDE BY HIS PARENTS. THE VICTIM LATER DIED FROM INJURIES RECEIVED IN HIS FALL FROM T
16	6	
17	7	
18	7	
19	8	
20	9	
21	9	
22	9	
23	10	
24	10	
26	_	GROUND WHILE THEY WERE REVOLVING AT A HIGH RATE OF SPEED. THE FEMALE FATALITY WAS STRUCK IN THE HEAD BY ANOTHER
27	11	GOOD THE HEITERCROSSING AND AND THE LIGHTER AND THE PERSON AND THE
28	11	
29	11	
30	11	
31	12	
32	12	TRACK TO GROUND, A DISTANCE OF 42 INCHES. VICTIM CLIMBED BACK ONTO TRACK AND WAS STRUCK BY COASTER AS IT RETURNE
33	12	
34	13	
35	14	
36	14	THE VICTIM'S FRIEND HAD SUCCESSFULLY JUMPED FROM THE LOG TO SHORE, AND THE VICTIM WAS ATTEMPTING TO FOLLOW HIS F
37	14	<u></u>
39	15	
40	16	
41	16	<del></del>
42	17	· · · · · · · · · · · · · · · · · · ·
43	18*	
44	18	BY A RAILED WALKWAY. THE VICTIMS WERE DRAGGED ALONG THIS WALKWAY STRIKING THEIR HEADS.
45	18	
46	18	
47	19	
48	19	
49	20	
50	21	
51	22	
52	23	
54	24	
55	24	
_ <del></del> _		<u> </u>

RECORD	CASE	NARRATIVE 4
1	1	
2		OF INCIDENT
3	2	
4	3	
5	3	PROBLEMS WERE NOTED WITH THE RIDE.
6	3	
7	3	
8	3	
9	4	
10	4	
11	4	
12	5	
13	5	
14	6	
15		THE RIDE WAS IN GOOD OPERATING CONDITION AT THE TIME OF THE ACCIDENT. THERE WERE NO OTHER INJURIES
16	6	
17	7	
18	7	
19	8	
20	9	
21	9	<del></del>
22	9	
23 24	10	
25	11	<del></del>
26	1	VOLVED
27	11	VQQVED
28	11	
29	11	
30	11	
31	12	
32	12	- 1 <del>1</del>
33	12	
34	13	
35	14	
36		OF THE VICTIMS DEATH IS LISTED AS MECHANICAL ASPHYXIA.
37	14	
38	14	
39	15	
40	16	
41	16	
42	17	
43	18	
44	18	
45	18	<del> </del>
46	18	
47	19	<u> </u>
49	20	<del></del>
50	21	
51	22	<u></u>
52	23	<u> </u>
53	24	
54	24	
55	24	<del></del>
_ <del></del>	4	

RECORD	CASE	FILE	DTACC	AGE	SEX	STATE	CITY	TKNO	DOCNO	MOBIL	TYPE
56	25	DTHS	08/11/94	6	M	CT	WATERBURY	960730HCC5398	9409018505	F	WHIRLING
57	25	INDP	08/11/94	6	М	CT	MIDDLEBURY	960730HCC5398	9409018505	F	WHIRLING
58	25	INDP	08/11/94	6	м	CT	MIDDLEBURY	940922CCC1758	N9490119A	F	WHIRLING
59	25	IPII	08/01/94	6	M	NJ	BOWCRAFT		N9580417B	F	WHIRLING
60	25	IPII	08/11/94	6	М	CT	ANSONIA	940922CCC1758	N9490118A	F	WHIRLING
61	25	IPII	08/11/94	6	М	CT	MIDDLEBURY		N9480384A	F	WHIRLING
62	25	IPII	08/11/94	6	М	CT	MIDDLEBURY	<del></del>	X94C0726A	F	WHIRLING
63	26	IPII	06/01/95	13	F	FL	TAMPA		N9660173A	F	RC
64	27	DTHS	06/14/95	77	M	PA	ABINGTON	970424HCC1159	9542061243	F	RC
65	27	INDP	06/14/95	77	М	PA	ALLENTOWN	970424HCC1159	9542051243	F	RC
66	28	DTHS	06/30/95	14	F	MO	N KANSAS CITY		9529019093	F	RC
67	28	IPII	01/01/95	14	F	MQ	UNKNOWN		G9580191C	F	RC
68	28	IPII	06/01/95	14	F	LN	KANSAS		N9580294A	F	RC
69	28	1PII	06/30/95	14	F	MO	KANSAS CITY		G9570013A	F	RC
70	29	DTHS	11/25/95	2	F	FL	JACKSONVILLE		9512135919	М	U
71	29	(PII	11/25/95	2	F	FL	TALLAHASSEE	951128CAA1197	X9580789A	М	U
72	30	DTHS	08/11/96	57	F	Ŋ	THORNTOWN	960819HCC5534	9618025871	F	TRAIN
73	30	INDP	08/11/96	57	F	N	THORNTOWN	960819HCC5534	G9680075A	F	TRAIN
74	30	IPII	08/11/96	57	F	Z	THORTOWN	960819HCC5534	G9680075A	F	TRAIN
75	31	DTHS	08/16/96	14.	F	IL.	SANGAMON	960819CCN1702	9617049777	М	WHIRLING
76	31	INDP	08/16/96	13	F	Ĺ	SPRINGFIELD	960819CCN1702	G9680113A	М	WHIRLING
77	31	IPII	08/16/96	14	F	ÎL	SPRINGFIELD	960819CCN1702	G9680113A	М	WHIRLING
78	31	(PII	08/16/96	14	F		SPRINGFIELD	960819CCN1702	X9683698A	М	WHIRLING
79	32	DTHS	08/19/96	52	Σ	NY	STATEN ISLAND	970328HCC1056	9666042423	F	U
80	32	INDP	08/19/96	52	M	NY	VERNON	970328HCC1056	9666042423	F	U
81	33	DTHS	02/22/97	3	E,	N۷	LAS VEGAS	970409HCC3090	9732002247	Ċ	WHIRLING
82	33_	INDP	02/22/97	3	Œ.	NV	LAS VEGAS	970409HCC3090	X9741277A	U	WHIRLING
83	33	IPII	02/22/97	3	Œ.	N	LAS VEGAS	970409HCC3090	X9751749A	C	WHIRLING
84	33	(Pii	02/22/97	3	F	NV	LAS VEGAS	970409HCC3090	X9741277A	2	WHIRLING
85	34	DTHS	04/20/97	14		OK	TULSA		9740009986	٦	RC
86	35	IPII	05/23/97	14	F	ОН	AURORA		G9760114A	F	RC
87	36	DTHS	07/11/97	49	M	NJ	HACKENSACK	980204HCC0018	9734039685	2	RC
88	36	INDP	07/11/97	49	М	רא	JACKSON	980204HCC0018	9734039685	Ų	υ
89	37	IPII	01/01/98	25	M	CA	SANTA CLARA	<u> </u>	F9890039A	Ü	RC
90	_37	1PII	09/07/98	24	M	CA	SANTA CLARA		X98B0385A	>	RC
91	38	DTHS	03/19/98	15	F	TX	AUSTIN	980320CWE7133	9848025078	M	WHIRLING
92	38	INDP	03/19/98	15		TX	AUSTIN	980320CWE7133	F9837026A	M	WHIRLING
93	38	IPII	03/19/98	15	_		AUSTIN		F9837026A	М	WHIRLING
94	38	IPII	03/19/98	15		TX	AUSTIN	980320CWE7133	X9832564A	M	WHIRLING
95	39	IPII	08/01/98	12	_	MN	BLOOMINGTON		X9884596A	F	WATER
96	39	(PII	08/01/98	12		_	MINNEAPOLIS	<del></del> _	X9884463A	F	WATER
97	40	IPII	08/13/98	8			BLOOMINGTON	000000000000000000000000000000000000000	X99932481	F.	U
98	41	INDP	08/30/98	213	_	CA	MENDOTA	<del></del>	F9895002A	M	TRAIN
100	41	IPII	08/30/98	214	F	CA	MENDOTA	980902CWE5016	F9895002A	<u> </u>	TRAIN
100	42	IPII	12/24/98	33	×	CA	ANAHEIM		F9910017A	<u> </u>	BOAT
101	42_	IPII	12/24/98	33		CA	ANAHEIM		X9910197B	F	BOAT
102			12/31/98	46	11.	CA_	LAS VEGAS	0000000000	X9951823A	Ü	RC
103	44	INDP	03/21/99	28		TX TV	ARLINGTON	990322HWE7187	F9937180A	F	RAFT
105	45	INDP	03/21/99	28	F	TX	ARLINGTON	990322HWE7187	F9937180A	- F	RAFT
105			06/11/99	17	<u>.</u>	NY	BROOKLYN	990614CNE5191	N9960143A	F	WHIRLING
	45	IPII	06/11/99	17		NY	CONEY ISLAND	0000440155405	X9962154A	F	WHIRLING
107	45	IPII	06/11/99	17	F	NY	NEW YORK	990614CNE5191	N9960143A	F -	CARS
108	46	IPII	08/22/99	12	2 3	CA	SANTA CLARA	ļ	X0010186A	_ <u>F</u> _	<u> </u>
109	46	IPII	08/22/99	12	M	CA	SANTA CLARA	<del> </del> _	X9982937A	F	U
110 111	47	IPII .	08/23/99	20		_VA	DOSWELL	ļ	X9982972A	_ <u>F</u> _	RC
112	48	(PII)	08/23/99	20	_	VA	HANOVER	<del> </del>	X99A3473A	F	RC
112	49	IPII	08/29/99	30		NJ .	OCEAN CITY	<del></del>	X9993069A	F	RC
114	48	IPII :	08/29/99	39	F	NJ	OCEAN CITY	<u> </u>	X9993069A	F	RC

CASE	NARRATIVE 1
25	FELL UNDER AMUSEMENT PARK RIDE ON CAR TRACKS - CRANIOCEREBRAL TRAUMA, CRUSHING INJURY - AUTOPSY NO
25	6 YEAR OLD MALE SUSTAINED FATAL CRUSHING INJURY TO THE HEAD WHILE TRYING TO EXIT AN AMUSEMENT RIDE WHEN ANOTH
25	A 5 YEAR OLD MALE DIED WHEN HE BECAME ENTRAPPED BENEATH A RIDE THAT GOES IN CIRCLES AT AN AMUSEMENT PARK. IT IS
25	A 6 YEAR OLD MALE WAS KILLED WHEN HE FEEL FROM AN AMUSEMENT PARK RIDE A 7 YEAR OLD MALE AND 6 YEAR OLD MALE BR
25	A 5 YEAR OLD MALE DIED WHEN AN AMUSEMENT RIDE RESTARTED DRAGGING HIM UNDERNEATH AND CRUSHING HIM
25	A 6 YEAR OLD MALE DIED AFTER AN AMUSEMENT PARK RIDE'S CAR STRUCK HIM AND DRAGGED HIM ALONG THE TRACKS
75	A 6 YEAR OLD MALE DIED AFTER FALLING UNDER AN AMUSEMENT PARK RIDE
26	A GIRL, AGE 13, WHO SUFFERED FROM OTHER HEALTH PROBLEMS DIED AFTER SHE HAD A SEIZURE ON A ROLLER COASTER RIDE A
27	BUMPED HEAD ON ROLLER COASTER - INTRACEREBRAL HEMORRHAGE AND SUBDURAL HEMATOMA - AUTOPSY NO
27	A 77 YEAR OLD MALE WAS AT AN AMUSEMENT PARK WITH HIS GRANDCHILDREN THE VICTIM'S HEAD WAS BUMPED BY A ROLLER C
28	FELL FROM ROLLER COASTER RIDE AT AMUSEMENT PARK - MASSIVE HEAD TRAUMA, LACERATIONS OF LIVER AND SPLEEN - AUTOP
28	A 14 YEAR OLD FEMALE DIED FOLLOWING A 25 FOOT FALL FROM A ROLLER COAS TER
28	A 14 YEAR OLD FEMALE DIED WHEN SAFETY STRAPS ON A ROLLER COASTER FAIL ED
28	A 14 YEAR OLD FEMALE DIED OF MASSIVE HEAD INJURY IN A FALL FROM A ROL LER COASTER AT AN AMUSEMENT PARK
29	FELL FROM STAIRS ON CARNIVAL RIDE - CLOSED HEAD INJURY FALL FROM STAIRS ON CARNIVAL RIDE - AUTOPSY YES
29	A GIRL, AGE 2 DIED FOLLOWING A FALL ON THE STEPS LEADING TO A MOBILE AMUSEMENT RIDE
30	PASSENGER OF AMUSEMENT RIDE THROWN DURING DERAILMENT - BLUNT FORCE INJURY OF THE HEAD, AMUSEMENT RIDE - AUTO
30	A 57 YEAR OLD FEMALE DIED OF HEAD INJURIES AND A 4 YEAR OLD FEMALE SUSTAINED SEVERE HEAD INJURIES WHEN TWO CARS
30	A WOMAN, AGE 57 WAS KILLED AND HER GRAND-DAUGHTER SEVERELY INJURED WHEN TWO AMUSEMENT PARK TRAIN CARS FLIPP
31	FALL FROM AMUSEMENT PARK RIDE - DUE TO BRAIN TRAUMA, MULTIPLE TRAUMATIC INJURIES AND HEMORRHAG - AUTOPSY YES
31	THIS INVESTIGATION REVEALED THAT, ON 8/16/96, AT APPROXIMATELY 7 15 PM, A 13 YEAR OLD DEVELOPMENTALLY DISABLED GIRL
31	A GIRL, AGE 14, WAS KILLED AFTER SHE SLIPPED FROM A HARNESS IN THE GONDOLA OF AN AMUSEMENT RIDE AT A STATE FAIR A
31	A GIRL, AGE 14, WAS KILLED AFTER SHE SLIPPED FROM A HARNESS IN THE GONDOLA OF AN AMUSEMENT RIDE AT A STATE FAIR A
32	INJURED KNEE ON RIDE AT AMUSEMENT PARK - PULMONARY THROMBOEMBOLISM, PHLEBOTHROMBOSIS OF LEFT LEG, BLUNT IMP A 52-YEAR OLD MALE INJURED HIS KNEE ON A RIDE AT AN AMUSEMENT PARK, AND DIED 5 DAYS LATER FROM PULMONARY THROMB
32	FELL FROM AMUSEMENT PARK RIDE AND WAS CRUSHED - MULTIPLE TRAUMATIC INJURIES - AUTOPSY YES
33	A 3 YEAR OLD GIRL WAS RIDING IN A FIXED, ROTATING AMUSEMENT PARK RIDE SHE WAS IN A CAR WITH A SIX YEAR OLD CHILD T
33	A 3 YEAR OLD GIRL WAS RIDING IN A FIXED, ROTATING AMOSEMENT FARK NOT STEED AND AN AMUSTEMENT RIDE WHILE IT WAS IN MOTI
33	A GIRL, AGE 3, DIED OF MULTIPLE INJURIES RECEIVED WHEN SHE STOOD UP ON AN AMUSEMENT RIDE IN MOTION, FELL, AND MAY H
33	ROLLER COASTER ACCIDENT WITH EJECTION - BLUNT TRAUMA OF HEAD - AUTOPSY YES
34	AN ASTHMATIC GIRL, AGE 14, DIED AFTER SHE RODE A DOUBLE LOOP ROLLER COASTER AT AN AMUSEMENT PARK. HER ASTHMA A
35	STRUCK HEAD WHILE ON ROLLER-COASTER RIDE - COMPLICATIONS OF SUBDURAL HEMATOMA, HEAD INJURY - AUTOPSY
36	A 49 YEAR OLD MALE ALLEGEDLY SUFFERED A HEAD INJURY ON AN AMUSEMENT PARK RIDE WHICH CAUSED INJURY TO THE BRAIN
37	A MAN, AGE 25, WAS KILLED TRYING TO RETRIEVE A CAP FROM UNDER THE TRACKS OF A HIGH-SPEED ROLLER COASTER AT AN AM
42	A MAN, AGE 24, DIED OF INJURIES RECEIVED TRYING TO RETRIEVE HIS HAT (LOST WHILE RIDING A ROLLER COASTER) FROM A RES
38	LAP BAR OF A CARNIVAL RIDE BROKE AND SHE WAS EJECTED - CRANIOCEREBRAL TRAUMA - AUTOPSY YES - 980320CWE7133
38	THREE VICTIMS INCLUDING A 15 YEAR OLD FEMALE, A 16 YEAR OLD FEMALE AND A NINE YEAR OLD MALE WERE RIDING AN AMUSEM
38	A 15 YR OLD GIRL DIED AFTER BEING THROWN OFF A CARNIVAL RIDE. A 9 YR OLD BOY AND A 16 YR OLD WERE TREATED AND RELE
38	A 15 YR OLD GIRL WAS KILLED AND A 9 YR OLD BOY AND ANOTHER 16 YR OLD WERE SLIGHTLY INJURED WHEN THEY WERE THROW
39	A BOY, AGE 12, DIED OF HEAD AND ABDOMINAL INJURIES RECIEVED IN A FALL FROM A WATER RIDE AT AN INDOOR AMUSEMENT PA
39	A 12 YEAR OLD BOY DIED OF MULTIPLE BLUNT TRAUMA A DAY AFTER HE FELL OFF A LOG FLUME RIDE AT AN AMUSEMENT PARK. H
40	A GIRL AGE 8 DIED OF HEART ATTACK AFTER RIDE IN AN AMUSEMENT PARK.
41	A 13 MONTH OLD MALE VICTIM STOOD UP ON HIS SEAT OF A KIDDIE TRAIN MOBILE AMUSEMENT RIDE AS THE RIDE OPERATOR STAR
41	A 14 MONTH OLD FEMALE WAS KILLED IN A FALL FROM A KIDDIE TRAIN RIDE AT AN AMUSEMENT PARK
42	A MAN, AGE 33, KILLED AND HIS WIFE, AGE 43, WAS INJURED, AND AN EMPLOYEE WAS SERIOUSLY HURT WHEN A ROPE CLEAT PULL
42	A MAN, AGE 33, DIED AFTER HE AND HIS WIFE WERE HIT IN THE HEAD BY A METAL CLEAT THAT BROKE LOOSE ON AN AMUSEMENT
43	A WOMAN, AGE 46, DIED OF SUBDURAL HEMATOMA WITH BLEEDING INTO THE BRAIN 7 DAYS AFTER SHE WAS RIDING A ROLLERCOA
44	A 28 YEAR OLD FEMALE VICTIM DIED AND TEN OTHER INDIVIDUALS WERE INJURED WHEN A FIXED AMUSEMENT RIDE'S RAFT CAPSIZ
44	A WOMAN, AGE 28, DROWNED DURING A WATER RIDE AT AN AMUSEMENT PARK WHEN HER RAFT TIPPED OVER. 11 PEOPLE WERE I
45	A 17 YEAR OLD GIRL WAS KILLED AND EIGHT OTHER PEOPLE WERE INJURED WHEN A SUPER HIMALAYA RIDE MALFUNCTIONED IN A
45	A GIRL, AGE 17, WAS KILLED WHEN A COUPLING BETWEEN CARS ON AN AMUSEMENT PARK RIDE BROKE CAUSING VIOLENT GYRATI
45	AN AMUSEMENT PARK RIDE'S COUPLING BROKE BETWEEN TOW CARS 17 YEAR OLD FEMALE WAS THROWN OUT OF THE RIDE SH
45	A BOY, AGE 12, DIED OF MULTIPLE TRAUMATIC INJURIES SUSTAINED IN A FALL FROM A HEIGHT WHILE ON AN AMUSEMENT RIDE AT
46	A BOY, AGE 12, WAS KILLED AFTER HE FELL FROM AN AMUSEMENT RIDE AT PARK WHEN HE SLIPPED THROUGH A HARNESS ON THE
47	A MAN, AGE 20, DIED IN AN APPARENT ACCIDENT ON A ROLLER COASTER WHICH RIDERS STAND THROUGH SEVERAL LOOPS THAT T A MAN, AGE 20, DIED OF BLUNT FORCE INJURED TO HEAD RECEIVED IN AN ACCIDENT ON A ROLLER COASTER WHICH RIDERS STA
47	THE PROPERTY OF THE AREA SOUTH AS SOUTH AS SOUTH AS SAND THE DECOME WEDE IN HIDEN WHEN THE TWENT AFFAR
48	THE PROPERTY OF A SECOND PORTUGE OF AN AND THE DECOME WERE IN HIRED WHEN THEY WERE AFFAN
49	IN DIRL, AGE 0, AND HER MOTHER, AGE 35, BOTH WERE RELEAD AND 1110 OTHER TEST EST. EST. EST. EST.

RECORD	CASE	NARRATIVE 2
56	25	
57	25	BUTTON WHICH RE-STARTED THE RIDE AND THE SWEEP OF THE RIDE CAUGHT AND DRAGGED THE VICTIM.
58		EXITING THE CAR HE WAS SEATED IN, SOMEBODY STARTED THE RIDE MOVING HE WAS SWEPT BENEATH THE ARM THAT THE CAR EX
59		TO SUPPORT BARS
60	25	
61	25	
62	25	
63	26	
64	27	
65	27	SEEK MEDICAL TREATMENT 4 DAYS LATER, THE VICTIM BECAME ILL AND LAPSED INTO A COMA. HE WAS ADMITTED TO THE HOSPIT
<del>66</del>	28	SERVICE THE STATE OF THE VIOLENCE OF SEPTIMENCOME. THE WAS ARRESTED TO THE HOSPIT
67	28	
68	28	
89		
	28	<del></del>
70	29	
71	29	
72	30	
73	30	AMUSEMENT RIDE TRAIN OVERTURNED, SPILLING THE RIDERS ONTO THE GROUND
74	30	EIGHT OTHER PEOPLE WERE ALSO INJURED
75	31	
76	31_	COUNSELOR, AND THEY WERE RIDING AN AMUSEMENT RIDE AT A STATE FAIR, WHICH LOOKS SIMILAR TO TWO HAMMERS THAT APPA
	31	STRUCK
78	31	STRUCK.
79	32	AUTOPSY YES
80	32	
81	33	
82		BAR IN THE CAR WAS DESIGNED TO RESTRAIN THE LARGEST OCCUPANT. THE VICTIM HAD BEEN STANDING UP WHILE THE RIDE WAS I
83		ONTO CONCRETE AND WAS POSSIBLY RUN OVER BY RUNNING PARTS OF THE RIDE.
84	33	MOVING PARTS
85	34	
86	35	THE OPERATION OF THE RIDE.
87	36	
88		ON HIS WAY HOME HE DETERIORATED AND WAS TAKEN TO A HOSPITAL WHERE HE DIED THE NEXT DAY OFFICIAL CAUSE OF DEATH
89	37	RIDE PASSED OVERHEAD HE WAS HIT IN THE HEAD BY THE DANGLING FOOT OF A WOMAN AGE 28, RIDING THE COASTER, SHE SUFFE
90	37	AMUSEMENT PARK WHEN STRUCK BY THE LEG OF A ROLLER COASTER RIDER #98-250-007
91	38	
92_	38	WERE EJECTED FROM THEIR CAR. THE 15 YEAR OLD FEMALE WAS PRONOUNCED DOA AND THE OTHER TWO VICTIMS WERE TREATED
93_	38	
94	38	THE RIDE WHIPS PEOPLE AROUND AN UNDULATING TRACK AT HIGH SPEEDS
95		HE MAY HAVE BECOME SCARED AND TRIED TO CLIMB OUT DURING THE RIDE.
96	39	DURING THE RIDE. HE STOOD UP AND GRABBED THE RAILING, BUT HE FELL 30' ONTO THE ROCKS AND WATER POOL BELOW 98-1854
97	49	
98	41	THE VICTIM FELL OUT OF HIS SEAT AND WAS RUN OVER BY THE NEXT TRAIN CAR. THE VICTIM WAS PRONOUNCED DEAD AT THE HOSP
89	41	
100	42	BOAT (PART OF AN AMUSEMENT RIDE) AS THE TALL SHIP DOCKED AT AMUSEMENT PARK.
101	42	PARK. A FEMALE PARK EMPLOYEE SUFFERED A FOOT INJURY
102	43	
103	44	CAUSE OF DEATH OF THE VICTIM WAS DROWNING.
104	44	HAVE HAD DIFFICULTY GETTING THEIR SEAT BELTS OFF
105	45	
106	45	OFF EIGHT OTHERS WERE INJURED
107	45	INTERNAL INJURIES, 8 OTHERS INJURED
108	46	99-234-009
109	46	· · · · · · · · · · · · · · · · · · ·
110		AN AMUSEMENT PARK
111		LOOPS THAT TURN THEM UPSIDE DOWN AT AN AMUSEMENT PARK, 130386
112		COASTER WHILE RIDING IN THE CAR THAT SUPPED BACKWARD AND CRASHED INTO ANOTHER CAR BEING LOADED TO BEGIN THE RID
112		COASTER WHILE RIDING IN THE CAR THAT SUPPED BACKWARD AND CRASHED INTO ANOTHER CAR BEING LOADED TO BEGIN THE RID
		The man is a state of the section of

RECORD	CASE	NARRATIVE 3
56	25	
57	25	
58	25	
59	25	
60	25	
61	25	
62	25	
63	26	
64	27	
65	27	HEMORRHAGE. THE VICTIM WAS PLACED ON LIFE SUPPORT AND DIED WITHIN 24 HOURS OF THE REMOVAL OF LIFE SUPPORT
<b>6</b> 6	28	
67	28	
68	28	
59	28	
70	29	
71	29	
72	30	
73	30	
75	31	
76	31	PENDULUM IN OPPOSITE DIRECTIONS AS THE RIDE WAS OPERATING, THE 13 YEAR OLD GIRL PANICKED, AND SHE WIGGLED-OUT F
77	31	FEBRUAR IN A TOSTIC STILL OF SERVICE THE OF ENVIRON, THE IS TEN OLD GREEP AND SHE WIGGLEDOOT P
78	31	
79	32	
80	32	
81		1293
82		OPERATOR HAD WARNED HER TO STAY SEATED. THE VICTIM APPARENTLY FELL UNDER THE CAR AND WAS DRAGGED FOR 3/4 OF A R
83	33	
84	33	· · · · · · · · · · · · · · · · · · ·
85	34	1293
86	35	
87	36	1293
_ 88	36	SUBDURAL HEMATOMA.
89	37	
90	37	
91		1293
92		OF DEATH OF THE 15 YEAR OLD VICTIM WAS SEVERE HEAD INJURIES.
83	38	
94	38	
95	39	
96 97	39	
98	40	OFFICIALS FEEL THAT THE RIDE'S RESTRAINT SYSTEM DID NOT ADEQUATELY RESTRAIN THE VICTIM. THE RIDE HAS BEEN BANNED BY
99	41	OFFICE TIPE THE RIDE STREET STREET AND STREET HOUSE ALCOHAILET A RESIMAND THE ACTIME THE KIDE HAS BEEN BANNED BY
100	42	
101	12	
102	43	
103	44	
104	44	
105	45	<u> </u>
106	45	<del> </del>
107	45	<del></del>
108	46	<del></del>
109	46	
110	47	
111	47_	
112	48	
112	49	

								NARRATIVE 4		
						_		NAVV		
		-561								
	10 C	ASE 25								
55 57		25	<del>-</del>							
27	5	25 25	+-	 						
200	-	25	丁_				 			
-	61	25								
	€2 €3	25								
1	64_	1 2	$\overline{n}$			 				
It	65		27 28	1_					•	
1	66		28_	<del></del>						
1	68		28 28	+						
1	69		29	工				CIRL THEN FELL FROM THE		
'	7	1	23	+				ESTRAINT, & SHE THEN GOT OUT OF THE CAR THROUGH A HOLE IN THE CAR'S TOP THE GIRL THEN FELL FROM THE		
		73	1 3					THE CAR THROUGH A HOLE !!		
		74	1 3	30				AINT & SIFE THEN GOT OUT UP	ı	
		75		31	SHC	XLLX.	R R	ESTRAINT	1	
	-	76		31_	<del></del>				1	
	t	78		31 32	+-			TO IN URIES	Ĺ	
	I	79		32	エ			SIE SUFFERED FATAL HEAD II	4	7 7.
	1	81		T.33	R	DEO	<u>auc</u>	DBE STOPPED SHE SUFFERED FATAL HEAD INJURIES	-	(c)
	1	8	12 83	\ 3	2				コ	
	I		84		33					*
			85		35	سسسه سسد ا			$\Box$	
			87	士	35	<u> </u>			-1	
		t	88		36	+_				
		F	89		37	_				.
		+	8	1	38					1
		Ţ		93	1 3	<u>-</u>				1
		)	1	94	13	8				1
		,	1 _	95 96		39		CECLATE RESTRAINT SYSTEM		コ
			1	97		40	rev	ELOPMENT OF A MORE ADEQUATE RESTRAINT SYSTEM.		-
			t	95		41	۳			コ
			F	10		42	二			
			t	10	я <u> </u>	12	_			
			1		8	14				
			,	1	104	14	=			
					105		計			
				+	100	+	45			
				t	100		45			ļ
				1	109		47			
				t	11	$\Box$	47			
				1	1		49			ļ
					نسا					

# Appendix C

Investigation Reports of Amusement Ride-Related Incidents from 1 Jan 1990 to 30 April 2000

Appendix C lists the 85 in-scope in-depth investigation (INDP) records of amusement riderelated incidents in CPSC files. Complete investigation reports are not provided in Appendix C due to space constraints.

Care	Tuk No	Date	State	City	Age	Ş	Dup	Diag	BdPt	Head	Eye	Fatal
<u> </u>	900610CCN2216	04/14/90	МО	TROY	26	2	3	64	19		۰	2
2	900607CNE5194	05/19/90	K	TRENTON		-	4	37	75	┝╌╬┷┥	٥	2
	900803CCN2193	07/12/90	MO	TROY	18	Σ.	2	34	81	<u> </u>	•	7
	900808CE 9006	05/03/90		MILWAUKEE	35	-	9	3 =	89	0	0	z
	900827CBA1628	08/23/90	MN	SMETHPORT	<u> </u>	-		71	76			, z
<del>  -</del>	900827CCN2309 900830CCN2342	08/21/90	MN	ST PAUL	16	<u> </u>	┝╌╬╌╾	- <del>/ î</del>	115 12	0	9	<del>-2-</del>
<del></del>	910307CNES107	02/22/91	FL	KISSDOMEE	12	-	4	53	31	<del>  </del> →	-	7
<del>  •</del>	910925CCC2781	03/09/91	N N	MONROVIA	20	M	<del></del> -	53	82	-	-	7
10	910701CCN1356	06/09/91	wi -	MERRILL	27	M :	<del>- : -</del>	53	30	<del>   </del>	-	7
<del>                                     </del>	910812CCN1901	07/01/91	KS.	BELOIT	12	H <del>W</del>	<b>-</b>	- 57	17	<del>     </del>	-	<del>-7</del>
12	910729CBB2632	07/17/91	<del>- 11</del> -	PEONA	<del>  ;</del> -	<u>₩</u>		62	- 11			<del> </del>
<del>                                     </del>	910722CEP9012	07/11/91	<del>-</del>	AVOCA	13	- <del>M</del>	<b></b> -	70	75		-	<del>- 1</del>
1 12	91000 (CN1810	07/19/91	OH	LESOURDAVILLE	Ú	<del>- i</del>	-	71	99	-	<del>- 6 -</del>	<del></del> -
13	910723CCN1752	07/21/91	II.	MIDLOTHIAN	13	M	┝╌	53	<u> </u>	<del>                                     </del>	-	<del>- Ĥ</del>
16	910828CCN2063	06/12/91	OH	COLUMBUS	Ü	Ü	<del></del>	33	73	<del>- i-  </del>	8	<u> </u>
177	910(2)CCN1992	08/20/91	МО	SEDALIA	12	<del>- ŭ -</del>		52	75	H	<del>                                     </del>	<del>                                     </del>
110	930812CCC2490	09/01/91	Ok	OKLAHOMA CITY	U	7		- 53	79		-	- <del> </del>
19	911009CWE5008	09/11/91	AZ	LAKE HAVASUE ÇI		F	4	53	31	•	0	-
20	910930CCN2446	09/12/91	N	EDINBURG	26	F		53	75	0	0	7
21	911031CWE5024	10/17/91	AZ.	PHOENIX	. 10	М	4	53	89	0	0	Ä
22	911011CWE5025	10/22/91	AZ	PHOENIX	_ 10	_М	_	33	i.i	٥	Ò	X
2)	920810CCC1559	07/03/92	MŒ	BATH	, 11	. м	- 1	39	75	0	٥	
24	940721CCC2639	07/15/92	OH	BRUNSWICK	22	×		66_	76		F	, N
25	921013CWE5008	07/24/92	co	THORNTON	12	×		\$	71	$\Box$		z
26	920730CWE6001	07/25/92	NM	TAOS	22	F	-	57	89		0	_ <b>Y</b>
27	930826CCC1534	04/25/92	VA	NCHMOND	22	М		70	99		1	'n
28	930304CWE7030	02/21/93	TX	HOUSTON	33	M		71	75	1	0	N
29	930306CWE 1031	02/22/93	TX	GAILAND	0	۰	0	71	99		0	N
30	930413CNE5115	04/07/93	PA	PHILADELPHIA	13	М	_	53	15	0	•	_ אר_
31	930915CWE7048	04/30/93	AR.	CONWAY	13			8	22	0	6	7
12	930519C\E5140	05/13/93	^	MASONTOWN	15	٠	1	37	75	0	9	7
33	930607CWE7048	06/04/93	7 2	NEW ORLEANS	•	М	1	51	76	0	٥	2
74	930729CCC1483	06/18/93		VINELAND	6	-		33	89		٥	<u> </u>
35	930825CCN2280	08/04/93	MO	HARRISON	39	-		57	3[	0	9	[
1 33 T	930809CBB2486 931206CNE5027	08/13/93	WV	SPAUNGFÆLD LEWISBURG		×	+	57	76	-	9	1
38	930927CCC3631	08/15/93	- 27	UKIAH	21 U	ž	<del></del>	53	77	0	1	4
19	930916CCC1357	04/15/93	uv	LEWISBURG	29	M	<del>                                     </del>	70	17	-	_	7
40	930917CEP9010	09/04/93	OH	GLOUSTER		×	<del></del> -	67	83		0	<del>- ;-  </del>
41	940618CCN2210	07/07/94	MI	NEW BUFFALO	10	M	+	57	73	1	+	7
1-42	940117CCN2199	07/14/94	<del>Wi</del>	RIVERFALLS	<del>  ;</del>			37	79	-	8	<del>- 1</del>
1	940803CNE5177	07/26/94	PA	WEST PARK	<del>  0</del>	<del>  </del>	<del></del>	70	17	-	<del>- * -</del>	<del>- 11 - 1</del>
4	940922CCC1758	04/11/94	टर	MIDDLEBURY	-	M	-	54	7	<del>  *</del>	0	<del></del>
45	960730HCC5398	00/11/94	CT	MIDDLEBURY	- 6	- м	<del></del>	34	73	┝╌	+	<del>-                                    </del>
46	940830CW E5024	08/27/94	ČÁ	SACRAMENTO	4	M	4	70	75	<del>                                     </del>	+	- i
47	940829CAA1716	08/28/94	М	TIMONIUM		м		57	76	-	-	N N
14	950522CCC1679	05/14/95	NÝ	ROCHESTER		F	4	57	81	-	0	- 12
49	970424HCC1159	06/14/95	PA	ALLENTOWN	77	М		58	73	<del>                                     </del>	•	-
50	950623CCN2264	06/22/95	Щ	EVERGREEN PARK	18	Ŧ	4	52	75	-	•	4
51	931128CAA1197	11/25/95	FL	PALATKA	2	F	۰	62	75		Ó	-
52	\$60731CNE5190	07/21/96	MA	AGAWAM	U	U		53	67	-	ø	×
53	960819HCC5534	08/11/96	, IN	THORNTOWN	57	F		62	75		0	Y
<u> </u>	960819CCN1702	08/16/96	Ţ,	SPRINGFIELD	13	F		53	15	0	0	Y
35	970328HCC1056	06/19/96	77	VERNON	52	3		71	<b>\$</b> 3	6	6	Y
36	960828CCN1755	08/22/96	KS	PAOLA	5	М		53	76	Ô	0	N
37	9-1016HCC3702	09/14/96	MA	WEYMOUTH	•	F	4	72	75	0	0	N
38	970220CNE5083	02/07/97	FL	TAMPA	30	×	4_	30	- 3	-0	0	Z
39	970409HCC3090	02/22/97	×	LAS VEGAS	3		-	62	75		ď	
60	970304CNE5090	03/01/97	FL	PLANT CITY	10	¥;	$\vdash$	51	37	9		
61	980204HCC0018	07/11/97	2	JACKSON CATE DAVIDE	49	M		65	85		٥	1
62	911210CCN0075	10/01/97	12	GATLINBURG	57	×		37	10	6	9	
63	1971)17CNE5020	11/15/97	FL	HOLLYWOOD	3	┝╬┈	<del></del>	37	92	,	9	2
63	980329CWE7133 980708CNE3183	03/19/98	MA.	WALFOLE	13	Ţ	•	62	75		0	4
- <del>65</del>	960601CAA0468	05/07/98	MA	MARBELHEAD	15	м		57 53	37	0	<u> </u>	7
67	940607C WE7164	05/13/98	- MA TX	MARBELHEAD NOCONA	10	_		- 57	92 75		9	7
- 64	940720C CN0339	07/18/91	LĈ-	LANSING	43	M F	4	64	75			- <del>7</del> -
<del>- 69</del>	990923CCC0749	07/25/98	VA.	WILLIAMSBURG	45	2		8	79		0	
70	900924HCC0726	08/08/98	<del>- 10</del>	BERGENFIELD	-	Á	-	72	76	-1	-	2
70	940902CWE5016	08/30/98	~~	MENDOTA	<del>                                     </del>	<del>- M</del>	<del>- ĭ -</del>	62	75	- *	•	<del>- Ÿ -</del>
12	990205CEP9003	09/05/98	<u> </u>	NIVER MOUGE	21	7		4	79	<del>                                     </del>	-	- 7
<del>                                     </del>	911023CCC3028	09/28/98	73	PINE BLUFF	33	<del>                                     </del>	4-	57	79		-	- 4
<del>  74  </del>	990322HWE7187	03/21/99	TX	ARLINGTON	28	+		69	83	<del>  -</del>	ا ن	<del>- 7 -</del>
1 - <del>73</del> -	990524HCN0210	03/23/99	Νô	JENNINGS	16	2	4-	33	73		-	<del>- 4</del> -
<del>  %</del>	990712CNE5204	05/27/99	MA	FRAMINGHAM	13	1	<del></del>	32	75	<del>                                     </del>	<del>  •  </del>	<del>                                     </del>
<del>- ñ</del> -	991021CNE3318	05/30/99	MA	FRAMINGHAM	34	H	<del>  ;</del>	70	99	<del>                                     </del>	+	<del>Ñ</del> -
78	990614CNE5191	06/11/99	NY	NEW YORK	17	<del>                                     </del>	┝┋┑	70	83	- 6	1 8	<del>- Ÿ -</del>
79	990803CEF9009	07/11/99		BLOOMINGTON		1	<del></del>	33	75	<del>├─</del> ॉ─┤	<del>- }-</del>	<u> </u>
140	990921CCC0732	07/25/09	ΝY	WALKEL	12	<del>                                     </del>	-6	-2-	89	-	<del></del>	<u> </u>
61	990903HEP9005	06/25/99	CA	SACRAMENTO	22	1		71	85	<del>ſ</del> ─┭	8	N -
82	990917CWE6003	09/15/99	ČĀ.	SANTA CRUZ	22	<del></del> -	4	57	34	<del></del>	-	N N
10	991104CNE5339	09/24/99	10	LINCOLN	0	0	0	70	87	- 6	ð	N
뭐	000327HCC0512	02/22/00	FL	DADE CITY	19	2	<del></del>	32	75	<del>                                     </del>	Ò	N
85	000407CNE5485	04/01/00	PA	PHILADELPHIA	0	-	- T	33	87	6	0	N
									_			

A TWENTY SIX YEAR OLD MAN AND HIS THREE YEAR OLD SON SUFFERED INJURIES RESULTING FROM A FALL OUT OF A FERRIS WHEEL. THE BAR THAT A 3-1/2 YEAR OLD FEMALE SUSTAINED A FRACTURED SKULL AND A BROKEN LEFT LEG WHEN SHE FELL FROM AN AMUSEMENT RIDE AT A CARNIVAL DURING TWO MALES AGES EIGHTEEN AND TWENTY SEVEN WERE INJURED WHILE ON A RIDE AT A CARNIVAL IN THEIR RURAL HOME TOWN. THE RIDE WHICH TURNS AND MALES AGES EIGHT LEFT AND TWENTT SEVEN WERE INJURED WILLE ON A RIDE AT A CARRYLY ALTO THEIR KURAL HOME TOWN THE AIDE WHICH TURNS VICTIM WAS WITH AN OUT-OF-TOWN CHURCH GROUP VISITING A STATE FAIR DURING THE AFTERNOON THE 15 YR OLD FEMALE VICTIM WITH HER NOECE AND NEI A METAL BAR APPROXIMATELY 10 FT LONG DETACHED FROM A SPINNING AMUSEMENT RIDE AND FLEW INTO A CROWD OF SPECTATORS. THE BAR STRUCK THIS INVESTIGATION INVOLVED AN AMUSEMENT RIDE AT THE STATE FAIR. THE SPINNING RIDE WENT INTO OPERATION AND THE RIDE OPERATOR WASN'T ABLE THE ACCIDENT INVOLVED AN AMUSEMENT RIDE AT THE STATE FAIR A PASSENGER CAR (TUB) BROKE LOOSE FROM THE RIDES NOTATING ARM (SWEEP) THE ACCIDENT INVOLVED AN AMUSEMENT RIDE AT THE STATE PAIR A PASSENGER CARCITUD BROKE LOUSE FROM THE RESTRAINT SYSTEM WAS DEFEATED AS THE VICTUM

A 12 YOF SUSTAINED SPLEEN & OTHER INJURIES IN A MOBILE AMUSEMENT RIDE AT A FAIRGROUND WHEN THE RESTRAINT SYSTEM WAS DEFEATED AS THE VICTUM

A 20 YEAR-OLD MALE GOT HIS LEFT HAND CAUGHT BETWEEN 2 BACKBOARDS OF A CENTRIFUGAL FORCE CARNIVAL RIDE. WHEN HE WAS ABLE TO REMOVE HIS HAND

TWO ADULTS AND ONE SYR OLD FEMALE WERE INJURED WHEN THE SEAT ON THE PORTABLE AMUSEMENT RIDE THEY WERE OCCUPYING BECAME DETACHED FROM ITS A 12 YEAR OLD BOY SUSTAINED A FRACTURE TO HIS ANKLE WHILE RIDING A MOBILE AMUSEMENT RIDE AT A COUNTY FAIR. A SEAT COMPONENT FELL A YYEAR OLD MALE SUSTAINED INTURES REQUIRING REMOVAL OF ITS OF HIS FANCREAS & A SECTION OF INTESTANT WHEN A RIDE AT A COUNTY FAIR TWO TEENAGE FEMALE VICTOMS FELL FROM AN AMUSEMENT PARK RIDE FROM A HEIGHT OF ABOUT TO CAUSING INTURYS TO BOTH TEENS TWO SEPERATE RIDES HAD EQUIPMENT FAILURES NO INURIES OCCURRED IN ONE INCIDENT TWO CARS ON A ROLLERCOASTER BACAME UNCOUPLED. IN THE 11 A 16 YEAR OLD MALE AND A 15 YEAR OLD FEMALE SUFFERED MINOR INJURIES WHEN AN AMUSEMENT RIDE IN WHICH THEY WERE RIDING COLLAPSED. STATE 13 A FERRIS WHEEL SEAT CUSHION BECAME DISLODGED AND FELL ONTO TWO RIDERS IN THE SEAT BELOW ONLY BRUISES OCCURATED ON THE HEAD AND A 12 YEAR OLD MALE AND FEMALE RECEIVED CRITICAL HEAD INJURIES WHEN AN AMUSEMENT RIDE AT A STATE FAIR MALFUNCTION A THIRD VICTIM, 12 YEAR TWO VICTIMS, A MOTHER AND HER SON OF UNKNOWN AGES SUFFERED MINOR INJURIES WHILE RIDING AN AMUSEMENT RIDE. THE MOTHER SUFFERED A
THE STABILIERING BAR HOLDING UP AN AIRPLANE ON A CHILDREN'S AMUSEMENT RIDE BROKE CAUSING THE RIDE TO FALL TO THE GROUND. TWO CHILDREN A 26 YEAR OLD FEMALE FELL TO THE GROUND WHEN THE SAFETY BELT ON THE CARNIVAL RIDE ON WHICH SHE WAS RIDING CAME LOOSE TWO GROUPS OF CARS ON A ROLLER COASTER RIDE WERE BEING KEPT STATIONARY AT CERTAIN POINTS OF THE RIDE. THE RIDE BRAKEMAN THE REAR BRAKEMAN ON A ROLLER COASTER RIDE INADVERTENTLY HELD OPEN THE INCOMING BRAKES IN THE STATION THIS ALLOWED AN INCOMING CAR TO AN IT YEAR OLD MALE SUSTAINED A LACERATION ON HIS HEAD WHEN HE WAS STRUCK BY A LOADBINDER, WHICH SEPARATED FROM AN OVERHEAD CABLE OF A THE 22 YEAR OLD MALE VICTIM SUSTAINED A BROKEN BLOOD VESSEL IN HIS SINUSES AFTER RIDING IN AN AMUSEMENT DEVISE THAT SPIN HIM AROUND
A 17 YEAR OLD BOY SUFFERED EYE HEMORRIAGE INIURY AFTER RIDING A MOBILE "GYRÖSCOPE" TYPE AMUSEMENT RIDE. THE VICTIM ALSO SUFFERED
A 22 YEAR OLD FEMALE AND TWO OTHER YOUNG FEMALES WERE INIURED ON A MOBILE AMUSEMENT RIDE. THE HIMALAYA, WHEN A SAFETY LAP BAR APPARENTLY. A 22 YEAR OLD MALE COMPLAINED OF READACHE AND EYE BRITATION AFTER RIDING IN A MANUALLY OPERATED AMUSEMENT RIDE AT A STATE FAIR. THE
A 33 YEAR OLD MALE SUSTAINED MINOR DIZZINESS WHEN A AMUSEMENT RIDE FUMPER, MALFUNCTIONED. THE RESTRAINT BAR OF THE RIDES CAR WAS IN
ON FEBRUARY 22, 1993. AND ADULT MALE CONSUMER REPORTED A POSSIBLE ENTRAPMENT OR CRUSHING HAZARD ASSOCIATED WITH A CHILD'S ELECTRIC. SEVERAL CHILDREN SUSTAINED BRUISES AND CONTUSIONS WHEN TWO CIRCULAR CARS OF A FOUR CAR AMUSEMENT RIDE SPINNING COUNTERCLOCKWISE BROKE 20 IS YEAR OLD GIRL WAS - RIDING AN AMUSEMENT (CARNIVAL) RIDE. WHEN THE RIDE HAD CONCLUDED THE VICTIM REACHED UP WITH HER AUMS AND A 13 YEAR OLD GIRL SUFFERED FACIAL FRACTURES AND NERVE DAMAGE OF THE SHOULDER AREA IN AN ACCIDENT OF A BALREL-OFUN AMUSEMENT RIDE AT A 30 IA 13 TEAR OLD GIRL SUFFERED FACIAL FRACTURES AND NERVE DAMAGE OF THE SHOULDER AREA IN AN ACCIDENT OF A BARREL-GFON ANUSEMENT RIDE AT THIS IDI INVOLVED A MOBILE AMUSEMENT RIDE THAT CAUCHT ON FIRE AS IT WAS OPERATING. THE FIRE ORIGINATED IN THE RIDE'S MOTOR AREA. A FOUR CHILDREN AGES 6 TO 11 YEARS. WERE SLIGHTLY DIJURED WHEN THE CARS TO THE METRY MIXER AMUSEMENT RIDE THEY WERE IN AT THE TIME. A 39 YEAR OLD FEMALE A HER 9 YEAR OLD DAUGHTER WERE RIDING ON THE OCTOPUS AMUSEMENT RIDE AT A COUNTY FAIR. A "COTTER KEY" THAT HELD A 49 YEAR OLD MALE RECEIVED A FRACTURED NOSE WHEN A METAL FLAP BAR ON AN AMUSEMENT RIDE CAME OPEN AND HE WAS THROWN OUT OF THE CAR. 14 A 21 YEAR OLD MALE SUFFERED HEMORRHAGING OF BOTH EYES WHILE RIDING ON AN ONE PERSON CAPACITY AMUSEMENT RIDE AT A STATE FAIR. THE RIDE WAS 36 A TEEN-AGED GOLL SUFFERED A BUMP ON HEA HEAD. WHEN A MOBILE AMUSEMENT RIDE STOPPED ABRUPTLY THE MAIN DRIVE CHAIN BROKE CAUSING
A 29 YEAR OLD MALE SUFFERED A RETINAL TEAK CONJUNCTIVAL HEMORRHAGING AND OTHER INJURIES WHILE RIDING ON A ONE PERSON CAPACITY HAND POWERED 37 32 RESPONDENTS WERE THE VICTIM AND HIS FATHER VICTIM WAS AT A CARRIVAL WITH HIS FATHER IN HIS HOMETOWN AS VICTIM WAS GETTING OFF A A 10 YEAR OLD BOY WAS HOSPITALIZED FOR A HAIRLINE SKULL FRACTURE THAT HE RECEIVED AFTER BEING THROWN FROM A TIP TOP AMUSEMENT RIDE AT A TWO FEMALES AGES & 9 WERE INJURED WHEN THEY FELL APPROX. 20 FEET FROM A FERRIS WHEEL SEAT. THE RIDE WAS PART OF A TRAVELING CARNIVAL.
12 PERSONS WERE TREATED AND RELEASED FOR MINOR INJURIES RESULTING FROM AN AMUSEMENT RIDE ACCIDENT AT A CARNIVAL. THE ACCIDENT OCCURRED 47 A 6 YEAR OLD MALE DIED WHEN HE BECAME ENTRAPPED BENEATH A NIDE THAT GOES IN CIRCLES AT AN AMUSEMENT PARK. IT IS BELIEVED THAT AS HE WAS
6 YEAR OLD MALE SUSTAINED FATAL CRUSHING INDURY TO THE HEAD WHILE TRYING TO EXIT AN AMUSEMENT FIDE WHEN ANOTHER CHIED PUSHED THE START 43 A FOUR YEAR OLD CHILD SUFFERED A BROKEN LEG AND SPINAL, HEAD AND FACIAL INJURIES WHEN HE FELL OUT OF A FERRIS WHEEL CHAIR STATE 45 IT IS BELIEVED BY INSPECTORS FROM THE STATE OF MARYLAND THAT AN AMUSEMENT RIDE AT THE STATE FAIR HAD BEEN VANDALIZED BY PERSONIS THREE CHILDREN AGES 6 YEARS 4 YEARS AND 22 MONTHS WERE INJURED ON A AMUSEMENT RIDE AT A FESTIVAL. THE 6 YEAR OLD SUSTAINED A COMPOUND IMAGE CHILDREN AGES 6 TEARS 4 TEARS AND 22 MONTHS WERE INTERED ON A AMOSEMENT RIDE AT A PESTIVAL. THE 6 TEAR OLD SUSTAINED A COMPOUND A 77 YEAR OLD MALE WAS AT AN AMUSEMENT PARK WITH HIS GRANDCHILDREN. THE VICTOM'S HEAD WAS BUMPED BY A ROLLER COASTER RIDE. HE DID NOT THIS INVESTIGATION WAS INITIATED FROM A NEWSPAPER ARTICLE, WHICH STATED THAT SY PEOPLE WERE INJURED WHEN A FEARLY WHEEL CAR BROKE.

A 2 YEAR OLD FEMALE FELL APPROXIMATELY 14 FEET THROUGH AN OPENING BETWEEN THE STEPS AND SUPPORT TRUSS RAILS OF A MOBILE AMUSEMENT SLIDE 16 PASSENGERS ON A FIXED SITE AMUSEMENT RIDE SUSTAINED CONTUSIONS NECK OR BACK INJURIES WHEN THE OPERATOR STOPPED THIS RIDE, BY 49 40 41 A 37 YEAR OLD FEMALE DIED OF HEAD INTURIES AND A 4 YEAR OLD FEMALE SUSTAINED SEVERE HEAD INTURIES WHEN TWO CARS OF A FIXED SITE
THIS INVESTIGATION REVEALED THAT ON \$10.000 AT APPROXIMATELY 7 IS PM, A 13 YEAR OLD DEVELOPMENTALLY DISABLED GIRL WAS WITH A 33 A 33-YEAR OLD MALE INJURED HIS KNEE ON A RIDE AT AN AMUSEMENT PARK AND DIED 3 DAYS LATER FROM PULMONARY THROMBOENBOLISM 33 THE INVESTIGATED INCIDENT INVOLVED A KIDDLE MOBILE AMUSEMENT RIDE A FIVE YEAR OLD BOY WAS SITTING IN THE FRONT SEAT OF ONE OF THE RIDES WHILE RIDING ON A FIXED SITE AMUSEMENT RIDE AN 8 YEAR OLD FEMALE HAD HER SCALP RIPPED OFF WHEN HER HAIR FELL INTO THE MOTOR ON THE BACK A 30 YEAR OLD MALE SUFFERED A 50% AMPUTATION OF HIS FOOT WHEN HE WAS EJECTED FROM HIS SEAT ON THE MOBILE RIDE AT THE STATE FAIRGROUND 47 30 A 3 YEAR OLD GIRL WAS RIDING IN A FIXED ROTATING AMUSEMENT PARK RIDE. SHE WAS IN A CAR WITH A SIX YEAR OLD CHILD. THE SINGLE LAP A 3 YEAR OLD MALE AND HIS IN-YEAR OLD BROTHER WERE RIDING AN AMUSEMENT RIDE AT A LOCAL FAIRGROUND. THEY WERE THROWN FROM THEIR AN E-YEAR OLD MALE AND HIS IN-YEAR OLD BROTHER WERE RIDING AN AMUSEMENT RIDE AT A LOCAL FAIRGROUND. THEY WERE THROWN FROM THEIR 30 A 49 YEAR OLD MALE ALLEGEDLY SUFFERED A HEAD INJURY ON AN AMUSEMENT PARK RIDE WHICH CAUSED INJURY TO THE BRAIN WITH NO EXTERNAL SIGNS THE OWNER OF AN AMUSEMENT RIDE, A 57 YEAR OLD MALE, SUSTAINED A DISPLACED SHOULDER AND FRACTURES TO HIS RIGHT ARM WHEN HE GRABBED 61 ON 11-13-97 A NON-FIXED SITE / MOBILE MECHANIZED SWING AMUSEMENT RIDE TOPPLED OVER ONTO THE GROUND BURING OFERATION AT A WEEKEND THREE VICTIMS INCLUDING A 15 YEAR OLD FEMALE. A 16 YEAR OLD FEMALE AND A NINE YEAR OLD MALE WERE RIDING AN AMUSEMENT RIDE WHEN THEY A 15 YEAR OLD FEMALE SUSTAINED A BROKEN RIGHT ANKLE AFTER BEING THROWN FROM AN AMUSEMENT RIDE WHEN THE SAFETY LAP BAR FAILED WHILE 65 A 10 YEAR OLD MALE SUSTAINED SMALL SCRAPES TO HIS KNUCKLES AFTER FALLING TO THE GROUND WHEN THE OPERATOR OF AN AMUSEMENT RIDE THE VICTIM, AN IT YEAR OLD MALE, WAS EJECTED FROM HIS SEAT ON AN AMUSEMENT RIDE WHILE IT WAS IN FULL MOTION. HE VICTIM WAS STRUCK IN AN AMUSEMENT RIDE ACCIDENT OCCURRED WHEN ONE CAR HIT THE RIDE STRUCTURE AND TURNED UPSIDE DOWN AND SEVERAL CARS THEN PILED INTO A 49 YEAR OLD MALE ALLEGEDLY SUFFERED A HEAD INJURY ON AN AMUSEMENT PARK RIDE WHICH CAUSED INJURY TO THE BRAIN WITH NO EXTERNAL SIGNS 41 SIX PEOPLE HAD TO BE RESCUED FROM A FERRIS WHEEL WHEN THE RIDE MALFUNCTIONED AND STRANDED RIDERS IN CARRIAGES OFF THE GROUND A 13 MONTH OLD MALE VICTOM STOOD UP ON HIS SEAT OF A KIDDLE TRAIN MOBILE AMUSEMENT RIDE AS THE RIDE OPERATOR STARTED THE TRAIN AND THE 21 YEAR OLD FEMALE VICTOM SUFFERED CONTUSIONS AND ABRASIONS TO HER LOWER TRUNK AFTER RIDING IN AN AMUSEMENT RIDE AT A FAIR WHICH A 11 YEAR OLD WOMAN ENCURRED SEVERAL FRACTURES TO HER LEGS BACK, AND FELVIC AREA WHEN SHE WAS THROWN FROM A CHAIR SEAT OF AN AMUSEMENT A 28 YEAR OLD FEMALE VICTOM DIED AND TEN OTHER INDIVIDUALS WERE INJURED WHEN A FIXED AMUSEMENT RIDES RAFT CAPSIZED. THE OFFICIAL 73 TWO FEMALES AGES IS AND 20 AND A 17 YEAR OLD MALE WERE INJURED WHEN THE LAP BAR TO AN AMUSEMENT CAR RIDE IN WHICH THEY AND ANOTHER T × A 10 YEAR OLD BOY WAS HOSPITALIZED FOR A HAIRLINE SKULL FRACTURE THAT HE RECEIVED AFTER BEING THROWN FROM A TIP TOP AMUSEMENT RIDE AT A THE 24-YEAR OLD MALE AND 33 YEAR OLD FEMALE VICTIMS WERE UNINIDIZED WHEN THE RESTAINING BAR FOR THEIR SEAT ON A MOBILE AMUSEMENT RIDE. ONE DIED AND I WERE INJURED IN ACCIDENT INVOLVING HIMALAYA RIDE AT CONEY ISLAND PARK A 2-12 YEAR OLD FEMALE SUSTAINED A FRACTURED SKULL AND A BROKEN LEFT LEG WHEN SHE FELL FROM AN AMUSEMENT RIDE AT A CARNIVAL DURING A 12 YEAR OLD MALE AND A 13 YEAR OLD FEMALE RECEIVED NECK AND BACK INJURIES WHEN THE ROLLER COASTER CAR THEY WERE RIDING IN WAS HIT A 33 YEAR OLD MALE SUSTAINED MINOR DIZZINESS WHEN A AMUSEMENT RIDE JUMPER MALFUNCTIONED. THE RESTRAINT BAR OF THE RIDES CAR WAS IN A MENTALLY HANDICAPPED 22 YEAR OLD MALE RIDING A TRAVELING TYPE AMUSEMENT RIDE KNOWN AS THE ORBITEK BECAME FRIGHTENED AND SQUIRMED. THERE WERE NO DITURIES WHEN A 10 YEAR OLD BOY HIS MOTHER, AND 2 OTHER TEN YEAR OLD BOYS WERE STOPPED AT THE TOP OF A MOBILE A 19 YR OLD FEMALE SUFFERED A SEVERE CONCUSSION WHEN SHE WAS TOSSED AROUND THE CAR OF AN AMUSEMENT PARK RIDE. SHE HAS CONTINUED TO HAVE A MECHANICAL MALFUNCTION OCCURRED DURING THE OPERATION OF A SWING RIDE AT A CARNIVAL SITE. FOUR PEOPLE WERE INJURED DURING THE 13

Case | Narrative (continued) WAS SUPPOSED TO LATCH THEM IN RECAME OPENED AT TWENTY FEET IN THE AIR. THE TWO PEOPLE FELL TO THE GROUND AND WERE IMMEDIATELY TAKEN OPERATION OF THE RIDE. THE VICTIM WAS SEATED IN A CAR WITH HER TO YEAR OLD GRANDFATHER AT THE TIME WHEN HER GRANDFATHER LIFTED HER UP AT 160 DEGREE REVOLUTIONS, AND HAS TWO CARS AT 180 DEGREES APART ON ONE METAL ARM BEGAN TO BEND AND BUCKLE. SENDING ONE OF THE CARS. HEW WERE RIDING IN ONE TUB OF A LEVEL AMUSEMENT RIDE CONSISTING OF 5 OR 6 TUBS MOUNTED ON A CIRCULAR SPINNING HUB. ALL RIDERS HAD SAFETY THREE 14 YEAR OLD GIRLS IN THE CROWD. ALL THREE GIRLS SUFFERED BODY BRUISES. TWO OF THE GIRLS WERE EXAMINED AT A LOCAL HOSPITAL. ONE TO STOP IT BECAUSE OF A PROBLEM WITH THE ELECTRIC MOTOR THAT DRIVES THE HYDRAULIC SYSTEM. FORTY RIDERS WERE KEPT SPINNING IN THE AIR FOR AS THE DISC SHAPED PLATFORM WAS ROTATING IN THE OPPOSITE DIRECTION. THE CAR SLIDE ACROSS THE PLATFORM COMING TO REST AGAINST THE FENCE ATTEMPTED TO GET OUT OF THE RIDE AS IT WAS IN MOTION. THE VICTIM WAS THROWN OUT THE CAR AND SUFFERED SPLEEN, RIBS, AND LUNG INTIRIES IN AFTER THE RIDE HAD STOPPED HE NOTICED THAT IT WAS ABRAISED AND SWOLLEN SUPPORT ARMS. A DEFECTIVE WELD ON THE SEAT SUPPORT IS BELIEVED TO BE THE CAUSE OF THE ACCIDENT. THE THREE VICTIMS WERE TAKEN TO A
DOWN EXPOSING THE VICTIMS FEET/ANKLES TO THE MOVING METAL SUPPORT ARM. THE SUPPORT ARM AND THE SEAT COMPONENT WHICH FELL DOWN MALFUNCTIONED AND STOPPED SUDDENLY CAUSING HIM TO BE THROWN FORWARD AGAINST THE RESTRAINING BAR 12 13 OTHER INCIDENT AN UNOCCUPIED GONDOLA CAR ON A SKY RIDE FELL 25 FEET TO THE GROUND
INVESTIGATORS DETERMINED THAT AN "R KEY" SECURING A YOKE AND PIN SUPPORTING A RIDE COMPONENT FAILED THUS ALLOWING THE CAR IN WHICH 14 15 SHOUR DER AREAS OF ONE INDIVIDUAL OLD FEMALE WAS HOSPITALIZED WITH A BROKEN JAW. AND A 19 YEAR OLD FEMALE WAS HOSPITALIZED FOR A HEAD INJURY. THREE OTHER CHILDREN. CONTUSION TO THE LOWER ARDOMEN AND RIGHT HIP AND THE SON SUFFERED A CONTUSION TO THE RIGHT KNEE. INSPECTION OF THE AMUSEMENT RIDE BY 11 SUFFERED MINOR INTERIES WHEN THE TOY AIRPLANE IN WHICH THEY WERE RIDING SLAMMED INTO THE SUPPORT FRAME OF THE RIDE 19 20 INADVERTENTLY RELEASED THE BRAKE HOLDING ONE OF THE SETS OF CARS. THAT CAR ROLLED ALONG THE TRACK AND STRUCK A SECOND SET OF CARS WHICH GO INTO THE STATION WITHOUT SLOWING DOWN. THUS IT BUMPED ANOTHER CAR WHICH WAS UNLOADING PASSENGERS. FERRIS WHEEL IND PERMANENT INJURIES RESULTED FROM THIS ACCIDENT. THE WHITES OF HIS EYES WERE RED AND HE WAS BLEEDING FROM THE NOSE AND SPITTING UP BLOOD. HE WENT TO THE EMERGENCY ROOM WHERE HE WAS BLURRED VISION, HEADACHES, AND BLACK EYES BELIEVED TO BE CAUSED BY THE GRAVITATIONAL FORCE GENERATED BY THE SPACEBALL RIDE RELEASED WHILE THE RIDE WAS IN OPERATION AND THEY WERE EJECTED. THE RIDE ROTATED ABOUT A CENTRAL MOTOR OVER A CIRCULAR TRACK. SURROUNDED RIDE TWIRLED BY HAND BY THE RIDE ATTENDANT. USES THE WEIGHT AND FORCE OF THE RIDER TO SPIN THE PLASTIC GLOBE RIDE. VICTIM, DIZZY AND THE DOWN AND LOCK POSITION WHEN THE CAR ELEVATED ABRUPTLY APPROXIMATELY 10 FEET IN THE AIR. PROBABLE PRODUCT MALFUNCTION AND LOCK POSITION WHEN THE CAR ELEVATED ABRUPTLY APPROXIMATELY 10 FEET IN THE AIR. PROBABLE PRODUCT MALFUNCTION AND LAMISEMENT RIDE. THIS AMUSEMENT RIDE WAS LOCATED IN THE PLAY AREA OF A RESTAURANT. NO DIJURIES OCCURRED.

LOOSE FROM ITS CENTER SPINDLE. THE TWO CARS LANDED APPROXIMATELY 4 FT. FROM THE RIDE. EXTENDED HANDS AND TOUCHED A STRING OF ELECTRIC LIGHTS THAT WAS STRUNG ACROSS THE TOP METAL BAR OF THE RIDE. SHE WAS BURNED BY LOCAL CARNIVAL. THE VICTIM WAS THROWN OR FELL FROM HER SEAT DURING THE OPERATION OF THE RIDE AND BECAME TRAPPED BETWEEN THE SEAT AND TOTAL OF 25 RIDERS WERE INJURED WITH VARIOUS THERMAL BURNS. SUDDENLY DROPPED AND CAME IN CONTACT WITH THE BASE OF THE RIDE. INVESTIGATION FOUND THAT TWO MUTS HAD NOT BEEN SECURED TO THE SHAFT LARGE CYNDRICAL PIN IN PLACE THAT HELD THE END OF THE ARM ONTO THE TECENTRIC OF THE AMUSEMENT RIDE FELL OUT OF PLACE. THIS ACTION ONTO A RIDE EMPLOYEE VICTIM WAS TAKEN TO A HOSPITAL AND KEPT OVER MIGHT FOR OBSERVATION. THE RIDE OWNER HAS ALL LAP BARS CHARVED 15 36 MANUALLY POWERED BY THE RIDE OPERATOR AT A HIGH RATE OF SPEED. THE VICTIM RECOVERED FROM HIS INJURIES WITHIN 3 WEEKS THE APPARATUS TO STOP NO MEDICAL ATTENTION WAS REOUTED 38 AMUSEMENT RIDE. THE MOTION OF THE RIDE SPUNTHE VICTIMS BODY AT A HIGH RATE OF SPEED. THE VICTIM HAS RECOVERED FROM HIS EYE INJURIES HELICAPTER RIDE. HE TOUCHED THE RIDE FENCE SUFFERING AN ELECTRIC SHOCK TO ALL PARTS OF BODY. VICTIM WAS TAKEN TO THE HOSPITAL CHURCH CARNIVAL. RIDE USERS ARE NOT ALLOWED TO STAND IN THE CARS TO THE RIDE, AND THE RIDE OPERATOR HAD PREVIOUSLY WARNED THE VICTIM NOT AT A COMMUNITY FAIR. INVESTIGATING OFFICIALS DETERMINED THAT THE RIDE HAD BEEN INFROPERLY SET UP. CAUSING THE SEAT TO TILL FORWARD AND WHEN A HOLD DOWN STAKE FROM THE RIDE'S DRIVE TRAIN LOOSENED FROM THE GROUND AND BECAME ENTANGLED IN A DRIVE CABLE CAUSING THE RIDE TO AN 43 EXITING THE CAR HE WAS SEATED IN SOMEBODY STARTED THE RIDE MOVING HE WAS SWEPT BENEATH THE ARM THAT THE CAR EXTENDED FROM 44 BUTTON WHICH RE STARTED THE RIDE AND THE SWEEP OF THE RIDE CAUGHT AND DRAGGED THE VICTIM 45 AUTHORITIES CONCLUDED THE ATTENDANT FAILED TO PROPERLY SECURE THE SAFETY LAP BAR LUNKNOWN PRIOR TO THE ACCIDENT INVOLVING TWO CHILDREN FOLD AND THREE YEARS OF AGE. THESE BOYS WERE RIDING ON THE RIDE, WHEN THE "TUB" CAR FRACTURE TO HER LEFT FEMUR. THE OTHER TWO CHILDREN WERE TREATED AND RELEASED. THE SIDE CAME UNSECURED FROM ITS MOORING ON A GUSTY DAY SEEK MEDICAL TREATMENT. 4 DAYS LATER, THE VICTIM BECAME ILL AND LAPSED INTO A COMA. HE WAS ADMITTED TO THE HOSPITAL WITH A BRAIN LOOSE STRUCK A CAR BELOW IT, AND THEN WEDGED AGAINST SUPPORTS. THE INVESTIGATION REVEALED THAT, ON 06/2293, AT APPROX 8.15 PM, A FERRIS 40 RIDE. THE VICTIM FELL ONTO A STEEL HYDRAULIC TANK ON THE TRANSPORT TRAILER SECTION OF THE RIDE. THE VICTIM DIED THE NEXT DAY OF HEAD 51 PRESSING AN EMERGENCY BUTTON. AFTER HEARING A THIMPING SOUND, AMANATING FROM THIS RIDE, WHICH WAS SUBSEQUENTLY FOUND TO BE CAUSED AMBISEMENT RIDE TRAIN OVERTURNED, SPILLING THE RIDERS ONTO THE GROUND CONNSELOR, AND THEY WERE RIDING AN AMUSEMENT RIDE AT A STATE FAIR, WHICH LOOKS SIMILAR TO TWO HAMMERS THAT APPARENTLY SWING LIKE A SPACE CAPSULES HE WAS ALONE IN THIS OPEN CAPSULE AFTER MAKING SEVERAL REVOLUTIONS THE METAL ARM SUPPORTING THE VICTIM'S SPACE
TOP HER SEAT. THE DOCTORS UNSUCCESSFULLY ATTEMPTED TO REATTACH HER SCALP, AND THE VICTIM WILL HAVE A PERMANENT DISFIGUREMENT. 57 THE VICTM STATED THAT HE WAS SEATED ALONE ON THE INSIDE OF THE SEAT WITH BOTH FEET ON THE FLOORBOARD AND THE LAP BAR IN PLACE WHEN HE 42 BAR IN THE CAR WAS DESIGNED TO RESTRAIN THE LARGEST OCCUPANT. THE VICTIM HAD BEEN STANDING UP WHILE THE RIDE WAS IN MOTION. THE 59 SEATS TO THE BOARDWALK WHEN THE LAP BAR SEPARATED FROM THE RIDE CAR AT THE JUNCTION OF THE LAP BAR/ PRVOT ATTACHMENT. ONE VICTIM
ON HIS WAY HOME HE DETERIORATED AND WAS TAKEN TO A HOSPITAL WHERE HE DIED THE NEXT DAY, OFFICIAL CAUSE OF DEATH WAS COMPLICATIONS OF 60 61 THE "BICYCLE" PORTION OF HIS AMUSEMENT RIDE IN AN ATTEMPT TO STOP IT. THE INCIDENT OCCURRED WHEN A CUSTOMER, A 30 YEAR OLD FEMALE FESTIVAL AT A CITY PARK. SEVERAL OF THE 12 RIDERS CONSISTING OF 2 ADULTS (37M, 28F) AND 10 CHILDREN (16F, 14F, 12F, 8F, 8M, 6F, 5F, WERE FIECTED FROM THEIR CAR. THE 15 YEAR OLD FEMALE WAS PRONOUNCED DOA AND THE OTHER TWO VICTIMS WERE TREATED AND RELEASED. THE CAUSE THE RIDE WAS IN OPERATION RELEASED THE SAFETY BAR TO THE RIDE BEFORE THE RIDE CAME TO A COMPLETE STOP THE BACK OF THE HEAD BY EITHER ANOTHER SEAT OR THE FRAME OF THE RIDE. THE VICTIM RECEIVED SERIOUS HEAD INJURIES AND WAS RUSHED TO A IT 4 PASSENGERS ON THE RIDE WERE INTURED. THE CAUSE WAS FOUND TO BE A MISSING R KEY AND A RESULTING BROKEN OR MISSING CONNECTOR PIN ON HIS WAY HOME HE DETERIORATED AND WAS TAKEN TO A HOSPITAL WHERE HE DIED THE NEXT DAY. OFFICIAL CAUSE OF DEATH WAS COMPLICATIONS OF THERE WERE NO INJURIES 70 THE VICTIM FELL OUT OF HIS SEAT AND WAS RUN OVER BY THE NEXT TRAIN CAR. THE VICTIM WAS PRONOUNCED DEAD AT THE HOSPITAL. INVESTIGATING WAS MISSING THE PROPER RESTRAINTS. SHE WAS TRANSPORTED TO THE HOSPITAL TREATED AND RELEASED PARK RIDE. SHE WAS HOSPITALIZED FOR OVER A WEEK AND UNDERWENT SURGERY CAUSE OF DEATH OF THE VICTIM WAS DROWNING YEAR OLD MALE WERE RIDING IN RELEASED. THE FIRST THREE VICTIMS WERE THROWN TO THE GROUND. THE 4TH RIDER HELD ON UNTIL THE RIDE STOPPED CHURCH CARNITYAL. RIDE USERS ARE NOT ALLOWED TO STAND IN THE CARS TO THE RIDE, AND THE RIDE OPERATOR HAD PREVIOUSLY WARNED THE VICTIM NOT 76 OPENED. THE FERRIS WHEEL WAS STOPPED WITH THE VICTIM'S SEAT IN THE TOPMOST POSITION, THE LAP BELT HELD THE VICTIMS IN PLACE UNTIL THE OPERATION OF THE RIDE. THE VICTIM WAS SEATED IN A CAR WITH HER 70 YEAR OLD GRANDFATHER AT THE TIME WHEN HER GRANDFATHER LIFTED HER LIP FROM BEHIND BY ANOTHER ROLLER COASTER CAR. THE 13 YEAR OLD FEMALE WAS TREATED AND RELEASED FROM A LOCAL HOSPITAL THE DOWN AND LOCK POSITION WHEN THE CAR ELEVATED ABRUFTLY APPROXIMATELY 10 FEET IN THE AIR PROBABLE PRODUCT MALFUNCTION AND
FREE FROM THE SECURITY BAR WHILE IN MOTION. HE WAS THROWN FROM THE RIDE AND LANDED ON HIS SIDE ON A HARD SURFACE. HE SUFFERED A BROKEN
AND SEMENT RIDE FOR APPROXIMATELY 1.1/2 HOURS. THE RIDE WAS STOPPED BY THE OPERATOR WHEN A STABILIZING ROD. WHICH LIMITS THE VEHICLES. SEVERE HEADACHES. DIZZINESS AND MEMORY LOSS AS A RESULT OF THIS INCIDENT

Ζ

	Narraine (continued)
	TO THE HOSPITAL BY AN AMBULANCE. THE INCIDENT HAPPENED AT A CARNIVAL IN A PARKING LOT OF A SHOPPING CENTER.
	ABOVE THE RESTRAINING BAR SO SHE COULD SEE BETTER AT THE SAME TIME THE CAR BEGAN TO SPIN ELECTING THE VICTUM TO THE GROUND SHE WAS
3	DOWNWARDS THE EIGHTEEN YEAR OLD SUFFERED A WHIPLASH OF HIS NECK
4.	HANDLEBAAS TIGHTLY HELD DOWN THE RIDE STARTED UP AND ON THE JAD TIME AROUND CAME LOOSE THE TUB CAME OFF WHEN THE PIN SECURING IT TO THE
	GIRL DID NOT SEEK ANY MEDICAL TREATMENT
6	ALMOST 30 MINUTES UNTIL THE RIDE WAS MANUALLY LOWERED. THERE WERE 33 PEOPLE TREATED FOR NAUSEA. INCLUDING TWO THAT WENT TO A HOSPITAL AND
7	THAT SURROUNDS THE RIDE ONE PASSENGER SUFFERED A CUT LIP (MINOR)
	THE MISHAP
1	
	HOSPITAL EMERGENCY ROOM WHERE THEY WERE TREATED AND RELEASED STATE OF WILS INVESTIGATING AND WILL MONITOR REPAIRS BY THE RIDE OWNER
11	APPARENTLY STRUCK HIS ASKLE RESULTING IN THE FRACTURE
12	
13	
14	
15	THE VICTIMS WERE RIDING TO FALL TO THE GROUND
	THE VICTORS WERE REDING TO FALL TO THE GROUND
16	RECEIVED MINOR DULKIES. A RIDE PANEL WHERE THE THREE MOST SERIOUSLY HURT VICTIM'S WERE RIDING CAME OFF THE RIDE WHEN A FLOORPIN AND FLOOR
118	STATE OFFICIALS REVEALED THE DIPROPER INSTALLATION OF A MECHANICAL DEVICE CAUSED THE RIDE TO FAIL AND RESULT IN THE INCIDENT
19	STATE OFFICIALS REVEALED THE IMPROPER INSTALLATION OF A RECOGNICAL DEVICE CAUSED THE RUDE TO FALL AND RESULT IN THE INCIDENT
20	
21	WERE BEING HELD ON AN ANTI-ROLLBACK SECTION OF THE TRACK ALL 14 PASSENGERS ON THE CARS WERE SENT TO THE HOSPITAL FOR TREATMENT OF
	WERE BEING HELD ON AN ANTI-ROLLBACK SECTION OF THE TRACK ALL 14 PASSENGERS ON THE CARS WERE SENT TO THE HOSPITAL FOR TREATMENT OF
22	
23	
24	EXAMINED AND RELEASED
25	
	BY A RAILED WALKWAY. THE VICTIMS WERE DRAGGED ALONG THIS WALKWAY STRIKING THEIR HEADS
27	NASEOUS AFTER THE RIDE WAS SEEN AT A LOCAL MEDICAL FACILITY AND RELEASED WITH NO INJURY DETERMINED
28	OPERATOR EAROR CONTRIBUTED TO THIS INCIDENT
29	
30	
	THE ELECTRICAL WINE OF THE LIGHT SET. SHE WAS TAKEN TO ER OF NEARBY HOSPITAL AND TREATED FOR 2ND DEGREE BURN ON HIS HAND
32	THE RIDE'S OUTER WALL. THE VICTIM RECOVERED FROM HER FRACTURE IN JURIES AND IS UNDERGOING PHYSICAL THERAPY FOR THE NERVE INJURY. AN
33	
	HOLDING THE POD OF CARS SENDING IT TO THE GROUND. THE OPERATOR WAS CITED FOR FAILURE TO PROPERLY ASSEMBLE THE RUDE
35	CAUSED THE STEEL PIN TO DROP AND THE ARM & CAR FELL TO THE GROUND THE 19 YEAR OLD VICTOM SUFFERED A FRACTURED NECK & BACK. SHE WAS
36	DOWN AT HIS TIME. THE RIDE WAS IN REVEASE WHEN THE ACCIDENT OCCURRED. THE RIDE WILL NOW ONLY OPERATE IN THE FORWARD DIRECTION
37	
78	
	SINCE THE ACCIDENT. THE VICTIM IS UNDERGOING TREATMENT TO DETERMINE THE CAUSE OF AN EQUILLBRIUM PROBLEM RESULTING FROM THE ACCIDENT. THE
	EMEAGENCY ROOM. HE WAS OBSERVED FOR AN (1) HOUR, AFTERWARD HE WAS TREATED & RELEASED WITHOUT ANY FURTHER MEDICAL TREATMENT
41	TO STAND IN THE CAR ATTER HE (OPERATOR) STOPPED THE RIDE WHEN THE VICTIM STOOD IN THE SECOND TIME THE OPERATOR ATTEMPTED TO
42	THE LAP BAN TO RELEASE BOTH VICTIMS WERE TREATED AND RELEASED FROM A LOCAL HOSPITAL
43	ABRUPT STOP
4	DATE 1 STATE
43	<del></del>
46	SET SEAM THE MARK TO AME AT THE BIRL DETITION DECISION SERVICES AND RECEIVED AND RE
47	FELL FROM THE MAIN FRAME OF THE RIDE. NEITHER BOY RECEIVED PERMANENT INJURIES HOWEVER ONE RECEIVED A BROKEN NOSE AND THE OTHER FACIAL.
47	CAUSING IT TO BE LIFTED OFF THE GROUND TO A VERTICAL POSITION. THE CHILDREN AND THE RIDE WERE CATAPULTED INTO A NEARBY TREE
47	CAUSING IT TO BE LIFTED OFF THE GROUND TO A VERTICAL POSITION. THE CHILDREN AND THE RIDE WERE CATAPULTED INTO A NEARBY TREE HEMORRHAGE. THE VICTIM WAS PLACED ON LIFE SUPPORT AND DIED WITHIN 24 HOURS OF THE REMOVAL OF LIFE SUPPORT.
47 48 49 50	CAUSING IT TO BE LIFTED OFF THE GROUND TO A VERTICAL POSITION. THE CHILDREN AND THE RIDE WERE CATAPULTED INTO A NEARBY TREE HEMORRHAGE. THE VICTIM WAS PLACED ON LIFE SUPPORT AND DIED WITHIN 24 HOURS OF THE REMOVAL OF LIFE SUPPORT WHEEL AT A CHURCH CARNIVAL WAS ROTATING IN A COUNTERCLOCKWISE DIRECTION WHEN IT STRUCK A METAL RACKING SUPPORT TOWER ON THE
47 48 49 50 51	CAUSING IT TO BE LIGTED OFF THE GROUND TO A VERTICAL POSITION. THE CHILDREN AND THE RIDE WERE CATAPULTED INTO A NEARBY TREE HEMORRHAGE. THE VICTIM WAS PLACED ON LIFE SUPPORT AND DIED WITHIN 24 HOURS OF THE REMOVAL OF LIFE SUPPORT TOWER ON THE WHEEL AT A CHURCH CARNIVAL WAS ROTATING D. A COUNTERCL OCKWISC DIRECTION WHEN IT STRUCK A METAL TRACKING SUPPORT TOWER ON THE INVARIES ASSOCIATED WITH THE FALL. THE RIDE WAS BEING OPERATED ON A LOCAL FAIRGROUND SITE AT THE TIME OF THE INCIDENT
47 48 49 50 51 53	CAUSING IT TO BE LIFTED OFF THE GROUND TO A VERTICAL POSITION. THE CHILDREN AND THE RIDE WERE CATAPULTED INTO A NEARBY TREE HEMORRHAGE. THE VICTIM WAS PLACED ON LIFE SUPPORT AND DIED WITHIN 24 HOURS OF THE REMOVAL OF LIFE SUPPORT WHEEL AT A CHURCH CARNIVAL WAS ROTATING IN A COUNTERCLOCKWISE DIRECTION WHEN IT STRUCK A METAL RACKING SUPPORT TOWER ON THE
47 48 49 50 51 52 53	CAUSING IT TO BE LID TED OFF THE GROUND TO A VERTICAL POSITION. THE CHILDREN AND THE RIDE WERE CATAPULTED INTO A NEARBY TREE HEMORRHAGE. THE VICTIM WAS PLACED ON LIFE SUPPORT AND DIED WITHIN 24 HOURS OF THE REMOVAL OF LIFE SUPPORT WHEEL AT A CHURCH CARNIVAL WAS ROTATING IN A COUNTERCLOCKWISE DIRECTION WHEN IT STRUCK A METAL RACKING SUPPORT TOWER ON THE INJURIES ASSOCIATED WITH THE FALL. THE RIDE WAS BEING OPERATED ON A LOCAL FAIRGROUND SITE AT THE TIME OF THE INCIDENT BY A FRACTURED RAIL OF THIS RIDE.
47 48 49 50 51 52 53 54	CAUSING IT TO BE LIGTED OFF THE GROUND TO A VERTICAL POSITION. THE CHILDREN AND THE RIDE WERE CATAPULTED INTO A NEARBY TREE HEMORRHAGE. THE VICTIM WAS PLACED ON LIFE SUPPORT AND DIED WITHIN 24 HOURS OF THE REMOVAL OF LIFE SUPPORT TOWER ON THE WHEEL AT A CHURCH CARNIVAL WAS ROTATING D. A COUNTERCL OCKWISC DIRECTION WHEN IT STRUCK A METAL TRACKING SUPPORT TOWER ON THE INVARIES ASSOCIATED WITH THE FALL. THE RIDE WAS BEING OPERATED ON A LOCAL FAIRGROUND SITE AT THE TIME OF THE INCIDENT
47 48 49 50 51 52 53 54 55	CAUSING IT TO BE LID TED OFF THE GROUND TO A VERTICAL POSITION. THE CHILDREN AND THE RIDE WERE CATAPULTED INTO A NEARBY TREE HEMORRHAGE. THE VICTOM WAS PLACED ON LIFE SUPPORT AND DIED WITHIN 24 HOURS OF THE REMOVAL OF LIFE SUPPORT WHEELAT A CHURCH CARNIVAL WAS ROTATING ID. A COUNTERCLOCKWISE DIRECTION WHEN IT STRUCK A METAL RACKING SUPPORT TOWER ON THE INJURIES ASSOCIATED WITH THE FALL. THE RIDE WAS BEING OPERATED ON A LOCAL FAIRGROUND SITE AT THE TIME OF THE INCIDENT BY A FRACTURED RAIL OF THIS RIDE  PENDULUM. IN OPPOSITE DIRECTIONS. AS THE RIDE WAS OPERATING THE 13 YEAR OLD GIRL PANICKED. AND SHE WIGGLED-OUT FROM UNDER HER.
47 48 49 50 51 52 53 54 55 56	CAUSING IT TO BE LID TED OFF THE GROUND TO A VERTICAL POSITION. THE CHILDREN AND THE RIDE WERE CATAPULTED INTO A NEARBY TREE HEMORRHAGE. THE VICTIM WAS PLACED ON LIFE SUPPORT AND DIED WITHIN 24 HOURS OF THE REMOVAL OF LIFE SUPPORT WHEEL AT A CHURCH CARNIVAL WAS ROTATING IN A COUNTERCLOCKWISE DIRECTION WHEN IT STRUCK A METAL RACKING SUPPORT TOWER ON THE INJURIES ASSOCIATED WITH THE FALL. THE RIDE WAS BEING OPERATED ON A LOCAL FAIRGROUND SITE AT THE TIME OF THE INCIDENT BY A FRACTURED RAIL OF THIS RIDE.
47 44 46 50 51 52 53 54 55 54 57	CAUSING IT TO BE LID TED OFF THE GROUND TO A VERTICAL POSITION. THE CHILDREN AND THE RIDE WERE CATAPULTED INTO A NEARBY TREE HEMORRHAGE. THE VICTIM WAS PLACED ON LIFE SUPPORT AND DIED WITHIN 24 HOURS OF THE REMOVAL OF LIFE SUPPORT WHEEL AT A CHUNCH CARNIVAL WAS ROTATING IN A COUNTERCLOCKWISE DIRECTION WHEN IT STRUCK A METAL RACKING SUPPORT TOWER ON THE INJURIES ASSOCIATED WITH THE FALL. THE RIDE WAS BEING OPERATED ON A LOCAL FAIRGROUND SITE AT THE TIME OF THE INCIDENT BY A FRACTURED RAIL OF THIS RIDE  PENDULUM. IN OPPOSITE DIRECTIONS. AS THE RIDE WAS OPERATING. THE 13 YEAR OLD GIRL PANICKED, AND SHE WIGGLED-OUT FROM UNDER HER  CAPSULE DROPPED OF FELL ABOUT 5-7 FEET TO THE GROUND. BEFORE THE OPERATOR COULD STOP THE RIDE. THE VICTIM, SEAT RESTRAINED IN THE
47 44 46 50 51 52 53 54 55 56 57 58	CAUSING IT TO BE LID TED OFF THE GROUND TO A VERTICAL POSITION. THE CHILDREN AND THE RIDE WERE CATAPULTED INTO A NEARBY TREE HEMORRHAGE THE VICTIM WAS PLACED ON LIFE SUPPORT AND DIED WITHIN 24 HOURS OF THE REMOVAL OF LIFE SUPPORT TOWER ON THE WHEEL AT A CHURCH CARNIVAL WAS ROTATING ID. A COUNTERCL OCKWISE OF HEM THE RIDE WE LIR TACKING SUPPORT TOWER ON THE INJURIES ASSOCIATED WITH THE FALL. THE RIDE WAS BEING OPERATED ON A LOCAL FAIRGROUND SITE AT THE TIME OF THE INCIDENT BY A FRACTURED RAIL OF THIS RIDE  PENDULUM. IN OPPOSITE DIRECTIONS. AS THE RIDE WAS OPERATING. THE 13 YEAR OLD GIRL PANICKED AND SHE WIGGLED-OUT FROM UNDER HER  CAPSULE, DROPPED OF FELL ABOUT 5-7 FEET TO THE GROUND. BEFORE THE OPERATOR COULD STOP THE RIDE. THE VICTUM, SEAT RESTRAINED IN THE WAS ELECTED. CAUSING HIS FOOT TO CONTACT THE UPRIGHT SUPPORT ON THE RIDE BOARDWALK.
47 48 49 50 51 52 53 54 55 56 57 58	CAUSING IT TO BE LID TED OFF THE GROUND TO A VERTICAL POSITION. THE CHILDREN AND THE RIDE WERE CATAPULTED INTO A NEARBY TREE HEMORRHAGE. THE VICTIM WAS PLACED ON LIFE SUPPORT AND DIED WITHIN 24 HOURS OF THE REMOVAL OF LIFE SUPPORT WHEEL AT A CHURCH CARNIVAL WAS ROTATING IN A COUNTERCLOCKWISE DIRECTION WHEN IT STRUCK A METAL RACKING SUPPORT TOWER ON THE INJURIES ASSOCIATED WITH THE FALL. THE RIDE WAS BEING OPERATED ON A LOCAL FAIRGROUND SITE AT THE TIME OF THE INCIDENT BY AFRACTURED RAIL OF THIS RIDE  PENDULUM. IN OPPOSITE DIRECTIONS. AS THE RIDE WAS OPERATING THE 13 YEAR OLD GIRL PANICKED. AND SHE WIGGLED-OUT FROM UNDER HER  CAPSULE DROPPED OF FELL ABOUT 5-7 FEET TO THE GROUND BEFORE THE OPERATOR COULD STOP THE RIDE. THE VICTIM, SEAT RESTRAINED IN THE  WAS ELECTED. CAUSING HIS FOOT TO CONTACT THE UPRIGHT SUPPORT ON THE RIDE BOARDWALK.  OPERATOR HAD WALNED HER TO STAY SEATED. THE VICTIM APPARENTLY FELL UNDER THE CAR AND WAS DRAGGED FOR 3M OF A REVOLUTION BEFORE THE
47 48 49 50 51 53 53 54 55 56 57 58 58 59 60	CAUSING IT TO BE LID TED OFF THE GROUND TO A VERTICAL POSITION. THE CHILDREN AND THE RIDE WERE CATAPULTED INTO A NEARBY TREE HEMORRHAGE. THE VICTIM WAS PLACED ON LIFE SUPPORT AND DIED WITHIN 24 HOURS OF THE REMOVAL OF LIFE SUPPORT WHEEL AT A CHURCH CARNIVAL WAS ROTATING IN A COUNTERCLOCKWISE DIRECTION WHEN IT STRUCK A METAL RACKING SUPPORT TOWER ON THE INJURIES ASSOCIATED WITH THE FALL. THE RIDE WAS BEING OPERATED ON A LOCAL PAIRGROUND SITE AT THE TIME OF THE INCIDENT BY A FRACTURED RAIL OF THIS RIDE  PENDULUM, IN OPPOSITE DIRECTIONS. AS THE RIDE WAS OPERATING THE 13 YEAR OLD GIRL PANICKED. AND SHE WIGGLED-OUT FROM UNDER HER  CAPSULE, DROPPED OF FELL ABOUT 3-7 FEET TO THE GROUND BEFORE THE OPERATOR COULD STOP THE RIDE. THE VICTUM, SEAT RESTRAINED IN THE  WAS ELECTED. CAUSING HIS FOOT TO CONTACT THE UPRIGHT SUPPORT ON THE RIDE BOARDWALK.  OPERATOR HAD WARNED HER TO STAY SEATED. THE VICTUM APPARENTLY FELL UNDER THE CAR AND WAS DRAGGED FOR 3M OF A REVOLUTION BEFORE THE  SUSTAINED A BROKEN ANKLE, THE OTHER A BROKEN LEG.
47 48 49 50 51 52 53 54 55 56 57 58 59	CAUSING IT TO BE LID TED OFF THE GROUND TO A VERTICAL POSITION. THE CHILDREN AND THE RIDE WERE CATAPULTED INTO A NEARBY TREE HEMORRHAGE THE VICTIM WAS PLACED ON LIFE SUPPORT AND DIED WITHIN 24 HOURS OF THE REMOVAL OF LIFE SUPPORT TOWER ON THE WHEEL AT A CHURCH CARNIVAL WAS ROTATING ID. A COUNTERCLOCKWISE OF THE REMOVAL OF LIFE SUPPORT TOWER ON THE INJURIES ASSOCIATED WITH THE FALL. THE RIDE WAS BEING OPERATED ON A LOCAL FAIRGROUND SITE AT THE TIME OF THE INCIDENT BY A FRACTURED RAIL OF THIS RIDE  PENDULUM. IN OPPOSITE DIRECTIONS. AS THE RIDE WAS OPERATING. THE 13 YEAR OLD GIRL PANICKED AND SHE WIGGLED-OUT FROM UNDER HER  CAPSULE, DROPPED OF FELL ABOUT 5-7 FEET TO THE GROUND. BEFORE THE OPERATOR COULD STOP THE RIDE. THE VICTUM, SEAT RESTRAINED IN THE  WAS ELECTED. CAUSING HIS FOOT TO CONTACT THE UPRIGHT SUPPORT ON THE RIDE BOARDWALK.  OPERATOR HAD WASNED HER TO STAY SEATED. THE VICTUM APPARENTLY FELL UNDER THE CAR AND WAS DRAGGED FOR 3M OF A REVOLUTION BEFORE THE SUSTAINED A BROKEN ANKLE, THE OTHER A BROKEN LEG.  SUSPAINED. HE PROVED.
47 46 40 50 51 51 52 53 53 54 55 56 57 58 59 60	CAUSING IT TO BE LID TED OFF THE GROUND TO A VERTICAL POSITION. THE CHILDREN AND THE RIDE WERE CATAPULTED INTO A NEARBY TREE HEMORRHAGE THE VICTIM WAS PLACED ON LIFE SUPPORT AND DIED WITHIN 24 HOURS OF THE REMOVAL OF LIFE SUPPORT WHEEL AT A CHURCH CARNIVAL WAS ROTATING DIE A COUNTERLOCKWISE DIRECTION WHEN IT STRUCK A METAL TRACKING SUPPORT TOWER ON THE INVARIES ASSOCIATED WITH THE FALL. THE RIDE WAS BEING OPERATED ON A LOCAL FAIRGROUND SITE AT THE TIME OF THE INCIDENT BY A FRACTURED RAIL OF THIS RIDE  PENDULUM. IN OPPOSITE DIRECTIONS. AS THE RIDE WAS OPERATING THE 13 YEAR OLD GIRL PANICKED AND SHE WIGGLED-OUT FROM UNDER HER  CAPSULE DROFFED OF FELL ABOUT 5-7 FEET TO THE GROUND BEFORE THE OPERATOR COULD STOP THE RIDE. THE VICTUM, SEAT RESTRAINED IN THE  WAS ELECTED CAUSING HIS FOOT TO CONTACT THE UPRIGHT SUPPORT ON THE RIDE BOARDWALK.  OPERATOR HAD WASNED HER TO STAY SEATED. THE VICTUM APPARENTLY FELL UNDER THE CAR AND WAS DRAGGED FOR 3M OF A REVOLUTION BEFORE THE  SUSTAINED A BROKEN ANKLE, THE OTHER A BROKEN LEG  SUSTAINED A BROKEN ANKLE, THE OTHER A BROKEN LEG  SUBDURAL REMATOMA  LOST CONTROL OF THE BICYCLE. AND BEGAN TO TRAVEL BACKWARDS ON THE AMUSEMENT RIDE TRACK. THE CUSTOMER SUSTAINED ABRASIONS TO LOWER
47 46 40 50 51 52 53 54 55 56 57 58 59 60 61 62 63	CAUSING IT TO BE LIFTED OFF THE GROUND TO A VERTICAL POSITION. THE CHILDREN AND THE RIDE WERE CATAPULTED INTO A NEARBY TREE HEMORRHAGE. THE VICTIM WAS PLACED ON LIFE SUPPORT AND DIED WITHIN 24 HOURS OF THE REMOVAL OF LIFE SUPPORT WHEEL AT A CHURCH CARNIVAL WAS ROTATING IN A COUNTERCLOCKWISE DIRECTION WHEN IT STRUCK A METAL RACKING SUPPORT TOWER ON THE INJURIES ASSOCIATED WITH THE FALL. THE RIDE WAS BEING OPERATED ON A LOCAL FAIRGROUND SITE AT THE TIME OF THE INCIDENT BY AFRACTURED RAIL OF THIS RIDE  PENDULUM. IN OPPOSITE DIRECTIONS. AS THE RIDE WAS OPERATING THE 13 YEAR OLD GIRL PANICKED. AND SHE WIGGLED-OUT FROM UNDER HER  CAPSULE DROPFED OF FELL ABOUT 5-7 FEET TO THE GROUND BEFORE THE OPERATOR COULD STOP THE RIDE. THE VICTIM, SEAT RESTRAINED IN THE  WAS ELECTED. CAUSING HIS FOOT TO CONTACT THE UPRIGHT SUPPORT ON THE RIDE BOARDWALK.  OPERATOR HAD WALNED HER TO STAY SEATED. THE VICTIM APPARENTLY FELL UNDER THE CAR AND WAS DRAGGED FOR 3M OF A REVOLUTION BEFORE THE  SUSTAINED A BROKEN ANKLE. THE OTHER A BROKEN LEG.  SUBDURAL HEMATOMA.  LOST CONTROL OF THE "BICYCLE" AND BEGAN TO TRAVEL BACKWARDS ON THE AMUSEMENT RIDE TRACK. THE CUSTOMER SUSTAINED ABRASIONS TO LOWER.  15 25 25 10 ON THE RIDE SUFFERED INJURIES RANGING FROM NECK / BACK STRAINS CONTUSIONS TO ARMS / LEGS. TO ONE VICTIM WHO SUFFERED A
47 48 49 40 50 51 53 53 54 55 55 57 58 59 60 61 62	CAUSING IT TO BE LID TED OFF THE GROUND TO A VERTICAL POSITION. THE CHILDREN AND THE RIDE WERE CATAPULTED INTO A NEARBY TREE HEMORRHAGE THE VICTIM WAS PLACED ON LIFE SUPPORT AND DIED WITHIN 24 HOURS OF THE REMOVAL OF LIFE SUPPORT WHEEL AT A CHURCH CARNIVAL WAS ROTATING DIE A COUNTERLOCKWISE DIRECTION WHEN IT STRUCK A METAL TRACKING SUPPORT TOWER ON THE INVARIES ASSOCIATED WITH THE FALL. THE RIDE WAS BEING OPERATED ON A LOCAL FAIRGROUND SITE AT THE TIME OF THE INCIDENT BY A FRACTURED RAIL OF THIS RIDE  PENDULUM. IN OPPOSITE DIRECTIONS. AS THE RIDE WAS OPERATING THE 13 YEAR OLD GIRL PANICKED AND SHE WIGGLED-OUT FROM UNDER HER  CAPSULE DROFFED OF FELL ABOUT 5-7 FEET TO THE GROUND BEFORE THE OPERATOR COULD STOP THE RIDE. THE VICTUM, SEAT RESTRAINED IN THE  WAS ELECTED CAUSING HIS FOOT TO CONTACT THE UPRIGHT SUPPORT ON THE RIDE BOARDWALK.  OPERATOR HAD WASNED HER TO STAY SEATED. THE VICTUM APPARENTLY FELL UNDER THE CAR AND WAS DRAGGED FOR 3M OF A REVOLUTION BEFORE THE  SUSTAINED A BROKEN ANKLE, THE OTHER A BROKEN LEG  SUSTAINED A BROKEN ANKLE, THE OTHER A BROKEN LEG  SUBDURAL REMATOMA  LOST CONTROL OF THE BICYCLE. AND BEGAN TO TRAVEL BACKWARDS ON THE AMUSEMENT RIDE TRACK. THE CUSTOMER SUSTAINED ABRASIONS TO LOWER
47 48 46 46 50 51 52 53 54 55 57 58 59 60 61 62 63	CAUSING IT TO BE LIFTED OFF THE GROUND TO A VERTICAL POSITION. THE CHILDREN AND THE RIDE WERE CATAPULTED INTO A NEARBY TREE HEMORRHAGE. THE VICTIM WAS PLACED ON LIFE SUPPORT AND DIED WITHIN 24 HOURS OF THE REMOVAL OF LIFE SUPPORT WHEEL AT A CHURCH CARNIVAL WAS ROTATING IN A COUNTERCLOCKWISE DIRECTION WHEN IT STRUCK A METAL RACKING SUPPORT TOWER ON THE INJURIES ASSOCIATED WITH THE FALL. THE RIDE WAS BEING OPERATED ON A LOCAL FAIRGROUND SITE AT THE TIME OF THE INCIDENT BY AFRACTURED RAIL OF THIS RIDE  PENDULUM. IN OPPOSITE DIRECTIONS. AS THE RIDE WAS OPERATING THE 13 YEAR OLD GIRL PANICKED. AND SHE WIGGLED-OUT FROM UNDER HER  CAPSULE DROPFED OF FELL ABOUT 5-7 FEET TO THE GROUND BEFORE THE OPERATOR COULD STOP THE RIDE. THE VICTIM, SEAT RESTRAINED IN THE  WAS ELECTED. CAUSING HIS FOOT TO CONTACT THE UPRIGHT SUPPORT ON THE RIDE BOARDWALK.  OPERATOR HAD WALNED HER TO STAY SEATED. THE VICTIM APPARENTLY FELL UNDER THE CAR AND WAS DRAGGED FOR 3M OF A REVOLUTION BEFORE THE  SUSTAINED A BROKEN ANKLE. THE OTHER A BROKEN LEG.  SUBDURAL HEMATOMA.  LOST CONTROL OF THE "BICYCLE" AND BEGAN TO TRAVEL BACKWARDS ON THE AMUSEMENT RIDE TRACK. THE CUSTOMER SUSTAINED ABRASIONS TO LOWER.  15 25 25 10 ON THE RIDE SUFFERED INJURIES RANGING FROM NECK / BACK STRAINS CONTUSIONS TO ARMS / LEGS. TO ONE VICTIM WHO SUFFERED A
47 48 49 49 50 51 52 53 53 54 55 57 58 59 60 61 62 63 64 64	CAUSING IT TO BE LIB TED OFF THE GROUND TO A VERTICAL POSITION. THE CHILDREN AND THE RIDE WERE CATAPULTED INTO A NEARBY TREE HEMORRHAGE. THE VICTIM WAS PLACED ON LIFE SUPPORT AND DIED WITHIN 24 HOURS OF THE REMOVAL OF LIFE SUPPORT WHEEL AT A CHURCH CARNIVAL WAS ROTATING D. A COUNTERCLOCKWISE DIRECTION WHEN IT STRUCK A METAL TACKING SUPPORT TOWER ON THE INVARIES ASSOCIATED WITH THE FALL. THE RIDE WAS BEING OPERATED ON A LOCAL FAIRGROUND SITE AT THE TIME OF THE INCIDENT BY A FRACTURED RAIL OF THIS RIDE  PENDULUM. IN OPPOSITE DIRECTIONS. AS THE RIDE WAS OPERATING THE 13 YEAR OLD GIRL PANICKED AND SHE WIGGLED-OUT FROM UNDER HER  CAPSULE DROFFED OF FELL ABOUT 5-7 FEET TO THE GROUND BEFORE THE OPERATOR COULD STOP THE RIDE. THE VICTUM SEAT RESTRAINED IN THE  WAS ELECTED. CAUSING HIS FOOT TO CONTACT THE UPRIGHT SUPPORT ON THE RIDE BOARDWALK.  OPERATOR HAD WASVED HER TO STAY SEATED. THE VICTUM APPARENTLY FELL UNDER THE CAR AND WAS DRAGGED FOR 3M OF A REVOLUTION BEFORE THE  SUSTAINED A BROKEN ANKLE, THE OTHER A BROKEN LEG  SUSTAINED A BROKEN ANKLE, THE OTHER A BROKEN LEG  SUBDURAL NEMATOMA  LOST CONTROL OF THE "BICYCLE" AND BEGAN TO TRAVEL BACKWARDS ON THE AMUSEMENT RIDE TRACK. THE CUSTOMER SUSTAINED ABRASIONS TO LOWER  OF DEATH OF THE 13 YEAR OLD VICTIM WAS SEVERE HEAD INJURIES.
47 48 40 40 50 51 52 53 53 54 55 56 57 58 59 60 61 62 63 64 65	CAUSING IT TO BE LIFTED OFF THE GROUND TO A VERTICAL POSITION. THE CHILDREN AND THE RIDE WERE CATAPULTED INTO A NEARBY TREE HEMORRHAGE. THE VICTIM WAS PLACED ON LIFE SUPPORT AND DIED WITHIN 24 HOURS OF THE REMOVAL OF LIFE SUPPORT WHEEL AT A CHURCH CARNIVAL WAS ROTATING IN A COUNTERCLOCKWISE DIRECTION WHEN IT STRUCK A METAL RACKING SUPPORT TOWER ON THE INJURIES ASSOCIATED WITH THE FALL. THE RIDE WAS BEING OPERATED ON A LOCAL FAIRGROUND SITE AT THE TIME OF THE INCIDENT BY AFRACTURED RAIL OF THIS RIDE  PENDULUM. IN OPPOSITE DIRECTIONS. AS THE RIDE WAS OPERATING THE 13 YEAR OLD GIRL PANICKED. AND SHE WIGGLED-OUT FROM UNDER HER  CAPSULE DROPFED OF FELL ABOUT 5-7 FEET TO THE GROUND BEFORE THE OPERATOR COULD STOP THE RIDE. THE VICTIM, SEAT RESTRAINED IN THE  WAS ELECTED. CAUSING HIS FOOT TO CONTACT THE UPRIGHT SUPPORT ON THE RIDE BOARDWALK.  OPERATOR HAD WALNED HER TO STAY SEATED. THE VICTIM APPARENTLY FELL UNDER THE CAR AND WAS DRAGGED FOR 3M OF A REVOLUTION BEFORE THE  SUSTAINED A BROKEN ANKLE. THE OTHER A BROKEN LEG.  SUBDURAL HEMATOMA.  LOST CONTROL OF THE "BICYCLE" AND BEGAN TO TRAVEL BACKWARDS ON THE AMUSEMENT RIDE TRACK. THE CUSTOMER SUSTAINED ABRASIONS TO LOWER.  15 25 25 10 ON THE RIDE SUFFERED INJURIES RANGING FROM NECK / BACK STRAINS CONTUSIONS TO ARMS / LEGS. TO ONE VICTIM WHO SUFFERED A
47 48 40 40 50 51 53 53 54 55 55 56 57 58 59 60 61 62 63 64 65 64	CAUSING IT TO BE LIPTED OFF THE GROUND TO A VERTICAL POSITION. THE CHILDREN AND THE RIDE WERE CATAPULTED INTO A NEARBY TREE HEMORRHAGE. THE VICTIM WAS PLACED ON LIFE SUPPORT AND DIED WITHIN 24 HOURS OF THE REMOVAL OF LIFE SUPPORT. WHEEL AT A CHURCH CARNIVAL WAS ROTATING IN A COUNTERCLOCK WISE DIRECTION. WHEN ITS STAUCK A METAL FACKING SUPPORT TOWER ON THE INJURIES ASSOCIATED WITH THE FALL. THE RIDE WAS BEING OPERATED ON A LOCAL FAIRGROUND SITE AT THE TIME OF THE INCIDENT. BY A FRACTURED RAIL OF THIS RIDE  PENDULUM, IN OPPOSITE DIRECTIONS. AS THE RIDE WAS OPERATING THE 11 YEAR OLD GIRL PANICKED. AND SHE WIGGLED-OUT FROM UNDER HER.  CAPSULE, DROPPED OF FELL ABOUT 5-7 FEET TO THE GROUND. BEFORE THE OPERATOR COULD STOP THE RIDE. THE VICTIM, SEAT RESTRAINED IN THE  WAS EJECTED. CAUSING HIS FOOT TO CONTACT THE UPRIGHT SUPPORT ON THE RIDE BOARDWALK.  OPERATOR HAD WARNED HER TO STAY SEATED. THE VICTIM APPARENTLY FELL UNDER THE CAR AND WAS DRAGGED FOR 3M OF A REVOLUTION BEFORE THE SUBSTAINED A BROKEN. ANKLE, THE OTHER A BROKEN LEG.  SUBDURAL HEMATOMA.  LOST CONTROL OF THE BUSYFERED INJURIES RANGING FROM MECK / BACK STRAINS CONTUSIONS TO ARMS / LEGS. TO ONE VICTIM WHO SUFFERED A  OF DEATH OF THE 19 YEAR OLD VICTIM WAS SEVERE HEAD INJURIES.  INEARBY HOSPITAL. THE VICTIM IS NOW IN REHABILITATION TO RECOVER HIS HEALTH.
47 48 46 46 50 51 52 53 54 53 54 55 57 58 59 60 61 62 63 64 65 66	CAUSING IT TO BE LIB TED OFF THE GROUND TO A VERTICAL POSITION. THE CHILDREN AND THE RIDE WERE CATAPULTED INTO A NEARBY TREE HEMORRHAGE. THE VICTIM WAS PLACED ON LIFE SUPPORT AND DIED WITHIN 24 HOURS OF THE REMOVAL OF LIFE SUPPORT WHEEL AT A CHURCH CARNIVAL WAS ROTATING D. A COUNTERCLOCKWISE DIRECTION WHEN IT STRUCK A METAL TACKING SUPPORT TOWER ON THE INVARIES ASSOCIATED WITH THE FALL. THE RIDE WAS BEING OPERATED ON A LOCAL FAIRGROUND SITE AT THE TIME OF THE INCIDENT BY A FRACTURED RAIL OF THIS RIDE  PENDULUM. IN OPPOSITE DIRECTIONS. AS THE RIDE WAS OPERATING THE 13 YEAR OLD GIRL PANICKED AND SHE WIGGLED-OUT FROM UNDER HER  CAPSULE DROFFED OF FELL ABOUT 5-7 FEET TO THE GROUND BEFORE THE OPERATOR COULD STOP THE RIDE. THE VICTUM SEAT RESTRAINED IN THE  WAS ELECTED. CAUSING HIS FOOT TO CONTACT THE UPRIGHT SUPPORT ON THE RIDE BOARDWALK.  OPERATOR HAD WASVED HER TO STAY SEATED. THE VICTUM APPARENTLY FELL UNDER THE CAR AND WAS DRAGGED FOR 3M OF A REVOLUTION BEFORE THE  SUSTAINED A BROKEN ANKLE, THE OTHER A BROKEN LEG  SUSTAINED A BROKEN ANKLE, THE OTHER A BROKEN LEG  SUBDURAL NEMATOMA  LOST CONTROL OF THE "BICYCLE" AND BEGAN TO TRAVEL BACKWARDS ON THE AMUSEMENT RIDE TRACK. THE CUSTOMER SUSTAINED ABRASIONS TO LOWER  OF DEATH OF THE 13 YEAR OLD VICTIM WAS SEVERE HEAD INJURIES.
47 48 49 49 50 51 53 53 54 55 54 55 58 59 60 61 62 63 64 65 64 67 64	CAUSING IT TO BE LIFTED OFF THE GROUND TO A VERTICAL POSITION. THE CHILDREN AND THE RIDE WERE CATABULTED INTO A NEARBY TREE HEMORRHAGE. THE VICTIM WAS PLACED ON LIFE SUPPORT AND DIED WITHIN 24 HOURS OF THE REMOVAL OF LIFE SUPPORT WHEEL AT A CHURCH CARMIVAL WAS ROTATING ID. A COUNTERCLOCKWISE DIRECTION WHEN IT STRUCK A METAL RACKING SUPPORT TOWER ON THE INJURIES ASSOCIATED WITH THE FALL. THE RIDE WAS BEING OPERATED ON A LOCAL FAIRGROUND SITE AT THE TIME OF THE INCIDENT BY AFRACTURED RAIL OF THIS RIDE  PENDULUM, IN OPPOSITE DIRECTIONS. AS THE RIDE WAS OPERATING THE 13 YEAR OLD GIRL PANICKED. AND SHE WIGGLED-OUT FROM UNDER HER  CAPSULE, DROPFED OF FELL ABOUT 5-7 FEET TO THE GROUND BEFORE THE OPERATOR COULD STOP THE RIDE. THE VICTIM, SEAT RESTRAINED IN THE  WAS ELECTED. CAUSING HIS FOOT TO CONTACT THE UPRIGHT SUPPORT ON THE RIDE BOARDWALK.  OPERATOR HAD WARNED HER TO STAY SEATED. THE VICTIM APPARENTLY FELL UNDER THE CAR AND WAS DRAGGED FOR JM OF A REVOLUTION BEFORE THE SUSTAINED A BROKEN ANKLE. THE OTHER A BROKEN LEG. SUSTAINED A BROKEN ANKLE. THE OTHER A BROKEN LEG. SUBJURAL HEMATOMA.  LOST CONTROL OF THE 'BICYCLE' AND BEGAN TO TRAVEL BACKWARDS ON THE AMUSEMENT RIDE TRACK. THE CUSTOMER SUSTAINED ABRASIONS TO LOWER.  IF 22 37 ON THE RIDE SUFFERED DIVINES RANGING FROM NECK PRACK STRAINS CONTUSIONS TO ARMS / LEGS. TO ONE VICTIM WHO SUFFERED A  OF DEATH OF THE 15 YEAR OLD VICTIM WAS SEVERE HEAD INVIDES.  INEARBY HOSPITAL. THE VICTIM IS NOW IN REHABILITATION TO RECOVER HIS HEALTH.  SUBDURAL HEMATOMA.
47 48 46 46 47 50 51 52 53 53 54 55 56 57 58 59 60 61 62 63 64 65 64 65 67 68 68 68 68 68 68 68 68 68 68 68 68 68	CAUSING IT TO BE LIPTED OFF THE GROUND TO A VERTICAL POSITION. THE CHILDREN AND THE RIDE WERE CATAPULTED INTO A NEARBY TREE HEMORRHAGE. THE VICTIM WAS PLACED ON LIFE SUPPORT AND DIED WITHIN 24 HOURS OF THE REMOVAL OF LIFE SUPPORT. WHEEL AT A CHURCH CARNIVAL WAS ROTATING IN A COUNTERCLOCK WISE DIRECTION. WHEN ITS STAUCK A METAL FACKING SUPPORT TOWER ON THE INJURIES ASSOCIATED WITH THE FALL. THE RIDE WAS BEING OPERATED ON A LOCAL FAIRGROUND SITE AT THE TIME OF THE INCIDENT. BY A FRACTURED RAIL OF THIS RIDE  PENDULUM, IN OPPOSITE DIRECTIONS. AS THE RIDE WAS OPERATING THE 11 YEAR OLD GIRL PANICKED. AND SHE WIGGLED-OUT FROM UNDER HER.  CAPSULE, DROPPED OF FELL ABOUT 5-7 FEET TO THE GROUND. BEFORE THE OPERATOR COULD STOP THE RIDE. THE VICTIM, SEAT RESTRAINED IN THE  WAS EJECTED. CAUSING HIS FOOT TO CONTACT THE UPRIGHT SUPPORT ON THE RIDE BOARDWALK.  OPERATOR HAD WARNED HER TO STAY SEATED. THE VICTIM APPARENTLY FELL UNDER THE CAR AND WAS DRAGGED FOR 3M OF A REVOLUTION BEFORE THE SUBSTAINED A BROKEN. ANKLE, THE OTHER A BROKEN LEG.  SUBDURAL HEMATOMA.  LOST CONTROL OF THE BUSYFERED INJURIES RANGING FROM MECK / BACK STRAINS CONTUSIONS TO ARMS / LEGS. TO ONE VICTIM WHO SUFFERED A  OF DEATH OF THE 19 YEAR OLD VICTIM WAS SEVERE HEAD INJURIES.  INEARBY HOSPITAL. THE VICTIM IS NOW IN REHABILITATION TO RECOVER HIS HEALTH.
47 48 46 46 46 50 51 52 52 53 54 55 57 58 59 60 61 62 63 64 65 66 67 70 68	CAUSING IT TO BE LIFTED OFF THE GROUND TO A VERTICAL POSITION. THE CHILDREN AND THE RIDE WERE CATABULTED INTO A NEARBY TREE HEMORRHAGE. THE VICTIM WAS PLACED ON LIFE SUPPORT AND DIED WITHIN 24 HOURS OF THE REMOVAL OF LIFE SUPPORT WHEEL AT A CHURCH CARMIVAL WAS ROTATING ID. A COUNTERCLOCKWISE DIRECTION WHEN IT STRUCK A METAL RACKING SUPPORT TOWER ON THE INJURIES ASSOCIATED WITH THE FALL. THE RIDE WAS BEING OPERATED ON A LOCAL FAIRGROUND SITE AT THE TIME OF THE INCIDENT BY AFRACTURED RAIL OF THIS RIDE  PENDULUM, IN OPPOSITE DIRECTIONS. AS THE RIDE WAS OPERATING THE 13 YEAR OLD GIRL PANICKED. AND SHE WIGGLED-OUT FROM UNDER HER  CAPSULE, DROPFED OF FELL ABOUT 5-7 FEET TO THE GROUND BEFORE THE OPERATOR COULD STOP THE RIDE. THE VICTIM, SEAT RESTRAINED IN THE  WAS ELECTED. CAUSING HIS FOOT TO CONTACT THE UPRIGHT SUPPORT ON THE RIDE BOARDWALK.  OPERATOR HAD WARNED HER TO STAY SEATED. THE VICTIM APPARENTLY FELL UNDER THE CAR AND WAS DRAGGED FOR JM OF A REVOLUTION BEFORE THE SUSTAINED A BROKEN ANKLE. THE OTHER A BROKEN LEG. SUSTAINED A BROKEN ANKLE. THE OTHER A BROKEN LEG. SUBJURAL HEMATOMA.  LOST CONTROL OF THE 'BICYCLE' AND BEGAN TO TRAVEL BACKWARDS ON THE AMUSEMENT RIDE TRACK. THE CUSTOMER SUSTAINED ABRASIONS TO LOWER.  IF 22 37 ON THE RIDE SUFFERED DIVINES RANGING FROM NECK PRACK STRAINS CONTUSIONS TO ARMS / LEGS. TO ONE VICTIM WHO SUFFERED A  OF DEATH OF THE 15 YEAR OLD VICTIM WAS SEVERE HEAD INVIDES.  INEARBY HOSPITAL. THE VICTIM IS NOW IN REHABILITATION TO RECOVER HIS HEALTH.  SUBDURAL HEMATOMA.
47 48 49 49 50 51 52 53 54 53 54 55 57 58 59 60 61 62 63 64 65 67 68 70 71 72 72 73	CAUSING IT TO BE LIFTED OFF THE GROUND TO A VERTICAL POSITION. THE CHILDREN AND THE RIDE WERE CATABULTED INTO A NEARBY TREE HEMORRHAGE. THE VICTIM WAS PLACED ON LIFE SUPPORT AND DIED WITHIN 24 HOURS OF THE REMOVAL OF LIFE SUPPORT WHEEL AT A CHURCH CARMIVAL WAS ROTATING ID. A COUNTERCLOCKWISE DIRECTION WHEN IT STRUCK A METAL RACKING SUPPORT TOWER ON THE INJURIES ASSOCIATED WITH THE FALL. THE RIDE WAS BEING OPERATED ON A LOCAL FAIRGROUND SITE AT THE TIME OF THE INCIDENT BY AFRACTURED RAIL OF THIS RIDE  PENDULUM, IN OPPOSITE DIRECTIONS. AS THE RIDE WAS OPERATING THE 13 YEAR OLD GIRL PANICKED. AND SHE WIGGLED-OUT FROM UNDER HER  CAPSULE, DROPFED OF FELL ABOUT 5-7 FEET TO THE GROUND BEFORE THE OPERATOR COULD STOP THE RIDE. THE VICTIM, SEAT RESTRAINED IN THE  WAS ELECTED. CAUSING HIS FOOT TO CONTACT THE UPRIGHT SUPPORT ON THE RIDE BOARDWALK.  OPERATOR HAD WARNED HER TO STAY SEATED. THE VICTIM APPARENTLY FELL UNDER THE CAR AND WAS DRAGGED FOR JM OF A REVOLUTION BEFORE THE SUSTAINED A BROKEN ANKLE. THE OTHER A BROKEN LEG. SUSTAINED A BROKEN ANKLE. THE OTHER A BROKEN LEG. SUBJURAL HEMATOMA.  LOST CONTROL OF THE 'BICYCLE' AND BEGAN TO TRAVEL BACKWARDS ON THE AMUSEMENT RIDE TRACK. THE CUSTOMER SUSTAINED ABRASIONS TO LOWER.  IF 22 37 ON THE RIDE SUFFERED DIVINES RANGING FROM NECK PRACK STRAINS CONTUSIONS TO ARMS / LEGS. TO ONE VICTIM WHO SUFFERED A  OF DEATH OF THE 15 YEAR OLD VICTIM WAS SEVERE HEAD INVIDES.  INEARBY HOSPITAL. THE VICTIM IS NOW IN REHABILITATION TO RECOVER HIS HEALTH.  SUBDURAL HEMATOMA.
47 48 49 40 50 51 53 53 54 55 54 55 58 59 60 61 62 63 64 65 65 67 68 70 71 72 72 73	CAUSING IT TO BE LIFTED OFF THE GROUND TO A VERTICAL POSITION. THE CHILDREN AND THE RIDE WERE CATABULTED INTO A NEARBY TREE HEMORRHAGE. THE VICTIM WAS PLACED ON LIFE SUPPORT AND DIED WITHIN 24 HOURS OF THE REMOVAL OF LIFE SUPPORT WHEEL AT A CHURCH CARMIVAL WAS ROTATING ID. A COUNTERCLOCKWISE DIRECTION WHEN IT STRUCK A METAL RACKING SUPPORT TOWER ON THE INJURIES ASSOCIATED WITH THE FALL. THE RIDE WAS BEING OPERATED ON A LOCAL FAIRGROUND SITE AT THE TIME OF THE INCIDENT BY AFRACTURED RAIL OF THIS RIDE  PENDULUM, IN OPPOSITE DIRECTIONS. AS THE RIDE WAS OPERATING THE 13 YEAR OLD GIRL PANICKED. AND SHE WIGGLED-OUT FROM UNDER HER  CAPSULE, DROPFED OF FELL ABOUT 5-7 FEET TO THE GROUND BEFORE THE OPERATOR COULD STOP THE RIDE. THE VICTIM, SEAT RESTRAINED IN THE  WAS ELECTED. CAUSING HIS FOOT TO CONTACT THE UPRIGHT SUPPORT ON THE RIDE BOARDWALK.  OPERATOR HAD WARNED HER TO STAY SEATED. THE VICTIM APPARENTLY FELL UNDER THE CAR AND WAS DRAGGED FOR JM OF A REVOLUTION BEFORE THE SUSTAINED A BROKEN ANKLE. THE OTHER A BROKEN LEG. SUSTAINED A BROKEN ANKLE. THE OTHER A BROKEN LEG. SUBJURAL HEMATOMA.  LOST CONTROL OF THE 'BICYCLE' AND BEGAN TO TRAVEL BACKWARDS ON THE AMUSEMENT RIDE TRACK. THE CUSTOMER SUSTAINED ABRASIONS TO LOWER.  IF 22 37 ON THE RIDE SUFFERED DIVINES RANGING FROM NECK PRACK STRAINS CONTUSIONS TO ARMS / LEGS. TO ONE VICTIM WHO SUFFERED A  OF DEATH OF THE 15 YEAR OLD VICTIM WAS SEVERE HEAD INVIDES.  INEARBY HOSPITAL. THE VICTIM IS NOW IN REHABILITATION TO RECOVER HIS HEALTH.  SUBDURAL HEMATOMA.
47 48 46 46 50 51 53 53 53 54 55 56 57 58 59 60 61 61 62 64 65 67 68 68 67 70 71 72 72 73 74 75 75 75 76 77 77 77 77 77 77 77 77 77 77 77 77	CAUSING IT TO BE LUTED OFF THE GROUND TO A VEATICAL POSITION. THE CRILDREN AND THE RIDE WERE CATAPULTED INTO A NEABRY TREE HEMORRHAGE. THE VICTOM WAS PLACED ON LIFE SUPPORT AND DIED WITHIN 24 HOURS OF THE REMOVAL OF LIFE SUPPORT. WHEEL AT A CHURCH CADMIVAL WAS ROTATING IN A COUNTERCLOCKWISE DIRECTION. HEN IT STRUCK A METAL RACKING SUPPORT TOWER ON THE INJURIES ASSOCIATED WITH THE FALL. THE RIDE WAS BEING OPERATED ON A LOCAL FAIRGROUND SITE AT THE TIME OF THE INCIDENT BY A FRACTURED RAIL OF THIS RIDE.  PENDULUM, IN OPPOSITE DIRECTIONS. AS THE RIDE WAS OPERATING THE 13 YEAR OLD GIRL FANICKED. AND SHE WIGGLED-OUT FROM UNDER HER.  CAPSULE, DROHED OF FELL ABOUT 3-7 FEET TO THE GROUND BEFORE THE OPERATOR COULD STOP THE RIDE. THE VICTUM SEAT RESTRAINED IN THE  WAS ELECTED CAUSING HIS FOOT TO CONTACT THE UPRIGHT SUPPORT ON THE RIDE BOARDWALK.  OPPRATOR HAD WASNED HEN TO STAY SEATED. THE VICTUM APPARENTLY FELL UNDER THE CAR AND WAS DRACGED FOR 3M OF A REVOLUTION BEFORE THE  SUSTAINED A BROKEN ANKLE. THE OTHER A BROKEN LEG.  SUSTAINED A BROKEN ANKLE. THE OTHER A BROKEN LEG.  SUBDIDITAL HEMATOMA.  LOST CONTROL OF THE PICYCLE: AND BEGAN TO TRAVEL BACKWARDS ON THE AMUSEMENT RIDE TRACK. THE CUSTOMER SUSTAINED ABRASIONS TO LOWER.  IF 32 3F1 ON THE RIDE SUFFERED NUTLINES RANGING FROM NECK / BACK STRAINS CONTUSIONS TO ARMS / LEGS TO ONE VICTIM WHO SUFFERED A  OF DEATH OF THE 13 YEAR OLD VICTIM WAS SEVERE HEAD INJURIES.  NEARBY HOSPITAL. THE VICTIM IS NOW IN REHABILITATION TO RECOVER HIS HEALTH.  SUBDICAL FEMATOMA.  OFFICIALS FEEL TRAT THE RIDES RESTRAINT SYSTEM DID NOT ADEQUATELY RESTRAIN THE VICTIM. THE RIDE HAS BEEN BANNED BY THE STATE PENDING.
47 48 46 46 46 50 51 52 53 54 55 54 57 58 59 60 61 62 63 64 65 64 65 70 71 72 73 74	CAUSING IT TO BE LID TED OFF THE GROUND TO A VERTICAL POSITION. THE CRILDREN AND THE RIDE WERE CATAPULTED INTO A NEARLY TREE HEMORARAGE THE VICTIM WAS PLACED ON LIPE SUPPORT AND DIED WITHINS, HOURS OF THE SUPPORT. WHEEL AT A CHURCH CARNIVAL WAS ROTATING IN A COUNTERCLOCKWISE DIRECTION WHEN IT STRUCK A METAL RACKING SUPPORT TOWER ON THE INVERSES ASSOCIATED WITH THE FALL. THE RIDE WAS BEING OPERATED ON A LOCAL FAIRGROUND SITE AT THE TIME OF THE INCIDENT  BY AFRACTICATED RALL OF THIS RIDE  PENDULUM, IN OPPOSITE DIRECTIONS. AS THE RIDE WAS OPERATING THE 13 YEAR OLD GIRL PANICKED. AND SHE WIGGLED-OUT FROM UNDER HER  CAPSULE, DROPPED OF FELL ABOUT 5-7 FEET TO THE GROUND BEFORE THE OPERATOR COULD STOP THE RIDE. THE VICTIM, SEAT RESTRAINED IN THE  WAS ELECTED CAUSING HIS FOOT TO CONTACT THE UPRIGHT SUPPORT ON THE RIDE BOARDWALK.  OPPRATOR HAD WARNED HER TO STAY SEATED. THE VICTIM APPARENTLY FELL UNDER THE CAR AND WAS DRAGGED FOR 3M OF A REVOLUTION BEFORE THE  SUSTAMED A BROKEN ANKLE. THE OTHER A BROKEN LEG.  SUSTAMED A BROKEN ANKLE. THE OTHER A BROKEN LEG.  SUBDURAL HEMATOMA.  LOST CONTROL OF THE "BICYCLE" AND BEGAN TO TRAVEL BACKWARDS ON THE AMUSEMENT RIDE TRACK. THE CUSTOMER SUSTAINED ABRASIONS TO LOWER  IF 32 151 ON THE RIDE SUFFERED DIVINES RANGING FROM NECK YBACK STRAINS CONTUSIONS TO ARMS / LEGS. TO ONE VICTIM WHO SUFFERED A  OF DEATH OF THE 13 YEAR OLD VICTIM WAS SEVERE HEAD INJURIES.  SUBDURAL HEMATOMA.  OFFICIALS FEEL THAT THE RIDES RESTRAINT SYSTEM DID NOT ADEQUATELY RESTRAIN THE VICTIM. THE RIDE HAS BEEN BANNED BY THE STATE PENDING.  TO STAND BY THE CAR AFTER HE (OPERATOR) STOPPED THE RIDE. WHEN THE VICTIM STOOD IN THE CAR THE SECOND TIME, THE OPERATOR ATTEMPTED TO
47 48 46 46 46 50 51 52 53 54 53 54 55 54 61 62 64 64 65 64 65 70 71 72 73 74 75 77	CAUSING IT TO BE LUTED OFF THE GROUND TO A VEATICAL POSITION. THE CRILDREN AND THE RIDE WERE CATAPULTED INTO A NEABRY TREE HEMORRHAGE. THE VICTOM WAS PLACED ON LIFE SUPPORT AND DIED WITHIN 24 HOURS OF THE REMOVAL OF LIFE SUPPORT. WHEEL AT A CHURCH CADMIVAL WAS ROTATING IN A COUNTERCLOCKWISE DIRECTION. HEN IT STRUCK A METAL RACKING SUPPORT TOWER ON THE INJURIES ASSOCIATED WITH THE FALL. THE RIDE WAS BEING OPERATED ON A LOCAL FAIRGROUND SITE AT THE TIME OF THE INCIDENT BY A FRACTURED RAIL OF THIS RIDE.  PENDULUM, IN OPPOSITE DIRECTIONS. AS THE RIDE WAS OPERATING THE 13 YEAR OLD GIRL FANICKED. AND SHE WIGGLED-OUT FROM UNDER HER.  CAPSULE, DROHED OF FELL ABOUT 3-7 FEET TO THE GROUND BEFORE THE OPERATOR COULD STOP THE RIDE. THE VICTUM SEAT RESTRAINED IN THE  WAS ELECTED CAUSING HIS FOOT TO CONTACT THE UPRIGHT SUPPORT ON THE RIDE BOARDWALK.  OPPRATOR HAD WASNED HEN TO STAY SEATED. THE VICTUM APPARENTLY FELL UNDER THE CAR AND WAS DRACGED FOR 3M OF A REVOLUTION BEFORE THE  SUSTAINED A BROKEN ANKLE. THE OTHER A BROKEN LEG.  SUSTAINED A BROKEN ANKLE. THE OTHER A BROKEN LEG.  SUBDIDITAL HEMATOMA.  LOST CONTROL OF THE PICYCLE: AND BEGAN TO TRAVEL BACKWARDS ON THE AMUSEMENT RIDE TRACK. THE CUSTOMER SUSTAINED ABRASIONS TO LOWER.  IF 32 3F1 ON THE RIDE SUFFERED NUTLINES RANGING FROM NECK / BACK STRAINS CONTUSIONS TO ARMS / LEGS TO ONE VICTIM WHO SUFFERED A  OF DEATH OF THE 13 YEAR OLD VICTIM WAS SEVERE HEAD INJURIES.  NEARBY HOSPITAL. THE VICTIM IS NOW IN REHABILITATION TO RECOVER HIS HEALTH.  SUBDICAL FEMATOMA.  OFFICIALS FEEL TRAT THE RIDES RESTRAINT SYSTEM DID NOT ADEQUATELY RESTRAIN THE VICTIM. THE RIDE HAS BEEN BANNED BY THE STATE PENDING.
47 48 49 49 50 51 53 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 68 67 70 71 72 73 74	CAUSING IT TO BE LID TED OFF THE GROUND TO A VERTICAL POSITION. THE CRILDREN AND THE RIDE WERE CATAPULTED INTO A NEARLY TREE HEMORARAGE THE VICTIM WAS PLACED ON LIPE SUPPORT AND DIED WITHINS, HOURS OF THE SUPPORT. WHEEL AT A CHURCH CARNIVAL WAS ROTATING IN A COUNTERCLOCKWISE DIRECTION WHEN IT STRUCK A METAL RACKING SUPPORT TOWER ON THE INVERSES ASSOCIATED WITH THE FALL. THE RIDE WAS BEING OPERATED ON A LOCAL FAIRGROUND SITE AT THE TIME OF THE INCIDENT  BY AFRACTICATED RALL OF THIS RIDE  PENDULUM, IN OPPOSITE DIRECTIONS. AS THE RIDE WAS OPERATING THE 13 YEAR OLD GIRL PANICKED. AND SHE WIGGLED-OUT FROM UNDER HER  CAPSULE, DROPPED OF FELL ABOUT 5-7 FEET TO THE GROUND BEFORE THE OPERATOR COULD STOP THE RIDE. THE VICTIM, SEAT RESTRAINED IN THE  WAS ELECTED CAUSING HIS FOOT TO CONTACT THE UPRIGHT SUPPORT ON THE RIDE BOARDWALK.  OPPRATOR HAD WARNED HER TO STAY SEATED. THE VICTIM APPARENTLY FELL UNDER THE CAR AND WAS DRAGGED FOR 3M OF A REVOLUTION BEFORE THE  SUSTAMED A BROKEN ANKLE. THE OTHER A BROKEN LEG.  SUSTAMED A BROKEN ANKLE. THE OTHER A BROKEN LEG.  SUBDURAL HEMATOMA.  LOST CONTROL OF THE "BICYCLE" AND BEGAN TO TRAVEL BACKWARDS ON THE AMUSEMENT RIDE TRACK. THE CUSTOMER SUSTAINED ABRASIONS TO LOWER  IF 32 151 ON THE RIDE SUFFERED DIVINES RANGING FROM NECK YBACK STRAINS CONTUSIONS TO ARMS / LEGS. TO ONE VICTIM WHO SUFFERED A  OF DEATH OF THE 13 YEAR OLD VICTIM WAS SEVERE HEAD INJURIES.  SUBDURAL HEMATOMA.  OFFICIALS FEEL THAT THE RIDES RESTRAINT SYSTEM DID NOT ADEQUATELY RESTRAIN THE VICTIM. THE RIDE HAS BEEN BANNED BY THE STATE PENDING.  TO STAND BY THE CAR AFTER HE (OPERATOR) STOPPED THE RIDE. WHEN THE VICTIM STOOD IN THE CAR THE SECOND TIME, THE OPERATOR ATTEMPTED TO
47 48 46 46 46 50 51 52 53 54 53 54 55 54 61 62 64 64 65 64 65 70 71 72 73 74 75 77	CAUSING IT TO BE LID TED OFF THE GROUND TO A VERTICAL POSITION. THE CRILDREN AND THE RIDE WERE CATAPULTED INTO A NEARLY TREE HEMORARAGE THE VICTIM WAS PLACED ON LIPE SUPPORT AND DIED WITHINS, HOURS OF THE SUPPORT. WHEEL AT A CHURCH CARNIVAL WAS ROTATING IN A COUNTERCLOCKWISE DIRECTION WHEN IT STRUCK A METAL RACKING SUPPORT TOWER ON THE INVERSES ASSOCIATED WITH THE FALL. THE RIDE WAS BEING OPERATED ON A LOCAL FAIRGROUND SITE AT THE TIME OF THE INCIDENT  BY AFRACTICATED RALL OF THIS RIDE  PENDULUM, IN OPPOSITE DIRECTIONS. AS THE RIDE WAS OPERATING THE 13 YEAR OLD GIRL PANICKED. AND SHE WIGGLED-OUT FROM UNDER HER  CAPSULE, DROPPED OF FELL ABOUT 5-7 FEET TO THE GROUND BEFORE THE OPERATOR COULD STOP THE RIDE. THE VICTIM, SEAT RESTRAINED IN THE  WAS ELECTED CAUSING HIS FOOT TO CONTACT THE UPRIGHT SUPPORT ON THE RIDE BOARDWALK.  OPPRATOR HAD WARNED HER TO STAY SEATED. THE VICTIM APPARENTLY FELL UNDER THE CAR AND WAS DRAGGED FOR 3M OF A REVOLUTION BEFORE THE  SUSTAMED A BROKEN ANKLE. THE OTHER A BROKEN LEG.  SUSTAMED A BROKEN ANKLE. THE OTHER A BROKEN LEG.  SUBDURAL HEMATOMA.  LOST CONTROL OF THE "BICYCLE" AND BEGAN TO TRAVEL BACKWARDS ON THE AMUSEMENT RIDE TRACK. THE CUSTOMER SUSTAINED ABRASIONS TO LOWER  IF 32 151 ON THE RIDE SUFFERED DIVINES RANGING FROM NECK YBACK STRAINS CONTUSIONS TO ARMS / LEGS. TO ONE VICTIM WHO SUFFERED A  OF DEATH OF THE 13 YEAR OLD VICTIM WAS SEVERE HEAD INJURIES.  SUBDURAL HEMATOMA.  OFFICIALS FEEL THAT THE RIDES RESTRAINT SYSTEM DID NOT ADEQUATELY RESTRAIN THE VICTIM. THE RIDE HAS BEEN BANNED BY THE STATE PENDING.  TO STAND BY THE CAR AFTER HE (OPERATOR) STOPPED THE RIDE. WHEN THE VICTIM STOOD IN THE CAR THE SECOND TIME, THE OPERATOR ATTEMPTED TO
47 48 49 49 50 51 53 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 68 67 70 71 72 73 74	CAUSING IT TO BELLEY TED OFF THE GROUND TO A VERTICAL POSITION. THE CRILDREN AND THE RIDE WEBS CATAPULTED INTO A NEARBY TREE HEMORAHAGE THE VICTION WAS PLACED ON LIFE SUPPORT AND DEBUNTEN. 34 HOURS OF THE REMOVAL OF LIFE SUPPORT WREEL AT A CHURCH CARNIVAL WAS ROTATING IN A COUNTERCLOCKWISE DIRECTION WHEN IT STRUCK A METAL RACKING SUPPORT TOWER ON THE INJURIES ASSOCIATED WITH THE FALL. THE RIDE WAS BEING OPERATED ON A LOCAL PAIRGROUND SITE AT THE TIME OF THE INCIDENT  BY A FRACTIVATED RAIL OF THIS RIDE  PENDULUM, IN OFFOSITE DIRECTIONS. AS THE RIDE WAS OPERATING THE 11 YEAR OLD GIRL PANICKED AND SHE WIGGLED-OUT FROM UNDER HER  CAPSULE DROWED OF FELL ABOUT 5-1 FEET TO THE GROUND BEFORE THE OPERATOR COULD STOP THE RIDE. THE VICTIM, SEAT RESTRAINED IN THE  WAS ELECTED. CAUSING HIS FOOT TO CONTACT THE UPRIGHT SUPPORT ON THE RIDE BOARDWALK.  WAS ELECTED. CAUSING HIS FOOT TO CONTACT THE UPRIGHT SUPPORT ON THE RIDE BOARDWALK.  WAS ELECTED. CAUSING HIS FOOT TO CONTACT THE UPRIGHT SUPPORT ON THE RIDE BOARDWALK.  WAS ELECTED. CAUSING HIS FOOT TO CONTACT THE UPRIGHT SUPPORT ON THE RIDE BOARDWALK.  WAS ELECTED. CAUSING HIS FOOT TO CONTACT THE UPRIGHT SUPPORT ON THE RIDE BOARDWALK.  WAS ELECTED. CAUSING HIS FOOT TO CONTACT THE UPRIGHT SUPPORT ON THE RIDE BOARDWALK.  WAS ELECTED. CAUSING HIS FOOT TO CONTACT THE UPRIGHT SUPPORT ON THE RIDE BOARDWALK.  WAS ELECTED. CAUSING HIS FOOT TO CONTACT THE UPRIGHT SUPPORT ON THE RIDE BOARDWALK.  WAS ELECTED. CAUSING HIS FOOT TO CONTACT THE UPRIGHT SUPPORT ON THE RIDE BOARDWALK.  SUPPORT OF THE SUPPORT OF THE OTHER ABROXENIES.  SUPPORT OF THE FIRE CONTACT OF THE WICKLES TO THE PRICE OF THE OTHER ABROXENIES.  SUPPORT OF THE FIRE CYCLE AND BEGAN TO TRAVEL BACKWARDS ON THE AMUSEMENT RIDE TRACK. THE CUSTOMER SUSTAINED ABRASIONS TO LOWER  TO STAND ON THE RIDE SUFFERED DIVINES RANGING FROM NECK / BACK STRADY THE VICTUM. THE RIDE HAS BEEN BANNED BY THE STATE PENDING.  THE STAND ON THE FIRE ABROXED BANDWALK SYSTEM DID NOT ADEQUATELY RESTRADY THE VICTUM. THE RIDE HAS BEEN BANNED BY THE STATE PENDI
47 48 46 46 47 50 51 53 53 54 55 56 57 58 59 60 61 62 63 64 65 67 68 68 67 70 71 72 72 73 74 75 76 77 76 77 77 78	CAUSING IT TO BELLEY TED OFF THE GROUND TO A VERTICAL POSITION. THE CRILDREN AND THE RIDE WEBS CATAPULTED INTO A NEARBY TREE HEMORAHAGE THE VICTION WAS PLACED ON LIFE SUPPORT AND DEBUNTEN. 34 HOURS OF THE REMOVAL OF LIFE SUPPORT WREEL AT A CHURCH CARNIVAL WAS ROTATING IN A COUNTERCLOCKWISE DIRECTION WHEN IT STRUCK A METAL RACKING SUPPORT TOWER ON THE INJURIES ASSOCIATED WITH THE FALL. THE RIDE WAS BEING OPERATED ON A LOCAL PAIRGROUND SITE AT THE TIME OF THE INCIDENT  BY A FRACTIVATED RAIL OF THIS RIDE  PENDULUM, IN OFFOSITE DIRECTIONS. AS THE RIDE WAS OPERATING THE 11 YEAR OLD GIRL PANICKED AND SHE WIGGLED-OUT FROM UNDER HER  CAPSULE DROWED OF FELL ABOUT 5-1 FEET TO THE GROUND BEFORE THE OPERATOR COULD STOP THE RIDE. THE VICTIM, SEAT RESTRAINED IN THE  WAS ELECTED. CAUSING HIS FOOT TO CONTACT THE UPRIGHT SUPPORT ON THE RIDE BOARDWALK.  WAS ELECTED. CAUSING HIS FOOT TO CONTACT THE UPRIGHT SUPPORT ON THE RIDE BOARDWALK.  WAS ELECTED. CAUSING HIS FOOT TO CONTACT THE UPRIGHT SUPPORT ON THE RIDE BOARDWALK.  WAS ELECTED. CAUSING HIS FOOT TO CONTACT THE UPRIGHT SUPPORT ON THE RIDE BOARDWALK.  WAS ELECTED. CAUSING HIS FOOT TO CONTACT THE UPRIGHT SUPPORT ON THE RIDE BOARDWALK.  WAS ELECTED. CAUSING HIS FOOT TO CONTACT THE UPRIGHT SUPPORT ON THE RIDE BOARDWALK.  WAS ELECTED. CAUSING HIS FOOT TO CONTACT THE UPRIGHT SUPPORT ON THE RIDE BOARDWALK.  WAS ELECTED. CAUSING HIS FOOT TO CONTACT THE UPRIGHT SUPPORT ON THE RIDE BOARDWALK.  WAS ELECTED. CAUSING HIS FOOT TO CONTACT THE UPRIGHT SUPPORT ON THE RIDE BOARDWALK.  SUPPORT OF THE SUPPORT OF THE OTHER ABROXENIES.  SUPPORT OF THE FIRE CONTACT OF THE WICKLES TO THE PRICE OF THE OTHER ABROXENIES.  SUPPORT OF THE FIRE CYCLE AND BEGAN TO TRAVEL BACKWARDS ON THE AMUSEMENT RIDE TRACK. THE CUSTOMER SUSTAINED ABRASIONS TO LOWER  TO STAND ON THE RIDE SUFFERED DIVINES RANGING FROM NECK / BACK STRADY THE VICTUM. THE RIDE HAS BEEN BANNED BY THE STATE PENDING.  THE STAND ON THE FIRE ABROXED BANDWALK SYSTEM DID NOT ADEQUATELY RESTRADY THE VICTUM. THE RIDE HAS BEEN BANNED BY THE STATE PENDI
47 48 46 46 46 50 51 52 52 53 54 55 54 55 57 58 59 60 61 62 63 64 65 64 65 64 65 70 71 72 73 74 75 77 77 78 78 78 78 78 78 78 78 78 78 78	CAUSING IT TO BE LID TED OFF THE GROUND TO A VERTICAL POSITION. THE CHILDREN AND THE RIDE WEIGE CATAPULITED INTO A NEARBY TREE HEMORRANGE THE VICTION WAS PLACED ON LIFE SUPPORT AND DIED WHTEN 34 HOURS OF THE REMOVAL OF LIFE SUPPORT WHEEL AT A CHURCH CARNIVAL WAS ROTATING TO A COUNTERCL OCKWISE DIRECTION IN HER ITS TRUCK A METAL RACKING SUPPORT TOWER ON THE INVERSE A SECOLATED WITH THE FALL. THE RIDE WAS BEING OPERATED ON A LOCAL FAIRGROUND SITE AT THE VIME OF THE INVEDENT BY A FRACTURED RAIL OF THIS RIDE  PENDULUM, IN OPPOSITE DIRECTIONS. AS THE RIDE WAS OPERATING THE 13 YEAR OLD GIRL PAINCKED AND SHE WIGGLED-OUT FROM UNDER HER  CAPSULE. DROPPED OF FELL ABOUT 3-7 FEET TO THE GROUND BEFORE THE OPERATOR COULD STOP THE RIDE. THE VICTIM, SEAT RESTRAINED IN THE  WAS ELECTED CAUSING HIS FOOT TO CONTACT THE UPRIGHT SUPPORT ON THE RIDE BOARDWALK.  OPERATOR HAD WANNED HER TO STAY SEATED. THE VICTIM AFRAEVILLY FELL UNDER THE CAR AND WAS DRAGGED FOR 3M OF A REVOLUTION BEFORE THE  SUSTAINED A BROKEN ANKLE, THE OTHER AR BROKEN LIGG  SUBJURAL REMATIONA.  LOST CONTROL OF THE RICYCLE: AND BEGAN TO TRAVEL BACKWANDS ON THE AMUSEMENT RIDE TRACK. THE CUSTOMER SUSTAINED ARRASIONS TO LOWER  IF 3F 78F 10 NO THE RIDE SUFFERED INJURIES RANGING FROM NECK / BACK STRAINS CONTUSIONS TO ARMS / LEGS. TO ONE VICTIM WHO SUFFERED A  OF DEATH OF THE 13 YEAR OLD VICTIM WAS SEVERE HEAD INJURIES.  NEARBY HOSPITAL. THE VICTIM IS NOW IN REHABILITATION TO RECOVER HIS HEALTH  SUBDURAL HEMATOMA.  OFFICIALS FEEL THAT THE RIDE'S RESTRAINT SYSTEM DID NOT ADEQUATELY RESTRAINT THE VICTIM. THE RIDE HAS BEEN BANNED BY THE STATE PENDING.  TO STAND IN THE CAR AFTER HE (OPERATOR) STOPPED THE RIDE. WHEN THE VICTIM STOOD IN THE CAR THE SECOND TIME. THE OPERATOR ATTEMPTED TO WHEEL COLLD BE TURNED EXOLID TO THE GROUND. SHE WAS
47 48 46 46 46 46 50 51 52 53 54 53 54 53 54 53 54 64 64 65 66 67 68 68 70 71 72 72 73 74 75 76 77 78 78	CAUSING IT TO BE LIDTED OFF THE GROUND TO A VEATICAL POSITION. THE CHALDREN AND THE REMOVANCE OF THE PROPERTY
47 48 49 40 50 51 52 52 53 54 55 57 58 59 60 61 62 63 64 65 66 70 71 72 73 74 75 76 77 78 78 80 81	CAUSING IT TO BE LIDTED OF THE GROUND TO A VEATICAL POSITION. THE CHALDREY AND THE REMOVAL OF THE PROPERTY ON THE REPORT AND THE WILLIAM AS PLACE ON THE PROPERTY OF THE REMOVAL OF THE REMOVAL WAS ROTATING IN A COUNTERCLOCKWISE DIRECTION WHEN IT STRUCK A METAL RACKING SUPPORT TOWER ON THE INJURIES. ASSOCIATED WITH THE FALL. THE KIDE WAS BEING OPERATED ON A LOCAL FAIRGROUND SITE AT THE TIME OF THE INCIDENT BY A FRACTURED RALL OF THIS RIDE.  PENDULUM, IN OPPOSITE DIRECTIONS. AS THE RIDE WAS OPERATING THE 11 YEAR OLD GIRL PANICKED. AND SHE WIGGLED-OUT FROM UNDER HER.  CAPSULE, DROPPED OF FELL ABOUT 3-7 FEET TO THE GROUND BEFORE THE OPERATOR COULD STOP THE RIDE. THE VICTIM, SEAT RESTRAINED IN THE WAS ELECTED. CAUSING HIS FOOT TO CONTACT THE UPRIGHT SUPPORT ON THE RIDE BOADDWALK.  OPERATOR HAD WASNED HER TO STAY SEATED. THE VICTIM APPARENTLY FELL UNDER THE CAR AND WAS DRACGED FOR UN OF A REVOLUTION BEFORE THE SUSTAINED A BROKEN ANKLE. THE OTHER A BROKEN APPARENTLY FELL UNDER THE CAR AND WAS DRACGED FOR UN OF A REVOLUTION BEFORE THE SUSTAINED A BROKEN ANKLE. THE OTHER A BROKEN HAD BEGAN TO TRAVEL BACK WANDS ON THE AMUSEMENT RIDE TRACK. THE CUSTOMER SUSTAINED ABRASIONS TO LOWER THE SECOND THE BEFORE THE SECOND TO THE THE PROPERTY OF THE 13 YEAR OLD VICTIM WAS SEVERE HEAD INJURIES.  NEARBY HOSPITAL. THE VICTIM IS NOW IN REHABILITATION TO RECOVER HIS HEALTH.  SUBDURAL HEMATOMA.  OFFICIALS FEEL THAT THE RIDE'S RESTRAINT SYSTEM DID NOT ADEQUATELY RESTRAIN THE VICTIM. THE RIDE HAS BEEN BANNED BY THE STATE PENDING.  TO STAND IN THE CAR AFTER HE OPERATOR STOPPED THE RIDE. WHEN THE VICTIM STOOD IN THE CAR THE SECOND TIME, THE OPERATOR ATTEMPTED TO WHEEL COURSE BROWNED BAS SCHEEN TO THE WAS SOUND. SHE WAS  OPERATOR HER RESTRAINING BAS SO SHE COULD SEE BETTER. AT THE SAME TIME. THE CAR BEGAN TO SPIN ELECTING THE VICTIM TO THE GROUND. SHE WAS  OPERATOR HER RESTRAINING BAS SO SHE COULD SEE BETTER. AT THE SAME TIME. THE CAR BEGAN TO SPIN ELECTING THE VICTIM TO THE GROUND. SHE WAS
47 48 46 46 46 46 47 48 48 48 49 49 49 49 49 49 49 49 49 49 49 49 49	CAUSING IT TO BE LIDTED OFF THE GROUND TO A VEATICAL POSITION. THE CHALDREN AND THE REMOVANCE OF THE PROPERTY
47 48 49 50 51 52 53 54 55 56 67 61 62 61 62 63 64 65 66 67 77 78 78 78 76 77 78 78 78 78 78 78 78 78 78	CAUSING IT TO BE LIDTED OFF THE GROUND TO A VEATICAL POSITION. THE CHALDREN AND THE REMOVANCE OF THE PROPERTY

	Nerralive (coptioned)	
7		
1	VICTIM WENT TO HOSPITAL AT HOME THE NEXT DAY	
3		
F		
9		
10		
117		
12		
14		
13_		
16		
17		
19		
20		
21		
22		
2/2/		-
25		
26		
27 23		
29		ļ
30		
31		1
32 31		Í
<u> </u>		1
35		1
36		<b>{</b>
38		1
39		]
		4
		-
1		<u> </u>
		1
		<u> </u>
	6   6   7   7   7   7   7   7   7   7	<u> </u>
	APPLIED THE BRAKES AND ONE CAR DROPPED DOWN ONTO ANOTHER CAR, APPARENTLY AFTER IT BROKE FREE FROM ITS REAR CONNECTION TO AN A FRAME  APPLIED THE BRAKES AND ONE CAR DROPPED DOWN ONTO ANOTHER CAR, APPARENTLY AFTER IT BROKE FREE FROM ITS REAR CONNECTION TO AN A FRAME	
	APPLIED THE BRAKES AND ONE CAR DROPPED DOWN ONTO ANOTHER CAR, APPARENTLY AFTER IT BROKE FREE FROM ITS REAR CONNECTION TO AN A FRAME  APPLIED THE BRAKES AND ONE CAR DROPPED DOWN ONTO ANOTHER CAR, APPARENTLY AFTER IT BROKE FREE FROM ITS REAR CONNECTION TO AN A FRAME	
	A PPLIED THE BRAKES AND ONE CAR DROPPED DOWN ONTO ANOTHER CAR, APPARENTLY AFTER IT BROKE FREE FROM ITS REAR CONNECTION TO AN A FRAME  A PPLIED THE BRAKES AND ONE CAR DROPPED DOWN ONTO ANOTHER CAR, APPARENTLY AFTER IT BROKE FREE FROM ITS REAR CONNECTION TO AN A FRAME  A PPLIED THE BRAKES AND ONE CAR DROPPED DOWN ONTO ANOTHER CAR, APPARENTLY AFTER IT BROKE FREE FROM ITS REAR CONNECTION TO AN A FRAME  THE PLATFORM OF THE RIDE, & SHE WAS STRUCK BY THE CAR THAT SHE HAD BEEN RIDING IN & SHE WAS WIPED ACROSS THE PLATFORM, SHE WAS  ON THE PLATFORM OF THE RIDE, & SHE WAS STRUCK BY THE CAR THAT SHE HAD BEEN RIDING IN & SHE WAS WIPED ACROSS THE PLATFORM, SHE WAS	
	APPLIED THE BRAKES AND ONE CAR DROPPED DOWN ONTO ANOTHER CAR, APPARENTLY AFTER IT BROKE FREE FROM ITS REAR CONNECTION TO AN A FRAME  APPLIED THE BRAKES AND ONE CAR DROPPED DOWN ONTO ANOTHER CAR, APPARENTLY AFTER IT BROKE FREE FROM ITS REAR CONNECTION TO AN A FRAME  APPLIED THE BRAKES AND ONE CAR DROPPED DOWN ONTO ANOTHER CAR, APPARENTLY AFTER IT BROKE FREE FROM ITS REAR CONNECTION TO AN A FRAME  ON THE PLATFORM OF THE RIDE, & SHE WAS STRUCK BY THE CAR THAT SHE HAD BEEN RIDING IN & SHE WAS WIPED ACROSS THE PLATFORM, SHE WAS  ON THE PLATFORM OF THE RIDE, & SHE WAS STRUCK BY THE CAR THAT SHE HAD BEEN RIDING IN & SHE WAS WIPED ACROSS THE PLATFORM, SHE WAS  SON THE PLATFORM OF THE RIDE, & SHE WAS STRUCK BY THE CAR THAT SHE HAD BEEN RIDING IN & SHE WAS WIPED ACROSS THE PLATFORM, SHE WAS  SON THE PLATFORM OF THE RIDE, & SHE WAS STRUCK BY THE CAR THAT SHE HAD BEEN RIDING IN & SHE WAS WIPED ACROSS THE PLATFORM, SHE WAS  SON THE PLATFORM OF THE RIDE, & SHE WAS STRUCK BY THE CAR THAT SHE HAD BEEN RIDING IN & SHE WAS WIPED ACROSS THE PLATFORM.	
	A PPLIED THE BRAKES AND ONE CAR DROPPED DOWN ONTO ANOTHER CAR, APPARENTLY AFTER IT BROKE FREE FROM ITS REAR CONNECTION TO AN A FRAME  A PPLIED THE BRAKES AND ONE CAR DROPPED DOWN ONTO ANOTHER CAR, APPARENTLY AFTER IT BROKE FREE FROM ITS REAR CONNECTION TO AN A FRAME  A PPLIED THE BRAKES AND ONE CAR DROPPED DOWN ONTO ANOTHER CAR, APPARENTLY AFTER IT BROKE FREE FROM ITS REAR CONNECTION TO AN A FRAME  THE PLATFORM OF THE RIDE, & SHE WAS STRUCK BY THE CAR THAT SHE HAD BEEN RIDING IN & SHE WAS WIPED ACROSS THE PLATFORM, SHE WAS  ON THE PLATFORM OF THE RIDE, & SHE WAS STRUCK BY THE CAR THAT SHE HAD BEEN RIDING IN & SHE WAS WIPED ACROSS THE PLATFORM, SHE WAS	
	A PPLIED THE BRAKES AND ONE CAR DROPPED DOWN ONTO ANOTHER CAR, APPARENTLY AFTER IT BROKE FREE FROM ITS REAR CONNECTION TO AN A FRAME  A PPLIED THE BRAKES AND ONE CAR DROPPED DOWN ONTO ANOTHER CAR, APPARENTLY AFTER IT BROKE FREE FROM ITS REAR CONNECTION TO AN A FRAME  A PPLIED THE BRAKES AND ONE CAR DROPPED DOWN ONTO ANOTHER CAR, APPARENTLY AFTER IT BROKE FREE FROM ITS REAR CONNECTION TO AN A FRAME  ON THE PLATFORM OF THE RIDE & SHE WAS STRUCK BY THE CAR THAT SHE HAD BEEN RIDING IN & SHE WAS WIPED ACROSS THE PLATFORM, SHE WAS  ON THE PLATFORM OF THE RIDE & SHE WAS STRUCK BY THE CAR THAT SHE HAD BEEN RIDING IN & SHE WAS WIPED ACROSS THE PLATFORM, SHE WAS  SO SHE WAS SHE WAS STRUCK BY THE CAR THAT SHE HAD BEEN RIDING IN & SHE WAS WIPED ACROSS THE PLATFORM, SHE WAS  SHE WAS SHE WAS SHE WAS STRUCK BY THE CAR THAT SHE HAD BEEN RIDING IN & SHE WAS WIPED ACROSS THE PLATFORM, SHE WAS  SHE WAS SHE WAS SHE WAS STRUCK BY THE CAR THAT SHE HAD BEEN RIDING IN & SHE WAS WIPED ACROSS THE PLATFORM, SHE WAS  SHE WAS SHE WAS SHE WAS STRUCK BY THE CAR THAT SHE HAD BEEN RIDING IN & SHE WAS WIPED ACROSS THE PLATFORM.	
	A STATE OF THE BRAKES AND ONE CAR DROPPED DOWN ONTO ANOTHER CAR, APPARENTLY AFTER IT BROKE FREE FROM ITS REAR CONNECTION TO AN A FRAME  OF APPLIED THE BRAKES AND ONE CAR DROPPED DOWN ONTO ANOTHER CAR, APPARENTLY AFTER IT BROKE FREE FROM ITS REAR CONNECTION TO AN A FRAME  OF APPLIED THE BRAKES AND ONE CAR DROPPED DOWN ONTO ANOTHER CAR, APPARENTLY AFTER IT BROKE FREE FROM ITS REAR CONNECTION TO AN A FRAME  ON THE PLATFORM OF THE RIDE, & SHE WAS STRUCK BY THE CAR THAT SHE HAD BEEN RIDING IN & SHE WAS WIPED ACROSS THE PLATFORM, SHE WAS  ON THE PLATFORM OF THE RIDE, & SHE WAS STRUCK BY THE CAR THAT SHE HAD BEEN RIDING IN & SHE WAS WIPED ACROSS THE PLATFORM, SHE WAS  ON THE PLATFORM OF THE RIDE, & SHE WAS STRUCK BY THE CAR THAT SHE HAD BEEN RIDING IN & SHE WAS WIPED ACROSS THE PLATFORM, SHE WAS  ON THE PLATFORM OF THE RIDE, & SHE WAS STRUCK BY THE CAR THAT SHE HAD BEEN RIDING IN & SHE WAS WIPED ACROSS THE PLATFORM, SHE WAS  ON THE PLATFORM OF THE RIDE, & SHE WAS STRUCK BY THE CAR THAT SHE HAD BEEN RIDING IN & SHE WAS WIPED ACROSS THE PLATFORM, SHE WAS  ON THE PLATFORM OF THE RIDE, & SHE WAS STRUCK BY THE CAR THAT SHE HAD BEEN RIDING IN & SHE WAS WIPED ACROSS THE PLATFORM.	
	A SECONDARY OF THE RIDE, & SHE WAS STRUCK BY THE CAR THAT SHE HAD BEEN RIDING IN & SHE WAS WIPED ACROSS THE PLATFORM, SHE WAS STRUCK BY THE CAR THAT SHE HAD BEEN RIDING IN & SHE WAS WIPED ACROSS THE PLATFORM, SHE WAS STRUCK BY THE CAR THAT SHE HAD BEEN RIDING IN & SHE WAS WIPED ACROSS THE PLATFORM, SHE WAS STRUCK BY THE CAR THAT SHE HAD BEEN RIDING IN & SHE WAS WIPED ACROSS THE PLATFORM, SHE WAS STRUCK BY THE CAR THAT SHE HAD BEEN RIDING IN & SHE WAS WIPED ACROSS THE PLATFORM, SHE WAS STRUCK BY THE CAR THAT SHE HAD BEEN RIDING IN & SHE WAS WIPED ACROSS THE PLATFORM, SHE WAS STRUCK BY THE CAR THAT SHE HAD BEEN RIDING IN & SHE WAS WIPED ACROSS THE PLATFORM, SHE WAS STRUCK BY THE CAR THAT SHE HAD BEEN RIDING IN & SHE WAS WIPED ACROSS THE PLATFORM, SHE WAS STRUCK BY THE CAR THAT SHE HAD BEEN RIDING IN & SHE WAS WIPED ACROSS THE PLATFORM, SHE WAS STRUCK BY THE CAR THAT SHE HAD BEEN RIDING IN & SHE WAS WIPED ACROSS THE PLATFORM, SHE WAS STRUCK BY THE CAR THAT SHE HAD BEEN RIDING IN & SHE WAS WIPED ACROSS THE PLATFORM, SHE WAS STRUCK BY THE CAR THAT SHE HAD BEEN RIDING IN & SHE WAS WIPED ACROSS THE PLATFORM, SHE WAS STRUCK BY THE CAR THAT SHE HAD BEEN RIDING IN & SHE WAS WIPED ACROSS THE PLATFORM, SHE WAS STRUCK BY THE CAR THAT SHE HAD BEEN RIDING IN & SHE WAS WIPED ACROSS THE PLATFORM.	
	S S S S S S S S S S S S S S S S S S S	
	APPLIED THE BRAKES AND ONE CAR DROPPED DOWN ONTO ANOTHER CAR, APPARENTLY AFTER IT BROKE FREE FROM ITS REAR CONNECTION TO AN A FRAME  APPLIED THE BRAKES AND ONE CAR DROPPED DOWN ONTO ANOTHER CAR, APPARENTLY AFTER IT BROKE FREE FROM ITS REAR CONNECTION TO AN A FRAME  ON THE PLATFORM OF THE RIDE, & SHE WAS STRUCK BY THE CAR THAT SHE HAD BEEN RIDING IN & SHE WAS WIPED ACROSS THE PLATFORM, SHE WAS  ON THE PLATFORM OF THE RIDE, & SHE WAS STRUCK BY THE CAR THAT SHE HAD BEEN RIDING IN & SHE WAS WIPED ACROSS THE PLATFORM, SHE WAS  SO SHE WAS WIPED ACROSS THE PLATFORM, SHE WAS STRUCK BY THE CAR THAT SHE HAD BEEN RIDING IN & SHE WAS WIPED ACROSS THE PLATFORM, SHE WAS  SO SHE WAS WIPED ACROSS THE PLATFORM, SHE WAS STRUCK BY THE CAR THAT SHE HAD BEEN RIDING IN & SHE WAS WIPED ACROSS THE PLATFORM, SHE WAS  SO SHE WAS WIPED ACROSS THE PLATFORM, SHE WAS STRUCK BY THE CAR THAT SHE HAD BEEN RIDING IN & SHE WAS WIPED ACROSS THE PLATFORM, SHE WAS  SO SHE WAS WIPED ACROSS THE PLATFORM, SHE WAS STRUCK BY THE CAR THAT SHE HAD BEEN RIDING IN & SHE WAS WIPED ACROSS THE PLATFORM, SHE WAS  SO SHE WAS WIPED ACROSS THE PLATFORM OF THE CAR THAT SHE HAD BEEN RIDING IN & SHE WAS WIPED ACROSS THE PLATFORM, SHE WAS  SO SHE WAS WIPED ACROSS THE PLATFORM OF THE CAR THAT SHE HAD BEEN RIDING IN & SHE WAS WIPED ACROSS THE PLATFORM OF THE CAR THAT SHE HAD BEEN RIDING IN & SHE WAS WIPED ACROSS THE PLATFORM OF THE CAR THAT SHE HAD BEEN RIDING IN & SHE WAS WIPED ACROSS THE PLATFORM OF THE CAR THAT SHE HAD BEEN RIDING IN & SHE WAS WIPED ACROSS THE PLATFORM OF THE CAR THAT SHE HAD BEEN RIDING IN & SHE WAS WIPED ACROSS THE PLATFORM OF THE CAR THAT SHE HAD BEEN RIDING IN & SHE WAS WIPED ACROSS THE PLATFORM OF THE PLATFORM OF THE CAR THAT SHE HAD BEEN RIDING IN & SHE WAS WIPED ACROSS THE PLATFORM OF THE CAR THAT SHE HAD BEEN RIDING IN & SHE WAS WIPED ACROSS THE PLATFORM OF THE PLATFORM	
	A PPLIED THE BRAKES AND ONE CAR DROPPED DOWN ONTO ANOTHER CAR, APPARENTLY AFTER IT BROKE FREE FROM ITS REAR CONNECTION TO AN A FRAME  A PPLIED THE BRAKES AND ONE CAR DROPPED DOWN ONTO ANOTHER CAR, APPARENTLY AFTER IT BROKE FREE FROM ITS REAR CONNECTION TO AN A FRAME  A PPLIED THE BRAKES AND ONE CAR DROPPED DOWN ONTO ANOTHER CAR, APPARENTLY AFTER IT BROKE FREE FROM ITS REAR CONNECTION TO AN A FRAME  A PPLIED THE BRAKES AND ONE CAR DROPPED DOWN ONTO ANOTHER CAR, APPARENTLY AFTER IT BROKE FREE FROM ITS REAR CONNECTION TO AN A FRAME  A PPLIED THE BRAKES AND ONE CAR DROPPED DOWN ONTO ANOTHER CAR, APPARENTLY AFTER IT BROKE FREE FROM ITS REAR CONNECTION TO AN A FRAME  A PPLIED THE BRAKES AND ONE CAR DROPPED DOWN ONTO ANOTHER CAR, APPARENTLY AFTER IT BROKE FREE FROM ITS REAR CONNECTION TO AN A FRAME  A PRICE OF THE BROKE FROM ITS REAR CONNECTION TO AN A FRAME  A PRICE OF THE BROKE FROM ITS REAR CONNECTION TO AN A FRAME  A PRICE OF THE BROKE FREE FROM ITS REAR CONNECTION TO AN A FRAME  A PRICE OF THE BROKE FREE FROM ITS REAR CONNECTION TO AN A FRAME  A PRICE OF THE BROKE FREE FROM ITS REAR CONNECTION TO AN A FRAME  A PRICE OF THE BROKE FREE FROM ITS REAR CONNECTION TO AN A FRAME  A PRICE OF THE BROKE FREE FROM ITS REAR CONNECTION TO AN A FRAME  A PRICE OF THE BROKE FREE FROM ITS REAR CONNECTION TO AN A FRAME  A PRICE OF THE BROKE FREE FROM ITS REAR CONNECTION TO AN A FRAME  A PRICE OF THE BROKE FREE FROM ITS REAR CONNECTION TO AN A FRAME  A PRICE OF THE BROKE FREE FROM ITS REAR CONNECTION TO AN A FRAME  A PRICE OF THE BROKE FREE FROM ITS REAR CONNECTION TO AN A FRAME  A PRICE OF THE BROKE FREE FROM ITS REAR CONNECTION TO AN A FRAME  A PRICE OF THE BROKE FREE FROM ITS REAR CONNECTION TO AN A FRAME  A PRICE OF THE BROKE FREE FROM ITS REAR CONNECTION TO AN A FRAME  A PRICE OF THE BROKE FREE FROM ITS REAR CONNECTION TO AN A FRAME  A PRICE OF THE BROKE FREE FROM ITS REAR CONNECTION TO AN A FRAME  A PRICE OF THE BROKE FREE FROM ITS REAR CONNECTION TO AN A FRAME  A PRICE OF THE BROKE FREE FROM ITS REAR CONNECTION TO AN A FRAME	
	S S S S S S S S S S S S S S S S S S S	
	S S S S S S S S S S S S S S S S S S S	
	S   S   S   S   S   S   S   S   S   S	
	OR APPLIED THE BRAKES AND ONE CAR DROPPED DOWN ONTO ANOTHER CAR, APPARENTLY AFTER IT BROKE FREE FROM ITS REAR CONNECTION TO AN AFRAME OF APPLIED THE BRAKES AND ONE CAR DROPPED DOWN ONTO ANOTHER CAR, APPARENTLY AFTER IT BROKE FREE FROM ITS REAR CONNECTION TO AN AFRAME OF APPLIED THE BRAKES AND ONE CAR DROPPED DOWN ONTO ANOTHER CAR, APPARENTLY AFTER IT BROKE FREE FROM ITS REAR CONNECTION TO AN AFRAME OF APPLIED THE BRAKES AND ONE CAR DROPPED DOWN ONTO ANOTHER CAR, APPARENTLY AFTER IT BROKE FREE FROM ITS REAR CONNECTION TO AN AFRAME OF APPLIED THE BRAKES AND ONE CAR DROPPED DOWN ONTO ANOTHER CAR, APPARENTLY AFTER IT BROKE FREE FROM ITS REAR CONNECTION TO AN AFRAME OF APPLIED THE BRAKES AND ONE CAR DROPPED DOWN ONTO ANOTHER CAR, APPARENTLY AFTER IT BROKE FREE FROM ITS REAR CONNECTION TO AN AFRAME OF APPLIED THE BRAKES AND ONE CAR DROPPED DOWN ONTO ANOTHER CAR, APPARENTLY AFTER IT BROKE FREE FROM ITS REAR CONNECTION TO AN AFRAME OF APPLIED THE BRAKES AND ONE CAR DROPPED DOWN ONTO ANOTHER CAR, APPARENTLY AFTER IT BROKE FREE FROM ITS REAR CONNECTION TO AN AFRAME OF APPLIED THE BRAKES AND ONE CAR DROPPED DOWN ONTO ANOTHER CAR, APPARENTLY AFTER IT BROKE FREE FROM ITS REAR CONNECTION TO AN AFRAME OF APPLIED THE BROKE FREE FROM ITS REAR CONNECTION TO AN AFRAME OF APPLIED THE BROKE FREE FROM ITS REAR CONNECTION TO AN AFRAME OF APPLIED THE BROKE FREE FROM ITS REAR CONNECTION TO AN AFRAME OF APPLIED THE BROKE FREE FROM ITS REAR CONNECTION TO AN AFRAME OF APPLIED THE BROKE FREE FROM ITS REAR CONNECTION TO AN AFRAME OF APPLIED THE BROKE FREE FROM ITS REAR CONNECTION TO AN AFRAME OF APPLIED THE BROKE FREE FROM ITS REAR CONNECTION TO AN AFRAME OF APPLIED THE BROKE FREE FROM ITS REAR CONNECTION TO AN AFRAME OF APPLIED THE BROKE FREE FROM ITS REAR CONNECTION TO AN AFRAME OF APPLIED THE BROKE FREE FROM ITS REAR CONNECTION TO AN AFRAME OF APPLIED THE BROKE FREE FROM ITS REAR CONNECTION TO AN AFRAME OF APPLIED THE BROKE FREE FROM ITS REAR CONNECTION TO AN AFRAME OF APPLIED THE BROKE FREE FROM ITS REAR CONNECTION TO AN AFRAME FREE FRO	
	S   S   S   S   S   S   S   S   S   S	
	ON THE PLATFORM OF THE RIDE & SHE WAS STRUCK BY THE CAR THAT SHE HAD BEEN RIDING IN & SHE WAS WIPED ACROSS THE PLATFORM, SHE WAS  ON THE PLATFORM OF THE RIDE & SHE WAS STRUCK BY THE CAR THAT SHE HAD BEEN RIDING IN & SHE WAS WIPED ACROSS THE PLATFORM, SHE WAS  ON THE PLATFORM OF THE RIDE & SHE WAS STRUCK BY THE CAR THAT SHE HAD BEEN RIDING IN & SHE WAS WIPED ACROSS THE PLATFORM, SHE WAS  ON THE PLATFORM OF THE RIDE & SHE WAS STRUCK BY THE CAR THAT SHE HAD BEEN RIDING IN & SHE WAS WIPED ACROSS THE PLATFORM, SHE WAS  ON THE PLATFORM OF THE RIDE & SHE WAS STRUCK BY THE CAR THAT SHE HAD BEEN RIDING IN & SHE WAS WIPED ACROSS THE PLATFORM, SHE WAS  ON THE PLATFORM OF THE RIDE & SHE WAS STRUCK BY THE CAR THAT SHE HAD BEEN RIDING IN & SHE WAS WIPED ACROSS THE PLATFORM, SHE WAS  ON THE PLATFORM OF THE RIDE & SHE WAS STRUCK BY THE CAR THAT SHE HAD BEEN RIDING IN & SHE WAS WIPED ACROSS THE PLATFORM, SHE WAS  ON THE PLATFORM OF THE RIDE & SHE WAS STRUCK BY THE CAR THAT SHE HAD BEEN RIDING IN & SHE WAS WIPED ACROSS THE PLATFORM, SHE WAS  ON THE PLATFORM OF THE RIDE & SHE WAS STRUCK BY THE CAR THAT SHE HAD BEEN RIDING IN & SHE WAS WIPED ACROSS THE PLATFORM.	
	A APPLIED THE BRAKES AND ONE CAR DROPPED DOWN ONTO ANOTHER CAR, APPARENTLY AFTER IT BROKE FREE FROM ITS REAR CONNECTION TO AN A FRAME  APPLIED THE BRAKES AND ONE CAR DROPPED DOWN ONTO ANOTHER CAR, APPARENTLY AFTER IT BROKE FREE FROM ITS REAR CONNECTION TO AN A FRAME  APPLIED THE BRAKES AND ONE CAR DROPPED DOWN ONTO ANOTHER CAR, APPARENTLY AFTER IT BROKE FREE FROM ITS REAR CONNECTION TO AN A FRAME  APPLIED THE BRAKES AND ONE CAR DROPPED DOWN ONTO ANOTHER CAR, APPARENTLY AFTER IT BROKE FREE FROM ITS REAR CONNECTION TO AN A FRAME  APPLIED THE BRAKES AND ONE CAR DROPPED DOWN ONTO ANOTHER CAR, APPARENTLY AFTER IT BROKE FREE FROM ITS REAR CONNECTION TO AN A FRAME  APPLIED THE BRAKES AND ONE CAR DROPPED DOWN ONTO ANOTHER CAR, APPARENTLY AFTER IT BROKE FREE FROM ITS REAR CONNECTION TO AN A FRAME  APPLIED THE BRAKES AND ONE CAR DROPPED DOWN ONTO ANOTHER CAR, APPARENTLY AFTER IT BROKE FREE FROM ITS REAR CONNECTION TO AN A FRAME  APPLIED THE BRAKES AND ONE CAR DROPPED DOWN ONTO ANOTHER CAR, APPARENTLY AFTER IT BROKE FREE FROM ITS REAR CONNECTION TO AN A FRAME  APPLIED THE BRAKES AND ONE CAR DROPPED DOWN ONTO ANOTHER CAR, APPARENTLY AFTER IT BROKE FREE FROM ITS REAR CONNECTION TO AN A FRAME  APPLIED THE BROKE FREE FROM ITS REAR CONNECTION TO AN A FRAME  APPLIED THE BROKE FREE FROM ITS REAR CONNECTION TO AN A FRAME  APPLIED THE BROKE FREE FROM ITS REAR CONNECTION TO AN A FRAME  APPLIED THE BROKE FREE FROM ITS REAR CONNECTION TO AN A FRAME  APPLIED THE BROKE FREE FROM ITS REAR CONNECTION TO AN A FRAME  APPLIED THE BROKE FREE FROM ITS REAR CONNECTION TO AN A FRAME  APPLIED THE BROKE FREE FROM ITS REAR CONNECTION TO AN A FRAME  APPLIED THE BROKE FREE FROM ITS REAR CONNECTION TO AN A FRAME  APPLIED THE BROKE FREE FROM ITS REAR CONNECTION TO AN A FRAME  APPLIED THE BROKE FREE FROM ITS REAR CONNECTION TO AN A FRAME  APPLIED THE BROKE FREE FROM ITS REAR CONNECTION TO AN A FRAME  APPLIED THE BROKE FREE FROM ITS REAR CONNECTION TO AN A FRAME FREE FROM ITS REAR CONNECTION TO A SHE WAS STRUCK FROM ITS REAR CONNECTION TO A SHE WAS STRU	
	ON THE PLATFORM OF THE RIDE & SHE WAS STRUCK BY THE CAR THAT SHE HAD BEEN RIDING IN & SHE WAS WIFED ACROSS THE FLATFORM, SHE WAS ON THE PLATFORM OF THE RIDE & SHE WAS STRUCK BY THE CAR THAT SHE HAD BEEN RIDING IN & SHE WAS WIFED ACROSS THE FLATFORM, SHE WAS ON THE PLATFORM OF THE RIDE & SHE WAS STRUCK BY THE CAR THAT SHE HAD BEEN RIDING IN & SHE WAS WIFED ACROSS THE FLATFORM, SHE WAS ON THE PLATFORM OF THE RIDE & SHE WAS STRUCK BY THE CAR THAT SHE HAD BEEN RIDING IN & SHE WAS WIFED ACROSS THE FLATFORM, SHE WAS ON THE PLATFORM OF THE RIDE & SHE WAS STRUCK BY THE CAR THAT SHE HAD BEEN RIDING IN & SHE WAS WIFED ACROSS THE FLATFORM, SHE WAS ON THE PLATFORM OF THE RIDE & SHE WAS STRUCK BY THE CAR THAT SHE HAD BEEN RIDING IN & SHE WAS WIFED ACROSS THE FLATFORM, SHE WAS ON THE PLATFORM OF THE RIDE & SHE WAS STRUCK BY THE CAR THAT SHE HAD BEEN RIDING IN & SHE WAS WIFED ACROSS THE FLATFORM, SHE WAS ON THE PLATFORM OF THE RIDE & SHE WAS STRUCK BY THE CAR THAT SHE HAD BEEN RIDING IN & SHE WAS WIFED ACROSS THE FLATFORM, SHE WAS ON THE PLATFORM OF THE RIDE & SHE WAS STRUCK BY THE CAR THAT SHE HAD BEEN RIDING IN & SHE WAS WIFED ACROSS THE FLATFORM, SHE WAS ON THE PLATFORM OF THE RIDE & SHE WAS STRUCK BY THE CAR THAT SHE HAD BEEN RIDING IN & SHE WAS WIFED ACROSS THE FLATFORM, SHE WAS ON THE PLATFORM OF THE RIDE & SHE WAS STRUCK BY THE CAR THAT SHE HAD BEEN RIDING IN & SHE WAS WIFED ACROSS THE FLATFORM, SHE WAS ON THE PLATFORM OF THE RIDE & SHE WAS STRUCK BY THE CAR THAT SHE HAD BEEN RIDING IN & SHE WAS WIFED ACROSS THE FLATFORM.	
	APPLIED THE BRAKES AND ONE CAR DROPPED DOWN ONTO ANOTHER CAR, APPARENTLY AFTER IT BROKE FREE FROM ITS REAR CONNECTION TO AN A FRAME  APPLIED THE BRAKES AND ONE CAR DROPPED DOWN ONTO ANOTHER CAR, APPARENTLY AFTER IT BROKE FREE FROM ITS REAR CONNECTION TO AN A FRAME  NOT THE PLATFORM OF THE RIDE, & SHE WAS STRUCK BY THE CAR THAT SHE HAD BEEN RIDING IN & SHE WAS WIPED ACROSS THE PLATFORM, SHE WAS  NOT THE PLATFORM OF THE RIDE, & SHE WAS STRUCK BY THE CAR THAT SHE HAD BEEN RIDING IN & SHE WAS WIPED ACROSS THE PLATFORM, SHE WAS  NOT THE PLATFORM OF THE RIDE, & SHE WAS STRUCK BY THE CAR THAT SHE HAD BEEN RIDING IN & SHE WAS WIPED ACROSS THE PLATFORM, SHE WAS  NOT THE PLATFORM OF THE RIDE, & SHE WAS STRUCK BY THE CAR THAT SHE HAD BEEN RIDING IN & SHE WAS WIPED ACROSS THE PLATFORM, SHE WAS  NOT THE PLATFORM OF THE RIDE, & SHE WAS STRUCK BY THE CAR THAT SHE HAD BEEN RIDING IN & SHE WAS WIPED ACROSS THE PLATFORM, SHE WAS  NOT THE PLATFORM OF THE RIDE, & SHE WAS STRUCK BY THE CAR THAT SHE HAD BEEN RIDING IN & SHE WAS WIPED ACROSS THE PLATFORM, SHE WAS  NOT THE PLATFORM OF THE RIDE, & SHE WAS STRUCK BY THE CAR THAT SHE HAD BEEN RIDING IN & SHE WAS WIPED ACROSS THE PLATFORM, SHE WAS  NOT THE PLATFORM OF THE RIDE, & SHE WAS STRUCK BY THE CAR THAT SHE HAD BEEN RIDING IN & SHE WAS WIPED ACROSS THE PLATFORM, SHE WAS  NOT THE PLATFORM OF THE RIDE, & SHE WAS STRUCK BY THE CAR THAT SHE HAD BEEN RIDING IN & SHE WAS WIPED ACROSS THE PLATFORM, SHE WAS  NOT THE PLATFORM OF THE RIDE, & SHE WAS STRUCK BY THE CAR THAT SHE HAD BEEN RIDING IN & SHE WAS WIPED ACROSS THE PLATFORM, SHE WAS  NOT THE PLATFORM OF THE RIDE, & SHE WAS STRUCK BY THE CAR THAT SHE HAD BEEN RIDING IN & SHE WAS WIPED ACROSS THE PLATFORM, SHE WAS  NOT THE PLATFORM OF THE RIDE, SHE WAS SHE WAS SHE WAS WIPED ACROSS THE PLATFORM OF THE P	
	APPLIED THE BRAKES AND ONE CAR DROPPED DOWN ONTO ANOTHER CAR, APPARENTLY AFTER IT BROKE FREE FROM ITS REAR CONNECTION TO AN A FRAME  APPLIED THE BRAKES AND ONE CAR DROPPED DOWN ONTO ANOTHER CAR, APPARENTLY AFTER IT BROKE FREE FROM ITS REAR CONNECTION TO AN A FRAME  APPLIED THE BRAKES AND ONE CAR DROPPED DOWN ONTO ANOTHER CAR, APPARENTLY AFTER IT BROKE FREE FROM ITS REAR CONNECTION TO AN A FRAME  APPLIED THE BRAKES AND ONE CAR DROPPED DOWN ONTO ANOTHER CAR, APPARENTLY AFTER IT BROKE FREE FROM ITS REAR CONNECTION TO AN A FRAME  APPLIED THE BRAKES AND ONE CAR DROPPED DOWN ONTO ANOTHER CAR, APPARENTLY AFTER IT BROKE FREE FROM ITS REAR CONNECTION TO AN A FRAME  APPLIED THE BRAKES AND ONE CAR DROPPED DOWN ONTO ANOTHER CAR, APPARENTLY AFTER IT BROKE FREE FROM ITS REAR CONNECTION TO AN A FRAME  APPLIED THE BRAKES AND ONE CAR DROPPED DOWN ONTO ANOTHER CAR, APPARENTLY AFTER IT BROKE FREE FROM ITS REAR CONNECTION TO AN A FRAME  APPARENTLY AFTER ITS REAR CONNECTION TO AN A FRAME ITS REAR CONNECTION TO AN A FRAME ITS REAR CONNECTION TO AN A FRAME ITS REAR	
	APPLIED THE BRAKES AND ONE CAR DROPPED DOWN ONTO ANOTHER CAR APPARENTLY APTER IT BROKE FREE FROM ITS REAR CONNECTION TO AN A TRAME  APPLIED THE BRAKES AND ONE CAR DROPPED DOWN ONTO ANOTHER CAR APPARENTLY APTER IT BROKE FREE FROM ITS REAR CONNECTION TO AN A TRAME  APPLIED THE BRAKES AND ONE CAR DROPPED DOWN ONTO ANOTHER CAR APPARENTLY APTER IT BROKE FREE FROM ITS REAR CONNECTION TO AN A TRAME  APPLIED THE BRAKES AND ONE CAR DROPPED DOWN ONTO ANOTHER CAR APPARENTLY APTER IT BROKE FREE FROM ITS REAR CONNECTION TO AN A TRAME  APPLIED THE BRAKES AND ONE CAR DROPPED DOWN ONTO ANOTHER CAR APPARENTLY APTER IT BROKE FREE FROM ITS REAR CONNECTION TO AN A TRAME  APPLIED THE BRAKES AND ONE CAR DROPPED DOWN ONTO ANOTHER CAR APPARENTLY APTER IT BROKE FREE FROM ITS REAR CONNECTION TO AN A TRAME  APPLIED THE BRAKES AND ONE CAR DROPPED DOWN ONTO ANOTHER CAR APPARENTLY APTER IT BROKE FREE FROM ITS REAR CONNECTION TO AN A TRAME  APPLIED THE BRAKES AND ONE CAR DROPPED DOWN ONTO ANOTHER CAR APPARENTLY APTER IT BROKE FREE FROM ITS REAR CONNECTION TO AN A TRAME  APPLIED THE BROKE FREE FROM ITS REAR CONNECTION TO AN A TRAME  APPLIED THE BROKE FREE FROM ITS REAR CONNECTION TO AN A TRAME  APPLIED THE BROKE FREE FROM ITS REAR CONNECTION TO AN A TRAME  APPLIED THE BROKE FREE FROM ITS REAR CONNECTION TO AN A TRAME  APPLIED THE BROKE FREE FROM ITS REAR CONNECTION TO AN A TRAME  APPLIED THE BROKE FREE FROM ITS REAR CONNECTION TO AN A TRAME  APPLIED THE BROKE FREE FROM ITS REAR CONNECTION TO AN A TRAME  APPLIED THE BROKE FREE FROM ITS REAR CONNECTION TO AN A TRAME  APPLIED THE BROKE FREE FROM ITS REAR CONNECTION TO AN A TRAME  APPLIED THE BROKE FREE FROM ITS REAR CONNECTION TO AN A TRAME  APPLIED THE BROKE FREE FROM ITS REAR CONNECTION TO AN A TRAME  APPLIED THE BROKE FREE FROM ITS REAR CONNECTION TO AN A TRAME  APPLIED THE BROKE FREE FROM ITS REAR CONNECTION TO AN A TRAME  APPLIED THE BROKE FREE FROM ITS REAR CONNECTION TO A TRAME FREE FROM ITS REAR CONNECTION TO A TRANE  APPLIED THE BROKE FREE FROM ITS REAR CONNECTION TO A TRANE  APPLIED TH	
	ON THE PLATFORM OF THE RIDE & SHE WAS STRUCK BY THE CAR THAT SHE HAD BEEN RIDING IN & SHE WAS WIPED ACROSS THE PLATFORM, SHE WAS  ON THE PLATFORM OF THE RIDE & SHE WAS STRUCK BY THE CAR THAT SHE HAD BEEN RIDING IN & SHE WAS WIPED ACROSS THE PLATFORM, SHE WAS  ON THE PLATFORM OF THE RIDE & SHE WAS STRUCK BY THE CAR THAT SHE HAD BEEN RIDING IN & SHE WAS WIPED ACROSS THE PLATFORM, SHE WAS  ON THE PLATFORM OF THE RIDE & SHE WAS STRUCK BY THE CAR THAT SHE HAD BEEN RIDING IN & SHE WAS WIPED ACROSS THE PLATFORM, SHE WAS  ON THE PLATFORM OF THE RIDE & SHE WAS STRUCK BY THE CAR THAT SHE HAD BEEN RIDING IN & SHE WAS WIPED ACROSS THE PLATFORM, SHE WAS  ON THE PLATFORM OF THE RIDE & SHE WAS STRUCK BY THE CAR THAT SHE HAD BEEN RIDING IN & SHE WAS WIPED ACROSS THE PLATFORM, SHE WAS  ON THE PLATFORM OF THE RIDE & SHE WAS STRUCK BY THE CAR THAT SHE HAD BEEN RIDING IN & SHE WAS WIPED ACROSS THE PLATFORM, SHE WAS  ON THE PLATFORM OF THE RIDE & SHE WAS STRUCK BY THE CAR THAT SHE HAD BEEN RIDING IN & SHE WAS WIPED ACROSS THE PLATFORM, SHE WAS  ON THE PLATFORM OF THE RIDE & SHE WAS STRUCK BY THE CAR THAT SHE HAD BEEN RIDING IN & SHE WAS WIPED ACROSS THE PLATFORM, SHE WAS  ON THE PLATFORM OF THE RIDE & SHE WAS STRUCK BY THE CAR THAT SHE HAD BEEN RIDING IN & SHE WAS WIPED ACROSS THE PLATFORM OF T	
	ON THE PLATFORM OF THE RIDE & SHE WAS STRUCK BY THE CAR THAT SHE HAD BEEN RIDING IN & SHE WAS WIPED ACROSS THE PLATFORM, SHE WAS THE PLATFORM OF THE RIDE & SHE WAS STRUCK BY THE CAR THAT SHE HAD BEEN RIDING IN & SHE WAS WIPED ACROSS THE PLATFORM, SHE WAS TO THE PLATFORM OF THE RIDE & SHE WAS STRUCK BY THE CAR THAT SHE HAD BEEN RIDING IN & SHE WAS WIPED ACROSS THE PLATFORM, SHE WAS TO THE PLATFORM OF THE RIDE & SHE WAS STRUCK BY THE CAR THAT SHE HAD BEEN RIDING IN & SHE WAS WIPED ACROSS THE PLATFORM, SHE WAS TO THE PLATFORM OF THE RIDE & SHE WAS STRUCK BY THE CAR THAT SHE HAD BEEN RIDING IN & SHE WAS WIPED ACROSS THE PLATFORM, SHE WAS THE PLATFORM OF THE RIDE & SHE WAS STRUCK BY THE CAR THAT SHE HAD BEEN RIDING IN & SHE WAS WIPED ACROSS THE PLATFORM, SHE WAS THE PLATFORM OF THE RIDE & SHE WAS STRUCK BY THE CAR THAT SHE HAD BEEN RIDING IN & SHE WAS WIPED ACROSS THE PLATFORM, SHE WAS THE PLATFORM OF THE RIDE & SHE WAS STRUCK BY THE CAR THAT SHE HAD BEEN RIDING IN & SHE WAS WIPED ACROSS THE PLATFORM, SHE WAS THE PLATFORM OF THE RIDE & SHE WAS STRUCK BY THE CAR THAT SHE HAD BEEN RIDING IN & SHE WAS WIPED ACROSS THE PLATFORM, SHE WAS THE PLATFORM OF THE RIDE & SHE WAS STRUCK BY THE CAR THAT SHE HAD BEEN RIDING IN & SHE WAS WIPED ACROSS THE PLATFORM, SHE WAS THE PLATFORM OF THE RIDE & SHE WAS STRUCK BY THE CAR THAT SHE HAD BEEN RIDING IN & SHE WAS WIPED ACROSS THE PLATFORM, SHE WAS THE PLATFORM OF THE RIDE & SHE WAS STRUCK BY THE CAR THAT SHE HAD BEEN RIDING IN & SHE WAS WIPED ACROSS THE PLATFORM OF THE RIDE OF THE RIDE OF THE RIDING IN A SHE WAS WIPED ACROSS THE PLATFORM OF THE RIDE OF THE RIDING IN A SHE WAS WIPED ACROSS THE PLATFORM OF THE RIDE OF THE RIDE OF THE RIDING IN A SHE WAS WIPED ACROSS THE PLATFORM OF THE RIDE	
	S S S S S S S S S S S S S S S S S S S	
	S S S S S S S S S S S S S S S S S S S	
	S S S S S S S S S S S S S S S S S S S	
	S S S S S S S S S S S S S S S S S S S	

	Narrative (coauseed)	1
2	TAKEN TO THE HOSPITAL UNCONSCIOUS BUT REPORTEDLY HAS GAINED CONSCIOUSNESS AND IS RECOVERING	ł
3	FRAME OF THE RIDE CAME OUT THE RIDE WAS STOPPED AND THE RIDERS IN-CLUDING THE VICTIM WERE OFFERED MEDICAL TREATMENT BUT DECLINED	1
- 5		1
7	WERE RELEASED	1
9		1
10		1
11		₹′
13		1
14 15		┨
16	PLATE BROKE	7
18		1
19 20		1
21 22	MONOR INJURIES	7
25		1
24		4
26 27		7
2		Ⅎ
29 30		7
31	RELEASED AFTER THE TREATMENT INSPECTION OF THE RIDE AFTER THE ACCIDENT BY A STATE RIDE INSPECTOR DETERMINED THE ACCIDENT WAS NOT THE RESULT OF A MECHANICAL OPERATION	1
32	E-MECTION OF THE CAMP IN THE C	3
34 33	HOSPITALIZED THE 9 YEAR OLD VICTIM SUFFERED EXTENSIONS & ABRASIONS	7
36		7
37		$\exists$
19	ACCIDENT OCCURRED AT A STATE FAIR	7
41	STOP THE RIDE AGAIN BUT COULD NOT DO SO. THE VICTOM WAS THROWN FROM THE RIDE	_
42		┨
44		7
46	LACERATIONS A CHECK OF THE RIDE INDICATED THAT A FIN HAD BEEN REMOVED FROM THE "TUB" WHICH CONNECTED IT TO THE FRAME	╛
47	LACERATIONS A CRECK OF THE RIDE INDICATED THAT ATTAINED	┨
49	PLATFORM AT THE NORTH END OF THE FERRIS WHEEL. THE CAR THEN CONTINUED MOVING IN A COUNTERCLOCKWISE DIRECTION. THE RIDE OPERATOR	7
31	FEATIVAL AT THE POSITION OF TH	╛
52		ᅱ
35	SHOULDER RESTRAINT & SHE THEN GOT OUT OF THE CAR THROUGH A HOLE IN THE CAR'S TOP THE GIRL THEN FELL FROM THE CAR & SHE LANDED	$\exists$
36	SPACE CAPSULE, WAS DRAGGED ALONG THE GROUND FOR 13-20 FEET NO SERIOUS INJURY	╛
57 58		ᅱ
39		二
61		ᆸ
43		刁
3		コ
		Ⅎ
67		$\dashv$
69		コ
70	DEVELOPMENT OF A MORE ADEQUATE RESTRAINT SYSTEM	$\exists$
72		
74		
75		-
77		
75	TAKEN TO THE HOSPITAL UNCONSCIOUS BUT REPORTEDLY HAS GAINED CONSCIOUSNESS AND IS RECOVERING	
84		
E		
8		
1:		

	Narrative (continued)
<del></del>	······································
3	
•	
10	
Ξ	
12	
13_	
14	
15	
16	
17	
18	
-:	
19	
20	
21 22 23	
22	
23	
24	
25	
26	
27	
28	
29	
70	
20	
31	
1 44	
35.	
34 33	
33	
36 37	
37	
38	
39	
40	
4	
42	
43	
4	
45	
46	
46 47	
46 47 48	
46 47 48	
46 47 48 49 50	SUPPORT BAR. THE CAR, WHICH BROKE FREE FROM ITS REAR CONNECTION. THEN DAMAGED THE CAR BELOW IT AS IT STRUCK THE CAR, AND THE TWO CARS
46 47 48 49 50	SUPPORT BAR. THE CAR, WHICH BROKE FREE FROM IT'S REAR CONNECTION. THEN DAMAGED THE CAR BELOW IT AS IT STRUCK THE CAR, AND THE TWO CARS
46 47 48 49 50	SUPPORT BAR. THE CAR, WHICH BROKE FREE FROM IT'S REAR CONNECTION. THEN DAMAGED THE CAR BELOW IT AS IT STRUCK THE CAR, AND THE TWO CARS
46 47 48 49 50	
46 47 48 49 50	
46 47 48 49 50	SUPPORT BAR. THE CAR, WHICH BROKE FREE FROM ITS REAR CONNECTION. THEN DAMAGED THE CAR BELOW IT AS IT STRUCK THE CAR, AND THE TWO CARS  FRONOUNCED DECEASED.
46 47 48 49 50	
46 47 48 49 50 51 53 53 54 55 55 56 60 61 62 63	
46 47 48 49 50 51 53 53 54 55 55 56 60 61 62 63	
46 47 48 49 50 51 51 52 53 54 55 55 56 57 58 60 61 62 64 64 65	PRONOUNCED DECEASED
46 47 48 49 50 51 51 52 53 54 55 55 56 57 58 60 61 62 64 64 65	PRONOUNCED DECEASED
46 47 48 49 50 51 51 52 53 54 55 55 56 57 58 60 61 62 64 64 65	PRONOUNCED DECEASED
46 47 48 49 50 51 52 53 53 54 55 55 56 61 62 62 63 64 65	PRONOUNCED DECEASED
46 47 48 49 50 51 51 52 53 54 55 55 55 56 61 62 63 64 65 65 66 67	PRONOUNCED DECEASED
46 47 48 49 50 51 51 52 53 54 55 55 56 60 61 62 63 64 65 67	PRONOUNCED DECEASED
46 47 48 49 50 51 51 52 53 54 55 55 56 61 61 62 63 64 65 67	PRONOUNCED DECEASED
46 47 48 49 50 51 51 52 53 54 55 55 55 56 61 62 63 64 65 65 66 67	PRONOUNCED DECEASED