

Progress 360 Docking to SM aft.**SM (Aft) / Progress 360 Interface Leak Check**

GMT	CREW	ACTIVITY
00:40-00:50	.	Morning Inspection
00:50-01:20	.	Post-Sleep
01:20-02:10	.	Breakfast
02:10-02:40	.	Work Prep
02:40-02:55	.	Daily Planning Conference (<i>S-band</i>)
02:55-03:10		A31P Laptop Activation
03:10-03:15	FE-2	ALTEA: Hardware Deactivation
03:15-03:20		Closing LAB Window Shutter
03:15-03:45		Progress 360 Docking Prep
03:45-05:15	CDR, FE-1	Progress360 Docking to SM Aft <i>BM LIV Video Imagery of Docking</i>
05:15-05:25	FE-1	Post-Progress Dock/Undock Comm Reconfig
05:15-05:45	FE-2	Teardown of test TV hardware for video downlink via Ku-band (post Progress 360 dock)
05:55-06:55		Physical Exercise - RED
06:30-07:45	CDR, FE-1	SM (Aft) / Progress 360 Interface Leak Check
06:55-07:25	FE-2	LOCAD: Experiment Hardware Install
07:25-07:45		LOCD: Sample Prep
07:45-08:05	CDR, FE-1	PPK-CY and TKF-CY Hatch Opening
07:45-08:00	FE-2	LOCD: Sampling Ops
08:00-08:15		LOCD: Sampling Ops
08:05-08:25	CDR, FE-1	Quick-Disconnect Clamp Install
08:15-08:30	FE-2	LOCD: Sampling Ops
08:25-08:30	CDR	Node 1 and Airlock Luminaire Activation
08:25-08:40	FE-1	Progress Air Sampling Using AK-1M
08:30-08:45	FE-2	LOCD: Sampling Ops
08:40-09:10	FE-1	Progress Deactivation, Airduct Install
08:45-09:05	FE-2	LOCAD: Kit 1
09:05-09:10		DCP Power Cable Demate
09:10-10:10	.	Lunch
10:10-11:10	CDR, FE-2	Progress 360 Docking Mechanism Disassembly
11:10-12:40	CDR	Progress 360 unloading w/IMS support
11:10-12:10	FE-1	
11:30-11:40		ALTEA: Dosimeter Activation
11:55-12:00	FE-2	ALTEA: Dosimeter Activation
12:10-13:40		Progress 360 unloading w/IMS support
12:10-12:40	FE-1	STATOKONIA. Hardware Transfer to and Install in SM
12:40-13:40	CDR	Physical Exercise (RED) – Day 4
13:30-13:45	FE-1	Private Medical Conference (<i>Ku+S-band</i>)
13:40-15:10	FE-2	Physical Exercise - TVIS
13:45-14:05	FE-1	IMS Updates

14:05-15:05		Physical Exercise (RED) – Day 4
14:40-14:55	CDR	Private Medical Conference (<i>Ku+S-band</i>)
15:10-15:15	FE-2	TVIS, RED, CEVIS, and HRM Data Transfer to MEC
15:15-15:20		HAM Radio Setup
15:20-15:30		HAM Radio Pass
15:40-16:10		COX Maintenance
16:15-16:30	.	Daily Planning Conference (<i>S-band</i>)
16:50-17:05	FE-2	Private Medical Conference (<i>Ku+S-band</i>)
18:30-19:30	.	Evening Work Prep
19:30-20:00	.	Dinner
20:00-20:30	.	Daily Food Prep
20:30-21:30	.	Pre-Sleep
21:30-06:00	.	Sleep
Task List	FE-1	Condensate Transfer from CWC to EDV using filter

Note: Cf. OSTP for any missing references to US Activities.

End of Radiogram