ADDRESSES: Comments on this application may be mailed or delivered in triplicate to the FAA at the following address: David S. Stelling, Manager; Helena Airports District Office, HLN–ADO; Federal Aviation Administration; FAA Building, Suite 2; 2725 Skyway Drive, Helena, Montana 59602–1213.

In addition, one copy of any comments submitted to the FAA must be mailed or delivered to John Seymour, AAE, Director of Airports: Missoula County Airport Authority, 5225 Highway 10 West, Missoula, Montana 59808.

Air Carriers and foreign air carriers may submit copies of written comments previously provided to Missoula International Airport, under section 158.23 of part 158.

FOR FURTHER INFORMATION CONTACT:

David S. Stelling, Manager; Helena Airports District Office, HLN–ADO; Federal Aviation Administration; FAA Building, Suite 2; 2725 Skyway Drive, Helena, Montana 59602–1213. The application may be reviewed in person at this same location.

SUPPLEMENTARY INFORMATION: The FAA proposes to rule and invites public comment on the application 03–04–C–00–MSO to impose and use PFC revenue at Missoula International Airport, under the provisions of 49 U.S.C. 40117 and part 158 of the Federal Aviation Regulations (14 CFR Part 158).

On November 13, 2002, the FAA determined that the application to impose and use the revenue from a PFC submitted by Missoula County Airport Authority, Missoula International Airport, Missoula, Montana, was substantially complete within the requirements of section 158.25 of Part 158. The FAA will approve or disapprove the application, in whole or in part, no later than March 5, 2003.

The following is a brief overview of the application.

Level of the proposed PFC: \$4.50. Proposed charge—effective date: February 1, 2004.

Proposed charge—expiration date: April 1, 2006.

Total requested for use approval: \$832,464.

Brief description of proposed project: Rehabilitate air carrier apron (Phrase

Class or classes of air carriers, which the public agency has requested not be required to collect PFC's: Air Taxi/ Commercial Operators (ATCO) filing FAA Form 1800–31.

Any person may inspect the application in person at the FAA office listed above under FOR FURTHER INFORMATION CONTACT and at the FAA

Regional Airports Office located at: Federal Aviation Administration, Northwest Mountain Region, Airports Division, ANM–600, 1601 Lind Avenue SW., Suite 315, Renton, WA 98055– 4056.

In addition, any person may, upon request, inspect the application, notice and other documents germane to the application in person at the Missoula International Airport.

Issued in Renton, Washington on November 13, 2002.

David A. Field,

Manager, Planning, Programming and Capacity Branch, Northwest Mountain Region.

[FR Doc. 02–29663 Filed 11–20–02; 8:45 am] BILLING CODE 4910–13–M

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

Notice of Intent To Rule on Application To Impose and Use the Revenue From a Passenger Facility Charge (PFC) at Palm Beach International Airport, West Palm Beach, FL

AGENCY: Federal Aviation Administration (FAA), DOT. ACTION: Notice of intent to rule on application.

SUMMARY: This correction revises information from the previously published notice. In notice document 02–26585 appearing on page 64444 in the issue of Friday, October 18, 2002, under **SUPPLEMENTARY INFORMATION**, in the first column, in the 48th line, the PFC Application No., should read, 02–07–C–00–PBI.

FOR FURTHER INFORMATION CONTACT:

Matthew J. Thys, Program Manager, Orlando Airports District Office, 5950 Hazeltine National Drive, Suite 400, Orlando, FL 32822, (407) 812–6331.

Issued in Orlando, Florida on November 13, 2002.

W. Dean Stringer,

Manager, Orlando Airports District Office, Southern Region.

[FR Doc. 02–29665 Filed 11–20–02; 8:45 am]

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration [Proposed Policy Statement No. ANE-2002-35.15-R0]

Policy for Propeller Safety Analysis

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed policy statement; request for comments.

SUMMARY: The Federal Aviation Administration (FAA) announces the availability of proposed policy for propeller safety analysis.

DATES: Comments must be received by January 20, 2003.

ADDRESSES: Send all comments on the proposed policy to the individual identified under **FOR FURTHER INFORMATION CONTACT.**

FOR FURTHER INFORMATION CONTACT: Jay Turnberg, FAA, Engine and Propeller Standards Staff, ANE–110, 12 New England Executive Park, Burlington, MA 01803; e-mail: *jay.turnberg@faa.gov*; telephone: (781) 238–7116; fax: (781) 238–7199.

SUPPLEMENTARY INFORMATION:

Comments Invited

The proposed policy statement is available on the Internet at the following address: http://www/airweb/faa/gov/rgl. If you do not have access to the Internet, you may request a copy by contacting the individual listed under FOR FURTHER **INFORMATION CONTACT.** The FAA invites interested parties to comment on the proposed policy. Comments should identify the subject of the proposed policy and be submitted to the individual identified under FOR FURTHER INFORMATION CONTACT. The FAA will consider all comments received by the closing date before issuing the final policy.

Background

The intent of this proposed policy is to provide guidance for conducting a propeller safety analysis. Although part 35 of Title 14 of the Code of Federal Regulations (14 CFR part 35) does not explicitly require a safety analysis, safety analyses are frequently conducted to support part 35 requirements, special conditions, and aircraft manufacturer certification requirements. The proposed policy would not establish new requirements.

Authority: 49 U.S.C. 106(g), 40113, 44701–44702, 44704.

Issued in Burlington, Massachusetts, on November 6, 2002.

Francis A. Favara,

Assistant Manager, Engine and Propeller Directorate, Aircraft Certification Service. [FR Doc. 02–29662 Filed 11–20–02; 8:45 am]