Radiogram No. 513 Form 24 for 01.29.2001

IMAX Operations

GMT	Crew	Activity and links to ODF or R/G
06:00-06:10		Morning inspection
06:10-06:40		Post-sleep
06:40-07:30		BREAKFAST
07:30-07:40		Daily planning conference (morning) via OCA
07:40-08:10		Work prep
08:10–10:10		Review 5A flight plan / ÎÑÀ_0918, ÎÑÀ_0919
10:10–10:35		Monthly TVIS maintenance / ÎÑÀ_1116 step 3
10:35–11:35	CDR	Physical exercise (TVIS)
10:40–10:50	FE-1	Inspect ÁÐ ÏÊ-1 separator
11:30–13:00	FE-1	Physical exercise (TVIS-1)
11:35–12:00	CDR	Replace IRED cables / ÎÑÀ_1067
12:00–13:00	CDR	Earth observations (candidate activity) on GO from MCC
12:00–13:00	PLT	Physical exercise (IRED-1)
13:00–14:00		LUNCH
14:00–16:00	FE-1, CDR	IMAX setup / Đ/Ã ÎÑÀ_1003
14:00–14:30	PLT	Verify zero airflow using È Ï-1 sensors in SM & FGB / <u>r/g 514</u>
16:00–16:15	PLT	Replace Ñ Î2 ÈÊ0501 filter assembly (ÁÔ) / Ñ ÎÃÑ Ñ Ì item 10.11.2, pg. 10-13
16:00–17:00	FE-1	Physical exercise (IRED-1)
16:20–16:50	PLT	Verify zero airflow using È Ï-1 sensors in SM & FGB / <u>r/g 514</u>
16:50–18:15	CDR	Physical exercise (IRED)
16:50–18:15	PLT	Physical exercise (TVIS-1)
17:25–17:55	FE-1	Checkout ÀÏÑ ÏÑÑ panel / <u>r/g 367</u>
17:55–18:15	FE-1	Prep delta file for downlink
18:15–18:45		Report prep
18:45–19:15		Review plan for the next day
19:15–19:30		Daily planning conference (evening)
19:30–20:00		DINNER
20:00–20:30		Daily food ration prep
20:30–21:30		Pre-sleep
21:30-06:00		SLEEP

End of radiogram