December 3, 2001

Mr. Ted C. Feigenbaum Executive Vice President and Chief Nuclear Officer North Atlantic Energy Service Corporation c/o Mr. James M. Peschel P.O. Box 300 Seabrook, NH 03874

SUBJECT: BULLETIN 2001-01, "CIRCUMFERENTIAL CRACKING OF REACTOR PRESSURE VESSEL HEAD PENETRATION NOZZLES," RESPONSES FOR SEABROOK STATION, UNIT NO. 1 (TAC NO. MB2669)

Dear Mr. Feigenbaum:

On August 3, 2001, the staff issued Bulletin 2001-01, "Circumferential Cracking of Reactor Pressure Vessel Head Penetration Nozzles," to the industry requesting that addressees provide information related to the structural integrity of the reactor pressure vessel head penetration (VHP) nozzles for their respective facilities, including the extent of VHP nozzle leakage and cracking that has been found to date, the inspections and repairs that have been undertaken to satisfy applicable regulatory requirements, and the basis for concluding that their plans for future inspections will ensure compliance with applicable regulatory requirements at their respective pressurized water reactor plants. You were requested to provide your response to Item 1 of the Bulletin within 30 days of its issuance.

You provided your response by letter dated August 31, 2001. The staff finds that you have provided the requested information and that, based on this information, there is reasonable assurance that the public health and safety will be maintained.

Addressees are reminded that Item 5 of the bulletin requested the following information within 30 days after plant restart following the next refueling outage:

a. A description of the extent of VHP nozzle leakage and cracking detected at your plant, including the number, location, size, and nature of each crack detected;

T. Feigenbaum

b. If cracking is identified, a description of the inspections (type, scope, qualification requirements, and acceptance criteria), repairs, and other corrective actions you have taken to satisfy applicable regulatory requirements. This information is requested only if there are any changes from prior information submitted in accordance with this bulletin.

Sincerely,

/**RA**/

George F. Wunder, Project Manager, Section 2 Project Directorate I Division of Licensing Project Management Office of Nuclear Reactor Regulation

Docket No. 50-443

cc: See next page

T. Feigenbaum

b. If cracking is identified, a description of the inspections (type, scope, qualification requirements, and acceptance criteria), repairs, and other corrective actions you have taken to satisfy applicable regulatory requirements. This information is requested only if there are any changes from prior information submitted in accordance with this bulletin.

Sincerely,

/RA/

George F. Wunder, Project Manager, Section 2 Project Directorate I Division of Licensing Project Management Office of Nuclear Reactor Regulation

Docket No. 50-443

cc: See nest page

DISTRIBUTION:

PUBLIC PDI-2 R/F EMCB R/F TClark

JClifford GWunder JZimmerman OGC ACRS CAnderson, DRP WBateman AHiser **JCollins**

ACCESSION NO.: ML013310326

OFFICE	PDI-2/PM	PDI-2/LA	PDI-2/SC
NAME	GWunder	TClark	JClifford
DATE	11/29/01	11/29/01	12/3/01

OFFICIAL RECORD

Seabrook Station, Unit No. 1 cc:

William J. Quinlan, Esq. Assistant General Counsel Northeast Utilities Service Company P.O. Box 270 Hartford, CT 06141-0270

Mr. Peter Brann Assistant Attorney General State House, Station #6 Augusta, ME 04333

Resident Inspector U.S. Nuclear Regulatory Commission Seabrook Nuclear Power Station P.O. Box 1149 Seabrook, NH 03874

Town of Exeter 10 Front Street Exeter, NH 03823

Regional Administrator, Region I U.S. Nuclear Regulatory Commission 475 Allendale Road King of Prussia, PA 19406

Office of the Attorney General One Ashburton Place 20th Floor Boston, MA 02108

Board of Selectmen Town of Amesbury Town Hall Amesbury, MA 01913

Mr. Dan McElhinney Federal Emergency Management Agency Region I J.W. McCormack P.O. & Courthouse Building, Room 401 Boston, MA 02109 Mr. Stephen McGrail, Director ATTN: James Muckerheide Massachusetts Emergency Management Agency 400 Worcester Road Framingham, MA 01702-5399

Philip T. McLaughlin, Attorney General Steven M. Houran, Deputy Attorney General 33 Capitol Street Concord, NH 03301

Mr. Woodbury Fogg, Director New Hampshire Office of Emergency Management State Office Park South 107 Pleasant Street Concord, NH 03301

Mr. Daniel G. Roy Nuclear Training Manager Seabrook Station North Atlantic Energy Service Corp. P.O. Box 300 Seabrook, NH 03874

Mr. James M. Peschel Manager - Regulatory Programs Seabrook Station North Atlantic Energy Service Corp. P.O. Box 300 Seabrook, NH 03874

Mr. Gene F. St. Pierre Station Director Seabrook Station North Atlantic Energy Service Corporation P.O. Box 300 Seabrook, NH 03874

Mr. Frank W. Getman, Jr. President and Chief Executive Officer BayCorp Holdings, LTD 20 International Drive, Suite 301 Portsmouth, NH 03801-6809 Seabrook Station, Unit No. 1 cc:

Mr. Bruce D. Kenyon President and Chief Executive Officer Northeast Utilities Service Company P.O. Box 270 Hartford, CT 06141-0270

Mr. Steve Allen Polestar Applied Technology, Inc. 77 Franklin Street, Suite 507 Boston, MA 02110