good repair to prevent accidents and injuries to employees.

## § 77.201 Methane content in surface installations.

The methane content in the air of any structure, enclosure or other facility shall be less than 1.0 volume per centum

# § 77.201-1 Tests for methane; qualified person; use of approved device.

Tests for methane in structures, enclosures, or other facilities, in which coal is handled or stored shall be conducted by a qualified person with a device approved by the Secretary at least once during each operating shift, and immediately prior to any repair work in which welding or an open flame is used, or a spark may be produced.

# § 77.201-2 Methane accumulations; change in ventilation.

If, at any time, the air in any structure, enclosure or other facility contains 1.0 volume per centum or more of methane changes or adjustments in the ventilation of such installation shall be made at once so that the air shall contain less than 1.0 volume per centum of methane.

## § 77.202 Dust accumulations in surface installations.

Coal dust in the air of, or in, or on the surfaces of, structures, enclosures, or other facilities shall not be allowed to exist or accumulate in dangerous amounts.

# § 77.203 Use of material or equipment overhead; safeguards.

Where overhead repairs are being made at surface installations and equipment or material is taken into such overhead work areas, adequate protection shall be provided for all persons working or passing below the overhead work areas in which such equipment or material is being used.

# § 77.204 Openings in surface installations; safeguards.

Openings in surface installations through which men or material may fall shall be protected by railings, barriers, covers or other protective devices.

### § 77.205 Travelways at surface installations.

- (a) Safe means of access shall be provided and maintained to all working places.
- (b) Travelways and platforms or other means of access to areas where persons are required to travel or work, shall be kept clear of all extraneous material and other stumbling or slipping hazards.
- (c) Inclined travelways shall be constructed of nonskid material or equipped with cleats.
- (d) Regularly used travelways shall be sanded, salted, or cleared of snow and ice as soon as practicable.
- (e) Crossovers, elevated walkways, elevated ramps, and stairways shall be of substantial construction, provided with handrails, and maintained in good condition. Where necessary toeboards shall be provided.
- (f) Crossovers shall be provided where it is necessary to cross conveyors.
- (g) Moving conveyors shall be crossed only at designated crossover points.

# § 77.206 Ladders; construction; installation and maintenance.

- (a) Ladders shall be of substantial construction and maintained in good condition.
- (b) Wooden members of ladders shall not be painted.
- (c) Steep or vertical ladders which are used regularly at fixed locations shall be anchored securely and provided with backguards extending from a point not more than 7 feet from the bottom of the ladder to the top of the ladder
- (d) Fixed ladders shall not incline backwards at any point unless provided with backguards.
- (e) Fixed ladders shall be anchored securely and installed to provide at least 3 inches of toe clearance.
- (f) Fixed ladders shall project at least 3 feet above landings, or substantial handholds shall be provided above the landings.

#### § 77.207 Illumination.

Illumination sufficient to provide safe working conditions shall be provided in and on all surface structures, paths, walkways, stairways, switch

#### §77.208

panels, loading and dumping sites, and working areas.

#### § 77.208 Storage of materials.

- (a) Materials shall be stored and stacked in a manner which minimizes stumbling or fall-of-material hazards.
- (b) Materials that can create hazards if accidentally liberated from their containers shall be stored in a manner that minimizes the dangers.
- (c) Containers holding hazardous materials must be of a type approved for such use by recognized agencies.
- (d) Compressed and liquid gas cylinders shall be secured in a safe manner
- (e) Valves on compressed gas cylinders shall be protected by covers when being transported or stored, and by a safe location when the cylinders are in use.

[36 FR 9364, May 22, 1971, as amended at 67 FR 42389, June 21, 2002]

#### §77.209 Surge and storage piles.

No person shall be permitted to walk or stand immediately above a reclaiming area or in any other area at or near a surge or storage pile where the reclaiming operation may expose him to a hazard.

#### § 77.210 Hoisting of materials.

- (a) Hitches and slings used to hoist materials shall be suitable for handling the type of materials being hoisted.
- (b) Men shall stay clear of hoisted loads.
- (c) Taglines shall be attached to hoisted materials that require steadying or guidance.

## § 77.211 Draw-off tunnels; stockpiling and reclaiming operations; general.

- (a) Tunnels located below stockpiles, surge piles, and coal storage silos shall be ventilated so as to maintain concentrations of methane below 1.0 volume per centum.
- (b) In addition to the tests for methane required by §77.201 such tests shall also be made before any electric equipment is energized or repaired, unless equipped with a continuous methane monitoring device installed and operated in accordance with the provisions of §77.211–1. Electric equipment shall not be energized, operated, or repaired

until the air contains less than 1.0 volume per centum of methane.

# § 77.211-1 Continuous methane monitoring device; installation and operation; automatic deenergization of electric equipment.

Continuous methane monitoring devices shall be set to deenergize automatically electric equipment when such monitor is not operating properly and to give a warning automatically when the concentration of methane reaches a maximum percentage determined by an authorized representative of the Secretary which shall not be more than 1.0 volume per centum of methane. An authorized representative of the Secretary shall require such monitor to deenergize automatically electric equipment when the concentration of methane reaches a maximum percentage determined by such representative which shall not be more than 2.0 volume per centum of methane.

## § 77.212 Draw-off tunnel ventilation fans; installation.

When fans are used to ventilate drawoff tunnels the fans shall be:

- (a) Installed on the surface;
- (b) Installed in fireproof housings and connected to the tunnel openings with fireproof air ducts; and,
  - (c) Offset from the tunnel opening.

#### § 77.213 Draw-off tunnel escapeways.

When it is necessary for a tunnel to be closed at one end, an escapeway not less than 30 inches in diameter (or of the equivalent, if the escapeway does not have a circular cross section) shall be installed which extends from the closed end of the tunnel to a safe location on the surface; and, if the escapeway is inclined more than 30 degrees from the horizontal it shall be equipped with a ladder which runs the full length of the inclined portion of the escapeway.

#### § 77.214 Refuse piles; general.

(a) Refuse piles constructed on or after July 1, 1971, shall be located in areas which are a safe distance from all underground mine airshafts, preparation plants, tipples, or other surface installations and such piles shall not be