171113330	WA44650
ን19	WA44707
568	WA44717
. 3372	WA44763
WA43375	WA44765
WA43376	WA44788
WA43380	WA44951
WA43381	WA45108
WA-13382	WA45152
WA43383	WA45168
WA43385	WA45182
WA43388	WA45195
WA43391	WA45438
WA43392	WA45454
WA43398	WA45514
WA43410	WA45558
WA43417	WA45581
W A43451	WA45840
W.∧43458	WA45854
WA43478	WA45906
WA43507	WA45952
WA43520	WA46049
WA 43549	WA46069
WA43550	WA46168
WA43558	WA46240
WA43571	WA46357
WA43573	WA46359
WA43598	WA46504
WA43622	WA46597
WA43625	WA46724
WA43627	WA46747
WA43628	WA46772
WA43629	WA46812
WA43634	WA47241
W-143644	WA47424
Vi . N43657	WA47608
WA43668	WA47784
W.A43716	WA47109
W A 43724	WA47J21
WA43725	WF20322
A 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
1A' > (3732	WF20334
	WF20438
759	WF20497
2763	WF20500
VV 143784	
** 1.10/04	WF20545
WA43785	WF20556
WA43796	WF20573
W.\13807	WF20814
WA43887	WF29620
WA43894	WF20630
WA43928	WF20644
WA43984	WF20647
	111 20077
WA44113	WF20654
\V.\\44147	WF20659
WA44150	
	WF20662
WA44156	WF20663
WA44171	WF20743
W/A44190	Wi ² 0744
WA44193	WF20751
W.A44195	WF20765
W.X44219	WF20758
W.A44230	W F20756
WA44249	WF20768
WA 44255	WF20769
WA 14256	WF20776
- 1 7 1 2 1 2 1 2 1 2 1 2 1 2 1 2 1 2 1 2	
W-7\44259	WF20788
WA44278	WF20799
WA4429Z	WF20877
W/A44293	WF20891
V4.744302	WF20927
W/344317	WF21383
WA44337	
	WF21410
WA44351	WF21421
W. 3.14373	WF21423
W.144399	WF21439
W.344405	WF21445
557 T 444.00	
WA44417	
	WF21458
U. A 44428	
V. A44428	WF21470
WA44433	WF21470 WF21491
	WF21470
WA44433 14457	WF21470 WF21491 WF21513
WA44433 *4457 \464	WF21470 WF21491 WF21513 WF21528
WA44433 *4457 *464 {510	WF21470 WF21491 WF21513
WA44433 *4457 \464	WF21470 WF21491 WF21513 WF21528

Users of these cylinders should be advised that serious personal injury, death or property damage could result from the rupture of a cylinder. Accordingly, all persons owning, using or having access to the cylinders subject to the recall should immedaitely take the following precautions:

 If a cylinder has been filled, its entire contents should be vented in order to relieve internal pressure.

2. The vented cylinders should be segregated from all other cylinders by being placed in a secure place and marked conspicuously with a tag bearing the notation "Do Not Use" or similar warning.

3. Under no circumstances should any of the cylinders in question be sold or otherwise transferred, filled, refilled or used for any purpose.

Once the above procedures have been implemented, all cylinders bearing the serial numbers indicated should be returned for replacement to the company or distributor from whom they were purchased.

(49 U.S.C. 1804(c), 1805(a) and 1808(d)(3))

Issued in Washington, D.C. on July 12, 1985, under authority delegated in 49 CFR Part 106. Appendix A.

Alan I. Roberts,

Associate Director for Hazardous Materials Regulation, Materials Transportation Bureau. [FR Doc. 85–16972 Filed 7–16–85; 8:45 am] BILLING CODE 4910-60-M

4. -