Dana Mining Company LLC

August 15, 2008



308 Dents Run Road Morgantown, WV 26501 (304) 296.9701 Fax: (304) 296.9249

Mine Safety and Health Administration Office of Standards, Regulators, and Variances 111 Wilson Boulevard, Room 2350 Arlington, VA 22209-3939

Subject:

RIN 1219-AB58

June 16, 2008 Proposed Rules

Refuge Alternatives for Underground Coal Mines

To Whom It May Concern:

Attached are comments relative to the Proposed Rules for Refuge Alternatives for Underground Coal Mines. I request that you seriously consider the information presented. The rules and guidelines that the state of West Virginia approved were followed. Additionally, the shelter was tested and passed by NIOSH.

Sincerely,

Steve Polce, Superintendent

Prime No. 1 Mine

Enclosure

AB58-COMM-13

Listed below are comments relative to MSHA's proposed rules for refuge chambers:

- 1. Any state approved shelter should be approved for the life of that shelter as determined by the manufacturer's criteria and specifications, no matter what state it is installed.
- Additional units of the same type should be allowed for future purchase. A
 lot of evaluation was undertaken initially to arrive at the currently used
 shelter. It would not be advisable to have different types of shelters installed
 in a mine that could possibly cause confusion. During a time of emergency,
 consistency is very important.
- 3. There would be much less paper work for all involved if shelters were approved by design criteria rather than individual model approval.
- 4. Both the square footage (15 sq. ft.) and volume size (60 cu. ft.) are too large, particularly the thinner the seam thickness becomes. For mines with approximately 40 inches or less of height, it will become impossible to install a twenty (20) person rigid shelter to meet the square footage requirement of the proposed law and be able to advance the unit as the section advances, much less get it installed initially. Additionally, it would also be impossible to purge a large enough space to occupy twenty (20) persons and satisfy the volume size of 60 cu. ft. per person. It should be noted that South Africa has used 6.46 sq. ft. (0.6 sq. meters) per person as their standard for their shelters since 1994. Why is it necessary to specify a minimum size (square footage) for the shelter? As long as the people and everything that is necessary to sustain life are in the shelter, and can effectively be used, there does not need to be a minimum size (It should be remembered that survival is the first concern, not to see how big the chamber can be made thereby making it more comfortable.)
 - 5. With the differences in state laws and MSHA's proposal that the shelters be maintained between 1,000 and 2,000 feet of the face, a change is needed that

would require that the shelters be maintained a maximum of 2,000 feet from the face. That should satisfy both MSHA and the states that currently have laws in place.

6. Need to remove the requirement that the shelters be placed in crosscuts rather than remain in the entry. If tests that were conducted show that the shelter will survive, the shelter should be allowed to remain in the entry. This will reduce the amount of potential damage that may result from moving the shelter into and out of the crosscut as it is advanced towards the face area.

•

3042969429

DANA MINING COMPANY LLC

308 DENTS RUN ROAD MORGANTOWN, WV 26501 (304) 296-9701

FACSIMILE TRANSMITTAL SHEET	
TO: N5HA	FROM: HARRY SPRINGER
COMPANY:	B-15-08
PAX NUMBER: (202) 693-9441	TOTAL NO. OF PAGES INCLUDING COVER:
PHONE NUMBER: (304) 296-9701 Ext.	PLEASE CALL IF YOU HAVE PROBLEMS AND WE WILL RESEND. 223
RIN 1219-AB5B	
☐ URGENT ☑ FOR REVIEW ☐ PLEASE COMMENT ☐ PLEASE REPLY ☐ PLEASE RECYCLE	
NOTES/COMMENTS:	
PROPOSED RULES.	: REFUGE ALTERNATIVES
FOR UNDERGEOU	IND COM MINES.

The information contained in this facsimile message is legally privileged and confidential information intended for the use of the individual or entity named above. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copy of this telecopy is strictly prohibited. If you have received this telecopy in error, please immediately notify us by telephone and return the original message to us at the address above by the U.S. Postal Service.