

15, 2007, is found in the inspection per paragraph (f)(1) of this AD:

(i) Before further flight after the inspection per paragraph (f)(1) of this AD, insert Temporary Change 3, issued March 15, 2007, into the LIMITATIONS section of Report 6591 (the airplane flight manual (AFM)) for P-180 Avanti Aircraft or Temporary Change 2, issued March 15, 2007, into the LIMITATIONS section of Report 180-MAN-0010-01100 (the AFM) for P-180 Avanti II aircraft. The owner/operator holding at least a private pilot certificate as authorized by section 43.7 of the Federal Aviation Regulations (14 CFR 43.7) may do this action. Make an entry in the aircraft records showing compliance with this portion of the AD following section 43.9 of the Federal Aviation Regulations (14 CFR 43.9).

(ii) Within the next 600 hours TIS after October 11, 2007 (the effective date of this AD) or 12 months after October 11, 2007 (the effective date of this AD), whichever occurs first, replace the nose landing gear (NLG) following Piaggio Aero Industries S.p.A. Service Bulletin (Mandatory) N.: 80-0236 Rev. 1, dated May 15, 2007.

**Note 1:** The replacement NLG could be the same unit that was removed from the aircraft and serviced in accordance with Annex 8 of Piaggio Aero Industries S.p.A. Service Bulletin (Mandatory) N.: 80-0236 Rev. 1, dated May 15, 2007 (Messier-Dowty Service Bulletin No. P180-32-24, dated May 15, 2007), or it could be a different NLG that complies with this AD.

(iii) After replacement of the NLG per paragraph (f)(2)(ii) of this AD, remove the steering system temporary limitations from the LIMITATIONS section of the AFM.

(3) Before further flight after accomplishment of the inspection specified in paragraph (f)(1) of this AD, do not install any steering actuator listed in annex 7.1 or manifold listed in annex 7.2 of Piaggio Aero Industries S.p.A. Service Bulletin (Mandatory) N.: 80-0236 Rev. 1, dated May 15, 2007.

**Note 2:** We encourage you to incorporate Temporary Revision 1 into the maintenance program (aircraft maintenance manual (AMM) P.180 Avanti report 9066) or Temporary Revision 11 into the maintenance program (AMM P.180 Avanti II report 180-MAN-0200-01105). The temporary revisions require confirmation that the steering manifold and steering actuator are compliant with Piaggio Aero Industries S.p.A. Service Bulletin (Mandatory) N.: 80-0236 Rev. 1, dated May 15, 2007.

#### FAA AD Differences

**Note 3:** This AD differs from the MCAI and/or service information as follows: The MCAI requires the initial inspection action within 5 hours TIS. We consider 5 hours TIS an urgent safety of flight compliance time, and we do not consider this unsafe condition to be an urgent safety of flight condition. Because we do not consider this unsafe condition to be an urgent safety of flight condition, we issued this action through the normal notice of proposed rulemaking (NPRM) AD process followed by this final rule. The initial compliance time of 30 hours

TIS after the effective date of this AD or 30 days after the effective date of this AD, whichever occurs first, is an adequate compliance time for this AD action and met the FAA requirements for an NPRM followed by a final rule.

#### Other FAA AD Provisions

(g) The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, Standards Office, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Sarjapur Nagarajan, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4145; fax: (816) 329-4090. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) Airworthy Product: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA approved. Corrective actions are considered FAA approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) Reporting Requirements: For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act (44 U.S.C. 3501 et. seq.), the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120 0056.

#### Related Information

(h) Refer to MCAI European Aviation Safety Agency (EASA) Emergency Airworthiness Directive EAD No: 2007-0147-E, dated May 22, 2007; and Piaggio Aero Industries S.p.A. Service Bulletin (Mandatory) N.: 80-0236 Rev. 1, dated May 15, 2007, for related information.

#### Material Incorporated by Reference

(i) You must use Piaggio Aero Industries S.p.A. Service Bulletin (Mandatory) N.: 80-0236 Rev. 1, dated May 15, 2007, to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact Piaggio Aero Industries S.p.a., Via Cibrario, 4-16154 Genoa, Italy; telephone +39 010 06481 741; fax: +39 010 6481 309; e-mail: MMicheli@piaggioaero.it.

(3) You may review copies at the FAA, Central Region, Office of the Regional Counsel, 901 Locust, Room 506, Kansas City, Missouri 64106; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Kansas City, Missouri, on August 24, 2007.

**Brian A. Yanez,**

*Acting Manager, Small Airplane Directorate, Aircraft Certification Service.*

[FR Doc. E7-17304 Filed 9-5-07; 8:45 am]

BILLING CODE 4910-13-P

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 97

[Docket No. 30567; Amdt. No. 3233]

#### Standard Instrument Approach Procedures, and Takeoff Minimums and Obstacle Departure Procedures; Miscellaneous Amendments

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule.

**SUMMARY:** This Rule establishes, amends, suspends, or revokes Standard Instrument Approach Procedures (SIAPs) and associated Takeoff Minimums and Obstacle Departure Procedures for operations at certain airports. These regulatory actions are needed because of the adoption of new or revised criteria, or because of changes occurring in the National Airspace System, such as the commissioning of new navigational facilities, adding new obstacles, or changing air traffic requirements. These changes are designed to provide safe and efficient use of the navigable airspace and to promote safe flight operations under instrument flight rules at the affected airports.

**DATES:** This rule is effective September 6, 2007. The compliance date for each SIAP, associated Takeoff Minimums, and ODP is specified in the amendatory provisions.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of September 6, 2007.

**ADDRESSES:** Availability of matters incorporated by reference in the amendment is as follows:

#### For Examination—

1. FAA Rules Docket, FAA Headquarters Building, 800 Independence Avenue, SW., Washington, DC 20591;

2. The FAA Regional Office of the region in which the affected airport is located;

3. The National Flight Procedures Office, 6500 South MacArthur Blvd., Oklahoma City, OK 73169; or

4. The National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: [http://www.archives.gov/federal\\_register/code\\_of\\_federal\\_regulations/ibr\\_locations.html](http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html).

**Availability**—All SIAPs and Takeoff Minimums and ODPs are available online free of charge. Visit [nfdc.faa.gov](http://nfdc.faa.gov) to register. Additionally, individual SIAP and Takeoff Minimums and ODP copies may be obtained from:

1. FAA Public Inquiry Center (APA-200), FAA Headquarters Building, 800 Independence Avenue, SW., Washington, DC 20591; or

2. The FAA Regional Office of the region in which the affected airport is located.

**FOR FURTHER INFORMATION CONTACT:**

Harry J. Hodges, Flight Procedure Standards Branch (AFS-420), Flight Technologies and Programs Division, Flight Standards Service, Federal Aviation Administration, Mike Monroney Aeronautical Center, 6500 South MacArthur Blvd. Oklahoma City, OK. 73169 (Mail Address: P.O. Box 25082 Oklahoma City, OK 73125) telephone: (405) 954-4164.

**SUPPLEMENTARY INFORMATION:** This rule amends Title 14 of the Code of Federal Regulations, Part 97 (14 CFR part 97), by establishing, amending, suspending, or revoking SIAPs, Takeoff Minimums and/or ODPs. The complete regulatory description of each SIAP and its associated Takeoff Minimums or ODP for an identified airport is listed on FAA form documents which are incorporated by reference in this amendment under 5 U.S.C. 552(a), 1 CFR part 51, and 14 CFR part 97.20. The applicable FAA Forms are FAA Forms 8260-3, 8260-4, 8260-5, 8260-15A, and 8260-15B when required by an entry on 8260-15A.

The large number of SIAPs, Takeoff Minimums and ODPs, in addition to their complex nature and the need for a special format make publication in the **Federal Register** expensive and impractical. Furthermore, airmen do not use the regulatory text of the SIAPs, Takeoff Minimums or ODPs, but instead refer to their depiction on charts printed by publishers of aeronautical materials. Thus, the advantages of incorporation by reference are realized and publication of the complete description of each SIAP, Takeoff Minimums and ODP listed on FAA forms is unnecessary. This amendment provides the affected CFR sections and specifies the types of SIAPs and the effective dates of the SIAPs, the associated Takeoff Minimums, and ODPs. This

amendment also identifies the airport and its location, the procedure, and the amendment number.

**The Rule**

This amendment to 14 CFR part 97 is effective upon publication of each separate SIAP, Takeoff Minimums and ODP as contained in the transmittal. Some SIAP and Takeoff Minimums and textual ODP amendments may have been issued previously by the FAA in a Flight Data Center (FDC) Notice to Airmen (NOTAM) as an emergency action of immediate flight safety relating directly to published aeronautical charts. The circumstances which created the need for some SIAP and Takeoff Minimums and ODP amendments may require making them effective in less than 30 days. For the remaining SIAPs and Takeoff Minimums and ODPs, an effective date at least 30 days after publication is provided.

Further, the SIAPs and Takeoff Minimums and ODPs contained in this amendment are based on the criteria contained in the U.S. Standard for Terminal Instrument Procedures (TERPS). In developing these SIAPs and Takeoff Minimums and ODPs, the TERPS criteria were applied to the conditions existing or anticipated at the affected airports. Because of the close and immediate relationship between these SIAPs, Takeoff Minimums and ODPs, and safety in air commerce, I find that notice and public procedure before adopting these SIAPs, Takeoff Minimums and ODPs are impracticable and contrary to the public interest and, where applicable, that good cause exists for making some SIAPs effective in less than 30 days.

**Conclusion**

The FAA has determined that this regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. It, therefore—(1) Is not a “significant regulatory action” under Executive Order 12866; (2) is not a “significant rule” under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a regulatory evaluation as the anticipated impact is so minimal. For the same reason, the FAA certifies that this amendment will not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

**List of Subjects in 14 CFR part 97**

Air Traffic Control, Airports, Incorporation by reference, and Navigation (Air).

Issued in Washington, DC on August 24, 2007.

**James J. Ballough,**

*Director, Flight Standards Service.*

**Adoption of the Amendment**

■ Accordingly, pursuant to the authority delegated to me, under Title 14, Code of Federal Regulations, Part 97 (14 CFR part 97) is amended by establishing, amending, suspending, or revoking Standard Instrument Approach Procedures and/or Takeoff Minimums and/or Obstacle Departure Procedures effective at 0901 UTC on the dates specified, as follows:

**PART 97—STANDARD INSTRUMENT APPROACH PROCEDURES**

■ 1. The authority citation for part 97 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40103, 40106, 40113, 40114, 40120, 44502, 44514, 44701, 44719, 44721-44722.

■ 2. Part 97 is amended to read as follows:

**Effective 27 SEP 2007**

San Francisco, CA, San Francisco Intl, RNAV (GPS) X RWY 10R, Orig-A  
Valdosta, GA, Valdosta Rgnl, ILS OR LOC RWY 35, Amdt 6  
Valdosta, GA, Valdosta Rgnl, VOR RWY 35, Amdt 1  
Great Falls, MT, Great Falls Intl, ILS OR LOC/DME RWY 3, Amdt 4, ILS RWY 3 (CAT II), ILS RWY 3 (CAT III)  
Great Falls, MT, Great Falls Intl, RNAV (GPS) RWY 3, Amdt 2  
Laconia, NH, Laconia Muni, Takeoff Minimums and Obstacle DP, Amdt 3

**Effective 25 OCT 2007**

Kobuk, AK, Kobuk, RNAV (GPS) RWY 9, Orig  
Kobuk, AK, Kobuk, RNAV (GPS) RWY 27, Orig  
Kobuk, AK, Kobuk, Takeoff Minimums and Obstacle DP, Orig  
Siloam Springs, AR, Smith Field, RNAV (GPS) RWY 18, Orig  
Siloam Springs, AR, Smith Field, RNAV (GPS) RWY 36, Orig  
Siloam Springs, AR, Smith Field, VOR-A, Amdt 9  
Siloam Springs, AR, Smith Field, Takeoff Minimums and Obstacle DP, Orig  
Stuttgart, AR, Stuttgart AR, RNAV (GPS) RWY 36, Amdt 1  
St. Johns, AZ, St. Johns Industrial Air Park, RNAV (GPS) RWY 32, Orig-A  
Los Angeles, CA, Los Angeles Intl, RNAV (GPS) RWY 25L, Amdt 1A  
San Francisco, CA, San Francisco Intl, RNAV (RNP) Y RWY 28R, Orig-B  
Middletown, DE, Summit, NDB-A, Amdt 7  
Sebring, FL, Sebring Regional, Takeoff Minimums and Obstacle DP, Orig

- Tallahassee, FL, Tallahassee RGNL, Takeoff Minimums and Obstacle DP, Orig
- Cartersville, GA, Cartersville, Takeoff Minimums and Obstacle DP, Amdt 1
- Jasper, GA, Pickens County, RNAV (GPS) RWY 16, Orig
- Jasper, GA, Pickens County, RNAV (GPS) RWY 34, Orig
- Jasper, GA, Pickens County, GPS RWY 34, Orig, CANCELLED
- Jasper, GA, Pickens County, Takeoff Minimums and Obstacle DP, Amdt 1
- Fairfield, IA, Fairfield Muni, RNAV (GPS) RWY 18, Amdt 2
- Fairfield, IA, Fairfield Muni, RNAV (GPS) RWY 36, Amdt 1
- Fairfield, IA, Fairfield Muni, NDB RWY 36, Amdt 9
- Emporia, KS, Emporia Muni, RNAV (GPS) RWY 1, Orig
- Emporia, KS, Emporia Muni, RNAV (GPS) RWY 19, Orig
- Emporia, KS, Emporia Muni, VOR-A, Amdt 14
- Emporia, KS, Emporia Muni, GPS RWY 01, Orig, CANCELLED
- Emporia, KS, Emporia Muni, GPS RWY 19, Orig, CANCELLED
- Emporia, KS, Emporia Muni, Takeoff Minimums and Obstacle DP, Orig
- McPherson, KS, McPherson, RNAV (GPS) RWY 18, Orig
- McPherson, KS, McPherson, RNAV (GPS) RWY 36, Orig
- McPherson, KS, McPherson, GPS RWY 18, Orig, CANCELLED
- McPherson, KS, McPherson, GPS RWY 36, Amdt 1, CANCELLED
- McPherson, KS, McPherson, Takeoff Minimums and Obstacle DP, Amdt 2
- Wellington, KS, Wellington Muni, RNAV (GPS) RWY 17, Amdt 1
- Wellington, KS, Wellington Muni, RNAV (GPS) RWY 35, Amdt 1
- Wellington, KS, Wellington Muni, Takeoff Minimums and Obstacle DP, Orig
- Chatham, MA, Chatham Municipal, Takeoff Minimums and Obstacle DP, Orig
- Biddeford, ME, Biddeford Muni, Takeoff Minimums and Obstacle DP, Orig
- Frenchville, ME, Northern Aroostook Rgnl, Takeoff Minimums and Obstacle DP, Orig
- Portland, ME, Portland Intl Jetport, RADAR-1, Orig 28, CANCELLED
- Frankfort, MI, Frankfort Dow Memorial Field, RNAV (GPS) RWY 15, Amdt 1
- Frankfort, MI, Frankfort Dow Memorial Field, RNAV (GPS) RWY 33, Amdt 1
- Frankfort, MI, Frankfort Dow Memorial Field, VOR/DME-A, Amdt 1
- Fremont, MI, Fremont Muni, RNAV (GPS) RWY 18, Amdt 1
- Fremont, MI, Fremont Muni, RNAV (GPS) RWY 36, Amdt 1
- Bay St Louis, MS, Stennis Intl, RNAV (GPS) RWY 18, Orig
- Bay St Louis, MS, Stennis Intl, RNAV (GPS) RWY 36, Orig
- Bay St Louis, MS, Stennis Intl, VOR-A, Amdt 7
- Bay St Louis, MS, Stennis Intl, VOR/DME RNAV OR GPS RWY 18, Amdt 2B, CANCELLED
- Bay St Louis, MS, Stennis Intl, GPS RWY 36, Orig-B, CANCELLED
- Bay St Louis, MS, Stennis Intl, Takeoff Minimums and Obstacle DP, Orig
- Raymond, MS, John Bell Williams, RNAV (GPS) RWY 12, Amdt 1
- Raymond, MS, John Bell Williams, RNAV (GPS) RWY 30, Amdt 1
- Raymond, MS, John Bell Williams, Takeoff Minimums and Obstacle DP, Amdt 2
- Erwin, NC, Harnett County, RNAV (GPS) RWY 5, Amdt 2
- Erwin, NC, Harnett County, RNAV (GPS) RWY 23, Amdt 2
- Kinston, NC, Kinston Rgnl Jetport at Stallings Field, RNAV (GPS) RWY 5, Amdt 2
- Kinston, NC, Kinston Rgnl Jetport at Stallings Field, RNAV (GPS) RWY 23, Amdt 2
- Kinston, NC, Kinston Rgnl Jetport at Stallings Field, Takeoff Minimums and Obstacle DP, Orig
- Nashua, NH, Boire Field, Takeoff Minimums and Obstacle DP, Amdt 2
- Albany, NY, Albany Intl, COPTER ILS OR LOC/DME RWY 1, Amdt 1
- Delaware, OH, Delaware Muni, Takeoff Minimums and Obstacle DP, Orig
- Lebanon, OH, Lebanon-Warren County, RNAV (GPS) RWY 19, Amdt 1
- Clinton, OK, Clinton Regional, RNAV (GPS) RWY 17, Amdt 1
- Clinton, OK, Clinton Regional, RNAV (GPS) RWY 35, Amdt 2
- Clinton, OK, Clinton Regional, Takeoff Minimums and Obstacle DP, Orig
- Harrisburg, PA, Harrisburg Intl, Takeoff Minimums and Obstacle DP, Amdt 7
- Anderson, SC, Anderson Rgnl, RNAV (GPS) RWY 5, Amdt 1A
- Myrtle Beach, SC, Myrtle Beach Intl, ILS OR LOC RWY 18, Amdt 1G
- Myrtle Beach, SC, Myrtle Beach Intl, ILS OR LOC RWY 36, Amdt 1D
- Covington, TN, Covington Muni, Takeoff Minimums and Obstacle DP, Orig
- Lexington-Parsons, TN, Beech River Regional, VOR-A, Orig-A
- Brownfield, TX, Terry County, NDB RWY 2, Amdt 2A, CANCELLED
- Denton, TX, Denton Muni, Takeoff Minimums and Obstacle DP, Amdt 1
- Auburn, WA, Auburn Muni, RNAV (GPS)-A, ORIG
- Auburn, WA, Auburn Muni, Takeoff Minimums and Obstacle DP, Orig
- Port Angeles, WA, William R Fairchild Intl, RNAV (GPS) RWY 8, Orig
- Port Angeles, WA, William R Fairchild Intl, ILS OR LOC RWY 8, Amdt 2
- Port Angeles, WA, William R Fairchild Intl, Takeoff Minimums and Obstacle DP, Amdt 2
- Baraboo, WI, Baraboo Wisconsin Dells, LOC/DME RWY 1, Orig
- Baraboo, WI, Baraboo Wisconsin Dells, VOR-A, Amdt 12
- Boscobel, WI, Boscobel, Takeoff Minimums and Obstacle DP, Amdt 1
- Lone Rock, WI, Tri-County Regional, LOC RWY 27, Orig
- Middleton, WI, Middleton Muni-Morey Field, LOC/DME RWY 10, Orig
- Phillips, WI, Price County, RNAV (GPS) RWY 1, Orig
- Phillips, WI, Price County, RNAV (GPS) RWY 19, Orig
- Phillips, WI, Price County, GPS RWY 1, Orig, CANCELLED
- Phillips, WI, Price County, GPS RWY 19, Orig, CANCELLED
- Gillette, WY, Gillette-Campbell County, VOR/DME RWY 16, Orig
- Gillette, WY, Gillette-Campbell County, VOR RWY 16, Amdt 7, CANCELLED
- Wheatland, WY, Phifer Airfield, RNAV (GPS)-A, Orig
- Wheatland, WY, Phifer Airfield, Takeoff Minimums and Obstacle DP, Orig
- Effective 20 DEC 2007**
- Monee, IL, Bult Field, VOR OR GPS RWY 5, Amdt 3, CANCELLED
- Ann Arbor, MI, Ann Arbor Muni, Takeoff Minimums and Obstacle DP, Amdt 8
- Pontiac, MI, Oakland County Intl, Takeoff Minimums and Obstacle DP, Amdt 4
- Effective 14 FEB 2008**
- Chicago, IL, Chicago Midway Intl, ILS OR LOC RWY 4R, Orig-A
- [FR Doc. E7-17345 Filed 9-5-07; 8:45 am]
- BILLING CODE 4910-13-P**
- 
- DEPARTMENT OF TRANSPORTATION**
- Federal Aviation Administration**
- 14 CFR Part 97**
- [Docket No. 30568; Amdt. No. 3234]**
- Standard Instrument Approach Procedures; Miscellaneous Amendments**
- AGENCY:** Federal Aviation Administration (FAA), DOT.
- ACTION:** Final rule.
- SUMMARY:** This rule amends Standard Instrument Approach Procedures (SIAPs) for operations at certain airports. These regulatory actions are needed because of changes in the National Airspace System, such as the commissioning of new navigational facilities, adding of new obstacles, or changing air traffic requirements. These changes are designed to provide safe and efficient use of the navigable airspace and to promote safe flight operations under instrument flight rules at the affected airports.
- DATES:** This rule is effective September 6, 2007. The compliance date for each SIAP is specified in the amendatory provisions.
- The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of September 6, 2007.
- ADDRESSES:** Availability of matter incorporated by reference in the amendment is as follows:
- For Examination—*
1. FAA Rules Docket, FAA Headquarters Building, 800 Independence Avenue, SW., Washington, DC 20591;