

---

# Corrections

Federal Register

Vol. 71, No. 127

Monday, July 3, 2006

---

This section of the FEDERAL REGISTER contains editorial corrections of previously published Presidential, Rule, Proposed Rule, and Notice documents. These corrections are prepared by the Office of the Federal Register. Agency prepared corrections are issued as signed documents and appear in the appropriate document categories elsewhere in the issue.

---

**DEPARTMENT OF TRANSPORTATION****Federal Aviation Administration****14 CFR Part 39****[Docket No. FAA-2006-25102; Directorate Identifier 2006-NM-117-AD; Amendment 39-14666; AD 2006-13-13]****RIN 2120-AA64****Airworthiness Directives; Boeing Model 737 Airplanes***Correction*

In rule document 06-5585 beginning on page 35781 in the issue of Thursday,

June 22, 2006, make the following correction:

**§ 39.13 [Corrected]**

On page 35783, in §39.13, in the first column, in the first full paragraph, in the first two lines, “Warning Horn—Cabin Altitude or Configuration Recall” should read “WARNING HORN—CABIN ALTITUDE OR CONFIGURATION RECALL”.

[FR Doc. C6-5585 Filed 6-30-06; 8:45 am]

**BILLING CODE 1505-01-D**