

Issued in Minneapolis, Minnesota, on August 25, 2006.

**Robert A. Huber,**

*Manager, Minneapolis Airports District Office, FAA, Great Lakes Region.*

[FR Doc. 06-7460 Filed 9-5-05; 8:45 am]

**BILLING CODE 4910-13-M**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

[Summary Notice No. PE-2006-26]

#### Petitions for Exemption; Summary of Petitions Received

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of petitions for exemption received.

**SUMMARY:** Pursuant to FAA's rulemaking provisions governing the application, processing, and disposition of petitions for exemption part 11 of Title 14, Code of Federal Regulations (14 CFR), this notice contains a summary of certain petitions seeking relief from specified requirements of 14 CFR. The purpose of this notice is to improve the public's awareness of, and participation in, this aspect of FAA's regulatory activities. Neither publication of this notice nor the inclusion or omission of information in the summary is intended to affect the legal status of any petition or its final disposition.

**DATES:** Comments on petitions received must identify the petition docket number involved and must be received on or before September 26, 2006.

**ADDRESSES:** You may submit comments [identified by DOT DMS Docket Number FAA-2006-25466] by any of the following methods:

*Web Site:* <http://dms.dot.gov>. Follow the instructions for submitting comments on the DOT electronic docket site.

*Fax:* 1-202-493-2251.

*Mail:* Docket Management Facility; U.S. Department of Transportation, 400 Seventh Street, SW., Nassif Building, Room PL-401, Washington, DC 20590-0001.

*Hand Delivery:* Room PL-401 on the plaza level of the Nassif Building, 400 Seventh Street, SW., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal Holidays.

*Docket:* For access to the docket to read background documents or comments received, go to <http://dms.dot.gov> at any time or to Room PL-401 on the plaza level of the Nassif Building, 400 Seventh Street, SW.,

Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

**FOR FURTHER INFORMATION CONTACT:** Tim Adams (202) 267-8033, Sandy Buchanan-Sumter (202) 267-7271, or John Linsenmeyer (202) 267-5174, Office of Rulemaking (ARM-1), Federal Aviation Administration, 800 Independence Avenue, SW., Washington, DC 20591. This notice is published pursuant to 14 CFR 11.85 and 11.91.

Issued in Washington, DC, on August 30, 2006.

**Ida M. Klepper,**

*Acting Director, Office of Rulemaking.*

#### Petitions for Exemption

*Docket No.:* FAA-2006-25466.

*Petitioner:* Southwest Airlines

Company.

*Section of 14 CFR Affected:* 14 CFR 121.391(a) and 121.393(b).

*Description of Relief Sought:* To permit the Southwest Airlines Company to reduce the number of required flight attendants onboard during the boarding and deplaning of passengers at intermediate stops. During the boarding process at intermediate stops, the petitioner is requesting to substitute a pilot qualified in emergency evacuation procedures for the forward flight attendant. During the deplaning process at intermediate stops, the petitioner is requesting to allow a reduced number (one) of flight attendants in the cabin.

[FR Doc. E6-14734 Filed 9-5-06; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

[Summary Notice No. PE-2006-29]

#### Petitions for Exemption; Summary of Petitions Received

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of petition for exemption received.

**SUMMARY:** Pursuant to FAA's rulemaking provisions governing the application, processing, and disposition of petitions for exemption, part 11 of Title 14, Code of Federal Regulations (14 CFR), this notice contains a summary of a certain petition seeking relief from specified requirements of 14 CFR. The purpose of this notice is to improve the public's awareness of, and participation in, this aspect of FAA's regulatory activities. Neither publication of this notice nor the inclusion or omission of information

in the summary is intended to affect the legal status of any petition or its final disposition.

**DATES:** Comments on petitions received must identify the petition docket number involved and must be received on or before September 26, 2006.

**ADDRESSES:** You may submit comments identified by DOT DMS Docket Number FAA-2006-25568 by any of the following methods:

- *Web Site:* <http://dms.dot.gov>.

Follow the instructions for submitting comments on the DOT electronic docket site.

- *Fax:* 1-202-493-2251.

• *Mail:* Docket Management Facility; U.S. Department of Transportation, 400 Seventh Street, SW., Nassif Building, Room PL-401, Washington, DC 20590-0001.

• *Hand Delivery:* Room PL-401 on the plaza level of the Nassif Building, 400 Seventh Street, SW., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

• *Docket:* For access to the docket to read background documents or comments received, go to <http://dms.dot.gov> at any time or to Room PL-401 on the plaza level of the Nassif Building, 400 Seventh Street, SW., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

**FOR FURTHER INFORMATION CONTACT:** Paul Pellicano (770-703-6064), Small Airplane Directorate (ACE-111), Federal Aviation Administration, 901 Locust, Room 301, Kansas City, MO 64106; or John Linsenmeyer (202-267-5174), Office of Rulemaking (ARM-1) Federal Aviation Administration, 800 Independence Avenue, SW., Washington, DC 20591.

This notice is published pursuant to 14 CFR 11.85 and 11.91.

Issued in Washington, DC, on August 29, 2006.

**Ida M. Klepper,**

*Acting Director, Office of Rulemaking.*

#### Petitions for Exemption

*Docket No.:* FAA-2006-25568.

*Petitioner:* Diamond Aircraft.

*Sections of 14 CFR Affected:* 14 CFR 23.1419(a).

*Description of Relief Sought:* To allow certification of the Diamond DA-42 aircraft without meeting the 61 knot stall speed requirement in § 23.1419(a). Diamond states that the Model DA-42 has compensating factors listed in paragraph 12 of Advisory Circular 23.1419-2C, dated July 21, 2004, and that these factors should apply to