



# ENERGY STAR® Qualified Imaging Equipment Specification Revision

October 14, 2005 Stakeholder Meeting

## Meeting Agenda

<b>Time</b>	<b>Topic</b>
9:00 a.m.	Conference room opens
9:15 a.m.	Meeting begins
9:15 a.m.	Welcome and Introductions <ul style="list-style-type: none"><li>▪ Meeting Goals<ul style="list-style-type: none"><li>○ Ensure manufacturers are on schedule to complete TEC testing by November 1</li><li>○ Share initial EPA conclusions from TEC and OM data submitted</li><li>○ Discuss how specification limits will be developed</li><li>○ Share EPA's initial thoughts on Draft 1 comments received; explain how additional rationale will be conveyed</li><li>○ Gain feedback on key topics to reach resolution</li><li>○ Convey next steps and timeline</li></ul></li></ul>
9:30 a.m.	Discussion Topics <ul style="list-style-type: none"><li>▪ Typical Electricity Consumption (TEC) Data<ul style="list-style-type: none"><li>○ Summary of Initial Data and Findings</li><li>○ Method for Setting Specification Limits</li><li>○ Unit Accuracy</li><li>○ Questions/Concerns</li></ul></li><li>▪ Operational Mode (OM) Data<ul style="list-style-type: none"><li>○ Summary of Initial Data and Findings</li><li>○ Method for Setting Specification Limits</li><li>○ Unit Accuracy</li><li>○ Questions/Concerns</li></ul></li><li>▪ Draft 1 Specification<ul style="list-style-type: none"><li>○ Summary Introduction: Comments Received</li><li>○ Labeling and Other Partner Commitments</li><li>○ Digital Front-ends (DFEs)</li><li>○ Recovery Time</li><li>○ Functional Adder vs. Speed Test for Ink Jet Products</li><li>○ Standby Mode for OM Products</li><li>○ Remanufacturing</li></ul></li></ul>
	<b>Break for Lunch as Needed</b>
3:30 p.m.	Conclusion <ul style="list-style-type: none"><li>▪ Summary of Discussion</li><li>▪ Next Steps and Timeline</li></ul>
4:00 p.m.	Meeting Adjourn