ALL-VOLUME OVERVIEW	i
CHAPTER 5 Satellite Launches in the PRC: Hughes	
CHAPTER SUMMARY	2
OPTUS B2, APSTAR 2 LAUNCH FAILURES: PRC GAINS SENSITIVE KNOWLEDGE FROM HUGHES INVESTIGATIONS	6
THE PROHIBITION AGAINST TECHNOLOGY TRANSFER	
IN FOREIGN LAUNCHES	8
International Traffic in Arms Regulations and the U.S. Munitions List	
Department of Defense Monitoring Role	9
OPTUS B2	10
The Optus B2 Licenses	
The Optus B2 Fails To Achieve Orbit	
Failure Investigation Teams	
Failure Investigation Begins	
Hughes' Export Administrators Deal with the Licensing Question	
A 'Political' Business Solution	21
The Optus B3: Hughes' Efforts to Improve the Long March Continue	36
APSTAR 2	40
The Apstar 2 License	
The Apstar 2 Failure	
Failure Investigation Teams	42
Failure Investigation Schedule	42
The Need for a License	42
Commerce Department Conference	46
Same Fairing Failure Identified by Hughes	
A 'Political' Business Solution, Again?	48
The Commerce Department Approves Data Release to the PRC	50



Hughes Tries to Get the PRC to Accept Its Findings	51
CIA Analyst Visits Hughes	56
A 'Consolidated Solution'	58
Final Failure Investigation Report Released to the PRC by the Commerce Department	60
Implementing the 'Consolidated Solution'	64
U.S. Government Actions Following the Apstar 2 Launch Failure	66
Defense Department Assessments of Damage to National Security	68
Damage to National Security from the Apstar 2 Failure Investigation	69
Damage to National Security from the Sharing of Coupled Loads Analysis	72
Damage to National Security from Providing the PRC with	
Information Concerning Deficiencies in the Fairing, and	
Resultant Improvements to PRC Rockets and Ballistic Missiles	73
Other Information Learned by the PRC, and Defense Department Reaction	74
State Department Assessments of Damage to National Secuirty	75
Damage to National Security Identified by the Select	
Committee's Technical Consultant	85
CHARLIE TRIE, THE PRC, AND HUGHES ELECTRONICS	87
FURTHER INVESTIGATION WARRANTED	88
FECHNICAL AFTERWORD: Nose Fairings on Rockets and Ballistic Missiles	90
CHAPTER 6	
Satellite Launches in the PRC: Loral	
CHAPTER SUMMARY	96
INTELSAT 708 LAUNCH FAILURE: LORAL INVESTIGATION PROVIDES	
PRC WITH SENSITIVE INFORMATION: OVERVIEW OF EVENTS	
The PRC's Launch Failure Investigation	
The Asia Pacific Telecommunications Insurance Meeting	
The PRC's Creation of an 'Independent Review Committee'	
The Independent Review Committee's Meetings	
The Independent Review Committee's Report	



Substance of the Preliminary Report	110
The Report Goes to the PRC	
Defense Department Analyst Discovers the Activities	
of the Independent Review Committee	113
Loral and Hughes Investigate the Matter	
The Aftermath: China Great Wall Industry Corporation Revises Its	
Findings on the Cause of the Accident	114
U.S. Government Assessments of the Independent Review	
Committee's Report, and Referral to the Department of Justice	115
DETAILS OF THE FAILED LONG MARCH 3B-INTELSAT 708 LAUNCH	
AND INDEPENDENT REVIEW COMMITTEE ACTIVITIES	116
Background on Intelsat and Loral	116
Intelsat	116
Loral Space and Communications	117
Space Systems/Loral	118
Intelsat 708 Launch Program	118
The Intelsat 708 Launch Failure	119
Events Leading Up to the Creation of the Independent Review Committee	121
The Government Security Committee Meeting at Loral	124
The Apstar 1A Insurance Meeting	128
The April 1996 Independent Review Committee Meetings in Palo Alto	129
Meeting on April 22, 1996	129
Meeting on April 23, 1996	131
Meeting on April 24, 1996	132
United States Trade Representative Meeting on April 23, 1996	132
The April and May 1996 Independent Review Committee Meetings in Beijing	134
Meeting on April 30, 1996	134
Members' Caucus at the China World Hotel	134
Meeting on May 1, 1996	138
The Independent Review Committee Preliminary Report	140
Writing the Report	140
Loral Sends the Draft Report to the PRC	
The Contents of the Draft Report	141



Notification to Loral Officials That a Report Had Been Prepared	142
Loral Review and Analysis of the Independent Review Committee Report	143
The Final Preliminary Report is Sent to the PRC	
Another Copy of the Report is Sent to Beijing	
Loral Management Actions After Delivery of the Report to the PRC	
Defense Department Official Discovers the Activities	
of the Independent Review Committee	147
Meeting with the Defense Technology Security Administration	148
Meeting with the State Department	
Reynard's Telephone Call to Loral	
Loral Management Discovers the Independent Review Committee	
Report Has Been Sent to the PRC	150
Loral's 'Voluntary' Disclosure	151
Investigation by Loral's Outside Counsel	151
Loral Submits Its 'Voluntary' Disclosure to the State Department	151
The PRC Gives Its Final Failure Investigation Report	157
Assessments By U.S. Government Agencies and Referral to the Department of Justice	158
Defense Department 1996 Assessment	158
Central Intelligence Agency Assessment	159
Department of State Assessment	159
Defense Technology Security Administration 1997 Assessment	159
Interagency Review Team Assessment	160
Outline of What Was Transferred to the PRC	161
Independent Review Committee Meeting Minutes	161
Independent Review Committee Preliminary Report	162
Loral's Inaccurate Instructions on Releasing Public Domain Information to Foreigners	162
Instructions to the Independent Review Committee	
Regarding Public Domain Information	162
State Department Views on Public Domain Information	164
The Defense Department Concludes That the Independent Review Committee's	
Work Is Likely to Lead to the Improved Reliability of PRC Ballistic Missiles	164
The Cross-Fertilization of the PRC's Rocket and Missile Design Programs	166
The Independent Review Committee Aided the PRC in Identifying the Cause	
of the Long March 3B Failure	167



The PRC Implemented All of the Independent Review Committee's Recommenda The Independent Review Committee Helped the PRC Improve the Reliability	tions . 168
of Its Long March Rockets	171
AFTERWORD: U.S. COMPANIES' MOTIVATIONS	
TO LAUNCH SATELLITES IN THE PRC	172
CHRONOLOGY OF KEY EVENTS	176
TECHNICAL AFTERWORD: Technical Aspects of Technology Transfer During the Loral Failure Investigation: Background	194
CHAPTER 7	
Protecting Sensitive Information at PRC Launce	h Sites
CHAPTER SUMMARY	218
PROTECTING SENSITIVE INFORMATION AT PRC	
LAUNCH SITES: BACKGROUND	220
U.SPRC Bilateral Agreement	
Export Licenses for PRC Launching of U.S. Satellites	
Defense Department Monitors	222
UNAUTHORIZED ACCESS ALLOWS OPPORTUNITIES TO GAIN INFORMATION CONCERNING U.S. SATELLITES AND	
OTHER CONTROLLED TECHNOLOGY	222
INADEQUACY OF CURRENT SAFEGUARDS	227
SAFEGUARDING U.SBUILT SATELLITES AND U.S. ROCKET	
TECHNOLOGY AT PRC LAUNCHES	237
Country-to-Country Agreements	
Export Licenses	237



DEFICIENCIES OBSERVED IN THE CURRENT SYSTEM	239
U.SPRC Technical Discussions Occur Prior to the Issuance	
of Export Licenses	239
Technology Transfer Control Plans and Security Plans Vary	
Throughout the Space Industry	239
Temporary Assignments of Defense Department Monitors	
Disrupt Continuity of Launch Site Security	240
An Inadequate Number of Defense Department Monitors	
Is Assigned to PRC Launches	242
Uneven Prior Technical Experience of the Defense Department Monitors	244
Inadequate Headquarters Review of Monitor Reports	245
Lack of Headquarters' Support	246
Lack of Intermediate Sanction Authority	
Conflicting Industry Priorities	249
Satellite Manufacturers, Not the Defense Department,	
Supervise Site Security Personnel	250
Reliance on Private Contractor Security Is Inadequate	250
Insufficient Numbers of Security Guards at PRC Launche Sites	
CORRECTING SECURITY DEFICIENCIES	253
The 1999 Defense Authorization Act	



CHAPTER 8 The Role of Commercial Space Insurance in Technology Transfer to the PRC

CHAPTER SUMMARY	268
THE ROLE OF COMMERCIAL SPACE INSURANCE IN	
TECHNOLOGY TRANSFER TO THE PRC	270
Insurance Aspects of the Long March 3B-Loral-Intelsat 708 Failure	270
The Formation of the Independent Review Committee	276
The April 15-16, 1996 Insurance Meeting in Beijing	289
The Space Insurance Industry's Involvement in the Release of the Independent	
Review Committee's Interim Report	292
CHRONOLOGY OF KEY EVENTS	298
TECHNICAL AFTERWORD: The Commercial Space Insurance Industry	300
NOTES	312



