

Notice to Navigation Interests

In reply refer to Notice No. below

US Army Corps of Engineers, Pittsburgh District 1000 Liberty Avenue, Pittsburgh, PA 15222-4186 (412) 395-7640 http://www.lrd.usace.army.mil/navigation/notice/

Notice No. 05-32 Date: October 13, 2005

HANNIBAL LOCKS AND DAM, OHIO RIVER, MILE 126.4 Replace Land Wall Emptying Valve in the 110-ft x 600-ft Land Lock Chamber and Repair Lock Gates in the 110-ft x 1200-ft Lock Chamber

- 1. Notice to Navigation Interests No. 05-25 has been revised due to a change in the scope of work. Additional work needs to be accomplished to repair the lock gate seals in the 110-ft x 1200-ft river lock chamber. This additional work is necessary following a structural failure that occurred on September 15, 2005.
- 2. <u>To All Whom It May Concern:</u> Notice is given that the U.S. Army Corps of Engineers' Repair Fleet will replace the land wall emptying valve and renovate its operating machinery in the 110-ft x 600-ft land lock chamber at Hannibal L/D, Ohio River, Mile 126.4. The work is scheduled to begin at 1:00 A.M. on October 22, 2005 and be completed by about 11:00 P.M. on November 10, 2005.
- 3. The 110-ft x 600-ft land lock chamber will be closed to river traffic during this 20-day repair period. All traffic will pass through the 110-ft x 1200-ft river lock chamber.
- 4. The 110-ft x 1200-ft river lock chamber will also be closed for three (3) 8-hour periods during the 20-day timeframe to weld the miter and quoin seals on both the upstream and downstream lock gates.
- 5. General wear and deterioration of the tainter valve and lock gates have made it necessary to schedule this work.
- 6. Navigators are requested to use caution while entering or leaving the lock chamber and approaches during the repair period.

FOR THE DISTRICT ENGINEER:

/signed/

James J. Rockovich, P.E. Acting Chief, Operations Division

CELRP-OR-TW
Navigation Notice No. 98-25