

Summary Report of Occurrences Reviewed From May 26 –30, 2008

Summary: 20 occurrences at 14 sites reviewed during this period.

Significant Occurrences (1)

Injuries – 1 occurrence at 1 site

- ***NA – Y12 National Security Complex (Significance Category 3).*** On May 21, while welding, a pipefitter felt his arm getting hot, stopped welding, and noticed flames coming from the masking tape on the left forearm of his Anti-C's. The pipefitter and his welder's helper immediately extinguished the flame. The pipefitter then removed his gloves, exited the radiological area through the personnel monitoring station, and reported to supervision. The pipefitter was immediately taken to medical facilities and treated for second degree burns on his left forearm. There was no employee contamination as a result of the incident. Construction welding work was suspended for the Building 9998 job only, notifications were made, and a critique was held.

Other Occurrences (19). See Table (Note: The Table includes the occurrences listed above).

Occurrence Category	Number of Occurrences				Number of Sites
	E&E	NNSA	SC	DOE Total	
Injury - Industrial Hygiene/Occupational Safety	2	2	3	7	7
Near Miss	0	0	0	0	0
Authorization Basis	2	2	0	4	4
Radiological Concerns	0	1	0	1	1
Environmental	0	0	0	0	0
Fire Safety	0	1	0	1	1
Shipping/Quality Assurance	0	0	0	0	0
Criticality Concerns	0	0	0	0	0
Industrial Operations	0	0	0	0	0
Conduct of Operations	0	3	0	3	3
Electrical Safety	0	0	1	1	1
Vehicle Accident	0	0	0	0	0
Equipment Failures	0	0	0	0	0
Safeguards and Security	0	0	0	0	0
Suspect & Counterfeit Parts	0	2	1	3	2
Other	0	0	0	0	0
Total	4	11	5	20	

Secretarial Office Summary

National Nuclear Security Administration	11 occurrences	(6 sites)
Office of Environmental Management	3 occurrences	(3 sites)
Office of Nuclear Energy	1 occurrence	(1 site)
Office of Science	5 occurrences	(4 sites)