Summary Report of Occurrences Reviewed

From December 1 - 8, 2006

Summary: 22 occurrences at 13 sites reviewed during this period.

Significant Occurrences (1)

Injuries – 1 occurrence at 1 site

• <u>Sandia National Laboratory (Significance Category 3)</u>. On November 29, 2006, a subcontract skid-steer loader operator fractured the right fibula when the operator's leg became pinned between the boom and the body of the loader. Operator error caused the boom to lower and pin the right leg. A laborer raised the boom off the operator's leg. The operator was treated at a local hospital.

Other Occurrences (21). See Table (Note: The Table includes the occurrences listed above).

Occurrence Category	Number of Occurrences			Number of Sites
	NNSA	ESE	DOE Total	
Injury – Industrial Hygiene/Occupational	2	0	2	2
Safety				
Near Miss	0	1	1	1
Authorization Basis	1	5	6	6
Environmental	0	3	3	3
Fire Safety	0	1	1	1
Lockout/Tagout	0	1	1	1
Conduct of Operations	1	1	2	2
Equipment Failures	1	0	1	1
Electrical Safety	0	1	1	1
Suspect & Counterfeit Parts	1	1	2	2
Industrial Operations	0	2	2	2
Total	6	16	22	

Secretarial Office Summary

National Nuclear Security Administration	6 occurrences	(5 sites)
Office of Environmental Management	10 occurrences	(5 sites)
Office of Science	3 occurrences	(2 sites)
Office of Nuclear Energy	2 occurrences	(1 site)
Office of Fossil Energy	1 occurrence	(1 site)