Door Retention Components, 207 Seating Systems, 209 Seat Belt Assemblies, 210 Seat Belt Assembly Anchorages, 212 Windshield Mounting, 214 Side Impact Protection, 216 Roof Crush Resistance, 219 Windshield Zone Intrusion, and 302 Flammability of Interior Materials.

Petitioner also contends that the vehicles are capable of being able to meet the following standards, in the manner indicated:

Standard No. 101 Controls and Displays: (a) Replacement of the instrument cluster with the U.S.-model component; (b) replacement of the cruise control lever with a U.S.-model component on vehicles that are not so equipped; (c) reprogramming and initialization of the vehicle control system to integrate the new instrument cluster and activate required warning systems.

Standard No. 108 Lamps, Reflective Devices and Associated Equipment: (a) Installation of U.S.-model headlamps and front sidemarker lights; (b) installation of U.S.-model taillamp assemblies or modification of existing taillamps to conform to the standard; (c) installation of U.S.-model sidemarker lights.

Standard No. 111 Rearview Mirrors: replacement of the passenger side rearview mirror with a U.S.-model component or inscription of the required warning statement on the mirror's surface.

Standard No. 114 *Theft Protection:* reprogramming of the vehicle control systems to activate the required driver warning.

Standard No. 118 Power-Operated Window, Partition, and Roof Panel Systems: reprogramming of the vehicle control systems to meet the requirements of this standard.

Standard No. 120 Tire Selection and Rims for Motor Vehicles Other than Passenger Cars: installation of a tire information placard.

Standard No. 208 Occupant Crash Protection: programming of the vehicle control systems to activate the required seat belt warning system. The petitioner states that the vehicles are equipped with driver's and passenger's air bags and knee bolsters, and with combination lap and shoulder belts that are self-tensioning and that release by means of a single red push button at the front and rear outboard seating positions.

Standard No. 225 Child Restraint
Anchorage Systems: installation of U.S.model child seat anchorage
components.

Standard No. 301 Fuel System Integrity: The petitioner states that the

vehicles' fuel systems must be modified with U.S.-model parts to meet U.S. Environmental Protection Agency (EPA) OBDII, Spit Back, and enhanced EVAP requirements. The petitioner claims that as modified, these systems will control all fuel leaks in the case of an impact.

The petitioner also states that a vehicle identification plate must be affixed to the vehicle near the left windshield post and a reference and certification label must be affixed in the area of the left front door post to meet the requirements of 49 CFR part 565.

Interested persons are invited to submit comments on the petition described above. Comments should refer to the docket number and be submitted to: Docket Management, Room PL–401, 400 Seventh St., SW., Washington, DC 20590. [Docket hours are from 9 am to 5 pm.] It is requested but not required that 10 copies be submitted.

All comments received before the close of business on the closing date indicated above will be considered, and will be available for examination in the docket at the above address both before and after that date. To the extent possible, comments filed after the closing date will also be considered. Notice of final action on the petition will be published in the Federal Register pursuant to the authority indicated below.

Authority: 49 U.S.C. 30141(a)(1)(A) and (b)(1); 49 CFR 593.8; delegations of authority at 49 CFR 1.50 and 501.8.

Claude H. Harris,

Director, Office of Vehicle Safety Compliance. [FR Doc. 04–26752 Filed 12–3–04; 8:45 am] BILLING CODE 4910–59–P

DEPARTMENT OF THE TREASURY

Submission for OMB Review; Comment Request

November 29, 2004.

The Department of Treasury has submitted the following public information collection requirement(s) to OMB for review and clearance under the Paperwork Reduction Act of 1995, Public Law 104–13. Copies of the submission(s) may be obtained by calling the Treasury Bureau Clearance Officer listed. Comments regarding this information collection should be addressed to the OMB reviewer listed and to the Treasury Department Clearance Officer, Department of the Treasury, Room 11000, 1750 Pennsylvania Avenue, NW., Washington, DC 20220.

Dates: Written comments should be received on or before January 5, 2005 to be assured of consideration.

Financial Crimes Enforcement Network (FinCEN)

OMB Number: 1506-0013.

Form Number: FinCEN 104 (Formerly Customs Form 4789).

Type of Review: Revision.

Title: Registration of Money Services Business, 31 CFR 103.41.

Description: Money services businesses file Form 107 to register with the Department of the Treasury pursuant to 31 U.S.C. 5330 and 31 CFR 103.41. The information on the form is used by criminal investigators, and taxation and regulatory enforcement authorities, during the course of investigations involving financial crimes.

Respondents: Business or other forprofit, Individuals or households, Notfor-profit institutions.

Estimated Number of Respondents/ Recordkeepers: 17,000.

Estimated Burden Hours Per Respondent/Recordkeeper: 45 minutes. Frequency of Response: Other (as required).

Estimated Total Reporting/ Recordkeeping Burden: 17,600 hours.

Clearance Officer: Steve Rudzinski, (703) 905–3845, Financial Crimes Enforcement Network, 2070 Chain Bridge Road, Suite 200, Vienna, VA 22182.

OMB Reviewer: Joseph F. Lackey, Jr., (202) 395–7316, Office of Management and Budget, Room 10235, New Executive Office Building, Washington, DC 20503.

Lois K. Holland,

Treasury PRA Clearance Officer. [FR Doc. 04–26720 Filed 12–3–04; 8:45 am] BILLING CODE 4810–02–P

DEPARTMENT OF THE TREASURY

Submission for OMB Review; Comment Request

November 29, 2004.

The Department of Treasury has submitted the following public information collection requirement(s) to OMB for review and clearance under the Paperwork Reduction Act of 1995, Public Law 104–13. Copies of the submission(s) may be obtained by calling the Treasury Bureau Clearance Officer listed. Comments regarding this information collection should be addressed to the OMB reviewer listed and to the Treasury Department Clearance Officer, Department of the Treasury, Room 11000, 1750