

Issued in College Park, Georgia, on August 13, 2003.

**Walter R. Cochran,**  
Acting Manager, Air Traffic Division,  
Southern Region.

[FR Doc. 03-21323 Filed 8-19-03; 8:45 am]

BILLING CODE 4910-13-M

**DEPARTMENT OF TRANSPORTATION**

**Federal Aviation Administration**

**14 CFR Parts 121, 125, and 135**

[Docket No.: FAA-2003-15682; Amendment Nos. 121-288, 125-42, 135-84]

RIN 2120-AH89

**Digital Flight Data Recorder Requirements—Changes to Recording Specifications and Additional Exceptions; Correction**

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule, correction.

**SUMMARY:** This document makes corrections to the final rule published in the **Federal Register** on July 18, 2003. This document makes some minor corrections and it also adds Parameter 15 to the document under parts 121 and 125, and changes the resolution in Parameter 15 by 0.1%.

**DATES:** This correction is effective August 18, 2003.

**FOR FURTHER INFORMATION CONTACT:** Gary Davis, Flight Standards Service, Air Transportation Division; telephone (202) 267-8166; facsimile (202) 267-5229; e-mail [gary.davis@faa.gov](mailto:gary.davis@faa.gov).

**Background**

In response to a series of recommendations issued by the National Transportation Safety Board (NTSB), the FAA revised and updated parts 121, 125 and 135 of Title 14, Code of Federal Regulations (14 CFR) in 1997 to require that flight data recorders on U.S. registered airplanes be upgraded to record additional parameters of data (62 FR 38362, July 17, 1997). The exact number of parameters required depends on the age of the airplane; airplanes manufactured after August 19, 2002, must record 88 parameters of flight data.

The final rule published on July 18, 2003 (68 FR 42932) amends the flight data recorder regulations by expanding the recording specifications of certain data parameters for specified airplanes, and by adding aircraft models to the lists of aircraft excepted from the 1997 regulations. In addition, this rule corrects specifications in an operating rule appendix that were inadvertently omitted in previous actions. These changes are necessary to allow the continued operation of certain aircraft that are unable to meet the existing recorder criteria using installed equipment. The changes are also necessary for certain aircraft for which the cost to retrofit under 1997 regulatory changes would be cost prohibitive.

**List of Subjects**

*14 CFR Part 121*

Air carriers, Aircraft, Aviation safety, Reporting and recordkeeping requirements, Safety, Transportation.

*14 CFR Part 125*

Aircraft, Aviation safety, Reporting and recordkeeping requirements.

*14 CFR Part 135*

Air taxis, Aircraft, Aviation safety, Reporting and record keeping requirements.

**The Amendment**

■ In consideration of the foregoing, the Federal Aviation Administration corrects Chapter I of Title 14, Code of Federal Regulations as follows:

**Correction**

■ In the final rule “Digital Flight Data Recorder Requirements—Changes to Recording Specifications and Additional Exceptions” published in the **Federal Register** on July 18, 2003, FR Doc. No. 03-18269 (68 FR 42932) make the following correction:

1. On Page 42932, in the first column, in the document heading, correct “RIN 2120-AH81” to read “RIN 2120-AH89”.
2. On Page 42936, in the second column, in paragraph (2), line 9, correct the words “Jetstream 4100” to read “Jetstream 4100 Series,”.
3. On Page 42936, in the third column, in Amendment Number 4, line 2, correct “5, 9, 12a, 14a, 16,” to read “5, 9, 12a, 14a, 15, 16,”.
4. On Page 42937, in the second column, in paragraph (2), line 9, correct the words “Jetstream 4100” to read “Jetstream 4100 Series,”.
5. On Page 42937, in the third column, in Amendment Number 9, line 2, correct “5, 9, 12a, 14a, 16,” to read “5, 9, 12a, 14a, 15, 16,”.
6. In the charts on pages 42936 and 42938 after “14a” insert the following:

15. Pitch Control Surface(s) Position. <sup>6</sup>	Full Range .....	+/- 2° Unless Higher Accuracy Uniquely Required.	0.5 or 0.25 for airplanes operated under § 135.152(j).	0.3% of full range.	For airplanes fitted with multiple or split surfaces, a suitable combination of inputs is acceptable in lieu of recording each surface separately. The control surfaces may be sampled alternately to produce the sampling interval of 0.5 or 0.25.
---	------------------	--	--	---------------------	---

7. On page 42939, in the “Parameters” column, in 15, in the “Resolution” column, correct “0.2% of full range” to read “0.3% of full range.”.

Issued in Washington, DC, on August 12, 2003.

**Donald P. Byrne,**  
Assistant Chief Counsel for Regulations.

[FR Doc. 03-21329 Filed 8-19-03; 8:45 am]

BILLING CODE 4910-13-U

**DEPARTMENT OF HEALTH AND HUMAN SERVICES**

**Food and Drug Administration**

**21 CFR Part 172**

[Docket No. 98F-0717]

**Food Additives Permitted for Direct Addition to Food for Human Consumption; Sucrose Oligoesters**

**AGENCY:** Food and Drug Administration, HHS.

**ACTION:** Final rule.

**SUMMARY:** The Food and Drug Administration (FDA) is amending the food additive regulations to provide for the safe use of sucrose oligoesters (sucrose esters of fatty acids with an average degree of esterification ranging from four to seven) as an emulsifier or stabilizer, at a level not to exceed 2.0 percent, in chocolate and in butter-substitute spreads. This action is in response to a petition filed by Mitsubishi Chemical Corp.