




Structurally Deficient Bridges on the National Highway System Massachusetts - Congressional District 01



Consult your state DOT for the most up-to-date status of bridges.

Area of Detail



Note: The bridges displayed on this map represent the results of a combined BTS/FHWA effort to geocode bridges from the FHWA's National Bridge Inventory (NBI). With the exception of Kentucky and Pennsylvania, whose most current data is 2006, all data is from the 2007 NBI. Of the 187 structurally deficient NHS bridges in Massachusetts, 11 could not be geolocated because of insufficient data. Structurally deficient bridges are not necessarily unsafe; all public road bridges receive regular safety inspections. The bridges listed were categorized as structurally deficient at the time the maps were developed.

Bridge Label	Structure ID	Bridge Description	Location Description
1	N140320DPMHD634	ST 2 W MAIN ST	W OF RTE 2 VIADUCT
2	W250100V8MHDNBI	US202 /ST10/ELM ST	JCT MEADOW ST.
3	E050060V0MHDNBI	ST 10 NORTHMPTN ST	1.3 M S EASTHAMPTON T.L.
4	D060450X5MHDNBI	I 91 SB	3.1 M S GFLD-DFLD T.L.
5	D060440X4MHDNBI	I 91 SB	OVER DEERFIELD RIVER
6	D060440X3MHDNBI	I 91 NB	OVER DEERFIELD RIVER
7	G120600XLMHDNBI	I 91 NB	OVER ST 2 WB ROTARY
8	G120580XEMHDNBI	I 91 NB	.7 M N DFLD-GFLD T.L.
9	E050240X7MHDNBI	I 91 SB	.2 M N HOLYOKE C.L.
10	E050240X8MHDNBI	I 91 NB	.2 M N HOLYOKE C.L.
11	H210380VRMHDNBI	US202 SB	.1 M S BR # H-21-35
12	G120070UGMHDNBI	ST 2 A/LOWER MAIN	100' E JCT RIVER ST.
13	H210390VQMHDNBI	US202 NB/BEECH ST	JCT LYMAN ST.
14	H21018126MHDNBI	HWY LYMAN ST	AT JCT E COURT ST.
15	H21016125MHDNBI	HWY LYMAN ST	AT JCT RACE ST.
16	G120550XVMHDNBI	I 91 SB/ST2 WB	.5 MI S EXIT #27 SB
17	W2102515DMHDNBI	ST147 WB/MEM AVE	AT JCT US 5 & MEMORIAL AV
18	G120420Y0MHDNBI	I 91 SB	.7 M S BERNDSTN-GFLD T.L.
19	G040030UFMHDNBI	ST 2	0.1 MI W OF MAIN RD
20	E100130UEMHDNBI	ST 2 MOHAWK TRAIL	.7 M E CONN RIVER
21	E100160UDMHDNBI	ST 2 MOHAWK TRAIL	1.0 MI E OF CONN RIV
22	B050270UTMHDNBI	ST 9 WARE RD	.3 M W JCT RIVER RD.
23	O030210VYMHDNBI	US202 ST2	4.8 M E JCT WENDELL T.L.
24	A1503019LMHDNBI	ST 2	ST 2 /LAKE ROHUNTA
25	A1503319QMHDNBI	ST 2	ST 2 / WHITE POND RD
26	A1501818TMHDNBI	ST 2 A/S MAIN ST	0.1 KM E OF TL
27	A1503419PMHDNBI	ST 2	STATE 2 / SOUTH ATHOL RD
28	A1500618RMHDNBI	ST 2 A/S MAIN ST	WEST END OF DWNTWN MAIN S
29	W050040UWMHDNBI	ST 9 EAST ST	AT GROVE ST.
30	A150131B2MHD634	ST 2 A/MAIN ST	.1 M W JCT CHSNT HILL RD.
31	P0900419BMHDNBI	US202 /ST2	AT EXIT 18
32	P09006199MHDNBI	ST 2 WB	ST 2WB/US202 & ST 2A
33	G010351NHMHDNBI	ST 2 EB	.5 MI. EAST OF ST-2A
34	W280211P3MHDNBI	ST 2 WB	.6 MI NORTH OF JCT. OF 2A
35	W280211P4MHDNBI	ST 2 EB	.6 MI NO. OF JCT OF 2A
36	W280221NYMHDNBI	ST 2 EB	.25 MILES MORTH OF ST 2A
37	W280221P0MHDNBI	ST 2 WB	.25 MILES NORTH OF ST 2A
38	F040081KTMHDNBI	ST 31 RIVER ST	100 FT EA OF WALLACE ST
39	F040101KRMHDNBI	ST 31 RIVER ST	EAST OF BROAD STREET
40	S250241WBMHDNBI	I 190 SB	.4 MILES EAST OF ST. 140
41	S250261WFMHDNBI	I 190 NB	1 MILE NORTH OF ST 140
42	L080241KEMHDNBI	ST 12 N MAIN ST	NORTH MAIN ST/ ST 2